

CK-2236

SOWAQUA CREEK 9.6km

2016 Inspection



CBR iPad Offline Ver 0.23

CBR Data

Latitude	Longitude		
49°23'44.59"	-121°11'51.7"		
Crossing Name	Not Known		
FSR #	7004	Branch #	1
Road Name	SOWAQUA CREEK		
User km	9.6		
Current Load Rating (tonnes)	68		
Structure Class	Temporary Bridge		
Portable	Y		
Superstructure	Steel I-beam		
Deck Type	Timber - Untreated		
Abutment Left	Sill -Temporary Materials		
Abutment Right	Sill -Temporary Materials		
Spans	1		
Total Length (m)	15.2		
Deck Width (m)	4.9		

Updated Data

Latitude	Longitude		
49°23'44.51"	-121°11'51.87"		
HD Diff. (m)	4.4	Accuracy (m)	5

Inspection

Date of Inspection 2016-08-17 10:29:04 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Post bridge ahead signs and monitor bridge following high flow events to confirm the stability of the abutments due to the limited riprap protection. Due to the incomplete bearing of the steel bearing plates and the log sill monitor the plates for deformation during industrial use. There is no indication of the term of this installation, and given the abutment material it is considered temporary; however there is no indication of it meeting the Q10 or Q50 flows (it doesn't meet the Q100 flows as indicated on the record drawings on file). The steel girders indicate L75 loading; however the record drawings on file indicate L100 design. Please send in the signed record drawings, structural drawings and crossing assurance statement ASAP.



28/02/2017

P.Eng Seal

CK-2236

SOWAQUA CREEK 9.6km

2016 Inspection



CBR iPad Offline Ver 0.23

Approach

Alignment Fair

VC both approaches

 Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

 Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

boulders at left approach

Posted Load Rating

not posted

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete N/A

Caps or Sills Fair

single log sill wrapped in fabric

Piles or Posts N/A

Ballast Wall Fair

Wing Wall N/A

Bracing N/A

Hardware Fair

Fill Fair

Riprap Fair to poor

limited and not well keyed in or tied together

Bearings Poor

bear plates not completely on sills and loosely fasten

Corrosion Protection N/A

CK-2236

SOWAQUA CREEK 9.6km

2016 Inspection



CBR iPad Offline Ver 0.23

Deck

Running Surface N/A

Running Planks Fair

Sub Deck Fair

Ties Fair

Nails Fair

Deck to Girder Bolts Good

Concrete Deck N/A

Grout Pockets N/A

Deck Joints N/A

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts N/A

Hardware N/A

Overall Deck Condition Fair

Gravel Depth (mm)

CK-2236

SOWAQUA CREEK 9.6km

2016 Inspection



CBR iPad Offline Ver 0.23

Steel/Concrete

Serial/ID Plate

Girders Fair

minor corrosion

Diaphragms Fair

bottom chords are twisted

Bracing Fair

Under Trussing N/A

Hardware N/A

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2236

SOWAQUA CREEK 9.6km

2016 Inspection

CBR iPad Offline Ver 0.23



Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1	Medium	post bridge ahead signs
---	--------	-------------------------

2		
---	--	--

3		
---	--	--

Item	Monitor Description	Frequency
1	due to limited riprap monitor abutment scour	following high flow events

2	due to the poor bearing monitor the bearing plates for deformation	during industrial use
---	--	-----------------------

3		
---	--	--

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



looking upstream from deck



Deck



looking downstream from deck



Approach from Right Bank when facing downstream



Left Bank Abutment when facing downstream



Structure ID



right bank downstream bearing - not fully on log sill - no signs of stress



Right Bank Abutment when facing downstream



left bank upstream bearing not fully on log sill - no signs of stress



deck clips



left bank downstream bearing plate barely on log sill - no signs of stress