

CK-2525

BIG SILVER 2.5km

2016 Inspection

CBR iPad Offline Ver 0.23



CBR Data

Latitude	Longitude
49°36'2"	-121°49'57"
Crossing Name	Side Creek
FSR #	5748
Branch #	30
Road Name	BIG SILVER
User km	2.5
Current Load Rating (tonnes)	68
Structure Class	Temporary Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Removable
Abutment Left	Concrete Lock Blocks
Abutment Right	Concrete Lock Blocks
Spans	1
Total Length (m)	16.2
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°36'3.35"	-121°49'55.75"
HD Diff. (m)	48.6
Accuracy (m)	5

Inspection

Date of Inspection 2016-11-08 10:41:28 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Repair damaged panels and replace missing deck joint seals. Present load rating of L75 or 68 tonnes to continue.



17/01/2017

P.Eng Seal

CK-2525

BIG SILVER 2.5km

2016 Inspection



CBR iPad Offline Ver 0.23

Approach

Alignment Fair

 Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

 Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating not posted

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete Good 4x lock blocks

Caps or Sills Good timber

Piles or Posts N/A

Ballast Wall Good concrete

Wing Wall Good lock blocks

Bracing Good geotextile between each row of blocks

Hardware Good

Fill Good

Riprap Good

Bearings Good

Corrosion Protection N/A

CK-2525

BIG SILVER 2.5km

2016 Inspection

CBR iPad Offline Ver 0.23

**Deck**

Running Surface Fair

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts Good

Concrete Deck Fair some damage to underside of 2 panels

Grout Pockets N/A

Deck Joints Fair deck seals missing in couple locations

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts N/A

Hardware N/A

Overall Deck Condition Fair

Gravel Depth (mm)

CK-2525

BIG SILVER 2.5km

2016 Inspection



CBR iPad Offline Ver 0.23

Steel/Concrete

Serial/ID Plate

Girders Good

Diaphragms Good

Bracing Good

Under Trussing N/A

Hardware Good

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

CK-2525

BIG SILVER 2.5km

2016 Inspection

CBR iPad Offline Ver 0.23



Hazards

Estimated Present Water Level Depth (m)	0.4	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	7.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1	Medium	repair damaged panels
2	Medium	replace missing deck joint seals

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Deck



Approach from Left Bank when facing downstream



deck seals missing in some locations



Approach from Right Bank when facing downstream



deck panel damage and rebar exposed



Left Bank Abutment when facing downstream



deck panel damage at right bank



Right Bank Abutment when facing downstream



Upstream Profile



deck panel damage at left bank