

49km Harrison

East

CBR iPad Offline Ver 0.23

Harrison East FSR 48.8km

2016 Inspection



CBR Data

Latitude	Longitude
°0'0"	°0'0"
Crossing Name	unknown
FSR #	5748
Branch #	01
Road Name	Harrison East FSR
User km	48.8
Current Load Rating (tonnes)	L150 or 136 tonnes
Structure Class	Major Culvert
Culvert Type	Round
Culvert Material	Corrugated Steel
Opening Height (mm)	2000
Opening Width (mm)	2000
Inlet Cover (mm)	1300
Outlet Cover (mm)	1300
Culvert Gradient %	2
Culvert Length (m)	22

Updated Data

Latitude	Longitude
49°42'54.49"	-121°51'4.22"
HD Diff. (m)	9968450.2
Accuracy (m)	5

Inspection

Date of Inspection 2016-08-09 10:45:08 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

culvert skewed approx 20 degrees

P.Eng Comments

Present load rating of L150 or 136 tonnes to continue.



02/03/2017

P.Eng Seal

49km Harrison

East

Harrison East FSR 48.8km

2016 Inspection

CBR iPad Offline Ver 0.23



Approach

Alignment **Excellent**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Unrated** **NA**

Posted Load Rating **not posted**

Road Surface **Good**

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall **N/A**

Bracing

Hardware

Fill **Good**

Riprap **Good**

Bearings

Corrosion Protection

49km Harrison

East

CBR iPad Offline Ver 0.23

Harrison East FSR 48.8km

2016 Inspection

**Culvert**

Baffles N/A

Bolted Connections N/A

Coating Good

Coupled Connections Good

Embedment Materials N/A

Fill Good

Floor Good

Footing Good

Head Walls N/A

Inlet Good

Outlet Good

Overall Good

Rip Rap Good

Roof Good

Sidewalls Good

Trash Rack N/A

Weirs/Backwater
Structures N/A

Wing Walls N/A

49km Harrison

East

CBR iPad Offline Ver 0.23

Harrison East FSR 48.8km

2016 Inspection



Hazards

Estimated Present Water Level Depth (m)	0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



looking upstream from road surface



Fir creek jct



looking downstream from road surface

49km Harrison

Harrison East FSR 48.8km

2016 Inspection



Approach from Right Bank when facing downstream



fibre optics line buried in road