

CK-2045

CHEHALIS-MYSTERY 6.9km

2017 Inspection

CBR iPad Offline Ver 0.26



CBR Data

Latitude	Longitude
49°30'56.99"	-121°55'44"
Crossing Name	Mystery creek
FSR #	8241
Branch #	11
Road Name	CHEHALIS-MYSTERY
User km	6.9
Current Load Rating (tonnes)	68
Structure Class	Permanent Bridge
Portable	N
Superstructure	Concrete Slab Girders
Deck Type	Concrete
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	14
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°30'57.3"	-121°55'43.9"
HD Diff. (m)	9.5
Accuracy (m)	10
1.5	

Inspection

Date of Inspection 2017-06-20 9:32:05 AM

Recommended Next Inspection Year 2020

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Realign the concrete no post barriers and post bridge ahead signs. Present load rating of L75 or 68 tonnes to continue.



07/09/2017

P.Eng Seal

CK-2045

CHEHALIS-MYSTERY 6.9km

2017 Inspection



CBR iPad Offline Ver 0.26

Approach

Alignment Fair

VC and HC both approaches

Bridge Ahead Signs
Missing
☐ 0
 ☐ 1
 ☒ 2

Brushing Required N

Delineator Missing
Left
☒ 0
 ☐ 1
 ☐ 2
Delineator Missing
Right
☒ 0
 ☐ 1
 ☐ 2

Fender Condition Fair

concrete no post barriers not aligned properly

Posted Load Rating

not posted

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills Good

Cap/wall combo

Piles or Posts Unrated

Buried behind riprap

Ballast Wall Good

Wing Wall

Bracing Unrated

Buried

Hardware Fair

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Unrated

Buried

CK-2045

CHEHALIS-MYSTERY 6.9km

2017 Inspection

CBR iPad Offline Ver 0.26



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Fair Some track damage on wheel path

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Fair minor damage down stream right approach

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Fair

Gravel Depth (mm)

CK-2045

CHEHALIS-MYSTERY 6.9km

2017 Inspection

CBR iPad Offline Ver 0.26

**Steel/Concrete**

Serial/ID Plate

Girders Good 4 concrete slabs

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted shear connectors Good Grouted

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2045

CHEHALIS-MYSTERY 6.9km

2017 Inspection

CBR iPad Offline Ver 0.26



Hazards

Estimated Present Water Level Depth (m)	0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	0	Aggradation	☒	Scour	☐
Estimated High Water Level Clearance (m)	0.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	Medium	Realign concrete no post barriers prior to hauling

2	Medium	Post bridge ahead signs
---	--------	-------------------------

3		
---	--	--

Item	Monitor Description	Frequency
1		

2		
---	--	--

3		
---	--	--

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Right downstream approach concrete no pos barriers could be realigned



Deck



Looking upstream from deck



Looking downstream from deck



Damage to right downstream guardrail - still functional



Left upstream approach concrete no post barriers should be realigned



Left downstream concrete no post barriers should be realigned



Approach from Left Bank when facing downstream



Left Bank Abutment when facing downstream



Upstream Profile



Right Bank Abutment when facing downstream