

CK-2123

SHOVEL CREEK 7.6km

2017 Inspection

CBR iPad Offline Ver 0.26



CBR Data

Latitude	Longitude
49°48'34.09"	-121°46'43.3"
Crossing Name	Pick Creek
FSR #	5748
Branch #	6
Road Name	SHOVEL CREEK
User km	7.6
Current Load Rating (tonnes)	64
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Removable
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	18.3
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°48'34.43"	-121°46'43.24"
HD Diff. (m)	10.4
Accuracy (m)	5

Inspection

Date of Inspection 2017-08-01 9:31:42 AM

Inspector Name Tyson Miller

Inspector Comments

Recommended Next Inspection Year 2020

Inspection Company MFLNRO

P.Eng Comments

Brush and grade approaches. Current load rating of BCL625 or 64 tonnes to continue.



05/02/2018

P.Eng Seal

CK-2123

SHOVEL CREEK 7.6km

2017 Inspection



CBR iPad Offline Ver 0.26

Approach

Alignment Fair

HC both approaches

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating 63730

Road Surface Fair

Fair to poor as wilderness road

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts Good

Ballast Wall Good

Wing Wall

Bracing Good

Hardware

Fill Good

Riprap Good

Bearings Fair

Bearing plates at right abutment at extent of slot causing pad to bulge

Corrosion Protection Good

CK-2123

SHOVEL CREEK 7.6km

2017 Inspection

CBR iPad Offline Ver 0.26



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts **Good**

Concrete Deck **Good**

Grout Pockets **Good**

Deck Joints **Good**

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware **Good**

Overall Deck Condition **Good**

Gravel Depth (mm)

CK-2123

SHOVEL CREEK 7.6km

2017 Inspection



CBR iPad Offline Ver 0.26

Steel/Concrete

Serial/ID Plate See photo

Girders Good

Diaphragms Good 6 bolted bays

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2123

SHOVEL CREEK 7.6km

2017 Inspection

CBR iPad Offline Ver 0.26



Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	7.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	3.0	Ice	☐		

Comments

Repairs and Monitoring

Repair

Item	Priority	Repair Description
1	Low	Grade and brush road if/when used for industrial purposes
2		
3		

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Deck



Approach from Left Bank when facing downstream



Looking upstream from deck



Looking downstream from deck



Approach from Right Bank when facing downstream



Approach from Right Bank when facing downstream



Structure ID



Left Bank Abutment when facing downstream



Upstream Profile



Bolts at extent of slots at right abutment



Deck bolts - typical



Right Bank Abutment when facing downstream



Superstructure



Small spall at left bank ballast wall