

CK-2319

GARNET CREEK 9km

2017 Inspection



CBR iPad Offline Ver 0.26

CBR Data

Latitude	Longitude
49°25'30.9"	-121°35'53.6"
Crossing Name	Side Creek
FSR #	7558
Branch #	1
Road Name	GARNET CREEK
User km	9
Current Load Rating (tonnes)	63
Structure Class	Temporary Bridge
Portable	Y
Superstructure	Steel Box Beam
Deck Type	Steel
Abutment Left	Sill -Temporary Materials
Abutment Right	Sill -Temporary Materials
Spans	1
Total Length (m)	18.3
Deck Width (m)	4.3

Updated Data

Latitude	Longitude
49°25'30.87"	-121°35'53.25"
HD Diff. (m)	7.1
Accuracy (m)	5

Inspection

Date of Inspection 2017-06-14 11:05:58 AM

Recommended Next Inspection Year 2019

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Brush when active. Present load rating of BCL-625 or 63 tonnes to continue.



19/06/2017

P.Eng Seal

CK-2319

GARNET CREEK 9km

2017 Inspection



CBR iPad Offline Ver 0.26

Approach

Alignment Fair

HC and VC both approaches

Bridge Ahead Signs

Missing

☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing

Left

☒ 0 ☐ 1 ☐ 2

Delineator Missing

Right

☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Logs

Posted Load Rating

Not posted

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills Fair

Logs, LB has a timber plate on top of log

Piles or Posts

Ballast Wall Poor

None

Wing Wall

Bracing

Hardware

Fill Good

Riprap Good

Bearings Good

Corrosion Protection

CK-2319

GARNET CREEK 9km

2017 Inspection

CBR iPad Offline Ver 0.26



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate **Good**

Gravel Surface

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware

Overall Deck Condition **Good**

Gravel Depth (mm)

CK-2319

GARNET CREEK 9km

2017 Inspection



CBR iPad Offline Ver 0.26

Steel/ConcreteSerial/ID Plate **Magnum, BCL-625**Girders **Good**Diaphragms **Unrated** Inside box beams, no deformation notedBracing **Unrated** Inside box beams, no deformation noted

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2319

GARNET CREEK 9km

2017 Inspection

CBR iPad Offline Ver 0.26



Hazards

Estimated Present Water Level Depth (m)	0.3	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	4.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1	Low	Brush when active
---	-----	-------------------

2		
---	--	--

3		
---	--	--

Item	Monitor Description	Frequency
------	---------------------	-----------

1		
---	--	--

2		
---	--	--

3		
---	--	--

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Looking upstream from deck



Deck



Looking downstream from deck



Approach from Left Bank when facing downstream



Right Bank Abutment when facing downstream



Structure ID - wrong site ID



Superstructure