

CK-2332

STAVE RIVER 1.4km

2017 Inspection



CBR iPad Offline Ver

Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2 N/A

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated N/A

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall N/A

Bracing

Hardware

Fill Good

Riprap Good

Bearings

Corrosion Protection

CK-2332

STAVE RIVER 1.4km

2017 Inspection

CBR iPad Offline Ver



Culvert

Baffles N/A

Bolted Connections N/A

Coating N/A

Coupled Connections Good

Embedment Materials Good

Fill Good

Floor Good

Footing Unrated N/A

Head Walls N/A

Inlet Fair Left culvert has damaged inlet and small buildup of bedload. Right culvert appears nicely embedded

Outlet Good

Overall Good

Rip Rap Good

Roof Good

Sidewalls Good

Trash Rack N/A

Weirs/Backwater Structures N/A

Wing Walls N/A

CK-2332

STAVE RIVER 1.4km

2017 Inspection

CBR iPad Offline Ver



Hazards

Estimated Present Water Level Depth (m)	0	High Water	☐	Debris	☒
Estimated Present Water Level Width (m)	0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1	Ice	☐		

Comments Stream appears capable of transporting bedload as Site is likely on a fan.

Repairs and Monitoring

Repair		Repair Description	Frequency
Item	Priority		
1			
2			
3			

Item	Monitor Description	Frequency
1	bedload	Routine inspection
2		
3		

Sketch
(Select Signature)

CK-2332

STAVE RIVER 1.4km

2017 Inspection



Left approach viewed from bridge



Approach from Right Bank when facing downstream



Right approach viewed from bridge



Approach from Left Bank when facing downstream



Inlet



Outlet



Damaged inlet likely from excavator cleaning bedload