

CK-2360

KOOKIPI SEVEN 3.8km

2017 Inspection

CBR iPad Offline Ver 0.26



CBR Data

Latitude	Longitude
49°57'10.29"	-121°43'2.4"
Crossing Name	Not Known
FSR #	6996
Branch #	7
Road Name	KOOKIPI SEVEN
User km	3.8
Current Load Rating (tonnes)	68
Structure Class	Permanent Bridge
Portable	N
Superstructure	Other
Deck Type	Concrete
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	14.6
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°57'10.16"	-121°43'2.9"
HD Diff. (m)	10.9
Accuracy (m)	5

Inspection

Date of Inspection 2017-08-09 11:22:38 AM

Inspector Name Tyson Miller

Inspector Comments

Recommended Next Inspection Year 2020

Inspection Company MFLNRO

P.Eng Comments

Replace guardrail, risers and blocks. Clean debris and sediment from the deck and post bridge ahead signs. Present load rating of L75 or 68 tonnes to continue.



15/01/2018

P.Eng Seal

CK-2360

KOOKIPI SEVEN 3.8km

2017 Inspection



CBR iPad Offline Ver 0.26

Approach

Alignment Good

 Bridge Ahead Signs
 Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

 Delineator Missing
 Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing
 Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating Not posted

Road Surface Poor Semi deactivated

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills Good Concrete cap

Piles or Posts Unrated Buried

Ballast Wall Good

Wing Wall Fair lock blocks at both downstream abutments

Bracing

Hardware

Fill Fair

Riprap Good

Bearings Good

Corrosion Protection

CK-2360

KOOKIPI SEVEN 3.8km

2017 Inspection

CBR iPad Offline Ver 0.26

**Deck**

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Good

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Poor Rotten and broken

Hand Rails/Walkouts

Hardware Poor Loose rail bolts

Overall Deck Condition Poor Due to rail condition

Gravel Depth (mm)

CK-2360

KOOKIPI SEVEN 3.8km

2017 Inspection



CBR iPad Offline Ver 0.26

Steel/Concrete

Serial/ID Plate

Girders **Good**

2 inverted C channels

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2360

KOOKIPI SEVEN 3.8km

2017 Inspection

CBR iPad Offline Ver 0.26



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	0.3	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

- | | | |
|---|--------|--------------------------------------|
| 1 | Medium | Replace guardrail, risers and blocks |
| 2 | Medium | Post bridge ahead signs |
| 3 | Medium | Clean debris and sediment from deck |

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Guard Rail



Deck



Looking upstream from deck



Looking downstream from deck



Right Bank Abutment when facing downstream



Approach from Left Bank when facing downstream



Left Bank Abutment when facing downstream