

CK-2406

PITT RIVER 18.5km

2017 Inspection



CBR iPad Offline Ver

## CBR Data

|                              |                               |
|------------------------------|-------------------------------|
| Latitude                     | Longitude                     |
| 49°40'47.79"                 | -122°41'8.5"                  |
| Crossing Name                | not known                     |
| FSR #                        | 8394                          |
| Branch #                     | 1                             |
| Road Name                    | PITT RIVER                    |
| User km                      | 18.5                          |
| Current Load Rating (tonnes) | 109                           |
| Structure Class              | Temporary Bridge              |
| Portable                     | N                             |
| Superstructure               | Log Stringers                 |
| Deck Type                    | Gravel                        |
| Abutment Left                | Crib, Log or Untreated Timber |
| Abutment Right               | Crib, Log or Untreated Timber |
| Spans                        | 1                             |
| Total Length (m)             | 11.7                          |
| Deck Width (m)               | 5                             |

## Updated Data

|                   |               |
|-------------------|---------------|
| Latitude          | Longitude     |
| 49°40'46.01"      | -122°41'6.53" |
| HD Diff. (m)      | 68.0          |
| Accuracy (m)      | 5             |
| L100 or 91 tonnes |               |

## Inspection

Date of Inspection 2017-09-14 6:10:21 PM

Recommended Next Inspection Year 2019

Inspector Name Michael Foster

Inspection Company Onsite Engineering Ltd

Inspector Comments

Appears to be good bridge. stringer 1 has woodpecker damage and should be replaced. Other stringers were cored without issue.

P.Eng Comments

L100 or 91 tonnes load rating. Update load rating sign. Replace stringer 1.



19/02/2018

P.Eng Seal

CK-2406

PITT RIVER 18.5km

2017 Inspection



CBR iPad Offline Ver

## Approach

Alignment Good

Bridge Ahead Signs  
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing  
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing  
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating 100

Road Surface Good

## Abutment

Log/Timber Cribs Fair

Tie Backs Fair

Bin Wall N/A

Concrete N/A

Caps or Sills N/A

Piles or Posts N/A

Ballast Wall N/A

Wing Wall N/A

Bracing N/A

Hardware N/A

Fill Good

Riprap Fair

Bearings N/A

Corrosion Protection N/A

CK-2406

PITT RIVER 18.5km

2017 Inspection

CBR iPad Offline Ver

**Deck**

|                        |      |
|------------------------|------|
| Running Surface        | Good |
| Running Planks         | N/A  |
| Sub Deck               | N/A  |
| Ties                   | N/A  |
| Nails                  | N/A  |
| Deck to Girder Bolts   | N/A  |
| Concrete Deck          | N/A  |
| Grout Pockets          | N/A  |
| Deck Joints            | N/A  |
| Steel Deck Plate       | N/A  |
| Gravel Surface         | Good |
| Curb Rail/Blocks/Posts | Fair |
| Hand Rails/Walkouts    | N/A  |
| Hardware               | N/A  |
| Overall Deck Condition | Fair |
| Gravel Depth (mm)      | 0.5  |

CK-2406

PITT RIVER 18.5km

2017 Inspection



CBR iPad Offline Ver

**Steel/Concrete**

Serial/ID Plate

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted  
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/  
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer  
Number

Species

Peeled

Diameter  
(mm)Rot Depth  
(mm)

Condition

Comment

1

Woodpecker damage

See documentation on file for stringer information

CK-2406

PITT RIVER 18.5km

2017 Inspection

CBR iPad Offline Ver



## Hazards

|                                          |     |             |                          |        |                          |
|------------------------------------------|-----|-------------|--------------------------|--------|--------------------------|
| Estimated Present Water Level Depth (m)  | 0   | High Water  | <input type="checkbox"/> | Debris | <input type="checkbox"/> |
| Estimated Present Water Level Width (m)  | 0   | Aggradation | <input type="checkbox"/> | Scour  | <input type="checkbox"/> |
| Estimated High Water Level Clearance (m) | 1.2 | Ice         | <input type="checkbox"/> |        |                          |

Comments

## Repairs and Monitoring

Repair

| Item | Priority | Repair Description                                     |
|------|----------|--------------------------------------------------------|
| 1    | Medium   | Stringer 1 shows woodpecker damage due to rot. Replace |
| 2    |          |                                                        |
| 3    |          |                                                        |

| Item | Monitor Description | Frequency |
|------|---------------------|-----------|
| 1    |                     |           |
| 2    |                     |           |
| 3    |                     |           |

Sketch  
(Select Signature)



Left approach viewed from bridge



Upstream from Crossing



Right approach viewed from bridge



Downstream from Crossing



Approach from Left Bank when facing downstream



Stringers



Upstream Profile



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



Approach from Right Bank when facing downstream