

CK-2455

NORRISH CREEK 8.5km

2017 Inspection



CBR iPad Offline Ver 0.26

CBR Data

Latitude	Longitude
49°14'28.1"	-122°7'13.4"
Crossing Name	Unknown
FSR #	10326
Branch #	1
Road Name	NORRISH CREEK
User km	8.5
Current Load Rating (tonnes)	150
Structure Class	Major Culvert
Culvert Type	Round
Culvert Material	Corrugated Steel
Opening Height (mm)	2700
Opening Width (mm)	2700
Inlet Cover (mm)	1200
Outlet Cover (mm)	1600
Culvert Gradient %	5
Culvert Length (m)	17

Updated Data

Latitude	Longitude
49°14'28.08"	-122°7'14.87"
HD Diff. (m)	29.7
Accuracy (m)	10
8.9	
2000	

Inspection

Date of Inspection 2017-08-24 9:34:06 AM

Recommended Next Inspection Year 2020

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Brush approaches. Current load rating of L165 or 150 tonnes to continue.



05/02/2018

P.Eng Seal

CK-2455

NORRISH CREEK 8.5km

2017 Inspection



CBR iPad Offline Ver 0.26

Approach

Alignment Fair

HC both approaches

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☐ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating

Not posted

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

CK-2455

NORRISH CREEK 8.5km

2017 Inspection

CBR iPad Offline Ver 0.26



Culvert

Baffles

Bolted Connections

Coating Good

Coupled Connections Good

Embedment Materials

Fill Good

Floor Good

Footing

Head Walls

Inlet Good

Outlet Good

Overall Good

Rip Rap Good

Roof Good

Sidewalls Good

Trash Rack

Weirs/Backwater
Structures

Wing Walls

CK-2455

NORRISH CREEK 8.5km

2017 Inspection

CBR iPad Offline Ver 0.26



Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.0	Aggradation	☒	Scour	☐
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments

Repairs and Monitoring

Repair

Item	Priority	Repair Description
1	Low	Brush approaches
2		
3		

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Looking upstream from road



Approach from Right Bank when facing downstream



Looking downstream from road



Approach from Left Bank when facing downstream



Inlet



Inlet



Outlet

CK-2455

NORRISH CREEK 8.5km

2017 Inspection



Outlet