

CK-2457

NORRISH CREEK 13.6km

2017 Inspection

CBR iPad Offline Ver 0.26



CBR Data

Latitude	Longitude
49°16'31.69"	-122°5'23.8"
Crossing Name	Unknown
FSR #	10326 Branch # 1
Road Name	NORRISH CREEK
User km	13.6
Current Load Rating (tonnes)	63
Structure Class	Major Culvert
Culvert Type	Open Bottom
Culvert Material	Corrugated Steel
Opening Height (mm)	1440
Opening Width (mm)	2740
Inlet Cover (mm)	600
Outlet Cover (mm)	700
Culvert Gradient %	
Culvert Length (m)	10

Updated Data

Latitude	Longitude
49°16'31.34"	-122°5'23.8"
HD Diff. (m)	11.1 Accuracy (m) 10

500

Inspection

Date of Inspection 2017-08-24 10:04:21 AM

Recommended Next Inspection Year 2018

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

Consider replacing structure with a large culvert or bridge

P.Eng Comments

Monitor aggradation following heavy rainfall or rain on snow events. Consider replacing with a larger culvert or bridge. Current load rating of BCL625 or 63 tonnes to continue.



05/02/2018

P.Eng Seal

CK-2457

NORRISH CREEK 13.6km

2017 Inspection



CBR iPad Offline Ver 0.26

Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required **N**

Delineator Missing
Left ☐ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating **Not posted**

Road Surface **Good**

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

CK-2457

NORRISH CREEK 13.6km

2017 Inspection

CBR iPad Offline Ver 0.26



Culvert

Baffles

Bolted Connections

Good

Coating

Good

Coupled Connections

Embedment Materials

Fair

Fill

Fair

Floor

Footing

Fair

Has been repaired since last inspection

Head Walls

Inlet

Fair

Aggrading, approx 50% full

Outlet

Fair

Overall

Fair

Rip Rap

Fair

Roof

Fair

Minor damage noted

Sidewalls

Fair

Trash Rack

Weirs/Backwater
Structures

Wing Walls

CK-2457

NORRISH CREEK 13.6km

2017 Inspection

CBR iPad Offline Ver 0.26



Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☒
Estimated Present Water Level Width (m)	1.5	Aggradation	☒	Scour	☐
Estimated High Water Level Clearance (m)	0.5	Ice	☐		

Comments Stream aggrades consistently, consider replacing this structure

Repairs and Monitoring

Repair

Item	Priority	Repair Description
------	----------	--------------------

1

2

3

Item

Monitor Description

Frequency

1	Monitor aggradation	Anually
---	---------------------	---------

2

3

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Looking downstream from road



Looking upstream from road



Approach from Right Bank when facing downstream



Inlet



Outlet



Looking from outlet



Outlet

CK-2457

NORRISH CREEK 13.6km

2017 Inspection



Consistent bearing on both footings, right bank shown