

CK-2499

BENCH 2.7km

2017 Inspection



CBR iPad Offline Ver 0.26

CBR Data

Latitude	Longitude
49°5'44.99"	-121°40'42"
Crossing Name	Side Creek
FSR #	5127
Branch #	10
Road Name	BENCH
User km	2.7
Current Load Rating (tonnes)	136
Structure Class	Major Culvert
Culvert Type	Open Bottom
Culvert Material	Corrugated Steel
Opening Height (mm)	1120
Opening Width (mm)	2130
Inlet Cover (mm)	1100
Outlet Cover (mm)	1300
Culvert Gradient %	2
Culvert Length (m)	15.9

Updated Data

Latitude	Longitude
49°5'45.15"	-121°40'42.25"
HD Diff. (m)	6.8
Accuracy (m)	10

Inspection

Date of Inspection 2017-07-26 1:49:17 PM

Recommended Next Inspection Year 2020

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Brush and grade approaches. Present load rating of L150 or 136 tonnes to continue.



29/08/2017

P.Eng Seal

CK-2499

BENCH 2.7km

2017 Inspection



CBR iPad Offline Ver 0.26

Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating Not posted

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill Good

Riprap Good

Bearings

Corrosion Protection

CK-2499

BENCH 2.7km

2017 Inspection

CBR iPad Offline Ver 0.26



Culvert

Baffles

Bolted Connections Good

Coating Good

Coupled Connections

Embedment Materials Good

Fill Good

Floor

Footing Good

Head Walls

Inlet Good

Outlet Good

Overall Good

Rip Rap Good

Roof Good

Sidewalls Good

Trash Rack

Weirs/Backwater
Structures

Wing Walls

CK-2499

BENCH 2.7km

2017 Inspection

CBR iPad Offline Ver 0.26



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

CK-2499

BENCH 2.7km

2017 Inspection



CBR iPad Offline Ver 0.26

Hazards

Estimated Present Water Level Depth (m)	0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.0	Ice	☐		

Comments

Repairs and Monitoring

Repair

Item	Priority	Repair Description
------	----------	--------------------

1	Low	Grade and brush
---	-----	-----------------

2		
---	--	--

3		
---	--	--

Item	Monitor Description	Frequency
------	---------------------	-----------

1		
---	--	--

2		
---	--	--

3		
---	--	--

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Inlet



Approach from Right Bank when facing downstream



Looking through culvert from inlet

CK-2499

BENCH 2.7km

2017 Inspection



Outlet