

CK-2007

ANDERSON SEVEN 0.1km

2018 Inspection

CBR iPad Offline Ver 0.26



CBR Data

Latitude	Longitude		
49°43'35.5"	-121°21'52.4"		
Crossing Name	Anderson River		
FSR #	8074	Branch #	7
Road Name	ANDERSON SEVEN		
User km	0.1		
Current Load Rating (tonnes)	68		
Structure Class	Temporary Bridge		
Portable	N		
Superstructure	Steel I-beam		
Deck Type	Timber - Treated		
Abutment Left	Crib, Log or Untreated Timber		
Abutment Right	Crib, Log or Untreated Timber		
Spans	2		
Total Length (m)	27.4		
Deck Width (m)	4.3		

Updated Data

Latitude	Longitude		
49°43'36.47"	-121°21'51.38"		
HD Diff. (m)	36.4	Accuracy (m)	5
Pile - Permanent Materials			
Pile - Permanent Materials			
1			

Inspection

Date of Inspection 2018-08-22 12:57:05 PM

Recommended Next Inspection Year 2021

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Replace log fenders, install bridge ahead signs, and brush approaches. Monitor the crib condition and bearings. The present load rating of L45 or 41 tonnes can continue.



06/09/2018

P.Eng Seal

CK-2007

ANDERSON SEVEN 0.1km

2018 Inspection



CBR iPad Offline Ver 0.26

Approach

Alignment Fair

HC both approaches

 Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

 Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Poor

The logs that are present are rotten

Posted Load Rating 41000

Road Surface Fair

Abutment

Log/Timber Cribs Fair

Log cribs only for fill retention. 450 - 800mm diameter face logs with up to 400mm heart rot as noted in larger logs at the ends. No signs of crushing of any face logs noted

Tie Backs

Heart rot noted in many, however no signs of crushing

Bin Wall

Concrete

Caps or Sills Fair

H beam

Piles or Posts Fair

4 H piles at each abutment

Ballast Wall Fair

Part of large log crib with up to 200mm heart rot noted. No signs of distress

Wing Wall Fair

Top log on downstream right abutment has horizontal crack - monitor condition

Bracing Fair

Hardware NA

Fill Fair

Upstream left abutment scour extends 400mm behind crib and wingwall, however no signs of movement

Riprap Fair

Upstream left abutment has large round boulders that are loose

Bearings Unrated

No access to bearing locations

Corrosion Protection Fair

CK-2007

ANDERSON SEVEN 0.1km

2018 Inspection

CBR iPad Offline Ver 0.26



Deck

Running Surface

Running Planks **Good**

Sub Deck **Good** Creosote

Ties **Good** Creosote

Nails **Good**

Deck to Girder Bolts **Good**

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware **Good**

Overall Deck Condition **Good**

Gravel Depth (mm)

CK-2007

ANDERSON SEVEN 0.1km

2018 Inspection



CBR iPad Offline Ver 0.26

Steel/Concrete

Serial/ID Plate

Girders Fair

Diaphragms Fair

Bracing Fair

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2007

ANDERSON SEVEN 0.1km

2018 Inspection

CBR iPad Offline Ver 0.26



Hazards

Estimated Present Water Level Depth (m)	0.8	High Water	☐	Debris	☒
Estimated Present Water Level Width (m)	9.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	3.0	Ice	☐		

Comments Some large debris noted upstream

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

- | | | |
|---|--------|----------------------------|
| 1 | Low | Brush with activity |
| 2 | Medium | Replace log fenders |
| 3 | Medium | Install bridge ahead signs |

Item	Monitor Description	Frequency
1	Log crib condition	Routine Inspection
2	Bearing locations	Routine Inspection

3

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Load Rating Sign



Deck



Upstream from Crossing



Downstream from Crossing



Left Bank Abutment when facing downstream



Approach from Right Bank when facing downstream



Old bearing plates still visible



Upstream left approach crib condition



Superstructure



Right Bank Abutment when facing downstream