

CK-2037

STATLU 7300 3.7km

2018 Inspection

CBR iPad Offline Ver 0.28



CBR Data

Latitude	Longitude		
49°21'17.49"	-122°8'11.9"		
Crossing Name	Towhead Creek		
FSR #	8241	Branch #	3
Road Name	STATLU 7300		
User km	3.7		
Current Load Rating (tonnes)	136		
Structure Class	Permanent Bridge		
Portable	N		
Superstructure	Steel I-beam		
Deck Type	Concrete Composite		
Abutment Left	Steel Pipe and Precast Pad		
Abutment Right	Steel Pipe and Precast Pad		
Spans	1		
Total Length (m)	15.9		
Deck Width (m)	5.6		

Updated Data

Latitude	Longitude		
49°21'16.87"	-122°8'11.53"		
HD Diff. (m)	20.9	Accuracy (m)	5
L150 or 136 tonnes			

Inspection

Date of Inspection 2018-06-18 10:58:25 AM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2021


Inspection Company MFLNRO

Inspector Comments

Girders approx 4200mm on center

P.Eng Comments

Replace guardrail, risers and blocks. Brush approaches, replace missing delineators, and post bridge ahead signs. When the road is opened for industrial use monitor the deck joints, grout pockets and overall deck panel condition. Current load rating of L150 or 136 tonnes to continue.



04/02/2019

P.Eng Seal

CK-2037

STATLU 7300 3.7km

2018 Inspection



CBR iPad Offline Ver 0.28

Approach

Alignment Fair

HC both approaches

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing
Left ☐ 0 ☒ 1 ☐ 2Delineator Missing
Right ☐ 0 ☐ 1 ☒ 2

Fender Condition Fair

Old rotting logs

Posted Load Rating

Not posted

Road Surface Poor

Semi deactivated road with little surfacing and overgrown

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts Good

Ballast Wall Good

Wing Wall

Bracing Good

Hardware

Fill Good

Riprap Fair

Bearings Good

Corrosion Protection Good

CK-2037

STATLU 7300 3.7km

2018 Inspection

CBR iPad Offline Ver 0.28

**Deck**

Running Surface	Fair	Semi deactivated road with little surfacing and overgrown
-----------------	------	---

Running Planks		
----------------	--	--

Sub Deck		
----------	--	--

Ties		
------	--	--

Nails		
-------	--	--

Deck to Girder Bolts		
----------------------	--	--

Concrete Deck	Fair	
---------------	------	--

Grout Pockets	Fair	Indications of water leakage throughout
---------------	------	---

Deck Joints	Fair	Worn in locations at surface
-------------	------	------------------------------

Steel Deck Plate		
------------------	--	--

Gravel Surface		
----------------	--	--

Curb Rail/Blocks/Posts	Poor	Rotten
------------------------	------	--------

Hand Rails/Walkouts		
---------------------	--	--

Hardware	Fair	
----------	------	--

Overall Deck Condition	Poor	Due to rail condition
------------------------	------	-----------------------

Gravel Depth (mm)		
-------------------	--	--

CK-2037

STATLU 7300 3.7km

2018 Inspection



CBR iPad Offline Ver 0.28

Steel/Concrete

Girders Fair Pitting and flaking

Diaphragms Good

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2037

STATLU 7300 3.7km

2018 Inspection

CBR iPad Offline Ver 0.28



Hazards

Estimated Present Water Level Depth (m)	0.8	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	8.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.0	Ice	☐		

Comments

Repairs and Monitoring

Repair

Item	Priority	Repair Description
1	Medium	Brush and grade approaches when active
2	Medium	Replace guardrail, risers and blocks when active
3	Medium	Replace missing delineators and post bridge ahead signs

Item	Monitor Description	Frequency
1	Concrete deck condition	Routine Inspection

2

3

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Upstream from Crossing



Deck



Downstream from Crossing



Deck panel joints worn



Left Bank Abutment when facing downstream



Approach from Right Bank when facing downstream



Girders corrosion at deck joint and grout pocket locations



Cracking on underside of girders throughout



Deck panel cracks



Deck panel cracks



Deck joints cracks



Panels being lifted due to rusting, typical throughout



Right Bank Abutment when facing downstream



Deck panel cracks



Downstream left approach deck panel