

CK-2093

FLORENCE LAKE 7km

2018 Inspection

CBR iPad Offline Ver 0.28



CBR Data

Latitude	Longitude		
49°16'54.3"	-122°21'52.2"		
Crossing Name	79 Creek		
FSR #	8648	Branch #	1
Road Name	FLORENCE LAKE		
User km	7		
Current Load Rating (tonnes)	54		
Structure Class	Permanent Bridge		
Portable	N		
Superstructure	Other		
Deck Type	Concrete Composite		
Abutment Left	Steel Pipe and Precast Pad		
Abutment Right	Steel Pipe and Precast Pad		
Spans	1		
Total Length (m)	30.1		
Deck Width (m)	5		

Updated Data

Latitude	Longitude		
49°16'55.16"	-122°21'52.47"		
HD Diff. (m)	27.1	Accuracy (m)	10
6.9			
L60 or 54 tonnes			
Compo Girders			

Inspection

Date of Inspection 2018-04-25 9:16:32 AM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2021

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Repair/replace the damaged sections of guardrail. Remove the downed trees noted upstream (or cut into small pieces so they flow through the crossing in high flows). Monitor the CIP under the large boulder at the left abutment. Present load rating of L60 or 54 tonnes to continue.



09/01/2019

P.Eng Seal

CK-2093

FLORENCE LAKE 7km

2018 Inspection



CBR iPad Offline Ver 0.28

Approach

Alignment Fair

HC left approach

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating

Not posted

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts Good

Ballast Wall Good

Wing Wall Good

Bracing Good

Hardware

Fill Good

Riprap Fair Monitor CIP under boulder at left bank

Bearings Fair

Corrosion Protection Fair

CK-2093

FLORENCE LAKE 7km

2018 Inspection

CBR iPad Offline Ver 0.28

**Deck**Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck **Good**Grout Pockets **Good**Deck Joints **Good**

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Fair** Minor damage noted in 2 locations but still functional

Hand Rails/Walkouts

Hardware **Good**Overall Deck Condition **Fair**

Gravel Depth (mm)

CK-2093

FLORENCE LAKE 7km

2018 Inspection

CBR iPad Offline Ver 0.28

**Steel/Concrete**

Girders Good

Diaphragms Good 2 bolted bays

Bracing

Under Trussing

Hardware Good

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2093

FLORENCE LAKE 7km

2018 Inspection

CBR iPad Offline Ver 0.28



Hazards

Estimated Present Water Level Depth (m)	1.0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	10.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.5	Ice	☐		

Comments

Repairs and Monitoring

Repair

Item	Priority	Repair Description
1	Medium	Remove trees noted upstream or cut into small pieces so they will pass at high flows
2	Medium	Repair/replace damaged sections of guardrail
3		

Item	Monitor Description	Frequency
1	CIP under large boulder at left bank	Routine Inspection
2		
3		

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Guardrail damage upstream right bank



Deck



Looking upstream from deck - full length trees noted 40 meters upstream



Looking downstream from deck



Right Bank Abutment when facing downstream



Approach from Left Bank when facing downstream



Superstructure



Damage noted to downstream left bank guardrail



Upstream Profile



Downstream left bank precast wingwall - slight out of alignment with ballast wall



Left Bank Abutment when facing downstream



CIP to support large boulder in front of abutment at left bank



Utility hung fastened to underside of deck



Minor bulging of bearing pads at right bank, and slight deformation noted