

CK-2153

JONES LAKE 8.5km

2018 Inspection

CBR iPad Offline Ver 0.28



CBR Data

Latitude 49°14'53.99" Longitude -121°36'4.4"

Crossing Name Boulder Creek

FSR # 8149 Branch # 1

Road Name JONES LAKE

User km 8.5

Current Load Rating (tonnes) 68

Structure Class Permanent Bridge

Portable N

Superstructure Steel I-beam

Deck Type Concrete Composite

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 33.6

Deck Width (m) 4.3

Updated Data

Latitude 49°14'54.17" Longitude -121°36'4.07"

HD Diff. (m) 8.5 Accuracy (m) 5

L75 or 68 tonnes

Inspection

Date of Inspection 2018-05-30 2:05:41 PM

Inspector Name Tyson Miller


Inspector Comments

Recommended Next Inspection Year 2021

Inspection Company MFLNRO

P.Eng Comments

Present load rating of L75 or 68 tonnes to continue.



17/01/2019

P.Eng Seal

CK-2153

JONES LAKE 8.5km

2018 Inspection



CBR iPad Offline Ver 0.28

Approach

Alignment Fair

HC both approaches

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating 68040

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts Good

Ballast Wall Good

Wing Wall

Bracing Good

Hardware

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Fair

CK-2153

JONES LAKE 8.5km

2018 Inspection

CBR iPad Offline Ver 0.28



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck **Good**

Grout Pockets **Good**

Deck Joints **Good**

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware **Good**

Overall Deck Condition **Good**

Gravel Depth (mm)

CK-2153

JONES LAKE 8.5km

2018 Inspection

CBR iPad Offline Ver 0.28

**Steel/Concrete**

Girders Good

Spliced girders

Diaphragms Good

7 bolted bays

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2153

JONES LAKE 8.5km

2018 Inspection

CBR iPad Offline Ver 0.28



Hazards

Estimated Present Water Level Depth (m)	1.0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	9.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	4.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Upstream from Crossing



Deck



Downstream from Crossing



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Right Bank Abutment when facing downstream

CK-2153

JONES LAKE 8.5km

2018 Inspection



Superstructure