

CK-2173

LOST CREEK 18.9km

2018 Inspection

CBR iPad Offline Ver 0.28



CBR Data

Latitude	Longitude
49°24'1"	-122°14'29.4"
Crossing Name	Side Creek
FSR #	8466 Branch # 1
Road Name	LOST CREEK
User km	18.9
Current Load Rating (tonnes)	2
Structure Class	Temporary Bridge
Portable	N
Superstructure	Log Stringers
Deck Type	Gravel
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	8
Deck Width (m)	6.5

Updated Data

Latitude	Longitude
49°24'.66"	-122°14'29.45"
HD Diff. (m)	10.7 Accuracy (m) 5
2 tonnes	

Inspection

Date of Inspection 2018-06-07 1:29:39 PM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2020

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

The structure and access to the structure is in poor condition. The current load rating of 2 tonnes can continue. Post load rating signs.



01/02/2019

P.Eng Seal

CK-2173

LOST CREEK 18.9km

2018 Inspection



CBR iPad Offline Ver 0.28

Approach

Alignment Fair

HC right approach

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing
Left ☐ 0 ☐ 1 ☒ 2Delineator Missing
Right ☐ 0 ☐ 1 ☒ 2

Fender Condition Poor

None

Posted Load Rating

Not posted

Road Surface Poor

Road access is limited to 4x4, no surfacing material

Abutment

Log/Timber Cribs Fair

2x

Tie Backs Fair

Fair to poor, rotting

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill Fair

Riprap Poor

None

Bearings Fair

Corrosion Protection

CK-2173

LOST CREEK 18.9km

2018 Inspection

CBR iPad Offline Ver 0.28

**Deck**

Running Surface

Road access is limited to 4x4, no surfacing material

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface Fair

Curb Rail/Blocks/Posts Poor None

Hand Rails/Walkouts

Hardware

Overall Deck Condition Poor Due to rail

Gravel Depth (mm) 500

CK-2173

LOST CREEK 18.9km

2018 Inspection

CBR iPad Offline Ver 0.28

**Steel/Concrete**

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**Log Curbs **Poor** None

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

Structure is in poor condition
See last inspection for stringer details

CK-2173

LOST CREEK 18.9km

2018 Inspection

CBR iPad Offline Ver 0.28



Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	3.5	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	High	Post load rating signs

2

3

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Downstream from Crossing



Upstream from Crossing



Approach from Left Bank when facing downstream



Right Bank Abutment when facing downstream



Stringers



Left Bank Abutment when facing downstream



Stringer 5