

CK-2175

MURDO 1.2km

2018 Inspection

CBR iPad Offline Ver 0.28



CBR Data

Latitude	Longitude		
49°17'39.4"	-122°13'35.6"		
Crossing Name	Not Known		
FSR #	8466	Branch #	2
Road Name	MURDO		
User km	1.2		
Current Load Rating (tonnes)	54		
Structure Class	Temporary Bridge		
Portable	N		
Superstructure	Steel I-beam		
Deck Type	Timber - Untreated		
Abutment Left	Crib, Log or Untreated Timber		
Abutment Right	Crib, Log or Untreated Timber		
Spans	1		
Total Length (m)	10.4		
Deck Width (m)	4.1		

Updated Data

Latitude	Longitude		
49°17'39.66"	-122°13'34.92"		
HD Diff. (m)	15.8	Accuracy (m)	10
L60 or 54 tonnes			

Inspection

Date of Inspection 2018-04-25 2:15:57 PM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2020

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Replace both left approach delineators with proper ones. Monitor the vertical crack noted on the downstream end of the top face log on the right bank - no apparent change from last inspection. Present load rating of L60 or 54 tonnes to continue.



P.Eng Seal

CK-2175

MURDO 1.2km

2018 Inspection



CBR iPad Offline Ver 0.28

Approach

Alignment Fair

VC and HC at both approaches

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☐ 0 ☐ 1 ☒ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating

Road Surface Fair

Abutment

Log/Timber Cribs Good 3x left bank, 4x right bank

Tie Backs Good 3x

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall Good Treated timbers

Wing Wall

Bracing

Hardware Fair Lashing

Fill Fair

Riprap Fair

Bearings Good

Corrosion Protection

CK-2175

MURDO 1.2km

2018 Inspection

CBR iPad Offline Ver 0.28



Deck

Running Surface

Running Planks Fair

Sub Deck Fair

Ties Good

Nails Fair

Deck to Girder Bolts Good

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts

Hardware Good

Overall Deck Condition Fair

Gravel Depth (mm)

CK-2175

MURDO 1.2km

2018 Inspection



CBR iPad Offline Ver 0.28

Steel/Concrete

Girders Fair

Surface corrosion

Diaphragms Fair

3 welded bays

Bracing Fair

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2175

MURDO 1.2km

2018 Inspection

CBR iPad Offline Ver 0.28



Hazards

Estimated Present Water Level Depth (m)	0.3	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	Medium	Replace both left side delineators with correct ones

2

3

Item	Monitor Description	Frequency
1	vertical crack on downstream end of top face log on right bank	Routine Inspection

2

3

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Looking upstream from deck



Deck



Looking downstream from deck



Approach from Right Bank when facing downstream



Indication of rot on subdeck - cored and fair condition



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream

CK-2175

MURDO 1.2km

2018 Inspection



Superstructure



Vertical crack in crib log on right bank