

CK-2209

MOWHOKAM EAST 0.1km

2018 Inspection

CBR iPad Offline Ver 0.26



CBR Data

Latitude 50°4'28.99" Longitude -121°25'15.7"

Crossing Name Mohawkum Creek

FSR # 8019 Branch # 3

Road Name MOWHOKAM EAST

User km 0.1

Current Load Rating (tonnes) 68 tonnes

Structure Class Temporary Bridge

Portable N

Superstructure Steel I-beam

Deck Type Timber - Untreated

Abutment Left Sill -Temporary Materials

Abutment Right Sill -Temporary Materials

Spans 1

Total Length (m) 18.3

Deck Width (m) 4

Updated Data

Latitude 50°4'28.73" Longitude -121°25'15.74"

HD Diff. (m) 8.4 Accuracy (m) 5

L75 or 68 tonnes

Inspection

Date of Inspection 2018-08-23 9:32:03 AM

Recommended Next Inspection Year 2020

Inspector Name Tyson Miller


Inspection Company MFLNRO

Inspector Comments

In order to place log fenders at approaches granular fill will be required to widen road

P.Eng Comments

Brush approaches and post bridge ahead signs. Replace missing fenders at both approaches. Continue to monitor the riprap condition for further scour. The Coast Engineering Group (CEG) does not have the record drawings, structural drawings or Crossing Assurance Statement on file for this site. Limit loading to L75 or 68 tonnes and send the missing documents to the CEG for review.



01/02/2019

P.Eng Seal

CK-2209

MOWHOKAM EAST 0.1km

2018 Inspection



CBR iPad Offline Ver 0.26

Approach

Alignment Fair

HC and VC right approach

Bridge Ahead Signs
Missing
☐ 0
 ☐ 1
 ☒ 2

Brushing Required Y

Delineator Missing
Left
☒ 0
 ☐ 1
 ☐ 2
Delineator Missing
Right
☒ 0
 ☐ 1
 ☐ 2

Fender Condition Poor

None

Posted Load Rating

Not posted

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills Fair

Log sills both banks

Piles or Posts

Ballast Wall Fair

Logs

Wing Wall

Bracing

Hardware Fair

Fill Fair

Riprap Fair

Round riprap, not well graded or tied into the streambed and is scouring

Bearings Fair

Corrosion Protection

CK-2209

MOWHOKAM EAST 0.1km

2018 Inspection

CBR iPad Offline Ver 0.26



Deck

Running Surface

Running Planks

Fair

Sub Deck

Fair

Cored random locations

Ties

Fair

Cored random locations

Nails

Fair

Deck to Girder Bolts

Poor

None visible

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts

Fair

Hand Rails/Walkouts

Hardware

Overall Deck Condition

Fair

Gravel Depth (mm)

CK-2209

MOWHOKAM EAST 0.1km

2018 Inspection



CBR iPad Offline Ver 0.26

Steel/Concrete

Serial/ID Plate

Girders Fair

Only a section of longer set

Diaphragms Fair

Bracing Fair

Under Trussing

Hardware Fair

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2209

MOWHOKAM EAST 0.1km

2018 Inspection

CBR iPad Offline Ver 0.26



Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	9.0	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance (m)	2.0	Ice	☐		

Comments

Round riprap, not well graded or tied into the streambed and is scouring

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	Medium	Brush approaches and post bridge ahead signs

2 Medium Place log fenders at approaches

3

Item	Monitor Description	Frequency
1	Riprap condition	Routine Inspection

2

3

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Upstream from Crossing



Approach from Right Bank when facing downstream



Downstream from Crossing




Approach from Left Bank when facing downstream



Rot indicators on underside of deck starting to show



Right Bank Abutment when facing downstream



Structure ID



Left Bank Abutment when facing downstream



Superstructure