

CK-2309

UZTLIUS-E ANDERSON 17.1km

2018 Inspection



CBR iPad Offline Ver 0.26

CBR Data

Latitude	Longitude
49°43'3.5"	-121°13'43.1"
Crossing Name	not known
FSR #	7972
Branch #	2
Road Name	UZTLIUS-E ANDERSON
User km	17.1
Current Load Rating (tonnes)	68
Structure Class	Major Culvert
Culvert Type	Round
Culvert Material	Corrugated Steel
Opening Height (mm)	2000
Opening Width (mm)	2000
Inlet Cover (mm)	2300
Outlet Cover (mm)	3000
Culvert Gradient %	6
Culvert Length (m)	16

Updated Data

Latitude	Longitude
49°43'3.42"	-121°13'43.22"
HD Diff. (m)	3.4
Accuracy (m)	5

L75 or 68 tonnes

Inspection

Date of Inspection 2018-08-28 11:30:46 AM

Recommended Next Inspection Year 2021

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Clean inlet and brush approaches when active. Monitor the bedload at the inlet. Present load rating of L75 or 68 tonnes to continue.



09/01/2019

P.Eng Seal

CK-2309

UZTLIUS-E ANDERSON 17.1km

2018 Inspection



CBR iPad Offline Ver 0.26

Approach

Alignment Fair

HC both approaches

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2 NA

Brushing Required Y

Delineator Missing
Left ☐ 0 ☐ 1 ☐ 2 NADelineator Missing
Right ☐ 0 ☐ 1 ☐ 2 NA

Fender Condition NA

Posted Load Rating Not posted

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

CK-2309

UZTLIUS-E ANDERSON 17.1km

2018 Inspection

CBR iPad Offline Ver 0.26



Culvert

Baffles

Bolted Connections

Coating

Fair

Coupled Connections

Good

Embedment Materials

Fill

Good

Floor

Good

Footing

Head Walls

Inlet

Fair

Fair to poor as material is building up at inlet

Outlet

Good

Overall

Fair

Rip Rap

Good

Roof

Good

Sidewalls

Good

Trash Rack

Weirs/Backwater
Structures

Wing Walls

CK-2309

UZTLIUS-E ANDERSON 17.1km

2018 Inspection

CBR iPad Offline Ver 0.26



Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	0.1	Aggradation	☒	Scour	☐
Estimated High Water Level Clearance (m)		Ice	☐		

Comments

Repairs and Monitoring

Repair

Item	Priority	Repair Description
------	----------	--------------------

1	High	Brush prior to activity
---	------	-------------------------

2	High	Clean inlet
---	------	-------------

3		
---	--	--

Item	Monitor Description	Frequency
1	Aggradation	Routine Inspection

2		
---	--	--

3		
---	--	--

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Inlet



Approach from Left Bank when facing downstream



Looking through from inlet

CK-2309

UZTLIUS-E ANDERSON 17.1km

2018 Inspection



Material building up at inlet



Outlet