

CK-2315

BERKEY 5700 0.3km

2018 Inspection

CBR iPad Offline Ver 0.28



CBR Data

Latitude	Longitude
49°19'33.7"	-121°20'56"
Crossing Name	Berkey Creek
FSR #	8113
Branch #	4
Road Name	BERKEY 1900
User km	4.2
Current Load Rating (tonnes)	0
Structure Class	Temporary Bridge
Portable	N
Superstructure	Log Stringers
Deck Type	Timber - Untreated
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	8.5
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°19'33.67"	-121°20'55.98"
HD Diff. (m)	1.1
Accuracy (m)	5
Berkey 5700	
0.3km	
0 tonnes	

Inspection

Date of Inspection 2018-05-31 9:04:05 AM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2020

Inspection Company MFLNRO

Inspector Comments

No vehicle access to site due to brush

P.Eng Comments

Bridge condemned, 0 tonnes load rating. Replace the entire structure prior to activity. Due to the poor condition of the bridge components monitor for failure until removed.



P.Eng Seal

CK-2315

BERKEY 5700 0.3km

2018 Inspection



CBR iPad Offline Ver 0.28

Approach

Alignment Good

 Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

 Delineator Missing
Left ☐ 0 ☒ 1 ☐ 2

 Delineator Missing
Right ☐ 0 ☐ 1 ☒ 2

Fender Condition Poor None

Posted Load Rating Not posted

Road Surface Poor Grown over with Alder

Abutment

Log/Timber Cribs Fair Fair to poor, Cw and Fd

Tie Backs Poor Rotten

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill Fair

Riprap Poor None in front of crib

Bearings Poor Components rotting

Corrosion Protection

CK-2315

BERKEY 5700 0.3km

2018 Inspection

CBR iPad Offline Ver 0.28

**Deck**

Running Surface	Poor	Grown over with Alder
-----------------	------	-----------------------

Running Planks	Poor	Rotten
----------------	------	--------

Sub Deck		
----------	--	--

Ties	Poor	Rotten
------	------	--------

Nails		
-------	--	--

Deck to Girder Bolts		
----------------------	--	--

Concrete Deck		
---------------	--	--

Grout Pockets		
---------------	--	--

Deck Joints		
-------------	--	--

Steel Deck Plate		
------------------	--	--

Gravel Surface		
----------------	--	--

Curb Rail/Blocks/Posts	Poor	Rotten
------------------------	------	--------

Hand Rails/Walkouts		
---------------------	--	--

Hardware		
----------	--	--

Overall Deck Condition	Poor	Rotten
------------------------	------	--------

Gravel Depth (mm)		
-------------------	--	--

CK-2315

BERKEY 5700 0.3km

2018 Inspection

CBR iPad Offline Ver 0.28

**Steel/Concrete**

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

All stringers visually rotten

CK-2315

BERKEY 5700 0.3km

2018 Inspection

CBR iPad Offline Ver 0.28



Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	4.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1	High	Replace bridge with activity
---	------	------------------------------

2		
---	--	--

3		
---	--	--

Item	Monitor Description	Frequency
1	Monitor for failure as components extremely rotten	Routine Inspection

2		
---	--	--

3		
---	--	--

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Upstream from Crossing



Deck



Downstream from Crossing



Approach from Left Bank when facing downstream



Stringers



Left Bank Abutment when facing downstream



Stringers



Water gauge under bridge and attached to left abutment



Tieback condition



Right Bank Abutment when facing downstream