

CK-2452

NORRISH CREEK 7.1km

2018 Inspection



CBR iPad Offline Ver 0.26

CBR Data

Latitude	Longitude
49°13'58.5"	-122°8'9.24"
Crossing Name	Rose Creek
FSR #	10326
Branch #	1
Road Name	NORRISH CREEK
User km	7.1
Current Load Rating (tonnes)	150
Structure Class	Temporary Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Concrete Cast in Place
Abutment Right	Concrete Cast in Place
Spans	1
Total Length (m)	18.3
Deck Width (m)	4.8

Updated Data

Latitude	Longitude
49°13'58.59"	-122°8'9.76"
HD Diff. (m)	10.8
Accuracy (m)	10
L165 or 150 tonnes	

Inspection

Date of Inspection 2018-08-21 9:22:30 AM

Inspector Name Tyson Miller

Inspector Comments

Recommended Next Inspection Year 2020

Inspection Company MFLNRO

P.Eng Comments

Reconnect concrete bullnose at upstream right approach and brush approaches. Current load rating of L165 or 150 tonnes to continue.



P.Eng Seal

CK-2452

NORRISH CREEK 7.1km

2018 Inspection

CBR iPad Offline Ver 0.26



Approach

Alignment Fair

HC and VC right approach

Bridge Ahead Signs
Missing
☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left
☒ 0 ☐ 1 ☐ 2
Delineator Missing
Right
☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Upstream right approach bullnose not connected

Posted Load Rating 149700

Road Surface Good

Abutment

Log/Timber Cribs Fair

Left bank large dia. Cw 3x closed face with up to 50mm sap rot

Tie Backs Fair

3 on bottom log and 4 under girders, all with end splits and rot

Bin Wall

Concrete Fair

CIP left bank with vertical crack under upstream girder, no apparent change. Precast and lock blocks right bank. Blocks are spalling throughout and some have visible cold joints

Caps or Sills Fair

Log sill right bank with 60mm sap rot

Piles or Posts

Ballast Wall Fair

Logs

Wing Wall

Bracing

Hardware Good

Fill Fair

Riprap Poor

None in front of either abutment

Bearings Fair

Corrosion Protection

CK-2452

NORRISH CREEK 7.1km

2018 Inspection

CBR iPad Offline Ver 0.26



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck **Fair** Some wear noted on wheel path

Grout Pockets **Good**

Deck Joints **Good**

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware

Overall Deck Condition **Good**

Gravel Depth (mm)

CK-2452

NORRISH CREEK 7.1km

2018 Inspection



CBR iPad Offline Ver 0.26

Steel/Concrete

Serial/ID Plate

Girders Fair

Painted steel box girders

Diaphragms Fair

2 bays, painted

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2452

NORRISH CREEK 7.1km

2018 Inspection

CBR iPad Offline Ver 0.26



Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	8.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	3.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1	Low	Reconnect upstream right approach bullnose
---	-----	--

2	Medium	Brush approaches
---	--------	------------------

3		
---	--	--

Item	Monitor Description	Frequency
------	---------------------	-----------

1	Abutment condition	Anually
---	--------------------	---------

2		
---	--	--

3		
---	--	--

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Bullnose not connected at upstream right approach



Load Rating Sign



Deck



Upstream from Crossing



Approach from Left Bank when facing downstream



Downstream from Crossing



Right Bank Abutment when facing downstream



Approach from Left Bank when facing downstream



Right bank log sill condition



Superstructure



Lock block condition



Lock block condition



Scour under CIP extends 600mm in places



Vertical crack in CIP



Log crib condition