

CK-2139

STS'AILES (WEST) 42km

2019 Inspection

CBR iPad Offline Ver 0.31



CBR Data

Latitude	Longitude
49°35'29.79"	-121°55'49.1"
Crossing Name	Kirkland Creek
FSR #	6314
Branch #	1
Road Name	STS'AILES (WEST)
User km	42
Previous Load Rating (tonnes)	136
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Concrete Cast in Place
Spans	1
Total Length (m)	27.4
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°35'30.03"	-121°55'48.86"
HD Diff. (m)	8.6
Accuracy (m)	10

L150 or 136 tonnes

Inspection

Date of Inspection 2019-08-26 12:49:50 PM

Inspector Name Tyson Miller

Inspector Comments

Recommended Next Inspection Year 2022

Inspection Company FLNRORD

P.Eng Comments

The current load rating of L150 or 136 tonnes to continue.



P.Eng Seal

CK-2139

STS'AILES (WEST) 42km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Fair

HC and VC right approach

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating 136090

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts Good

Ballast Wall Good

Wing Wall

Bracing Good

Hardware

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Good

CK-2139

STS'AILES (WEST) 42km

2019 Inspection

CBR iPad Offline Ver 0.31



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck **Good** Minor damage due to track equipment

Grout Pockets **Good**

Deck Joints **Good**

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware **Good**

Overall Deck Condition **Good**

Gravel Depth (mm)

Pier Deck

CK-2139

STS'AILES (WEST) 42km

2019 Inspection

CBR iPad Offline Ver 0.31

**Steel/Concrete**

Girders Good

Diaphragms Good 5 bolted bays

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2139

STS'AILES (WEST) 42km

2019 Inspection



CBR iPad Offline Ver 0.31

Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	6.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	4.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Deck



Upstream from Crossing



Downstream from Crossing



Minor damage to deck from track equipment



Approach from Right Bank when facing downstream



Structure ID



Bearing shim - typical



Left Bank Abutment when facing downstream



Superstructure



Right Bank Abutment when facing downstream



Downstream Profile



Splice plates