

CK-2168

LOST CREEK 8.6km

2019 Inspection



CBR iPad Offline Ver 0.31

CBR Data

Latitude	Longitude
49°20'29.19"	-122°14'26.2"
Crossing Name	Twin Lakes Creek
FSR #	8466
Branch #	1
Road Name	LOST CREEK
User km	8.6
Previous Load Rating (tonnes)	68
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	21.4
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°20'27.76"	-122°14'31.11"
HD Diff. (m)	108.4
Accuracy (m)	30

L75 or 68 tonnes

Inspection

Date of Inspection 2019-04-26 11:31:46 AM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2022

Inspection Company FLNRORD

Inspector Comments

P.Eng Comments

Repair the damage noted to the top of the right bank ballast wall and adjacent deck panel consistent with the Concrete Repair Guide for Concrete Bridge Components (MoFLNRO, 2017); replace the missing bridge ahead sign; and grade approaches. Monitor the riprap scour noted at downstream right bank. The current load rating of L75 or 68 tonnes to continue.



P.Eng Seal

CK-2168

LOST CREEK 8.6km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Fair

HC right approach

Bridge Ahead Signs
Missing
☐ 0
 ☒ 1
 ☐ 2

Brushing Required N

Delineator Missing
Left
☒ 0
 ☐ 1
 ☐ 2
Delineator Missing
Right
☒ 0
 ☐ 1
 ☐ 2

Fender Condition Good

Posted Load Rating

Not posted

Road Surface Poor

Large Potholes

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts Good

Ballast Wall Poor

Top surface of right bank has significant damage

Wing Wall Good

Upstream left bank and downstream right bank have lock blocks retaining fill

Bracing Good

Hardware

Fill Good

Riprap Fair

Downstream right bank has sustained minor scour

Bearings Good

Corrosion Protection Good

CK-2168

LOST CREEK 8.6km

2019 Inspection

CBR iPad Offline Ver 0.31



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck **Good**

Grout Pockets **Good**

Deck Joints **Good**

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware **Good**

Overall Deck Condition **Good**

Gravel Depth (mm)

Pier Deck

CK-2168

LOST CREEK 8.6km

2019 Inspection



CBR iPad Offline Ver 0.31

Steel/Concrete

Girders Good

Diaphragms Good 5 bolted bays

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2168

LOST CREEK 8.6km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)	0.3	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	6.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	Low	Replace missing bridge ahead sign
2	High	Repair damage to right bank ballast wall and panel 1
3	High	Grade approaches

Item	Monitor Description	Frequency
1	Riprap scour noted downstream right bank	Routine Inspection
2		
3		

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Deck



Upstream from Crossing



Downstream from Crossing



Riprap scour noted downstream right bank



Approach from Right Bank when facing downstream



Requires surfacing at both approaches



Right abutment top ballast wall condition



Missing rebar on right bank ballast wall



Right bank panel 1 damage



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Downstream right bank fill retaining blocks



Upstream left bank fill retaining blocks