

CK-2450

NORRISH 5.1km

2019 Inspection

CBR iPad Offline Ver 0.31



CBR Data

Latitude	Longitude
49°13'8.29"	-122°8'52.8"
Crossing Name	Unknown
FSR #	10326
Branch #	1
Road Name	NORRISH
User km	5.1
Previous Load Rating (tonnes)	63
Structure Class	Major Culvert
Culvert Type	Round
Culvert Material	Corrugated Steel
Opening Height (mm)	2200
Opening Width (mm)	2200
Inlet Cover (mm)	300
Outlet Cover (mm)	400
Culvert Gradient %	5
Culvert Length (m)	9

Updated Data

Latitude	Longitude
49°13'8.76"	-122°8'53.53"
HD Diff. (m)	20.4
Accuracy (m)	5

BCL-625 or 63 tonnes

Inspection

Date of Inspection 2019-08-13 1:36:32 PM

Recommended Next Inspection Year 2020

Inspector Name Tyson Miller

Inspection Company FLNRORD

Inspector Comments

No indications that the large log at the outlet has moved since last inspection

P.Eng Comments

Continue to monitor the log retaining fill at the outlet. Brush approaches and remove the vegetation from the inlet. Excavate a small sump at the inlet. The current load rating of BCL-625 or 63 tonnes to continue.



2020-02-11

P.Eng Seal

CK-2450

NORRISH 5.1km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Fair

HC at both approaches

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required Y

Inside of curve can be brushed to increase visibility

Delineator Missing
Left ☐ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

CK-2450

NORRISH 5.1km

2019 Inspection

CBR iPad Offline Ver 0.31



Culvert

Baffles

Bolted Connections

Coating

Fair

Minor corrosion on floor

Coupled Connections

Embedment Materials

Fill

Fair

Floor

Fair

Last 2 m has slight dip in floor

Footing

Head Walls

Inlet

Fair

Minor aggradation

Outlet

Fair

1 m drop

Overall

Fair

Rip Rap

Fair

Lock blocks and rock retain fill at inlet

Roof

Fair

Sidewalls

Fair

Trash Rack

Weirs/Backwater
Structures

Wing Walls

CK-2450

NORRISH 5.1km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.0	Aggradation	☒	Scour	☐
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments

Minor aggradation at inlet

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	Medium	Remove the vegetation from the inlet and excavate a small sump
2	Low	Brush the inside of the curve
3		

Item	Monitor Description	Frequency
1	Large large log retaining fill at outlet	Anually
2		
3		

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Upstream from Crossing



Downstream from Crossing



Approach from Right Bank when facing downstream



Inlet



Eroding fill inlet



Outlet



Large log retaining fill at outlet



Large log retaining fill at outlet



Large log retaining fill at outlet