

CK-2097
CK-2097

FLORENCE LAKE 13.2km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude 49°19'9.99" Longitude -122°20'11.1"

Crossing Name Not Known

FSR # 8648 Branch # 1

Road Name FLORENCE LAKE

User km 13.2

Previous Load Rating (tonnes) 68

Structure Class Permanent Bridge

Portable N

Superstructure Other

Deck Type Concrete

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 11.9

Deck Width (m) 4.9

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5490215.4 Accuracy (m)

L75 or 68 tonnes

Inspection

Date of Inspection 2020-05-26 10:33:32 AM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2023

Inspection Company FLNRORD

Inspector Comments

P.Eng Comments

Replace the guardrail, risers and blocks. Brush and grade approaches. The current load rating of L75 or 68 tonnes to continue.



CK-2097
CK-2097

FLORENCE LAKE 13.2km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☒ 1 ☐ 2

Fender Condition Good

Posted Load Rating Not posted

Road Surface Poor Large potholes at both approaches

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills Good

Piles or Posts Unrated Buried

Ballast Wall Good

Wing Wall

Bracing Unrated Buried

Hardware

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Unrated Buried

CK-2097
CK-2097

FLORENCE LAKE 13.2km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Good

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Good

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Poor Rotten

Hand Rails/Walkouts

Hardware Poor Loose rail bolts

Overall Deck Condition Poor Due to rail condition

Gravel Depth (mm)

Pier Deck

CK-2097
CK-2097

FLORENCE LAKE 13.2km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders **Good**

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors **Good** **Welded**

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

CK-2097
CK-2097

FLORENCE LAKE 13.2km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. Full Curb Replacement. . Priority:Medium	Replace guardrail, risers and blocks
2 Approach. Area/sight line brushing. m². Priority:Low	Brush approaches
3 Approach. Approach surfacing grading. m. Priority:Medium	Grade approaches
4	
5	
6	
7	

Item	Monitor Description	Frequency
1		
2		
3		



Approach from Left Bank when facing downstream



Guard Rail



Guard Rail



Deck



Shear connectors



Upstream from Crossing



Downstream from Crossing



Concrete wear at downstream right bank



Approach from Right Bank when facing downstream



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream