

CK-2167
CK-2167

LOST CREEK 8km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
49°20'26.4"	-122°14'32.6"
Crossing Name	Lost Creek
FSR #	8466
Branch #	1
Road Name	LOST CREEK
User km	8
Previous Load Rating (tonnes)	68
Structure Class	Temporary Bridge
Portable	Y
Superstructure	Steel Box Beam
Deck Type	Steel
Abutment Left	Concrete Lock Blocks
Abutment Right	Concrete Lock Blocks
Spans	1
Total Length (m)	24.4
Deck Width (m)	4.95

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5492577.9
Accuracy (m)	
L75 or 68 tonnes	

Inspection

Date of Inspection 2020-05-26 2:16:37 PM

Inspector Name Tyson Miller

Inspector Comments

Recommended Next Inspection Year 2023

Inspection Company FLNRORD

P.Eng Comments

Replace all delineators and grade approaches. Monitor the debris accumulations upstream the crossing. The current load rating of L75 or 68 tonnes to continue.



CK-2167
CK-2167

LOST CREEK 8km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating Not posted

Road Surface Poor Potholes at both approaches

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Good 5 rows of lock blocks visible

Caps or Sills Good Treated timbers

Piles or Posts

Ballast Wall Good Logs

Wing Wall

Bracing

Hardware Good Geogrid between each row of lock blocks

Fill Good

Riprap Good

Bearings Good

Corrosion Protection

CK-2167
CK-2167

LOST CREEK 8km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Good Potholes at both approaches

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate Fair Minor damage on wheel path and all anti skid worn off

Gravel Surface

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts

Hardware

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

CK-2167
CK-2167

LOST CREEK 8km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Good

Diaphragms Unrated Internal

Bracing Unrated Internal

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

CK-2167
CK-2167

LOST CREEK 8km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	2.0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	20	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	7.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. Delineator maintenance. . Priority:Low	Replace all delineators
2 Approach. Approach surfacing grading. m. Priority:Medium	Grade approaches
3	
4	
5	
6	
7	

Item	Monitor Description	Frequency
1	debris accumulations upstream	Routine Inspection
2		
3		



Approach from Right Bank when facing downstream



Existing delineators



Deck



Upstream from Crossing



Downstream from Crossing



Approach from Left Bank when facing downstream



Structure ID



Right Bank Abutment when facing downstream

CK-2167
CK-2167

LOST CREEK 8km

2020 Inspection

CBR iPad Offline Ver 0.33



Left Bank Abutment when facing downstream



Superstructure