

CK-2454  
CK-2454

NORRISH 8.4km

2020 Inspection

CBR iPad Offline Ver 0.33



### CBR Data

|                               |                  |
|-------------------------------|------------------|
| Latitude                      | Longitude        |
| 49°14'17.99"                  | -122°7'27"       |
| Crossing Name                 | Unknown          |
| FSR #                         | 10326            |
| Branch #                      | 1                |
| Road Name                     | NORRISH          |
| User km                       | 8.4              |
| Previous Load Rating (tonnes) | 150              |
| Structure Class               | Major Culvert    |
| Culvert Type                  | Round            |
| Culvert Material              | Corrugated Steel |
| Opening Height (mm)           | 3000             |
| Opening Width (mm)            | 3000             |
| Inlet Cover (mm)              | 1000             |
| Outlet Cover (mm)             | 1200             |
| Culvert Gradient %            | 5                |
| Culvert Length (m)            | 19               |

### Updated Data

|                    |           |
|--------------------|-----------|
| Latitude           | Longitude |
| °0'0"              | °0'0"     |
| HD Diff. (m)       | 5481186.2 |
| Accuracy (m)       |           |
| L165 or 150 tonnes |           |

### Inspection

Date of Inspection 2020-05-27 10:27:21 AM

Inspector Name Tyson Miller

Inspector Comments

Recommended Next Inspection Year 2023

Inspection Company FLNRORD

P.Eng Comments

Remove the accumulated stream material at the inlet and dig a sump. The current load rating of L165 or 150 tonnes to continue.



2020-12-02

P.Eng Seal

CK-2454  
CK-2454

NORRISH 8.4km

2020 Inspection

CBR iPad Offline Ver 0.33



## Approach

Alignment Fair

HC both approaches

Bridge Ahead Signs  
Missing ☒ 0 ☐ 1 ☐ 2 NA

Brushing Required N

Delineator Missing  
Left ☒ 0 ☐ 1 ☐ 2 NA

Delineator Missing  
Right ☒ 0 ☐ 1 ☐ 2 NA

Fender Condition Good

Posted Load Rating Not posted

Road Surface Good

## Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

CK-2454  
CK-2454

NORRISH 8.4km

2020 Inspection

CBR iPad Offline Ver 0.33



## Culvert

Baffles

Bolted Connections

Coating Fair

Coupled Connections Good

Embedment Materials

Fill Good

Floor Fair Minor corrosion

Footing

Head Walls

Inlet Poor Approx 50% end area blocked by aggraded material

Outlet Good

Overall Fair Culvert is functioning but inlet 50% plugged

Rip Rap Good

Roof Good

Sidewalls Good

Trash Rack

Weirs/Backwater  
Structures

Wing Walls

CK-2454  
CK-2454

NORRISH 8.4km

2020 Inspection

CBR iPad Offline Ver 0.33



### Hazards

|                                          |     |             |                                     |        |                          |
|------------------------------------------|-----|-------------|-------------------------------------|--------|--------------------------|
| Estimated Present Water Level Depth (m)  | 0.3 | High Water  | <input type="checkbox"/>            | Debris | <input type="checkbox"/> |
| Estimated Present Water Level Width (m)  | 2.0 | Aggradation | <input checked="" type="checkbox"/> | Scour  | <input type="checkbox"/> |
| Estimated High Water Level Clearance (m) | 1.5 | Ice         | <input type="checkbox"/>            |        |                          |

Comments

### Repairs and Monitoring

| Repair Item                                             | Repair Description                                  |
|---------------------------------------------------------|-----------------------------------------------------|
| 1 Channel. Remove Aggraded Material. .<br>Priority:High | Remove aggraded material from inlet and create sump |

2

3

4

5

6

7

| Item | Monitor Description | Frequency |
|------|---------------------|-----------|
|------|---------------------|-----------|

1

2

3



Approach from Right Bank when facing downstream



Upstream from Crossing



Downstream from Crossing



Approach from Left Bank when facing downstream



Inlet



Inlet



Inlet



Outlet



Outlet



Looking through culvert from outlet