

CK-2472
CK-2472

MAISAL 6km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude 49°25'11.6" Longitude -121°57'57.3"

Crossing Name Upper Maisal

FSR # 8241 Branch # 16

Road Name MAISAL

User km 6

Previous Load Rating (tonnes) 136

Structure Class Temporary Bridge

Portable N

Superstructure Steel I-beam

Deck Type Timber - Untreated

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 20.7

Deck Width (m) 4.9

Updated Data

Latitude 49°25'11.6" Longitude -121°57'57.77"

HD Diff. (m) 9.4 Accuracy (m) 5

L100 or 91 tonnes

Inspection

Date of Inspection 2020-08-25 9:22:45 AM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2021

Inspection Company FLNRORD

Inspector Comments

The timber deck is now 8 years old and nearing the end of its industrial life. Fruiting bodies are showing up at various locations on the underside of the subdeck. Only 1 fruiting body present on a single cross tie.

P.Eng Comments

Brush approaches and replace missing delineators. Limit the loading to L100 or 91 tonnes - post load rating signs. Replace the cross ties, subdeck, wear planks and guardrail system for design vehicle loading.



P.Eng Seal

CK-2472
CK-2472

MAISAL 6km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

HC right approach

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2 vegetation obstructs view

Delineator Missing
Right ☐ 0 ☐ 1 ☒ 2 vegetation obstructs view

Fender Condition Fair logs

Posted Load Rating not posted

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts Fair

Ballast Wall Fair Old logs

Wing Wall

Bracing Fair

Hardware

Fill Fair

Riprap Fair Sparse, round and not well graded or keyed together

Bearings Good

Corrosion Protection Fair

CK-2472
CK-2472

MAISAL 6km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface

Running Planks

Fair

Wearing at ends and in random locations throughout

Sub Deck

Fair

Fair to poor - small fruiting bodies at various locations on underside

Ties

Fair

A single fruiting body present on 1 tie

Nails

Fair

Deck to Girder Bolts

Fair

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts

Fair

Hand Rails/Walkouts

Hardware

Fair

Overall Deck Condition

Fair

Gravel Depth (mm)

Pier Deck

CK-2472
CK-2472

MAISAL 6km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Good

Diaphragms Good 4 bolted bays

Bracing Good

Hardware Good

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

CK-2472
CK-2472

MAISAL 6km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	0.3	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	9.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	3.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. Delineator maintenance. . Priority:Low	Replace right hand delineators
2 Approach. Area/sight line brushing. m². Priority:Medium	Brush approaches
3 High	Post load rating sign
4	
5	
6	
7	

Item	Monitor Description	Frequency
1		
2		
3		



Approach from Left Bank when facing downstream



Approach from Left Bank when facing downstream



Deck



Upstream from Crossing



Downstream from Crossing



Approach from Right Bank when facing downstream



Left Bank Abutment when facing downstream



Superstructure



2020 Inspection

CBR iPad Offline Ver 0.33

MAISAL 6km

CK-2472
CK-2472



Right Bank Abutment when facing downstream



Deck from underneath



Small fruiting body present on single tie and at various locations of subdeck -
typical size shown