

CK-2120
CK-2120A

BEAR 7km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°27'20.7" Longitude -121°42'17.1"

Site Status Active

Insp. Status Inspect

Crossing Name Not Known

FSR # 5748 Branch # 3

Road Name BEAR

User km 7

Previous Load Rating (tonnes) 64

Structure Class Temporary Bridge

Portable N

Superstructure Steel Box Beam

Deck Type Steel

Abutment Left Sill -Temporary Materials

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 10

Deck Width (m) 4.9

Updated Data

Latitude 49°27'21.09" Longitude -121°42'17.14"

HD Diff. (m) 11.9 Accuracy (m) 8

Y

Sill -Temporary Materials

Inspection

Date of Inspection 2022-08-30 10:55:57 AM

Inspector Name Cameron VandenBrink, EIT

Recommended Next Inspection 2024

Inspection Company Chartwell Resource Group Ltd

Inspector Comments Serial/ID Plate


P.Eng Comments

Load rated by: MoF Sasha Ward RPF, P.Eng Feb 6 2023

Load rating: maintain 64 tonne rating for All Steel Portable

Comments: monitor log structure that is overspanned with All Steel Portable to ensure sills sitting on competent foundation.

Next inspection: 2024



PERMIT TO
PRACTICE: 1003022

CK-2120
CK-2120A

BEAR 7km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment Fair

HC, wide running surface and turn radius

Bridge Ahead Signs
Missing

☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing
Left

☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right

☐ 0 ☒ 1 ☐ 2

Fender Condition Fair

Guidelogs small diameter but functional

Posted Load Rating

Not posted

Road Surface Fair

Woods approach has water bar 20m beyond.

Abutment

Log/Timber Cribs Fair

Original sills and structure beneath and over spanned with all steel portable on single sill logs each end.

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall Fair

Ballast logs

Wing Wall

Bracing

Hardware

Fill Good

Riprap Poor

Sills on stream edge beneath from original structure

Bearings Good

Single sills show no signs of crushing

Corrosion Protection

CK-2120
CK-2120A

BEAR 7km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface Woods approach has water bar 20m beyond.

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate Fair Some deformation at tracking locations. Sediment on deck

Gravel Surface

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts

Hardware

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

CK-2120
CK-2120A

BEAR 7km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

CK-2120
CK-2120A

BEAR 7km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	.5	Aggradation	☒	Scour	☐
Estimated High Water Level Clearance	.5	Ic	☐		

Comments Gravelly deposit beneath structure.

Repairs and Monitoring

Repair Item	Repair Description
1 Approach. Area/sight line brushing. m². Priority:Low	
2 Structure. Add Load Rating Signs. # sites. Priority:Low	
3 Approach. Bridge Ahead Signs. # of signs. Priority:Low	Install also install missing delineator
4	
5	
6	
7	


Item	Monitor Description	Frequency
1	Some gravelly debris accumulating beneath. Also monitor original sill logs for scour. Non currently noted but they sit on the wetted perimeter.	Routine Inspection
2		
3		



Approach from Right Bank when facing downstream



Upstream from Crossing



Downstream from Crossing



Approach from bridge deck of Right bank approach when facing downstream



Approach from bridge deck of Left bank approach when facing downstream



Deck



Approach from Left Bank when facing downstream



Upstream Profile



2022 Inspection

CBR iPad Offline Ver 0.36

BEAR 7km

CK-2120
CK-2120A



Upstream Profile



Downstream Profile