

CK-2237
CK-2237

SOWAQUA 14.6km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°22'9.19" Longitude -121°9'36.5"

Site Status Active

Insp. Status Inspect

Crossing Name Montigny Creek

FSR # 7004 Branch # 1

Road Name SOWAQUA

User km 14.6

Previous Load Rating (tonnes) 41

Structure Class Temporary Bridge

Portable N

Superstructure Steel I-beam

Deck Type Timber - Untreated

Abutment Left Crib, Log or Untreated Timber

Abutment Right Crib, Log or Untreated Timber

Spans 1

Total Length (m) 18.3

Deck Width (m) 4.3

Updated Data

Latitude 49°22'8.96" Longitude -121°9'36.28"

HD Diff. (m) 8.6 Accuracy (m) 5

0 tonnes

Inspection

Date of Inspection 2022-10-26 12:35:27 PM

Inspector Name Tyson Miller

Recommended Next Inspection 2024
Year


Inspection Company MoF

Inspector Comments Serial/ID Plate

Replace
Steel looks salvageable

P.Eng Comments

The bridge has washed out. The steel girders do not appear to have sustained damage and should be salvaged. A temporary access road has been constructed immediately below this structure; however, access over the bridge itself was not blocked on the right approach (Town Approach). I recommend blocking access over the bridge on the Town Approach and posting the bridge as washed out, 0 tonnes load rating.



PERMIT TO
PRACTICE: 1003022



Approach from Right Bank when facing downstream



Approach from Right Bank when facing downstream



Upstream from Crossing



Downstream from Crossing



Approach from Left Bank when facing downstream



Approach from Left Bank when facing downstream



Downstream Profile



Left Bank Abutment when facing downstream



Upstream Profile



Right Bank Abutment when facing downstream



Superstructure



2022 Inspection

CBR iPad Offline Ver 0.36

SOWAQUA 14.6km

CK-2237
CK-2237



Structure ID