

CK-2252
CK-2252

SPUZZUM 17000 4km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°42'5.1" Longitude -121°38'20.2"

Site Status Barricaded/Closed

Insp. Status Do Not Inspect

Crossing Name Southwest Fork

FSR # 8128 Branch # 10

Road Name SPUZZUM 17000

User km 4

Previous Load Rating (tonnes) 0

Structure Class Temporary Bridge

Portable N

Superstructure Timber - untreated stringers

Deck Type Gravel

Abutment Left Sill -Temporary Materials

Abutment Right Sill -Temporary Materials

Spans 1

Total Length (m) 11.5

Deck Width (m) 999

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5532736.4 Accuracy (m)

Inspection

Date of Inspection 2022-11-02 8:45 AM

Inspector Name Cameron VandenBrink, EIT

Recommended Next Inspection

Inspection Company Chartwell Resource Group Ltd

Inspector Comments Serial/ID Plate

Structure has been blown out. No sign of structure at crossing location. Stringers visible downstream on stream edge.

P.Eng Comments

Load Rated by: MoF, M.Lowe, RPF, PEng, February 16, 2023

Load Rating: 0 Tonnes GVW

Next Inspection: September 1, 2025

Comments: Consider changing structure/site status to deactivated.



PERMIT TO
PRACTICE: 1003022

CK-2252
CK-2252

SPUZZUM 17000 4km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required

Delineator Missing
Left ☐ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating

Road Surface

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

CK-2252
CK-2252

SPUZZUM 17000 4km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts

Hand Rails/Walkouts

Hardware

Overall Deck Condition

Gravel Depth (mm)

Pier Deck

CK-2252
CK-2252

SPUZZUM 17000 4km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

CK-2252
CK-2252

SPUZZUM 17000 4km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)

High Water ☐

Debris ☐

Estimated Present Water Level Width (m)

Aggradation ☐

Scour ☐

Estimated High Water Level Clearance

Ic ☐

Comments

Repairs and Monitoring

Repair Item

Repair Description

1

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3



2022 Inspection

CBR iPad Offline Ver 0.36

SPUZZUM 17000 4km

CK-2252
CK-2252



Structure no longer exists. 2 stringers visible down stream. Not In photo