

CK-2363
CK-2363

SPUZZUM 25.2km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°44'18.89" Longitude -121°41'18.9"

Site Status Active

Insp. Status Inspect

Crossing Name side creek

FSR # 8128 Branch # 1

Road Name SPUZZUM

User km 25.2

Previous Load Rating (tonnes) 68

Structure Class Permanent Bridge

Portable N

Superstructure Compo Girders

Deck Type Concrete

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 9.7

Deck Width (m) 4.9

Updated Data

Latitude 49°44'19.13" Longitude -121°41'19.34"

HD Diff. (m) 11.4 Accuracy (m) 7

Inspection

Date of Inspection 2022-11-01 3:55:19 PM

Inspector Name Cameron VandenBrink, EIT

Recommended Next Inspection 2024

Inspection Company Chartwell Resource Group Ltd

Inspector Comments Serial/ID Plate

P.Eng Comments

Load Rated by: MoF, M.Lowe, RPF, PEng, February 16, 2023
Load Rating: 5 Tonnes GVW
Next Inspection: September 1, 2025
Comments: Load rating only due to guard rail condition. Replace rails prior to next use.



PERMIT TO
PRACTICE: 1003022

CK-2363
CK-2363

SPUZZUM 25.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required **Y**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Fair**

Concrete no posts . Bullnose downstream right requires reconnection.

Posted Load Rating

Not posted

Road Surface **Fair**

25 meters down right approach, either culvert fully plugged or new side channel has eroded road prism, flow currently running in ditch to upstream right of bridge. High flows overtop

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills **Good**

Integrated ballast wall

Piles or Posts **Good**

What is visible

Ballast Wall **Good**

Wing Wall

Bracing **Unrated**

Buried

Hardware

Fill **Good**

Riprap **Fair**

Upstream left and downstream right tone monitored

Bearings **Good**

Corrosion Protection **Good**

CK-2363
CK-2363

SPUZZUM 25.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface

25 meters down right approach, either culvert fully plugged or new side channel has eroded road prism, flow currently running in ditch to upstream right of bridge. High flows

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck **Good**

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Fair** **Poor-rotten**

Hand Rails/Walkouts

Hardware **Fair**

Overall Deck Condition **Fair** **Poor due to guard rail**

Gravel Depth (mm)

Pier Deck

CK-2363
CK-2363

SPUZZUM 25.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders Good 2 inverted c channel

Diaphragms Good Monolithic end diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted shear connectors Good Welded

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

CK-2363
CK-2363

SPUZZUM 25.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m) .2

High Water ☐

Debris ☐

Estimated Present Water Level Width (m) 3

Aggradation ☐

Scour ☒

Estimated High Water Level Clearance

Ic ☐

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1 Structure. Curb Maintenance. # sites. Priority:Medium	Replace guard rail
---	--------------------

2 Approach. Area/sight line brushing. m². Priority:Low	
--	--

3 Approach. Approach fenders (re-Install). # of units. Priority:Low	Connect bullnose
---	------------------

4

5

6

7

Item	Monitor Description	Frequency
1	Upstream left and downstream, right riprap	Routine Inspection

2

3



Approach from bridge deck of Right bank approach when facing downstream



Approach from bridge deck of Left bank approach when facing downstream



Approach from Left Bank when facing downstream



Upstream from Crossing



Downstream from Crossing



Deck



Approach from Right Bank when facing downstream



Downstream right bullnose





Left Bank Abutment when facing downstream



Superstructure



Superstructure



Right Bank Abutment when facing downstream



Upstream Profile



Upstream left bank riprap



Downstream Profile



Downstream right riprap scour



2022 Inspection

CBR iPad Offline Ver 0.36

SPUZZUM 25.2km

CK-2363
CK-2363



High chain blow out