

CK-2453
CK-2453

NORRISH 7.4km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°14'9.09" Longitude -122°7'56.7"

Site Status Active

Insp. Status Inspect

Crossing Name Norrish Creek

FSR # 10326 Branch # 1

Road Name NORRISH

User km 7.4

Previous Load Rating (tonnes) 91

Structure Class Temporary Bridge

Portable N

Superstructure Steel I-beam

Deck Type Timber - Untreated

Abutment Left Sill -Temporary Materials

Abutment Right Sill -Temporary Materials

Spans 1

Total Length (m) 24.4

Deck Width (m) 4.8

Updated Data

Latitude 49°14'9.07" Longitude -122°7'56.18"

HD Diff. (m) 10.5 Accuracy (m) 7

Inspection

Date of Inspection 2022-10-21 10:58:09 AM

Inspector Name Cameron VandenBrink, EIT

Recommended Next Inspection 2024

Inspection Company Chartwell Resource Group Ltd

Inspector Comments Serial/ID Plate

P.Eng Comments

Load Rated by: MoF, M.Lowe, RPF, PEng, February 16, 2023
Load Rating: 91 Tonnes GVW, L-100
Next Inspection: September 1, 2024
Comments: No issues



PERMIT TO
PRACTICE: 1003022

CK-2453
CK-2453

NORRISH 7.4km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment Fair

HC right approach

Bridge Ahead Signs
Missing

☐ 0

☒ 1

☐ 2

Left approach missing

Brushing Required Y

Minor around fenders

Delineator Missing
Left

☒ 0

☐ 1

☐ 2

Delineator Missing
Right

☒ 0

☐ 1

☐ 2

Fender Condition Good

Posted Load Rating

90680

Road Surface Fair

Potholes each end of structure

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills Fair

Single sill

Piles or Posts

Ballast Wall Fair

Ballast logs

Wing Wall

Bracing

Hardware

Fill Fair

Ravelling below fill retainment logs on both sides.

Riprap N/A

Bed rock

Bearings Fair

Corrosion Protection

CK-2453
CK-2453

NORRISH 7.4km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface

Potholes each end of structure

Running Planks

Good

Sediment accumulating on deck

Sub Deck

Fair

Ties

Fair

Nails

Good

Deck to Girder Bolts

Good

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts

Fair

Slightly loose. All hardware present, likely due to age

Hand Rails/Walkouts

Hardware

Good

Overall Deck Condition

Fair

Water runs onto deck from left approach.

Gravel Depth (mm)

Pier Deck

CK-2453
CK-2453

NORRISH 7.4km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders Fair

Painted superstructure

Diaphragms Fair

4 welded bays

Bracing Fair

Under Trussing

Hardware Fair

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

CK-2453
CK-2453

NORRISH 7.4km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	15	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	10	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Approach. Bridge Ahead Signs. # of signs. Priority:Low	Left approach

2

3

4

5

6

7

Item	Monitor Description	Frequency
1 Erosion on both banks		Routine Inspection

2

3



Approach from Left Bank when facing downstream



Upstream from Crossing



Downstream from Crossing



Approach from bridge deck of Left bank approach when facing downstream



Approach from bridge deck of Right bank approach when facing downstream



Load Rating Sign



Approach from Right Bank when facing downstream



Downstream Profile



Bearing



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



Deck