

CK-2472
CK-2472

MAISAL 11.5km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°25'11.6" Longitude -121°57'57.3"

Site Status Active

Insp. Status Inspect

Crossing Name Upper Maisal

FSR # 8241 Branch # 16

Road Name MAISAL

User km 11.5

Previous Load Rating (tonnes) 64

Structure Class Temporary Bridge

Portable N

Superstructure Steel I-beam

Deck Type Timber - Untreated

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 20.7

Deck Width (m) 4.9

Updated Data

Latitude 49°25'12.14" Longitude -121°57'57.35"

HD Diff. (m) 16.8 Accuracy (m) 6

Inspection

Date of Inspection 2022-08-31 2:41:54 PM

Inspector Name Cameron VandenBrink, EIT

Inspector Comments Serial/ID Plate

Recommended Next Inspection 2024

Inspection Company Chartwell Resource Group Ltd

P.Eng Comments

Load Rated by: MoF, M.Lowe, RPF, PEng, February 16, 2023

Load Rating: 64 Tonnes GVW

Next Inspection: September 1, 2023

Comments: Load rating to continue for 1 year. Return to reassess timber deck in 2023.



PERMIT TO
PRACTICE: 1003022

CK-2472
CK-2472

MAISAL 11.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment Fair

HC and trough of vc

Bridge Ahead Signs
Missing

☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left

☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right

☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Guidelogs, ds woods to be rolled back to shoulder

Posted Load Rating

Not posted

Road Surface Fair

4x4 access to site due to x ditches

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts Good

Ballast Wall Poor

Rotting logs, starting to lose fill between girders on town end. Currently minor amounts

Wing Wall

Bracing Fair

Hardware Fair

Fill

Riprap Fair

Town side scouring.

Bearings Good

Corrosion Protection Poor

Does not appear to be coated

CK-2472
CK-2472

MAISAL 11.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface Fair 4x4 access to site due to x ditches

Running Planks Fair Few boards needs to be renailed

Sub Deck Fair

Ties Fair

Nails Fair Few missing into running planks

Deck to Girder Bolts Poor No clips or bolts to top flange observed. Panelized deck appears to rely on gravity load only for restriction onto girders

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts

Hand Rails/Walkouts Good

Hardware Good

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

CK-2472
CK-2472

MAISAL 11.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders Good

Diaphragms Good 3 bay

Bracing Fair Town end has one bent brace, likely installed bent

Under Trussing

Hardware Good Bolted bracing

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

CK-2472
CK-2472

MAISAL 11.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	7	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	2.2	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Approach. Area/sight line brushing. m². Priority:Low	
2 Approach. Approach fenders (re-Install). # of units. Priority:Low	Woods downstream,
3 Structure. Timber deck maintenance. # of signs. Priority:Medium	Fasten deck panels to girders

4

5

6

7

Item	Monitor Description	Frequency
1 Town riprap		Routine Inspection

2

3



Approach from Left Bank when facing downstream



Approach from bridge deck of Left bank approach when facing downstream



Upstream from Crossing



Downstream from Crossing



Approach from bridge deck of Right bank approach when facing downstream



Approach from Right Bank when facing downstream



Deck



Upstream Profile



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



Bearing



Left Bank Abutment when facing downstream



2022 Inspection

CBR iPad Offline Ver 0.36

MAISAL 11.5km

CK-2472
CK-2472



Downstream Profile