

CK-2520
CK-2520

LOST CREEK km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°17'33.6" Longitude -122°13'44.9"

Site Status Active

Insp. Status Inspect

Crossing Name Side Creek

FSR # 8466 Branch # 1

Road Name LOST CREEK

User km

Previous Load
Rating (tonnes) 91

Structure Class Major Culvert

Culvert Type Round

Culvert Material Corrugated Steel

Opening Height (mm) 2400

Opening Width (mm) 2400

Inlet Cover (mm) 700

Outlet Cover (mm) 1000

Culvert Gradient %

Culvert Length (m) 16

Updated Data

Latitude 49°17'34" Longitude -122°13'45.45"

HD Diff. (m) 16.7 Accuracy (m) 6

Inspection

Date of Inspection 2022-09-01 12:55:40 PM

Inspector Name Cameron VandenBrink, EIT

Recommended Next Inspection 2024

Inspection Company Chartwell Resource Group Ltd

Inspector Comments

P.Eng Comments

Load Rated by: MoF, M.Lowe, RPF, PEng, February 16, 2023

Load Rating: 91 Tonnes GVW, L-100

Next Inspection: September 1, 2025

Comments: No issues.



PERMIT TO
PRACTICE: 1003022

CK-2520
CK-2520

LOST CREEK km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment Fair

HC over culvert due to narrowing road running surface

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☐ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill Good

Riprap Good

Bearings

Corrosion Protection

CK-2520
CK-2520

LOST CREEK km

2022 Inspection

CBR iPad Offline Ver 0.36



Culvert

Baffles

Bolted Connections

Coating Good

Coupled Connections Fair

Embedment Materials

Fill Good

Floor Fair Infilled with 20-30cm of rock

Footing

Head Walls

Inlet Good

Outlet Good

Overall Good

Rip Rap Good

Roof Good

Sidewalls Good

Trash Rack

Weirs/Backwater
Structures

Wing Walls

CK-2520
CK-2520

LOST CREEK km

2022 Inspection

CBR iPad Offline Ver 0.36



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

CK-2520
CK-2520

LOST CREEK km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m) 0

High Water ☐

Debris ☐

Estimated Present Water Level Width (m) 0

Aggradation ☐

Scour ☐

Estimated High Water Level Clearance 2

Ic ☐

Comments Currently stream goes subsurface 30m upstream and is subsurface to the bottom of the armoured fill slope downstream of crossing

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
1	Amount of infill.	Routine Inspection

2

3



Approach from Left Bank when facing downstream



Upstream from Crossing



Downstream from Crossing



Inlet



Downstream from Crossing



Outlet