

CK-2225
CK-2225B

PITT RIVER 24.6km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°42'38.59" Longitude -122°42'49.7"

Site Status Active

Insp. Status Inspect

Crossing Name Blue Creek

FSR # 8394 Branch # 1

Road Name PITT RIVER

User km 24.6

Previous Load Rating (tonnes) 68

Structure Class Temporary Bridge

Portable N

Superstructure Log Stringers

Deck Type Gravel

Abutment Left Crib, Log or Untreated Timber

Abutment Right Crib, Log or Untreated Timber

Spans 1

Total Length (m) 16

Deck Width (m) 8

Updated Data

Latitude 49°42'39.48" Longitude -122°42'55.65"

HD Diff. (m) 121.9 Accuracy (m) 5

L30 or 27 tonnes

Inspection

Date of Inspection 2022-10-17 11:50:53 AM

Inspector Name Cameron VandenBrink, EIT

Recommended Next Inspection 2024

Inspection Company Chartwell Resource Group Ltd

Inspector Comments Serial/ID Plate

Average between left and right bearing for mid span diameter. Drilled all stringers right bank. Pocket/dry rot throughout structure. Stringer rot depths consistent with dry rot depth where noted.

P.Eng Comments

L30 or 27 tonnes rating. The structure also has the capacity for a 20 tonnes excavator. Post load rating signs. Brush approaches and post bridge ahead signs.



PERMIT TO
PRACTICE: 1003022

CK-2225
CK-2225B

PITT RIVER 24.6km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment Fair

HC both approaches

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Old logs, low on left approach

Posted Load Rating

Not posted

Road Surface Fair

Abutment

Log/Timber Cribbs Good 3 high

Tie Backs Good 3x

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware Good Well lashed

Fill Good

Riprap Fair Sparse beneath bridge.

Bearings Good

Corrosion Protection

CK-2225
CK-2225B

PITT RIVER 24.6km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Fair

Some gravel deck material getting lost beneath curb logs through cross puncheon.

Curb Rail/Blocks/Posts

Hand Rails/Walkouts

Hardware

Good

Well lashed

Overall Deck Condition

Fair

Gravel Depth (mm)

200

Atop average 300mm hemlock puncheon

Pier Deck

CK-2225
CK-2225B

PITT RIVER 24.6km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)			Needle Diameter (mm)			
Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
1	Fd	Y	755	60	Fair	
2	Fd	Y	725	50	Fair	
3	Fd	Y	725	50	Fair	
4	Fd	Y	855	80	Fair	
5	Fd	Y	830	60	Fair	
6	Fd	Y	815	53	Fair	
7	Fd	Y	88	60	Fair	
8	Fd	Y	795	55	Fair	
9	Fd	Y	930	50	Fair	Dry rot at bearing
10	Fd	Y	875	60	Fair	
11	Fd	Y	820	60	Fair	Dry rot left end
12	Fd	Y	855	90	Fair	

CK-2225
CK-2225B

PITT RIVER 24.6km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	.4	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	8	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	1.4	Ic	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

- 1 Approach. Bridge Ahead
Signs. # of signs.
Priority:Low
- 2 Approach. Area/sight line
brushing. m². Priority:Low
- 3 Structure. Add Load Rating
Signs. # sites.
Priority:Medium

4

5

6

7

Item	Monitor Description	Frequency
1 Riprap		Routine Inspection

2

3



Approach from bridge deck of Right bank approach when facing downstream



Approach from bridge deck of Left bank approach when facing downstream



Downstream from Crossing



Upstream from Crossing



Material loss beneath curb log.



Approach from Right Bank when facing downstream



Approach from Left Bank when facing downstream



Left Bank Abutment when facing downstream



Stringers



Stringers



Right Bank Abutment when facing downstream



Upstream Profile

CK-2225
CK-2225B

PITT RIVER 24.6km

2022 Inspection

CBR iPad Offline Ver 0.36



Cross puncheon



Stringer 11 dry rot, 1.5m inside bearing left bank