



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-191	Structure Name:	G4-901	Road Name:	COBB SOUTH FSR	Inspection Date:	2012/07/24
KM:	4.20	User km:	4.20	Crossing Name:	Unknown	Next Inspection Date:	2014/07/24
Project File ID #:	10235	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	18.3	# Spans:	1	Span Width:			Span Length(s) (metres): 18.3
UTM Zone:	10	UTM Easting:	465636	UTM Northing:	5973017		
Inspector Name:	Shane Gorezky			Year Superstructure Installed:	2006		

Access:	
---------	--

ABUTMENTS

Bearings	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	light surface rust
Caps or Sills	Good	
Fill	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	Concrete and logs, logs are completey rotten
Road Surface	Fair	

DECK

Span 1

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 2 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-191	Structure Name:	G4-901	Road Name:	COBB SOUTH FSR	Inspection Date:	2012/07/24	
Curb Rail/Blocks/Posts	Good							
Deck to Girder Bolts	Unrated	not rated on inspection						
Hardware	Fair	some nuts are missing						
Hand Rails/Walkouts	Not Applicable							
Nails	Good							
Overall Deck Condition	Fair	Replace rotten plans prior to industrial use						
Sub Deck	Poor	8 - 9 planks are in poor condition due to rot						
Ties	Fair	3 or 4 ties are getting soft spots where exposed						
SUPERSTRUCTURE								
Span 1								
Bracing	Good							
Diaphragms	Good	Damage to right abutment bracing from installation						
Girders	Good							
Hardware	Unrated	Not rated on inspection						
Under Trussing	Not Applicable							
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.2	
	Estimated High Water Level Clearance:		2.0					
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris: Yes	Aggradation: No
	Comment:	Dead Pine logs laying under the bridge						
REPAIRS	#	Status	Priority	Estimate	Description			
	1	Suggested	Medium	\$	Replace deck planks and cross ties as required prior to industrial use			
MONITORS	#	Description						
GENERAL	Inspector's Comment:	Need to confirm why comments state that bridge is G4-912 and if so is there a G4-901 bridge						

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 3 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-191	Structure Name:	G4-901	Road Name:	COBB SOUTH FSR	Inspection Date:	2012/07/24
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments					
GENERAL	Estimated Load Restriction (year):		2021	Estimated Replacement (year):		2021	
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?		No	Report Status: Accepted By Jason Olmsted on 2013/05/27 00:00:00			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 4 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-180	Structure Name:	G4-180	Road Name:	BARLOW FSR	Inspection Date:	2019/08/08
KM:	23.90	User km:	23.90	Crossing Name:	Un-named Creek	Next Inspection Date:	2022/08/08
Project File ID #:	10653	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	12.2	# Spans:	1	Span Width:	Span Length(s) (metres):		12
UTM Zone:	10	UTM Easting:	402220	UTM Northing:	6005460		
Inspector Name:	dawson smith			Year Superstructure Installed:	2006		
Access:							

ABUTMENTS

Bearings	Good
Bracing	Good
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Good
Piles or Posts	Good
Riprap	Good
Wing Wall	Not Applicable

APPROACHES

Alignment	Good
Bridge Ahead Signs Missing	0
Brushing Required	Yes
Delineator Missing Left (approaching structure)	0
Delineator Missing Right (approaching structure)	0
Fender Condition	Good
Posted Load Rating (Enter 0 if sign missing)	91000
Road Surface	Good

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 5 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-180	Structure Name:	G4-180	Road Name:	BARLOW FSR	Inspection Date:	2019/08/08
---------	--------	-----------------	--------	------------	------------	------------------	------------

DECK

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Good
---------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	2.0
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	2.0
---------------------------------------	-----

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$ 500.00	brush both sides

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 6 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-180	Structure Name:	G4-180	Road Name:	BARLOW FSR	Inspection Date:	2019/08/08
GENERAL	Inspector's Comment:	good					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2045	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/23 14:10:14			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 7 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-181	Structure Name:	G4-181	Road Name:	BARLOW FSR	Inspection Date:	2019/08/08
KM:	27.00	User km:	27.00	Crossing Name:	Un-named Creek	Next Inspection Date:	2022/08/08
Project File ID #:	10653	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	12.1	# Spans:	1	Span Width:	Span Length(s) (metres):		12
UTM Zone:	10	UTM Easting:	399328	UTM Northing:	6004168		
Inspector Name:	dawson smith			Year Superstructure Installed:	2005		
Access:	Travel up the Barlow FSR to 27 km to reach the bridge						

ABUTMENTS

Bearings	Good
Bracing	Good
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Good
Piles or Posts	Good
Riprap	Good
Wing Wall	Not Applicable

APPROACHES

Alignment	Good
Bridge Ahead Signs Missing	0
Brushing Required	Yes
Delineator Missing Left (approaching structure)	0
Delineator Missing Right (approaching structure)	0
Fender Condition	Good
Posted Load Rating (Enter 0 if sign missing)	91000
Road Surface	Good

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 8 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G4-181 Structure Name: G4-181 Road Name: BARLOW FSR Inspection Date: 2019/08/08

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Fair	minor burning on right center guardrail
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	2.0
	Estimated High Water Level Clearance:	2.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Low	\$ 500.00	brushing both sides

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 9 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-181	Structure Name:	G4-181	Road Name:	BARLOW FSR	Inspection Date:	2019/08/08
GENERAL	Inspector's Comment:	GOOD, MINOR BURN ON GUARD RAIL. NEEDS BRUSHING					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2045	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/23 14:22:56			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 10 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-019	Structure Name:	G4-019	Road Name:	BARLOW FSR	Inspection Date:	2021/07/09
KM:	31.10	User km:	31.10	Crossing Name:	Tatsutnia Creek	Next Inspection Date:	2024/07/09
Project File ID #:	10653	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	18.3	# Spans:	1	Span Width:	Span Length(s) (metres):		18.3
UTM Zone:	10	UTM Easting:	395491	UTM Northing:	6003141		
Inspector Name:	Dawson Smith		Year Superstructure Installed:	2002			
Access:	Turn right at approx km 8 on the Sutherland FSR and travel about 1 km to the site. Or from highway 27 turn onto the Barlow FSR and travel to 31.1 km						

ABUTMENTS

Bearings	Poor	Monitor bearing pads (Rate as GOOD. GZ) Rating is considered fair.
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 11 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-019	Structure Name:	G4-019	Road Name:	BARLOW FSR	Inspection Date:	2021/07/09
---------	--------	-----------------	--------	------------	------------	------------------	------------

DECK

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Good
---------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	1.0
Estimated High Water Level Clearance:	4.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
5	Required	Medium	\$ 500.00	Install 2 delineators

MONITORS

#	Description
4	Monitor bearing pads

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 12 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-019	Structure Name:	G4-019	Road Name:	BARLOW FSR	Inspection Date:	2021/07/09
GENERAL	Inspector's Comment:	No significant issues. Bearing pads look good, no information on why they are rated poor. GZ					
GENERAL	PEng's Comment:	Bearings appear stable. Bearing pads have minor deformation. BH					
GENERAL	Estimated Load Restriction (year):		2052	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/01 17:10:38			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 13 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-220	Structure Name:	G4-220	Road Name:	CRYSTAL	Inspection Date:	2021/06/13
KM:	0.10	User km:	0.10	Crossing Name:	Cabin Creek	Next Inspection Date:	2022/08/01
Project File ID #:	10660	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Steel I-beam				Right	Crib, Log or Untreated Timber	
Total Length (metres):	12.1	# Spans:	1	Span Width:			Span Length(s) (metres): 12.1
UTM Zone:	10		UTM Easting:	409092	UTM Northing:	5941123	
Inspector Name:	Dawson Smith			Year Superstructure Installed:			
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Good	(none GZ)
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	(FAIR, conks on log sills. GZ)
Fill	Fair	
Hardware	Good	
Log/Timber Crib	Good	(none. GZ)
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Tie-backs	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Poor	end caps out of position

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 14 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-220	Structure Name:	G4-220	Road Name:	CRYSTAL	Inspection Date:	2021/06/13			
Posted Load Rating (Enter 0 if sign missing)	91000									
Road Surface	Good									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Fair									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Good									
Sub Deck	Unrated	one layer of running palnks								
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		3.0			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	8	Suggested	Medium	\$ 500.00	Needs brushing					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 15 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-220	Structure Name:	G4-220	Road Name:	CRYSTAL	Inspection Date:	2021/06/13
MONITORS	#	Description					
GENERAL	Inspector's Comment:	very brushed in No pics of bearings:monitoring item, no pic from upstream, no cribs or bracing, no mention of scour.					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2035	Estimated Replacement (year):			
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Rejected By IDIR\GZSOMBOR on 2021/12/02 14:08:27			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 16 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-560	Structure Name:	G5-992	Road Name:	SUSCHONA	Inspection Date:	2021/09/22
KM:	0.70	User km:	0.70	Crossing Name:	unknown	Next Inspection Date:	2024/09/22
Project File ID #:	10797	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Steel I-beam				Right	Crib, Log or Untreated Timber	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	10		UTM Easting:	422026	UTM Northing:	6113836	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2013		
Access:							

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	see pic
Fill	Good	
Hardware	Good	
Log/Timber Crib	Fair	N/A. GZ
Piles or Posts	Not Applicable	
Riprap	Fair	
Tie-backs	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 17 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-560	Structure Name:	G5-992	Road Name:	SUSCHONA	Inspection Date:	2021/09/22			
Posted Load Rating (Enter 0 if sign missing)	91									
Road Surface	Good									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Good									
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		1.0		Estimated Present Water Level Width:		3.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 18 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-560	Structure Name:	G5-992	Road Name:	SUSCHONA	Inspection Date:	2021/09/22
MONITORS	#	Description					
GENERAL	Inspector's Comment:	Poor pics but no issues. GZ					
GENERAL	PEng's Comment:	No concerns. BH					
GENERAL	Estimated Load Restriction (year):		2025	Estimated Replacement (year):			
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.: L75
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/10 16:47:10	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 19 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-561	Structure Name:	G5-972	Road Name:	SUSCHONA	Inspection Date:	2021/09/22
KM:	3.00	User km:	3.00	Crossing Name:	unknown	Next Inspection Date:	2022/09/01
Project File ID #:	10797	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Steel I-beam				Right	Crib, Log or Untreated Timber	
Total Length (metres):	12.1	# Spans:	1	Span Width:			Span Length(s) (metres): 12.1
UTM Zone:	10		UTM Easting:	422884	UTM Northing:	6115916	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2013		
Access:							

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	
Fill	Good	
Hardware	Fair	
Log/Timber Crib	Fair	N/A. GZ
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Tie-backs	Fair	N/A. GZ
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 20 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-561	Structure Name:	G5-972	Road Name:	SUSCHONA	Inspection Date:	2021/09/22			
Posted Load Rating (Enter 0 if sign missing)	68									
Road Surface	Good									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Poor	guardrails rotting, see pics								
Deck to Girder Bolts	Good									
Hardware	Fair									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Poor	guardrails rotting, see pics								
Running Planks	Good									
Sub Deck	Good	N/A.GZ								
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		0.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 21 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-561	Structure Name:	G5-972	Road Name:	SUSCHONA	Inspection Date:	2021/09/22	
REPAIRS	#	Status	Priority	Estimate	Description			
	3	Suggested	High	\$				
	4	Suggested	High					
	5	Suggested	Medium					
MONITORS	#	Description						
GENERAL	Inspector's Comment:	Rated components that do not exist, missing pics. GZ						
GENERAL	PEng's Comment:							
GENERAL	Estimated Load Restriction (year):		2025		Estimated Replacement (year):			
	Current Inspection Load Rating:		See footnote	Design Load GVW (tonnes):		68	Design Vehicle Config.:	L75
	Professional Inspection Required?		No	Report Status:		Rejected By IDIR\GZSOMBOR on 2022/01/06 10:36:07		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 22 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-562	Structure Name:	G5-995	Road Name:	SUSCHONA	Inspection Date:	2021/09/22
KM:	5.50	User km:	5.50	Crossing Name:	Unnamed	Next Inspection Date:	2024/09/22
Project File ID #:	10797	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Steel I-beam				Right	Crib, Log or Untreated Timber	
Total Length (metres):	9.1	# Spans:	1	Span Width:			Span Length(s) (metres): 9.1
UTM Zone:	10		UTM Easting:	424345	UTM Northing:	6117599	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2013		
Access:							

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	
Fill	Good	
Hardware	Not Applicable	
Log/Timber Crib	Poor	down side showing more scour since last inspection
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Tie-backs	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	1	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 23 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-562	Structure Name:	G5-995	Road Name:	SUSCHONA	Inspection Date:	2021/09/22			
Posted Load Rating (Enter 0 if sign missing)	68									
Road Surface	Good									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Good									
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		0.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 24 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-562	Structure Name:	G5-995	Road Name:	SUSCHONA	Inspection Date:	2021/09/22
REPAIRS	#	Status	Priority	Estimate	Description		
	6	Required	Medium		Add one bridge ahead sign.		
	7	Required	Medium	\$ 0.00	Minor brushing required around bridge structure.		
	8	Required	High		Add riprap to both side of stream		
MONITORS	#	Description					
GENERAL	Inspector's Comment:	down side abutment showing a bit more scour since last inspection Poor inspection and pics but captured scour issue. GZ					
GENERAL	PEng's Comment:	Possible undermining of High chain abutment. Flagged for P.Eng Inspection in 2022 to check extent of scour. BH					
GENERAL	Estimated Load Restriction (year):			2028	Estimated Replacement (year):		
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.: L75
	Professional Inspection Required?		No	Report Status: Reviewed By Bruce Henderson on 2022/02/10 17:10:33			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 25 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-049	Structure Name:	G4-049	Road Name:	BOBTAIL LAKE	Inspection Date:	2019/08/09
KM:	47.40	User km:	10.40	Crossing Name:	Cluculz Creek	Next Inspection Date:	2022/08/09
Project File ID #:	1771	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Pipe Arch			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	2,000			Outlet Cover (mm):	2,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	21.4	Opening Height (mm):	3,330	Opening Width (mm):	5,050		
UTM Zone:	10	UTM Easting:	460476	UTM Northing:	5952895		
Inspector Name:	dawson smith			Year Superstructure Installed:	1997		
Access:	This site is located at 10.4 km of the Grizzly. Turn off the main Bobtail at 37 km and travel 10.4 km to the site.						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Good	
Fill	Good	
Floor	Not Applicable	
Head Wall	Good	
Inlet	Good	considerable debris
Outlet	Good	
Overall	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 26 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-049	Structure Name:	G4-049	Road Name:	BOBTAIL LAKE	Inspection Date:	2019/08/09			
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		2.5			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Medium	\$ 500.00	remove debris from upstream and brush					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	CULVERT IS AT 10.5KM ON THE GRIZZLY ROAD								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):			2047		Estimated Replacement (year):				
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/01/23 14:42:52			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 27 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-000	Structure Name:	G1-000	Road Name:	BOBTAIL LAKE	Inspection Date:	2019/06/07
KM:	12.27	User km:	12.27	Crossing Name:	Hwy 16	Next Inspection Date:	2022/06/07
Project File ID #:	1771	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Asphalt		
Curb Type:				Abutments (looking downstream)	Left	Concrete Cast in Place	
Superstructure:	Steel Box Beam				Right	Concrete Cast in Place	
Total Length (metres):	48.8	# Spans:	1	Span Width:	Span Length(s) (metres):		48.8
UTM Zone:	10	UTM Easting:	472592	UTM Northing:	5970853		
Inspector Name:	Pat Bredin		Year Superstructure Installed:	2009			
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Fair	
Concrete Cast in Place	Good	
Corrosion Protection	Good	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 28 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-000	Structure Name:	G1-000	Road Name:	BOBTAIL LAKE	Inspection Date:	2019/06/07			
Road Surface		Good								
DECK										
Span 1										
Concrete Deck		Good								
Curb Rail/Blocks/Posts		Good								
Deck Joints		Good								
Grout Pockets		Good								
Hardware		Good								
Hand Rails/Walkouts		Good								
Overall Deck Condition		Good								
Running Surface		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Not Applicable								
Diaphragms		Unrated		N/A						
Girders		Good								
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.0		Estimated Present Water Level Width:		0.0			
	Estimated High Water Level Clearance:		0.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Low	\$ 200.00	Replace missing delineators					
MONITORS	#	Description								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 29 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-000	Structure Name:	G1-000	Road Name:	BOBTAIL LAKE	Inspection Date:	2019/06/07
GENERAL	Inspector's Comment:	Reject inspection. Pat failed to take pictures of issues with ballast wall. GZ					
GENERAL	PEng's Comment:	pictures have been added					
GENERAL	Estimated Load Restriction (year):		2058	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/23 14:37:51			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 30 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-001	Structure Name:	G4-001	Road Name:	BOBTAIL LAKE	Inspection Date:	2002/07/23
KM:	20.60	User km:	20.60	Crossing Name:	Unnamed creek	Next Inspection Date:	2030/01/01
Project File ID #:	1771	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	500			Outlet Cover (mm):	500		
Footing Type:				Gradient (%):	1.0		
Culvert Length (metres):	18.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	465646	UTM Northing:	5968464		
Inspector Name:	Tim Silbernagel			Year Superstructure Installed:	1980		
Access:							

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Fair	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Fair	No Comment Available -Converter.RNI
Riprap	Fair	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 31 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-001	Structure Name:	G4-001	Road Name:	BOBTAIL LAKE	Inspection Date:	2002/07/23			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		1.2							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Suggested	Medium	\$ 0.00	Span: 1.0. Debris removal. remove debris from outlet.					
MONITORS	#	Description								
	1	Monitor for continued beaver activity. (no beaver problems at inlet but beaver debris collected at outlet TS2002)								
GENERAL	Inspector's Comment:	nullCulvert: 2) debris build-up at outlet - remove.								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):			2025	Estimated Replacement (year):					
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/12 16:18:45				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 32 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-002	Structure Name:	G4-002	Road Name:	BOBTAIL LAKE	Inspection Date:	2002/07/23
KM:	22.70	User km:	22.70	Crossing Name:	Norman Creek	Next Inspection Date:	2030/01/01
Project File ID #:	1771	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	3,000			Outlet Cover (mm):	3,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	15.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	463818	UTM Northing:	5967403		
Inspector Name:	Tim Silbernagel			Year Superstructure Installed:	1970		
Access:							

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Poor	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Fair	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 33 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-002	Structure Name:	G4-002	Road Name:	BOBTAIL LAKE	Inspection Date:	2002/07/23			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	3	Suggested	High	\$ 0.00	Span: 1.0. Remove Beaver Dam. Inlet fully plugged - remove.					
MONITORS	#	Description								
	1	MONITOR BEAVER DAM AT INLET. (inlet fully plugged TS2002)								
GENERAL	Inspector's Comment:	nullCulvert: 1) 95% blocked by beaver dam 4-7) hard to see inside - beaver dams 14) has been repaired with gravel.								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):			2020	Estimated Replacement (year):					
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/12 16:19:48				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 34 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-003	Structure Name:	G4-003A	Road Name:	BOBTAIL LAKE	Inspection Date:	2019/07/23
KM:	30.90	User km:	30.90	Crossing Name:	Cluculz Creek	Next Inspection Date:	2022/07/23
Project File ID #:	1771	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	18.3	# Spans:	1	Span Width:			Span Length(s) (metres): 18.3
UTM Zone:	10		UTM Easting:	456366	UTM Northing:	5964805	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2008		
Access:							

ABUTMENTS

Bearings	Good
Bracing	Good
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Good
Piles or Posts	Good
Riprap	Good
Wing Wall	Good

APPROACHES

Alignment	Good
Bridge Ahead Signs Missing	0
Brushing Required	No
Delineator Missing Left (approaching structure)	0
Delineator Missing Right (approaching structure)	0
Fender Condition	Good
Road Surface	Good

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 35 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-003	Structure Name:	G4-003A	Road Name:	BOBTAIL LAKE	Inspection Date:	2019/07/23
---------	--------	-----------------	---------	------------	--------------	------------------	------------

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Good
---------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Good
----------------	------

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	3.0
Estimated High Water Level Clearance:	3.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 36 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-003	Structure Name:	G4-003A	Road Name:	BOBTAIL LAKE	Inspection Date:	2019/07/23
GENERAL	Inspector's Comment:	good, beaver activity upstream					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2058	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/23 14:40:03			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 37 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-004	Structure Name:	G4-004	Road Name:	BOBTAIL LAKE	Inspection Date:	2019/08/09
KM:	62.50	User km:	62.50	Crossing Name:	Grizzly Creek	Next Inspection Date:	2022/08/09
Project File ID #:	1771	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Concrete Slab Girders				Right	Steel Pipe and Precast Pad	
Total Length (metres):	11.0	# Spans:	1	Span Width:	Span Length(s) (metres):		11
UTM Zone:	10	UTM Easting:	464057	UTM Northing:	5941097		
Inspector Name:	dawson smith			Year Superstructure Installed:	1999		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 38 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-004	Structure Name:	G4-004	Road Name:	BOBTAIL LAKE	Inspection Date:	2019/08/09
---------	--------	-----------------	--------	------------	--------------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	considerable rot and degradation
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Poor	guardrails
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Not Applicable	
Hardware	Not Applicable	
Welded/grouted shear connectors	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	2.0
Estimated High Water Level Clearance:	2.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Medium	\$	CAP APPROACHES
2	Required	Medium	\$	guardrails need replaced and brushing

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 39 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-004	Structure Name:	G4-004	Road Name:	BOBTAIL LAKE	Inspection Date:	2019/08/09
GENERAL	Inspector's Comment:	25.5 ON THE GRIZZLY FSR, GUARD RAILS NEED REPLACED, REQUIRES BRUSHING					
GENERAL	PEng's Comment:	Curbs need replacing soon or bridge load rating will be reduced.					
GENERAL	Estimated Load Restriction (year):		2049	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/24 12:18:42			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 40 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-030	Structure Name:	G1-030	Road Name:	BOBTAIL LAKE	Inspection Date:	2019/06/07
KM:	77.90	User km:	210.90	Crossing Name:	Chilako River	Next Inspection Date:	2022/06/07
Project File ID #:	1771	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	21.0	# Spans:	1	Span Width:			Span Length(s) (metres): 21
UTM Zone:	10		UTM Easting:	463629	UTM Northing:	5928549	
Inspector Name:	Pat Bredin			Year Superstructure Installed:	1986		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Not Applicable	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	0	51,000 kgs
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 41 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-030	Structure Name:	G1-030	Road Name:	BOBTAIL LAKE	Inspection Date:	2019/06/07
---------	--------	-----------------	--------	------------	--------------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	New deck
Running Planks	Good	
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	3.0	Estimated Present Water Level Width:	21.0
	Estimated High Water Level Clearance:	3.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 42 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-030	Structure Name:	G1-030	Road Name:	BOBTAIL LAKE	Inspection Date:	2019/06/07
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2026	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/23 14:44:51			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 43 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-008	Structure Name:	G4-008	Road Name:	BOBTAIL TATUK	Inspection Date:	2019/08/09
KM:	16.00	User km:	16.00	Crossing Name:	Meadow Creek	Next Inspection Date:	2022/08/09
Project File ID #:	1771	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	12.2	# Spans:	1	Span Width:	Span Length(s) (metres):		12.2
UTM Zone:	10	UTM Easting:	435566	UTM Northing:	5931683		
Inspector Name:	dawson smith			Year Superstructure Installed:	1995		
Access:							

ABUTMENTS

Bearings	Good
Bracing	Good
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Good
Piles or Posts	Good
Riprap	Good
Wing Wall	Not Applicable

APPROACHES

Alignment	Good
Bridge Ahead Signs Missing	0
Brushing Required	Yes
Delineator Missing Left (approaching structure)	2
Delineator Missing Right (approaching structure)	1
Fender Condition	Good
Road Surface	Good

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 44 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-008	Structure Name:	G4-008	Road Name:	BOBTAIL TATUK	Inspection Date:	2019/08/09
---------	--------	-----------------	--------	------------	---------------	------------------	------------

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	considerable damage needs replaced
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	1.0
	Estimated High Water Level Clearance:	2.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Medium	\$	replace guardrails and brush

MONITORS	#	Description

GENERAL	Inspector's Comment:	14.8 ON THE TATUK RD, GUARDRAILS NEED REPLACED
---------	----------------------	--

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 45 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-008	Structure Name:	G4-008	Road Name:	BOBTAIL TATUK	Inspection Date:	2019/08/09
GENERAL	PEng's Comment:	Bridge Load Rated to 30 tonnes until curbs are replaced					
GENERAL	Estimated Load Restriction (year):			2035	Estimated Replacement (year):		
	Current Inspection Load Rating:		30	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status: Reviewed By Jason Olmsted on 2020/01/24 12:56:57			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 46 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-012	Structure Name:	G4-012	Road Name:	BOBTAIL TATUK	Inspection Date:	2020/09/18
KM:	23.50	User km:	23.50	Crossing Name:	Falls Creek	Next Inspection Date:	2022/09/18
Project File ID #:	1771	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Steel I-beam				Right	Crib, Log or Untreated Timber	
Total Length (metres):	9.0	# Spans:	1	Span Width:	Span Length(s) (metres):		9
UTM Zone:	10	UTM Easting:	429437	UTM Northing:	5930587		
Inspector Name:	Bruce Henderson			Year Superstructure Installed:	1995		
Access:							

ABUTMENTS

Bearings	Poor	Poor connection to sill.
Bracing	Not Applicable	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Poor	Sill has completely rotted out below bearing plates.
Fill	Good	
Hardware	Fair	Bearing bolts not in sound wood.
Log/Timber Crib	Poor	Rot below bearings on both side of the bridge.
Piles or Posts	Not Applicable	
Riprap	Good	
Tie-backs	Poor	Significant rotting on tiebacks.
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	Poor alignment approaching the bridge. Sharp left turn before approach.
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	Brushing on inside of curve near bridge.
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	Fender rotten and some missing. Needs replacing

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 47 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-012	Structure Name:	G4-012	Road Name:	BOBTAIL TATUK	Inspection Date:	2020/09/18			
Posted Load Rating (Enter 0 if sign missing)	54									
Road Surface	Good									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Fair	Still functioning but showing some rot.								
Deck to Girder Bolts	Poor	None installed .								
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Fair	Some nails exposed due to worn surface.								
Overall Deck Condition	Fair									
Running Planks	Fair	Running planks worn and some rot. Nail heads protruding.								
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Poor	No deck clips.								
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		3.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	4	Required	High		Replace rotting cribs					

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 48 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-012	Structure Name:	G4-012	Road Name:	BOBTAIL TATUK	Inspection Date:	2020/09/18
MONITORS	#	Description					
GENERAL	Inspector's Comment:	The bridge is superstructure is in fair condition. Some rot evident on curb rails and blocks, running surface is worn and fenders need replacement. The log crib abutments have significant rotting in the ties and under the bearing plates on both sides. Recommend replacing timber cribs before industrial use.					
GENERAL	PEng's Comment:	Bridge to be posted at 30 tonnes because of rotting cribs. Bridge will soon be closed to all traffic.					
GENERAL	Estimated Load Restriction (year):		2018		Estimated Replacement (year):		
	Current Inspection Load Rating:		30		Design Load GVW (tonnes):		54
	Design Vehicle Config.:						
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/01/22 13:34:07			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 49 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-010	Structure Name:	G4-010	Road Name:	BOBTAIL TATUK	Inspection Date:	2019/07/24
KM:	7.00	User km:	44.00	Crossing Name:	Cluculz Creek	Next Inspection Date:	2022/07/24
Project File ID #:	1771	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	9.0	# Spans:	1	Span Width:	Span Length(s) (metres):		9
UTM Zone:	10	UTM Easting:	450289	UTM Northing:	5955053		
Inspector Name:	dawson smith			Year Superstructure Installed:	1989		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Not Applicable	MINIMAL
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	A BIT OUT OF POSITION
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 50 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-010	Structure Name:	G4-010	Road Name:	BOBTAIL TATUK	Inspection Date:	2019/07/24
---------	--------	-----------------	--------	------------	---------------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Fair	
Deck Joints	Poor	grouting is required
Grout Pockets	Not Applicable	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	6.0
	Estimated High Water Level Clearance:	2.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Low	\$ 250.00	PUT FENDERS BACK IN PLACE
	2	Not Required	Medium	\$	GROUT DECK JOINTS

MONITORS	#	Description
	1	beaver activity and grout situation

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 51 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-010	Structure Name:	G4-010	Road Name:	BOBTAIL TATUK	Inspection Date:	2019/07/24
GENERAL	Inspector's Comment:	bridge is in fair condition, grout on deck should be repired. beaver acivity upstream					
GENERAL	PEng's Comment:	There is NO issue with deck joint grout because the bridge is non-composite					
GENERAL	Estimated Load Restriction (year):		2029	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/24 12:48:55			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 52 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-009	Structure Name:	G4-009	Road Name:	BOBTAIL TATUK	Inspection Date:	2019/08/09
KM:	30.10	User km:	66.10	Crossing Name:	44 Mile Creek	Next Inspection Date:	2022/08/09
Project File ID #:	1771	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	2,000			Outlet Cover (mm):	2,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	21.0	Opening Height (mm):	2,000	Opening Width (mm):	2,000		
UTM Zone:	10	UTM Easting:	434491	UTM Northing:	5944268		
Inspector Name:	dawson smith			Year Superstructure Installed:	1997		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 53 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-009	Structure Name:	G4-009	Road Name:	BOBTAIL TATUK	Inspection Date:	2019/08/09
Overall	Good						
Riprap	Not Applicable						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		1.0
	Estimated High Water Level Clearance:		1.0				
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Aggradation: No
	Comment:						
REPAIRS	#	Status	Priority	Estimate	Description		
	1	Not Required	Medium	\$ 500.00	brush downstream side		
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):			2046	Estimated Replacement (year):		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/23 14:47:15			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 54 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-009	Structure Name:	G4-009-1	Road Name:	BOBTAIL TATUK	Inspection Date:	2019/07/24
KM:	30.10	User km:	66.10	Crossing Name:	44 Mile Creek	Next Inspection Date:	2022/07/24
Project File ID #:	1771	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	2,000			Outlet Cover (mm):	2,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	21.0	Opening Height (mm):	2,000	Opening Width (mm):	2,000		
UTM Zone:	10	UTM Easting:	434491	UTM Northing:	5944268		
Inspector Name:	dawson smith			Year Superstructure Installed:	1997		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Not Applicable	
Embedment Materials	Good	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 55 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-009	Structure Name:	G4-009-1	Road Name:	BOBTAIL TATUK	Inspection Date:	2019/07/24
Overall	Good						
Riprap	Good						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						
CHANNEL	Estimated Present Water Level Depth:	0.3			Estimated Present Water Level Width:	21.0	
	Estimated High Water Level Clearance:	1.0					
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Aggradation: No
	Comment:						
REPAIRS	#	Status	Priority	Estimate	Description		
MONITORS	#	Description					
GENERAL	Inspector's Comment:	Good, beaver activity upstream					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):	2046			Estimated Replacement (year):		
	Current Inspection Load Rating:	91		Design Load GVW (tonnes):	91		Design Vehicle Config.: L100
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/23 14:48:24			

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 56 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-035	Structure Name:	G1-035	Road Name:	BOBTAIL-	Inspection Date:	2019/06/26
KM:	2.90	User km:	2.90	Crossing Name:	Hutchinson Creek	Next Inspection Date:	2022/06/26
Project File ID #:	1771	Br.	06	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	15.3	# Spans:	1	Span Width:	Span Length(s) (metres):		15.3
UTM Zone:	10	UTM Easting:	478617	UTM Northing:	5974410		
Inspector Name:	Pat Bredin			Year Superstructure Installed:	2010		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Fair	Some scour on left side
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	1	Sign on far side of bridge damaged
Brushing Required	Yes	Brush around fenders reduce sight line
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 57 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-035	Structure Name:	G1-035	Road Name:	BOBTAIL-	Inspection Date:	2019/06/26			
Road Surface		Good								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good		U/S replaced recently						
Deck to Girder Bolts		Good								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Good								
Running Planks		Fair		Planks are showing wear						
Sub Deck		Good								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Medium	\$ 200.00	Brush area for site lines					
	2	Required	Low	\$ 100.00	Install bridge ahead sign					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 58 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-035	Structure Name:	G1-035	Road Name:	BOBTAIL-	Inspection Date:	2019/06/26
MONITORS	#	Description					
	1	Monitor deck plank wear					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2050	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/01/23 14:54:18	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 59 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-171	Structure Name:	G4-171	Road Name:	BOBTAIL GRIZZLY	Inspection Date:	2021/09/16
KM:	74.20	User km:	74.20	Crossing Name:	Unknown	Next Inspection Date:	2024/09/16
Project File ID #:	1771	Br.	10	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Concrete Slab Girders				Right	Pile -Permanent Materials	
Total Length (metres):	8.0	# Spans:	1	Span Width:	Span Length(s) (metres):		8
UTM Zone:	10	UTM Easting:	427338	UTM Northing:	5941665		
Inspector Name:	Dustin Anderberg			Year Superstructure Installed:			
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Caps or Sills	Fair	Slightly chipped on HC
Fill	Fair	Slightly undermined on LC
Hardware	Not Applicable	
Piles or Posts	Unrated	Not visible
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	Functional but slightly damaged
Road Surface	Good	

DECK

Span 1

Concrete Deck	Fair	Slightly gouged
Curb Rail/Blocks/Posts	Poor	Both sides rotten

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 60 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-171	Structure Name:	G4-171	Road Name:	BOBTAIL GRIZZLY	Inspection Date:	2021/09/16			
Deck Joints	Not Applicable									
Grout Pockets	Not Applicable									
Grout Pockets	Not Applicable									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Overall Deck Condition	Good									
Running Surface	Fair		Slightly gouged							
SUPERSTRUCTURE										
Span 1										
Bracing	Not Applicable									
Hardware	Not Applicable									
Welded/grouted shear connectors	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.0		Estimated Present Water Level Width:		0.8			
	Estimated High Water Level Clearance:		1.4							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	7	Required	Medium	\$ 1.00	Replace rotten sections of curbs.					
	8	Required	Low	\$ 0.00	Install 1 delineator					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Stream channel heavily brushed in.								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 61 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-171	Structure Name:	G4-171	Road Name:	BOBTAIL GRIZZLY	Inspection Date:	2021/09/16
GENERAL	PEng's Comment:	No major concerns. BH					
GENERAL	Estimated Load Restriction (year):		2025	Estimated Replacement (year):			
	Current Inspection Load Rating:	64	Design Load GVW (tonnes):		Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/02 14:55:40			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 62 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-172	Structure Name:	G4-172	Road Name:	BOBTAIL GRIZZLY	Inspection Date:	2021/09/16
KM:	75.60	User km:	75.60	Crossing Name:	Unknown	Next Inspection Date:	2024/09/16
Project File ID #:	1771	Br.	10	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	12.0	# Spans:	1	Span Width:			Span Length(s) (metres): 12
UTM Zone:	10		UTM Easting:	426049	UTM Northing:	5941262	
Inspector Name:	Dustin Anderberg			Year Superstructure Installed:			
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Unrated	N/A
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	Replace LC fender, Broken
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 63 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-172	Structure Name:	G4-172	Road Name:	BOBTAIL GRIZZLY	Inspection Date:	2021/09/16
---------	--------	-----------------	--------	------------	-----------------	------------------	------------

DECK

Span 1

Concrete Deck	Fair	Gouged from Machinery
---------------	------	-----------------------

Curb Rail/Blocks/Posts	Poor	Both sides and risers rotten
------------------------	------	------------------------------

Deck Joints	Fair	
-------------	------	--

Grout Pockets	Fair	
---------------	------	--

Hardware	Fair	
----------	------	--

Hand Rails/Walkouts	Not Applicable	
---------------------	----------------	--

Overall Deck Condition	Fair	
------------------------	------	--

Running Surface	Fair	
-----------------	------	--

SUPERSTRUCTURE

Span 1

Bracing	Good	
---------	------	--

Diaphragms	Good	
------------	------	--

Girders	Good	
---------	------	--

Hardware	Not Applicable	
----------	----------------	--

Under Trussing	Not Applicable	
----------------	----------------	--

CHANNEL

Estimated Present Water Level Depth:	0.0	Estimated Present Water Level Width:	2.3
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	2.4		
---------------------------------------	-----	--	--

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
5	Required	Medium		Brush around bridge
6	Required	High	\$ 0.00	Replace curbs and risers.

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 64 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-172	Structure Name:	G4-172	Road Name:	BOBTAIL GRIZZLY	Inspection Date:	2021/09/16
GENERAL	Inspector's Comment:	Stream heavily brushed in. Curbs need to be replaced, rotten and non-functional. DA					
GENERAL	PEng's Comment:	Bridge to be downrated 0 tonnes due to rotten and missing curbs. Repairs to be done as soon as feasible. BH					
GENERAL	Estimated Load Restriction (year):		2035		Estimated Replacement (year):		
	Current Inspection Load Rating:		0		Design Load GVW (tonnes):		91
	Design Vehicle Config.:		L100				
GENERAL	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/24 16:04:22			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 65 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-173	Structure Name:	G4-173	Road Name:	BOBTAIL GRIZZLY	Inspection Date:	2021/09/16
KM:	77.30	User km:	77.30	Crossing Name:	Unknown	Next Inspection Date:	2024/09/16
Project File ID #:	1771	Br.	10	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	18.0	# Spans:	1	Span Width:	Span Length(s) (metres):		18
UTM Zone:	10	UTM Easting:	424604	UTM Northing:	5940534		
Inspector Name:	Dustin Anderberg			Year Superstructure Installed:			
Access:							

ABUTMENTS

Bearings	Fair	Expanded on one side tight on the other
Bracing	Good	
Ballast Wall	Fair	Slight cracking on LC steel plate
Corrosion Protection	Fair	
Caps or Sills	Unrated	N/A
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	Cracking in sections
Road Surface	Good	

DECK

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 66 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-173	Structure Name:	G4-173	Road Name:	BOBTAIL GRIZZLY	Inspection Date:	2021/09/16
---------	--------	-----------------	--------	------------	-----------------	------------------	------------

Span 1

Concrete Deck	Fair	Gouged and dirty
Curb Rail/Blocks/Posts	Poor	Rotten and infested with insects
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	
Running Surface	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:		Estimated Present Water Level Width:	
Estimated High Water Level Clearance:			

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
4	Required	Medium	\$ 0.00	Brush around bridge
5	Required	High	\$ 0.00	Curbs and risers rotten and needs replacing
6	Required	Medium		Clean deck to maintain functionality and visual inspections

MONITORS

#	Description
3	Bearings for expansion and compression
4	Cracked ballast wall concrete on steel plate connections

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 67 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-173	Structure Name:	G4-173	Road Name:	BOBTAIL GRIZZLY	Inspection Date:	2021/09/16
GENERAL	Inspector's Comment:	Curbs need to be replaced, completely rotten and unfunctional. DA					
GENERAL	PEng's Comment:	Rotten curbs need replacement. Bridge could be downrated at any time if curbs deteriorate further. Complete high priority repair items. BH					
GENERAL	Estimated Load Restriction (year):		2035		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:		L100				
GENERAL	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/24 16:32:15			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 68 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-174	Structure Name:	G4-174	Road Name:	BOBTAIL GRIZZLY	Inspection Date:	2021/06/13
KM:	78.90	User km:	78.90	Crossing Name:	Unknown	Next Inspection Date:	2024/06/13
Project File ID #:	1771	Br.	10	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	18.0	# Spans:	1	Span Width:	Span Length(s) (metres):		18
UTM Zone:	10	UTM Easting:	423134	UTM Northing:	5940097		
Inspector Name:	Dawson Smith			Year Superstructure Installed:			
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	damaged and out of palce
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Fair	needs capping

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 69 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G4-174 Structure Name: G4-174 Road Name: BOBTAIL GRIZZLY Inspection Date: 2021/06/13

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Fair	considerable decay (Rate as POOR GZ)
Deck Joints	Excellent	
Grout Pockets	Good	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	2.0
	Estimated High Water Level Clearance:	4.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
3	Required	Medium	\$	Reposition and attach loose barrier components.
4	Required	High	\$	Full curb and riser replacement.
5	Required	Medium	\$	Grade approaches.
6	Required	Medium	\$ 0.00	Remove larger brush as required.

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 70 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-174	Structure Name:	G4-174	Road Name:	BOBTAIL GRIZZLY	Inspection Date:	2021/06/13
---------	--------	-----------------	--------	------------	-----------------	------------------	------------

MONITORS

#	Description
2	monitor guardrails and riser blocks

GENERAL

Inspector's Comment:	needs brushing and trees cut down, approaches capped and has significant guardrail decay Consider load restrictions.GZ
----------------------	---

GENERAL

PEng's Comment:	Curbs have significant rot and damage. May be downrated at any time due to condition of curbs. Complete repairs as soon as possible. BH
-----------------	---

GENERAL

Estimated Load Restriction (year):			2035	Estimated Replacement (year):				
Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:		L100
Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/03 13:37:01			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 71 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-175	Structure Name:	G4-175	Road Name:	BOBTAIL GRIZZLY	Inspection Date:	2021/09/16
KM:	80.10	User km:	80.10	Crossing Name:	Unknown	Next Inspection Date:	2024/09/16
Project File ID #:	1771	Br.	10	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	30.0	# Spans:	1	Span Width:			Span Length(s) (metres): 30
UTM Zone:	10		UTM Easting:	421843	UTM Northing:	5939883	
Inspector Name:	Dustin Anderberg			Year Superstructure Installed:			
Access:							

ABUTMENTS

Bearings	Fair	Expanded on LC compressed on High
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Fair	Broken and cracked
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Fair	Large pot hole on LC

DECK

Span 1

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 72 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-175	Structure Name:	G4-175	Road Name:	BOBTAIL GRIZZLY	Inspection Date:	2021/09/16			
Concrete Deck	Good	Gouged from machinery								
Curb Rail/Blocks/Posts	Poor	Rotten and non functional								
Deck Joints	Good									
Grout Pockets	Good									
Hardware	Poor	Bolts pulled out on LC								
Hand Rails/Walkouts	Not Applicable									
Overall Deck Condition	Fair									
Running Surface	Fair	Gouged from machinery								
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.3		Estimated Present Water Level Width:		5.0			
	Estimated High Water Level Clearance:		8.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	6	Required	High	\$ 1.00	Replace curbs rotten and non functional					
	7	Required	Medium	\$ 1.00	Fenders are broken and need replacing					
	8	Required	Medium	\$ 1.00	Concrete broken riser connector under HC down stream riser panel 10					
	9	Required	Low		Install 1 delineator					
	10	Required	Medium		Grade approaches .					
	11	Required	Medium		Remove debris from deck surface.					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 73 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G4-175 Structure Name: G4-175 Road Name: BOBTAIL GRIZZLY Inspection Date: 2021/09/16

MONITORS

#	Description
3	Bearings expanded on LC and compressed on HC
4	Pot holing on road surface

GENERAL

Inspector's Comment:	Full curb and riser replacement due to rot. DA
----------------------	--

GENERAL

PEng's Comment:	Replace curbs and risers. BH
-----------------	------------------------------

GENERAL

Estimated Load Restriction (year):			2035	Estimated Replacement (year):					
Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91		Design Vehicle Config.:		L100
Professional Inspection Required?		No	Report Status:	Reviewed By Bruce Henderson on 2022/02/04 11:37:11					

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 74 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-176	Structure Name:	G4-176	Road Name:	BOBTAIL GRIZZLY	Inspection Date:	2021/09/16
KM:	90.50	User km:	90.50	Crossing Name:	Unknown	Next Inspection Date:	2024/09/16
Project File ID #:	1771	Br.	10	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	15.0	# Spans:	1	Span Width:	Span Length(s) (metres):		15
UTM Zone:	10	UTM Easting:	410717	UTM Northing:	5940434		
Inspector Name:	Dustin Anderberg			Year Superstructure Installed:			
Access:							

ABUTMENTS

Bearings	Fair	Left bank compressed right bank expanded
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Unrated	N/A
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	Reposition
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Fair	Pot holing on both approaches

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 75 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-176	Structure Name:	G4-176	Road Name:	BOBTAIL GRIZZLY	Inspection Date:	2021/09/16
---------	--------	-----------------	--------	------------	-----------------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	Rotten and need replacing
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	
Running Surface	Fair	Pot holing on both approaches

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.3	Estimated Present Water Level Width:	1.5
	Estimated High Water Level Clearance:	3.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	6	Required	Medium	\$ 0.00	Add missing delineator
	7	Required	High	\$ 0.00	Full curb replacement.
	8	Required	Medium	\$ 0.00	Re-align approach fenders.

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 76 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-176	Structure Name:	G4-176	Road Name:	BOBTAIL GRIZZLY	Inspection Date:	2021/09/16
MONITORS	#	Description					
GENERAL	Inspector's Comment:	Heavily brushed in channel. Needs full curb replacement, rotten and non-functional. DA					
GENERAL	PEng's Comment:	Downrate bridge to 5 tonnes due to rotten curbs and risers. Replace as soon as feasible. BH					
GENERAL	Estimated Load Restriction (year):		2046		Estimated Replacement (year):		
	Current Inspection Load Rating:		5		Design Load GVW (tonnes):		91
	Design Vehicle Config.:		L100				
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/24 16:21:49			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 77 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-046	Structure Name:	G4-925	Road Name:	BOOMER	Inspection Date:	2020/09/18
KM:	7.00	User km:	7.00	Crossing Name:	unknown	Next Inspection Date:	2022/09/18
Project File ID #:	1771	Br.	15	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Steel I-beam				Right	Sill -Temporary Materials	
Total Length (metres):	12.2	# Spans:	1	Span Width:	Span Length(s) (metres):		12.2
UTM Zone:	10	UTM Easting:	427686	UTM Northing:	5927667		
Inspector Name:	Bruce Henderson			Year Superstructure Installed:	2006		
Access:							

ABUTMENTS

Bearings	Fair	Bearing not aligned properly over sills.
Bracing	Not Applicable	
Ballast Wall	Good	Log ballast wall untreated.
Corrosion Protection	Not Applicable	
Caps or Sills	Poor	Sills not centered under bearing plates
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	Load limit signs posted 91,000kg
Brushing Required	Yes	Brushed in under and next to bridge. Brush growing up against deck.
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 78 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-046	Structure Name:	G4-925	Road Name:	BOOMER	Inspection Date:	2020/09/18
---------	--------	-----------------	--------	------------	--------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Poor	No girder to deck clips.
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Fair	
Running Planks	Poor	Deck is worn and a small hole approximately 10cm2 punched through on low chain side.
Sub Deck	Fair	Hole punched down through subdeck
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	1.2
	Estimated High Water Level Clearance:	0.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	5	Required	Medium		replace running deck
	6	Required	Medium	\$ 0.00	need deck clips
	7	Required	High		Replace abutments

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 79 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-046	Structure Name:	G4-925	Road Name:	BOOMER	Inspection Date:	2020/09/18
MONITORS	#	Description					
GENERAL	Inspector's Comment:	Bridge is placed improperly on sills and are not centered under the bearing. Appears to be bolted down using steel plate clips. Sill is short on one side but seems stable. No movement of sills was observed since last inspection. The deck is excessively worn needs replacement. Possibly reduce load rating due to poor deck condition and improper placement of sills on both sides. Should replace or realign sills on solid base and replace deck before industrial use. BH					
GENERAL	PEng's Comment:	Bridge to down-rated to 30 tonnes until all the abutment and deck are fixed.					
GENERAL	Estimated Load Restriction (year):		2021		Estimated Replacement (year):		
	Current Inspection Load Rating:		30		Design Load GVW (tonnes):		91
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2021/02/17 10:33:05
Design Vehicle Config.: L100							

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 80 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-013	Structure Name:	G4-013	Road Name:	THRASHER	Inspection Date:	2019/08/09
KM:	0.40	User km:	136.00	Crossing Name:	Chilako River	Next Inspection Date:	2022/08/09
Project File ID #:	1771	Br.	18	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	18.3	# Spans:	1	Span Width:	Span Length(s) (metres):		18.3
UTM Zone:	10	UTM Easting:	434376	UTM Northing:	5930074		
Inspector Name:	dawson smith			Year Superstructure Installed:	1999		
Access:	Take left branch at junction with Tatuk lake access road. Crossing can also be accessed from Pelican-Chilako FSR km 37.0						

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	some out of place
Road Surface	Good	

DECK

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 81 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-013	Structure Name:	G4-013	Road Name:	THRASHER	Inspection Date:	2019/08/09
---------	--------	-----------------	--------	------------	----------	------------------	------------

Span 1

Concrete Deck	Good
Curb Rail/Blocks/Posts	Good
Deck Joints	Good
Grout Pockets	Good
Hardware	Good
Hand Rails/Walkouts	Not Applicable
Overall Deck Condition	Good
Running Surface	Good

SUPERSTRUCTURE

Span 1

Bracing	Good
Diaphragms	Good
Girders	Good
Hardware	Good
Under Trussing	Not Applicable

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	4.0
Estimated High Water Level Clearance:	2.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$	re position fenders

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 82 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-013	Structure Name:	G4-013	Road Name:	THRASHER	Inspection Date:	2019/08/09
GENERAL	Inspector's Comment:	GOOD, FENDERS NEED TO BE PUT BACK IN PLACE					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2049	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/23 14:34:13			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 83 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-045	Structure Name:	G5-299	Road Name:	BOOMER 1000	Inspection Date:	2021/09/09
KM:	0.40	User km:	0.30	Crossing Name:	Un-named Creek	Next Inspection Date:	2023/09/09
Project File ID #:	1771	Br.	20	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Steel I-beam				Right	Sill -Temporary Materials	
Total Length (metres):	12.2	# Spans:	1	Span Width:	Span Length(s) (metres):		12.2
UTM Zone:	10		UTM Easting:	426496	UTM Northing:	5925528	
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	2017		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Fair	Double row of small logs
Concrete Lock Blocks	Not Applicable	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Fair	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	1	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Unrated	None
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 84 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-045	Structure Name:	G5-299	Road Name:	BOOMER 1000	Inspection Date:	2021/09/09
---------	--------	-----------------	--------	------------	-------------	------------------	------------

Road Surface	Fair	Need more approach fill
--------------	------	-------------------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Not Applicable	Nothing securing deck to girders
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Good	
Sub Deck	Unrated	N/A
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.0	Estimated Present Water Level Width:	0.0
	Estimated High Water Level Clearance:	0.3		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	6	Required	Medium		Add fill to both approaches
	7	Required	Low	\$ 0.00	Install 1 bridge ahead sign
	8	Required	Medium		Install deck/girder bolts

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 85 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-045	Structure Name:	G5-299	Road Name:	BOOMER 1000	Inspection Date:	2021/09/09
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Temp bridge installed in 2017. L100 designed and certified by Canfor on Nov 22 2017 L100. BH					
GENERAL	Estimated Load Restriction (year):		2030		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Professional Inspection Required?		No		Report Status:		Reviewed By Bruce Henderson on 2022/02/01 17:51:10
Design Vehicle Config.: L100							

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 86 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-368	Structure Name:	G5-368	Road Name:	MCLEOD -	Inspection Date:	2019/09/05
KM:	3.90	User km:	3.90	Crossing Name:	Willow Creek	Next Inspection Date:	2022/09/05
Project File ID #:	1784	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:	Steel Footing			Gradient (%):	2.5		
Culvert Length (metres):	14.0	Opening Height (mm):	1,910	Opening Width (mm):	3,000		
UTM Zone:	10	UTM Easting:	427925	UTM Northing:	6074896		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2008		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Not Applicable	
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Poor	95% PLUGGED BY BEAVERS
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 87 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-368	Structure Name:	G5-368	Road Name:	MCLEOD -	Inspection Date:	2019/09/05			
Overall	Poor	95% PLUGGED BY BEAVERS								
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		1.5		Estimated Present Water Level Width:		1.5			
	Estimated High Water Level Clearance:		0.1							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	High	\$ 750.00	REMOVE BEAVER DEBRIS BLOCKING INLET					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	REMOVE BEAVER DEBRIS BLOCKING INLET								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):			2050		Estimated Replacement (year):				
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		Design Vehicle Config.:			
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/03/06 15:05:38			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 88 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-369	Structure Name:	G5-369	Road Name:	MCLEOD -	Inspection Date:	2021/09/21
KM:	5.80	User km:	5.80	Crossing Name:	Tributary to Willow Creek	Next Inspection Date:	2022/09/21
Project File ID #:	1784	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	12.2	# Spans:	1	Span Width:	Span Length(s) (metres):		12.2
UTM Zone:	10	UTM Easting:	429770	UTM Northing:	6074236		
Inspector Name:	Dawson Smith		Year Superstructure Installed:	2008			
Access:							

ABUTMENTS

Bearings	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Bracing	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Ballast Wall	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Corrosion Protection	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Caps or Sills	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Fill	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Hardware	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Piles or Posts	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Riprap	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Wing Wall	Not Applicable	Beavers have dammed, with mud right into the structure, the underside is plugged

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	some out of place
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Fair	needs grading

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 89 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-369	Structure Name:	G5-369	Road Name:	MCLEOD -	Inspection Date:	2021/09/21
---------	--------	-----------------	--------	------------	----------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Hardware	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Running Planks	Good	
Sub Deck	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Ties	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged

SUPERSTRUCTURE

Span 1

Bracing	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Diaphragms	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Girders	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Hardware	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged
Under Trussing	Unrated	Beavers have dammed, with mud right into the structure, the underside is plugged

CHANNEL

Estimated Present Water Level Depth:	2.0	Estimated Present Water Level Width:	10.0
Estimated High Water Level Clearance:	0.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:	Beavers have dammed, with mud right into the structure, the underside is plugged								

REPAIRS

#	Status	Priority	Estimate	Description
6	Required	High	\$	Beavers have dammed, with mud right into the structure, the underside is plugged

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 90 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-369	Structure Name:	G5-369	Road Name:	MCLEOD -	Inspection Date:	2021/09/21	
GENERAL	Inspector's Comment:	Beavers have dammed, with mud right into the structure, the underside is plugged with debris, could not see abutments or ballast wall Need to reinspect next year. GZ						
GENERAL	PEng's Comment:	Remove beaver dam as soon as possible. Schedule for inspection in 2022.BH						
GENERAL	Estimated Load Restriction (year):		2030		Estimated Replacement (year):		2030	
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/10 13:23:26		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 91 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-370	Structure Name:	G5-370A	Road Name:	MCLEOD -	Inspection Date:	2018/10/10
KM:	14.50	User km:	14.30	Crossing Name:	Silvi Creek	Next Inspection Date:	2017/05/17
Project File ID #:	1784	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	15.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	437311	UTM Northing:	6075559		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:			
Access:	This site is not deactivated. It is a small culvert that does not need inspection. VS May 2013						

APPROACHES

Alignment

Fair

Road Surface

Fair

CULVERT ELEMENT

Baffles

Not Applicable

Bolted Connections

Not Applicable

Coupled Connections

Fair

Coating

Fair

Embedment Materials

Not Applicable

Fill

Good

Floor

Poor

Rotting out

Footing

Not Applicable

Head Wall

Not Applicable

Inlet

Fair

Outlet

Fair

Overall

Fair

Riprap

Not Applicable

Roof

Fair

Side Walls

Fair

Trash Rack

Not Applicable

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 92 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-370	Structure Name:	G5-370A	Road Name:	MCLEOD -	Inspection Date:	2018/10/10			
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	0.3						
	Estimated High Water Level Clearance:	0.5								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Minor culvert with issues								
GENERAL	PEng's Comment:	no photos. Appears to be a small culvert that does not need engineered inspections. This should be completed during normal district road inspections								
GENERAL	Estimated Load Restriction (year):	2020	Estimated Replacement (year):							
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):		Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Rejected By IDIR\JOLMSTED on 2019/02/08 11:38:15						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 93 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-371	Structure Name:	G5-371	Road Name:	MCLEOD -	Inspection Date:	2019/09/05
KM:	15.30	User km:	15.30	Crossing Name:	Tsilcoh River	Next Inspection Date:	2022/09/05
Project File ID #:	1784	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	2,500			Outlet Cover (mm):	2,500		
Footing Type:				Gradient (%):	0.0		
Culvert Length (metres):	23.0	Opening Height (mm):	2,200	Opening Width (mm):	2,200		
UTM Zone:	10	UTM Easting:	437662	UTM Northing:	6075966		
Inspector Name:	Dawson SMITH		Year Superstructure Installed:	1988			
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 94 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-371	Structure Name:	G5-371	Road Name:	MCLEOD -	Inspection Date:	2019/09/05			
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	ALL GOOD, COULD STAND CREEK SIGN BACK UP								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):		2028		Estimated Replacement (year):					
	Current Inspection Load Rating:		54		Design Load GVW (tonnes):		54		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/01/30 15:03:44			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 95 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-371	Structure Name:	G5-371-2	Road Name:	MCLEOD -	Inspection Date:	2019/09/05
KM:	15.30	User km:	15.30	Crossing Name:	Tsilcoh River	Next Inspection Date:	2022/09/05
Project File ID #:	1784	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,700			Outlet Cover (mm):	1,700		
Footing Type:				Gradient (%):	0.0		
Culvert Length (metres):	22.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	437662	UTM Northing:	6075966		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1988		
Access:							

APPROACHES

Alignment Good

Road Surface Good

CULVERT ELEMENT

Baffles Not Applicable

Bolted Connections Not Applicable

Coupled Connections Good

Coating Fair MINOR RUST

Embedment Materials Not Applicable

Fill Good

Floor Fair MINOR RUST

Footing Not Applicable

Head Wall Not Applicable

Inlet Good

Outlet Good

Overall Good

Riprap Not Applicable

Roof Good

Side Walls Good

Trash Rack Not Applicable

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 96 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-371	Structure Name:	G5-371-2	Road Name:	MCLEOD -	Inspection Date:	2019/09/05			
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.0			Estimated Present Water Level Width:	0.0				
	Estimated High Water Level Clearance:	1.3								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	PIPE WAS DRY								
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	ALL GOOD, PIPE WAS DRY WHEN INSPECTED, CROSSING SIGN COULD BE STOOD UP								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):	2028			Estimated Replacement (year):					
	Current Inspection Load Rating:	54		Design Load GVW (tonnes):	54		Design Vehicle Config.:			
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/30 15:05:14						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 97 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-373	Structure Name:	G5-373	Road Name:	MCLEOD -	Inspection Date:	2021/09/21
KM:	26.70	User km:	26.70	Crossing Name:	Salmon River	Next Inspection Date:	2022/09/01
Project File ID #:	1784	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Binwall	
Superstructure:	Steel I-beam				Right	Binwall	
Total Length (metres):	18.0	# Spans:	1	Span Width:			Span Length(s) (metres): 18
UTM Zone:	10		UTM Easting:	447545	UTM Northing:	6076736	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1991		
Access:							

ABUTMENTS

Bearings	Fair	
Binwall	Good	
Bracing	Not Applicable	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 98 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-373	Structure Name:	G5-373	Road Name:	MCLEOD -	Inspection Date:	2021/09/21			
Road Surface		Fair	needs grading							
DECK										
Span 1										
Concrete Deck		Fair	joints need work							
Curb Rail/Blocks/Posts		Good								
Deck Joints		Fair	joints need work							
Grout Pockets		Fair								
Hardware		Fair								
Hand Rails/Walkouts		Not Applicable								
Overall Deck Condition		Fair	joints and pockets could use patching							
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		1.5		Estimated Present Water Level Width:		5.0			
	Estimated High Water Level Clearance:		3.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	6	Suggested	Medium	\$						
MONITORS	#	Description								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 99 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-373	Structure Name:	G5-373	Road Name:	MCLEOD -	Inspection Date:	2021/09/21
GENERAL	Inspector's Comment:	Previous inspections noted missing welds and joint issues. At the time of inspection the deck was wet, muddy and gravelly however the spots we could clean off and look at revealed the same issues. Weld issue remain the same however they appear the same. No pictures of weld issues, repaire do not match component ratings. GZ					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2031	Estimated Replacement (year):			
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):	54	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Rejected By IDIR\GZSOMBOR on 2022/01/05 10:00:14			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 100 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-367	Structure Name:	G5-367	Road Name:	MCLEOD -	Inspection Date:	2021/10/21
KM:	32.10	User km:	31.00	Crossing Name:	Unnamed Creek	Next Inspection Date:	2023/10/21
Project File ID #:	1784	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Arch			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	500			Outlet Cover (mm):	900		
Footing Type:	Steel Footing			Gradient (%):	5.0		
Culvert Length (metres):	9.6	Opening Height (mm):	800	Opening Width (mm):	1,610		
UTM Zone:	10	UTM Easting:	451069	UTM Northing:	6076916		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	2020		
Access:	Small arch installed in 2020. Minor structure, set to Do NOT Inspect. 2021 GZ						

APPROACHES

Alignment	Fair	Sharp curve
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Unrated	None
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Unrated	N/A
Footing	Fair	Exposed at inlet
Head Wall	Not Applicable	
Inlet	Poor	Scoured down to footing

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 101 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-367	Structure Name:	G5-367	Road Name:	MCLEOD -	Inspection Date:	2021/10/21			
Outlet	Fair	Aggravation occurring								
Overall	Fair									
Riprap	Not Applicable	Shot rock used for bedding but no applicable armouring completed								
Roof	Fair	Swayback								
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.5			
	Estimated High Water Level Clearance:		0.6							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	Outlet of large swamp. Old culvert left in 10m upchain								
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Monitor footing scour at inlet								
GENERAL	Inspector's Comment:	NEG staff to monitor scour next year.								
GENERAL	PEng's Comment:	New structure in 2020. Footing exposed at inlet. Continue to monitor scour. BH								
GENERAL	Estimated Load Restriction (year):			2065		Estimated Replacement (year):				
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.: L100	
	Professional Inspection Required?		No		Report Status:		Reviewed By Bruce Henderson on 2022/02/06 16:03:33			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 102 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-450	Structure Name:	G1-450	Road Name:	MCLEOD -	Inspection Date:	2002/09/06
KM:	0.20	User km:	34.20	Crossing Name:	Unnamed creek	Next Inspection Date:	2005/09/06
Project File ID #:	1784	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:				Culvert Material:			
Inlet Cover (mm):	0			Outlet Cover (mm):	0		
Footing Type:				Gradient (%):			
Culvert Length (metres):	12.0	Opening Height (mm):	1	Opening Width (mm):	1		
UTM Zone:	10	UTM Easting:	474864	UTM Northing:	6074893		
Inspector Name:	Gary Zsombor		Year Superstructure Installed:	1988			
Access:	Carp Lake Park						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Poor	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 103 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-450	Structure Name:	G1-450	Road Name:	MCLEOD -	Inspection Date:	2002/09/06			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	3	Suggested	Medium	\$ 0.00	Span: 1.0. Remove Beaver Dam. Remove beaver dam late in fall. Prior to freeze up..					
MONITORS	#	Description								
	1	MONITOR BEAVER DAM AT INLET. No riprap required.								
GENERAL	Inspector's Comment:	nullCulvert: 1) Beaver dam.								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):				Estimated Replacement (year):					
	Current Inspection Load Rating:		41	Design Load GVW (tonnes):		41	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Accepted By IDIR\JOLMSTED on 2012/03/30 14:00:28				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 104 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-451	Structure Name:	G1-451	Road Name:	MCLEOD -	Inspection Date:	2002/09/05
KM:	9.70	User km:	40.50	Crossing Name:	Unnamed creek	Next Inspection Date:	2005/09/05
Project File ID #:	1784	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:				Culvert Material:			
Inlet Cover (mm):	0			Outlet Cover (mm):	0		
Footing Type:				Gradient (%):			
Culvert Length (metres):	12.0	Opening Height (mm):	1	Opening Width (mm):	1		
UTM Zone:	10	UTM Easting:	469622	UTM Northing:	6075995		
Inspector Name:	Gary Zsombor		Year Superstructure Installed:		1988		
Access:	Carp Lake Park						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 105 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-451	Structure Name:	G1-451	Road Name:	MCLEOD -	Inspection Date:	2002/09/05			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.6							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Monitor for scour as no rip rap is on site.								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):				Estimated Replacement (year):					
	Current Inspection Load Rating:		41	Design Load GVW (tonnes):		41	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Accepted By IDIR\JOLMSTED on 2012/03/30 14:06:08				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 106 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-380	Structure Name:	G4-161	Road Name:	WHITEMUD	Inspection Date:	2021/09/21
KM:	0.40	User km:	0.40	Crossing Name:	Whitemud Creek	Next Inspection Date:	2024/09/21
Project File ID #:	1784	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:			Span Length(s) (metres): 12.2
UTM Zone:	10		UTM Easting:	450787	UTM Northing:	6075500	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2021		
Access:	Km 29.7 McLeod-Tsloch FSR. Start - McLeod Whitemud FSR.						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Fair	fill is soft
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Fair	need additional itiiprap
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	68	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 107 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-380	Structure Name:	G4-161	Road Name:	WHITEMUD	Inspection Date:	2021/09/21			
Road Surface		Good								
DECK										
Span 1										
Concrete Deck		Fair								
Curb Rail/Blocks/Posts		Good								
Deck Joints		Poor		joints need redone						
Grout Pockets		Not Applicable								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Overall Deck Condition		Fair		joints need redone						
Running Surface		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	2	Not Required	Medium	\$ 0.00	Install grouting in joints.					
	3	Required	High	\$ 0.00	Install curb risers on end panels.					
	4	Required	Medium	\$ 0.00	Add additional riprap along stream banks.					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 108 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-380	Structure Name:	G4-161	Road Name:	WHITEMUD	Inspection Date:	2021/09/21
MONITORS	#	Description					
GENERAL	Inspector's Comment:	No issues other than joints not grouted. GZ					
GENERAL	PEng's Comment:	Non composite bridge grouting is not required. Risers missing on interior deck panels. Does not conform with standard drawings timber curbs. BH					
GENERAL	Estimated Load Restriction (year):		2066	Estimated Replacement (year):			
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.: L75
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/10 13:17:01	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 109 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-381	Structure Name:	G4-953	Road Name:	WHITEMUD	Inspection Date:	2021/09/21
KM:	3.10	User km:	3.10	Crossing Name:	unnamed	Next Inspection Date:	2024/09/21
Project File ID #:	1784	Br.	06	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	18.3	# Spans:	1	Span Width:			Span Length(s) (metres): 18.3
UTM Zone:	10		UTM Easting:	453135	UTM Northing:	6070337	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2008		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Poor	log fenders
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 110 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-381	Structure Name:	G4-953	Road Name:	WHITEMUD	Inspection Date:	2021/09/21			
Road Surface		Good								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Poor		rotten riser blocks						
Deck to Girder Bolts		Good								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Fair								
Running Planks		Fair								
Sub Deck		Unrated		none						
Ties		Fair								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.0		Estimated Present Water Level Width:		0.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 111 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-381	Structure Name:	G4-953	Road Name:	WHITEMUD	Inspection Date:	2021/09/21
REPAIRS	#	Status	Priority	Estimate	Description		
	3	Required	High		Install approach fenders. (log)		
	4	Required	High		Install both bridge ahead signs		
	5	Required	High		Install 4 delineators		
	6	Required	Medium		Brush approaches		
	7	Required	High		Replace riser blocks		
MONITORS	#	Description					
GENERAL	Inspector's Comment:	Log fenders, it has a locked gate on the up end. see pictures Consider load restriction to flag maintenance items identified on previos inspection. GZ					
GENERAL	PEng's Comment:	Address high repair items before industrial use. BH					
GENERAL	Estimated Load Restriction (year):			2025	Estimated Replacement (year):		
	Current Inspection Load Rating:		64	Design Load GVW (tonnes):		64	Design Vehicle Config.: BCL62
	Professional Inspection Required?		No	Report Status: Reviewed By Bruce Henderson on 2022/02/06 19:19:38			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 112 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-120	Structure Name:	G4-120A	Road Name:	SINKUT	Inspection Date:	2020/07/22
KM:	0.20	User km:	0.20	Crossing Name:	Sinkut River	Next Inspection Date:	2023/07/22
Project File ID #:	1787	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	21.9	# Spans:	1	Span Width:	Span Length(s) (metres):		20.7
UTM Zone:	10	UTM Easting:	431510	UTM Northing:	5972565		
Inspector Name:	Vince Sewell			Year Superstructure Installed:	2016		
Access:	Go left at km 1 on Hargreaves road which is off Sinkut Lake road.						

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	low chain needs to be replaced
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	holder bent
Delineator Missing Right (approaching structure)	1	holder bent
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	75	old sign
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 113 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-120	Structure Name:	G4-120A	Road Name:	SINKUT	Inspection Date:	2020/07/22
---------	--------	-----------------	---------	------------	--------	------------------	------------

DECK

Span 1

Concrete Deck	Good	dirty
Curb Rail/Blocks/Posts	Good	
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.7	Estimated Present Water Level Width:	12.0
	Estimated High Water Level Clearance:	1.6		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 114 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-120	Structure Name:	G4-120A	Road Name:	SINKUT	Inspection Date:	2020/07/22
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	looks good					
GENERAL	Estimated Load Restriction (year):		2066		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:		L100				
GENERAL	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/02/16 14:18:47			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 115 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-016	Structure Name:	G4-016A	Road Name:	DOG CREEK	Inspection Date:	2019/08/08
KM:	2.00	User km:	2.00	Crossing Name:	Dog Creek	Next Inspection Date:	2022/08/08
Project File ID #:	1788	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Concrete Slab Girders				Right	Steel Pipe and Precast Pad	
Total Length (metres):	10.6	# Spans:	1	Span Width:			Span Length(s) (metres): 10.6
UTM Zone:	10	UTM Easting:	416386	UTM Northing:	6014431		
Inspector Name:	dawson smith			Year Superstructure Installed:	2008		
Access:	This road is accessed from highway 27 north of Vanderhoof.						

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	63700	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 116 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-016	Structure Name:	G4-016A	Road Name:	DOG CREEK	Inspection Date:	2019/08/08
---------	--------	-----------------	---------	------------	-----------	------------------	------------

DECK

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Not Applicable
---------------	----------------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

SUPERSTRUCTURE

Span 1

Bracing	Not Applicable
---------	----------------

Hardware	Not Applicable
----------	----------------

Welded/grouted shear connectors	Good
---------------------------------	------

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	3.0
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	2.5
---------------------------------------	-----

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$ 250.00	INSTALL MISSING DELINEATORS

MONITORS

#	Description
1	Concrete spall on upstream left side. Currently no rebar exposed.

GENERAL

Inspector's Comment:	GOOD, MISSING 2 DELINEATORS
----------------------	-----------------------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 117 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-016	Structure Name:	G4-016A	Road Name:	DOG CREEK	Inspection Date:	2019/08/08
---------	--------	-----------------	---------	------------	-----------	------------------	------------

GENERAL

PEng's
Comment:

GENERAL

Estimated Load Restriction (year):	2038	Estimated Replacement (year):	
Current Inspection Load Rating:	64	Design Load GVW (tonnes):	64
Design Vehicle Config.:	BCL62		
Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/22 10:57:48

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 118 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-026	Structure Name:	G4-026A	Road Name:	DOG CREEK	Inspection Date:	2019/08/08
KM:	11.10	User km:	11.10	Crossing Name:	Unknown	Next Inspection Date:	2022/08/08
Project File ID #:	1788	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):				Outlet Cover (mm):			
Footing Type:	Precast Concrete Footing			Gradient (%):			
Culvert Length (metres):	23.0	Opening Height (mm):	2,360	Opening Width (mm):	5,790		
UTM Zone:	10	UTM Easting:	407385	UTM Northing:	6014480		
Inspector Name:	dawson smith			Year Superstructure Installed:	2008		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Good	
Fill	Good	
Floor	Not Applicable	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 119 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-026	Structure Name:	G4-026A	Road Name:	DOG CREEK	Inspection Date:	2019/08/08			
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	GOOD								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):			2048		Estimated Replacement (year):				
	Current Inspection Load Rating:		68		Design Load GVW (tonnes):		Design Vehicle Config.:		CL625	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/01/22 11:00:28			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 120 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-130	Structure Name:	G4-130	Road Name:	SUTHERLAND	Inspection Date:	2001/06/14
KM:	18.00	User km:	0.00	Crossing Name:	Angly Creek	Next Inspection Date:	2004/06/14
Project File ID #:	1795	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	2,000			Outlet Cover (mm):	2,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	27.0	Opening Height (mm):	1,400	Opening Width (mm):	1,400		
UTM Zone:	10	UTM Easting:	388362	UTM Northing:	6008206		
Inspector Name:	Tim Silbernagel			Year Superstructure Installed:	1990		
Access:	1400mm culvert. Leave as DNI. GZ 2020						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Fair	No Comment Available -Converter.RNI
Riprap	Good	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 121 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-130	Structure Name:	G4-130	Road Name:	SUTHERLAND	Inspection Date:	2001/06/14			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.8							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Monitor for scour as no rip rap is on site. (no scour TS 2001)								
GENERAL	Inspector's Comment:	nullCulvert: 2) 0.1M drop, fast water, may not have fish passage.								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2040		Estimated Replacement (year):					
	Current Inspection Load Rating:		41		Design Load GVW (tonnes):		41		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/13 11:21:47			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 122 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-132	Structure Name:	G4-936	Road Name:	SUTHERLAND	Inspection Date:	2021/07/09
KM:	22.00	User km:	22.00	Crossing Name:	Peta Creek	Next Inspection Date:	2022/08/01
Project File ID #:	1795	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Steel I-beam				Right	Sill -Temporary Materials	
Total Length (metres):	15.2	# Spans:	1	Span Width:	Span Length(s) (metres):		15.2
UTM Zone:	10	UTM Easting:	385126	UTM Northing:	6009776		
Inspector Name:	Dawson Smith		Year Superstructure Installed:	2003			
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Fair	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 123 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-132	Structure Name:	G4-936	Road Name:	SUTHERLAND	Inspection Date:	2021/07/09
---------	--------	-----------------	--------	------------	------------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	guardrails and risers have decay
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Good	
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	1.0
Estimated High Water Level Clearance:	0.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
3	Suggested	Medium	\$ 500.00	install 3
4	Suggested	Medium	\$ 500.00	
5	Suggested	Medium	\$	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 124 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G4-132 Structure Name: G4-936 Road Name: SUTHERLAND Inspection Date: 2021/07/09

MONITORS

#	Description
2	Monitor guardrail and riser block decay

GENERAL

Inspector's Comment:	No up/down stream pics, rails very poor, repairs do not match conditions
----------------------	--

GENERAL

PEng's Comment:	
-----------------	--

GENERAL

Estimated Load Restriction (year):			2024	Estimated Replacement (year):				
Current Inspection Load Rating:		See footnote	Design Load GVW (tonnes):		91	Design Vehicle Config.:		L100
Professional Inspection Required?		No	Report Status:	Rejected By IDIR\GZSOMBOR on 2021/12/02 09:37:49				

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 125 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-159	Structure Name:	G4-159	Road Name:	SUTHERLAND	Inspection Date:	2019/08/08
KM:	26.50	User km:	26.50	Crossing Name:	Un-named	Next Inspection Date:	2022/08/08
Project File ID #:	1795	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,500		
Footing Type:	Steel Footing			Gradient (%):			
Culvert Length (metres):	18.4	Opening Height (mm):	1,910	Opening Width (mm):	3,660		
UTM Zone:	10	UTM Easting:	381768	UTM Northing:	6011076		
Inspector Name:	dawson smith			Year Superstructure Installed:	2009		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Good	
Fill	Good	
Floor	Not Applicable	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 126 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-159	Structure Name:	G4-159	Road Name:	SUTHERLAND	Inspection Date:	2019/08/08	
Overall	Good							
Riprap	Good							
Roof	Good							
Side Walls	Good							
Trash Rack	Not Applicable							
Wiers/Backwater Structures	Not Applicable							
Wing Wall	Not Applicable							
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		1.0	
	Estimated High Water Level Clearance:		2.0					
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Aggradation: No	
	Comment:							
REPAIRS	#	Status	Priority	Estimate	Description			
MONITORS	#	Description						
GENERAL	Inspector's Comment:	ALL GOOD						
GENERAL	PEng's Comment:							
GENERAL	Estimated Load Restriction (year):			2059	Estimated Replacement (year):			2059
	Current Inspection Load Rating:		64	Design Load GVW (tonnes):		64	Design Vehicle Config.: CL625	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/14 15:07:51				

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 127 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-162	Structure Name:	G4-162	Road Name:	OLD TROUT	Inspection Date:	2019/08/08
KM:	4.80	User km:	4.80	Crossing Name:	Tatin Creek	Next Inspection Date:	2022/08/08
Project File ID #:	1795	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Precast	
Superstructure:	Steel I-beam				Right	Concrete Precast	
Total Length (metres):	12.0	# Spans:	1	Span Width:	Span Length(s) (metres):		12
UTM Zone:	10		UTM Easting:	371188	UTM Northing:	5997663	
Inspector Name:	dawson smith			Year Superstructure Installed:	1993		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Concrete Precast	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	54000	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 128 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-162	Structure Name:	G4-162	Road Name:	OLD TROUT	Inspection Date:	2019/08/08			
Road Surface		Good								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Poor		damage on left side						
Deck to Girder Bolts		Not Applicable								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Good								
Running Planks		Fair								
Sub Deck		Fair								
Ties		Fair								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		2.0		Estimated Present Water Level Width:		3.5			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Medium	\$	REPLACE ROTTEN GUARD RAILS					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 129 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-162	Structure Name:	G4-162	Road Name:	OLD TROUT	Inspection Date:	2019/08/08
MONITORS	#	Description					
GENERAL	Inspector's Comment:	NEEDS GUARD RAILS REPLACED					
GENERAL	PEng's Comment:	I curbs are not replaced soon the bridge could be downrated.					
GENERAL	Estimated Load Restriction (year):		2033	Estimated Replacement (year):			
	Current Inspection Load Rating:		54	Design Load GVW (tonnes):		54	Design Vehicle Config.: L60
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/01/24 11:56:11	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 130 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-163	Structure Name:	G4-163	Road Name:	OLD TROUT	Inspection Date:	2019/08/08
KM:	9.00	User km:	9.00	Crossing Name:	unnamed	Next Inspection Date:	2022/08/08
Project File ID #:	1795	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	12.2	# Spans:	1	Span Width:			Span Length(s) (metres): 12.2
UTM Zone:	10	UTM Easting:	373141	UTM Northing:	5999712		
Inspector Name:	dawson smith			Year Superstructure Installed:	2011		
Access:							

ABUTMENTS

Bearings	Fair
Bracing	Good
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Good
Piles or Posts	Good
Riprap	Good
Wing Wall	Not Applicable

APPROACHES

Alignment	Good
Bridge Ahead Signs Missing	0
Brushing Required	Yes
Delineator Missing Left (approaching structure)	0
Delineator Missing Right (approaching structure)	0
Fender Condition	Good
Posted Load Rating (Enter 0 if sign missing)	63700
Road Surface	Good

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 131 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-163	Structure Name:	G4-163	Road Name:	OLD TROUT	Inspection Date:	2019/08/08
---------	--------	-----------------	--------	------------	-----------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Good	
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	0.2
	Estimated High Water Level Clearance:	2.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Low	\$	brushing

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 132 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-163	Structure Name:	G4-163	Road Name:	OLD TROUT	Inspection Date:	2019/08/08
GENERAL	Inspector's Comment:	GOOD, REQUIRES BRUSHING					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2056	Estimated Replacement (year):		2060	
	Current Inspection Load Rating:	64	Design Load GVW (tonnes):	64	Design Vehicle Config.:	BCL62	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/14 14:45:34			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 133 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-164	Structure Name:	G4-166A	Road Name:	OLD TROUT	Inspection Date:	2019/08/08
KM:	9.30	User km:	9.30	Crossing Name:	unnamed	Next Inspection Date:	2022/08/08
Project File ID #:	1795	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	18.3	# Spans:	1	Span Width:			Span Length(s) (metres): 18.3
UTM Zone:	10	UTM Easting:	373423	UTM Northing:	5999862		
Inspector Name:	dawson smith			Year Superstructure Installed:	2011		
Access:	Structure number was wrong. Changed to G4-166A						

ABUTMENTS

Bearings	Good
Bracing	Good
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Good
Piles or Posts	Good
Riprap	Good
Wing Wall	Not Applicable

APPROACHES

Alignment	Good
Bridge Ahead Signs Missing	0
Brushing Required	Yes
Delineator Missing Left (approaching structure)	0
Delineator Missing Right (approaching structure)	0
Fender Condition	Good
Posted Load Rating (Enter 0 if sign missing)	63700
Road Surface	Good

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 134 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-164	Structure Name:	G4-166A	Road Name:	OLD TROUT	Inspection Date:	2019/08/08
---------	--------	-----------------	---------	------------	-----------	------------------	------------

DECK

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Good
---------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	1.0
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	2.0
---------------------------------------	-----

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$ 500.00	brushing

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 135 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-164	Structure Name:	G4-166A	Road Name:	OLD TROUT	Inspection Date:	2019/08/08	
GENERAL	Inspector's Comment:	BRUSHED IN, COULD NOT GET UP OR DOWN PICTURES						
GENERAL	PEng's Comment:							
GENERAL	Estimated Load Restriction (year):		2056	Estimated Replacement (year):		2060		
	Current Inspection Load Rating:		64	Design Load GVW (tonnes):		64	Design Vehicle Config.:	BCL62
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/01/14 14:48:39		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 136 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-166	Structure Name:	G4-164A	Road Name:	OLD TROUT	Inspection Date:	2019/08/08
KM:	12.60	User km:	12.60	Crossing Name:	unnamed	Next Inspection Date:	2022/08/08
Project File ID #:	1795	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	18.3	# Spans:	1	Span Width:			Span Length(s) (metres): 18.3
UTM Zone:	10	UTM Easting:	375180	UTM Northing:	6001982		
Inspector Name:	dawson smith			Year Superstructure Installed:	2011		
Access:	Structure number was wrong. Changed from G4-166 to G4-164A.						

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	end of guardrailes exposed
Posted Load Rating (Enter 0 if sign missing)	63700	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 137 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G4-166 Structure Name: G4-164A Road Name: OLD TROUT Inspection Date: 2019/08/08

DECK

Span 1

Concrete Deck Good

Curb Rail/Blocks/Posts Good

Deck Joints Good

Grout Pockets Good

Hardware Good

Hand Rails/Walkouts Not Applicable

Overall Deck Condition Good

Running Surface Good

SUPERSTRUCTURE

Span 1

Bracing Good

Diaphragms Good

Girders Good

Hardware Good

Under Trussing Not Applicable

CHANNEL

Estimated Present Water Level Depth: 0.5 Estimated Present Water Level Width: 1.5

Estimated High Water Level Clearance: 4.0

HAZARDS

High Water: No Scour: No Ice: No Debris: No Aggradation: No

Comment:

REPAIRS

#	Status	Priority	Estimate	Description
1	Not Required	Medium	\$	PUT FENDERS BACK IN PLACE
2	Not Required	Medium	\$ 500.00	brushing

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 138 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-166	Structure Name:	G4-164A	Road Name:	OLD TROUT	Inspection Date:	2019/08/08
GENERAL	Inspector's Comment:	good, bridge is marked G4 164 but is G4 166 location?.					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2050	Estimated Replacement (year):			
	Current Inspection Load Rating:	64	Design Load GVW (tonnes):	64	Design Vehicle Config.:	BCL62	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/14 14:56:12			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 139 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-167	Structure Name:	G4-167	Road Name:	OLD TROUT	Inspection Date:	2020/05/06
KM:	20.10	User km:	20.10	Crossing Name:	Ormond Creek	Next Inspection Date:	2023/05/06
Project File ID #:	1795	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	15.2	# Spans:	1	Span Width:	Span Length(s) (metres):		15.2
UTM Zone:	10	UTM Easting:	380344	UTM Northing:	6006993		
Inspector Name:	Warren Wilkinson, Sott Atkinson			Year Superstructure Installed:	2010		
Access:	*** FIELD-CHECK 'kilometre' and 'user kilometre' ***						

ABUTMENTS

Bearings	Fair	
Bracing	Fair	
Ballast Wall	Fair	water running down walls left and right sides
Corrosion Protection	Fair	
Caps or Sills	Fair	
Fill	Fair	
Hardware	Fair	
Piles or Posts	Fair	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 140 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G4-167 Structure Name: G4-167 Road Name: OLD TROUT Inspection Date: 2020/05/06

DECK

Span 1

Concrete Deck	Fair	crack in downstream left at guard rail bracket
Curb Rail/Blocks/Posts	Poor	repair damage to rail and brackets
Deck Joints	Poor	re-seal joints
Grout Pockets	Fair	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	
Running Surface	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Fair	rust stains around joints
Hardware	Good	
Under Trussing	Good	

CHANNEL

Estimated Present Water Level Depth:	0.8	Estimated Present Water Level Width:	6.0
Estimated High Water Level Clearance:	2.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
2	Required	Medium	\$	replace broken bolts on curb

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 141 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-167	Structure Name:	G4-167	Road Name:	OLD TROUT	Inspection Date:	2020/05/06
GENERAL	Inspector's Comment:	Inspected by Scott Atkinson under direct supervision of W.Wilkinson joint inspection with Branch Engineer & DSN engineering staff					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2050	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/02/16 15:21:40			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 142 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-160	Structure Name:	G4-160	Road Name:	OLD TROUT	Inspection Date:	2019/10/17
KM:	29.70	User km:	23.32	Crossing Name:	Peta Creek	Next Inspection Date:	2022/10/17
Project File ID #:	1795	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Gravel			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Concrete Precast	
Superstructure:	Concrete Slab Girders				Right	Concrete Precast	
Total Length (metres):	8.0	# Spans:	1	Span Width:	Span Length(s) (metres):		8
UTM Zone:	10	UTM Easting:	381427	UTM Northing:	6008008		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2000		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Precast	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	NOT REQUIRED
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	NOT REQUIRED
Delineator Missing Right (approaching structure)	2	NOT REQUIRED
Fender Condition	None	NOT REQUIRED
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 143 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-160	Structure Name:	G4-160	Road Name:	OLD TROUT	Inspection Date:	2019/10/17
---------	--------	-----------------	--------	------------	-----------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Unrated	NOT REQUIRED
------------------------	---------	--------------

Gravel Deck Depth (metres)	0.5
----------------------------	-----

Grout Pockets	Not Applicable
---------------	----------------

Hardware	Not Applicable
----------	----------------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

SUPERSTRUCTURE

Span 1

Bracing	Not Applicable
---------	----------------

Hardware	Not Applicable
----------	----------------

Welded/grouted shear connectors	Not Applicable
---------------------------------	----------------

CHANNEL	Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	3.0
	Estimated High Water Level Clearance:	2.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

GENERAL	Inspector's Comment:	THIS IS LOCATED AT APPROX.14KM ON THE OONA FSR (2KMS OFF THE SOUTHERLAND TROUT)

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 144 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-160	Structure Name:	G4-160	Road Name:	OLD TROUT	Inspection Date:	2019/10/17
---------	--------	-----------------	--------	------------	-----------	------------------	------------

GENERAL

PEng's
Comment:

GENERAL

Estimated Load Restriction (year):	2050	Estimated Replacement (year):			
Current Inspection Load Rating:	68	Design Load GVW (tonnes):	68	Design Vehicle Config.:	L75
Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/03 11:08:23		

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 145 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-150	Structure Name:	G4-150	Road Name:	SUTHERLAND	Inspection Date:	2019/08/08
KM:	2.70	User km:	2.70	Crossing Name:	Duncan Creek	Next Inspection Date:	2022/08/08
Project File ID #:	1795	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	2,500			Outlet Cover (mm):	2,500		
Footing Type:				Gradient (%):			
Culvert Length (metres):	24.0	Opening Height (mm):	2,700	Opening Width (mm):	2,700		
UTM Zone:	10	UTM Easting:	379689	UTM Northing:	6014933		
Inspector Name:	bceid\dawson smith			Year Superstructure Installed:	1993		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	
Overall	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 146 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-150	Structure Name:	G4-150	Road Name:	SUTHERLAND	Inspection Date:	2019/08/08
Riprap	Not Applicable						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wing Wall	Not Applicable						
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		0.5
	Estimated High Water Level Clearance:		2.5				
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Aggradation: No
	Comment:						
REPAIRS	#	Status	Priority	Estimate	Description		
MONITORS	#	Description					
GENERAL	Inspector's Comment:	ALL GOOD					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):			2033	Estimated Replacement (year):		
	Current Inspection Load Rating:	54	Design Load GVW (tonnes):		54	Design Vehicle Config.:	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/23 14:05:55			

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 147 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-133	Structure Name:	G4-133	Road Name:	DIPPER	Inspection Date:	2020/09/04
KM:	0.70	User km:	0.70	Crossing Name:	Un-named	Next Inspection Date:	2023/09/04
Project File ID #:	1795	Br.	06	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:	Precast Concrete Footing			Gradient (%):	4.0		
Culvert Length (metres):	18.4	Opening Height (mm):	1,840	Opening Width (mm):	4,270		
UTM Zone:	10	UTM Easting:	374970	UTM Northing:	6022920		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2009		
Access:	Travel up the Sutherland FSR to 43 km. Turn left onto the Sutherland Dipper FSR and travel to 0.7 km						

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Fair	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Good	
Fill	Good	1m
Floor	Not Applicable	
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Fair	drop to stream, perched

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 148 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-133	Structure Name:	G4-133	Road Name:	DIPPER	Inspection Date:	2020/09/04			
Overall	Good									
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Good	downstream right only								
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		0.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	looks good								
GENERAL	Estimated Load Restriction (year):			2050		Estimated Replacement (year):				
	Current Inspection Load Rating:		64		Design Load GVW (tonnes):		64		Design Vehicle Config.: BCL62	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2021/02/16 14:21:39			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 149 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-140	Structure Name:	G4-927	Road Name:	SUTHERLAND	Inspection Date:	2019/08/08
KM:	4.90	User km:	4.90	Crossing Name:	Angly Creek	Next Inspection Date:	2022/08/08
Project File ID #:	1795	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	10		UTM Easting:	387742		UTM Northing:	6005979
Inspector Name:	bceid\dawson smith			Year Superstructure Installed:	2009		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Good	
Ballast Wall	Good	
Concrete Lock Blocks	Not Applicable	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	68000	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 150 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-140	Structure Name:	G4-927	Road Name:	SUTHERLAND	Inspection Date:	2019/08/08			
Road Surface		Good								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Deck to Girder Bolts		Not Applicable								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Good								
Running Planks		Good								
Sub Deck		Good								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Low	\$ 500.00	brushing					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 151 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-140	Structure Name:	G4-927	Road Name:	SUTHERLAND	Inspection Date:	2019/08/08
MONITORS	#	Description					
GENERAL	Inspector's Comment:	GOOD					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2024		Estimated Replacement (year):		
	Current Inspection Load Rating:		68		Design Load GVW (tonnes):		68
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/01/14 15:00:21
				Design Vehicle Config.:		L75	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 152 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-139	Structure Name:	G4-139	Road Name:	SUTHERLAND	Inspection Date:	2020/09/04
KM:	1.90	User km:		Crossing Name:	Un-named	Next Inspection Date:	2023/09/04
Project File ID #:	1795	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Steel			Running Surface:	Anti-skid		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel Box Beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:	Span Length(s) (metres):		12.2
UTM Zone:	10	UTM Easting:	390504	UTM Northing:	6005458		
Inspector Name:	Warren Wilkinson		Year Superstructure Installed:	2009			
Access:	Travel to 12.8 on the Sutherland FSR and turn left onto the Sutherland Oona FSR. Travel to 1.9 km						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	not sitting on center of blocks
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	75	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 153 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-139	Structure Name:	G4-139	Road Name:	SUTHERLAND	Inspection Date:	2020/09/04			
Road Surface	Good									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Overall Deck Condition	Good									
Running Surface	Poor	non slip worn off								
Steel Deck Plate	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Not Applicable									
Diaphragms	Unrated	does not have any								
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		0.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 154 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-139	Structure Name:	G4-139	Road Name:	SUTHERLAND	Inspection Date:	2020/09/04
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	looks good					
GENERAL	Estimated Load Restriction (year):		2039	Estimated Replacement (year):			
	Current Inspection Load Rating:	68	Design Load GVW (tonnes):	68	Design Vehicle Config.:	L75	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/02/16 14:26:39			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 155 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-145	Structure Name:	G4-123	Road Name:	ANGLY	Inspection Date:	2020/09/04
KM:	3.60	User km:	3.60	Crossing Name:	Angly Creek	Next Inspection Date:	2023/09/04
Project File ID #:	1795	Br.	08	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	9.1	# Spans:	1	Span Width:	Span Length(s) (metres):		9
UTM Zone:	10	UTM Easting:	390461	UTM Northing:	6010122		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2013		
Access:	Turn right at km 17 on the Sutherland FSR.						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	2 timbers right, log and timber on left
Concrete Lock Blocks	Good	Movement right side downstream block
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	Corner left side
Bridge Ahead Signs Missing	1	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Road Surface	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 156 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-145	Structure Name:	G4-123	Road Name:	ANGLY	Inspection Date:	2020/09/04
---------	--------	-----------------	--------	------------	-------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Good
----------------------	------

Hardware	Excellent
----------	-----------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Good
----------------	------

Sub Deck	Good
----------	------

Ties	Good
------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Good
----------------	------

CHANNEL

Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	2.0
Estimated High Water Level Clearance:	0.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 157 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-145	Structure Name:	G4-123	Road Name:	ANGLY	Inspection Date:	2020/09/04
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	looks good					
GENERAL	Estimated Load Restriction (year):		2045	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/02/16 14:29:42			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 158 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-148	Structure Name:	G4-148	Road Name:	ANGLY	Inspection Date:	2020/09/30
KM:	4.00	User km:	4.10	Crossing Name:	Unnamed Creek	Next Inspection Date:	2023/09/30
Project File ID #:	1795	Br.	08	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	480			Outlet Cover (mm):	670		
Footing Type:	Steel Footing			Gradient (%):	5.4		
Culvert Length (metres):	12.2	Opening Height (mm):	1,030	Opening Width (mm):	1,930		
UTM Zone:	10	UTM Easting:	390582	UTM Northing:	6010484		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	2020		
Access:							

APPROACHES

Alignment	Fair	Poor vertical, humped over arch
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Unrated	None
Road Surface	Fair	Poor vertical, humped over arch

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Not Applicable	
Embedment Materials	Poor	Footing exposed
Fill	Good	
Floor	Unrated	Open bottom
Footing	Poor	Exposed
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Poor	Exposed footing

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 159 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-148	Structure Name:	G4-148	Road Name:	ANGLY	Inspection Date:	2020/09/30			
Overall	Fair									
Riprap	Fair									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	1.0						
	Estimated High Water Level Clearance:	0.5								
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	New install, poor installation								
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Low	\$ 1.00	Install rock apron at outlet, construct wier for fish passage					
	2	Required	High	\$ 1.00	Add more fill to approaches so grader doesnt remove cover over arch					
	3	Required	Medium	\$ 1.00	Replace embedment material					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Possible failure next freshet as footings will undermine.Stream channel is about 8%, arch at 3%, outlet is perched.								
GENERAL	PEng's Comment:	Will look at this culvert in 2021 to confirm what repairs and/or load restrictions are required.								

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 160 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-148	Structure Name:	G4-148	Road Name:	ANGLY	Inspection Date:	2020/09/30	
GENERAL	Estimated Load Restriction (year):		2035	Estimated Replacement (year):				
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/02/16 15:17:27		

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 161 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-146	Structure Name:	G4-921	Road Name:	ANGLY	Inspection Date:	2021/07/09
KM:	7.30	User km:	7.30	Crossing Name:	Un-named	Next Inspection Date:	2024/07/09
Project File ID #:	1795	Br.	08	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Steel I-beam				Right	Sill -Temporary Materials	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	10	UTM Easting:	393494	UTM Northing:	6011692		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2009		
Access:	Travel up the Sutherland FSR to 17 km and turn right onto the Sutherland Angly FSR. Travel to 7.3 km						

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 162 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-146	Structure Name:	G4-921	Road Name:	ANGLY	Inspection Date:	2021/07/09
---------	--------	-----------------	--------	------------	-------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Not Applicable	(GOOD GZ)
Sub Deck	Good	(N/A GZ)
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	1.0
	Estimated High Water Level Clearance:	1.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 163 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-146	Structure Name:	G4-921	Road Name:	ANGLY	Inspection Date:	2021/07/09
GENERAL	Inspector's Comment:	No significant issues. GZ					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2024	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/02 14:22:00			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 164 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-147	Structure Name:	G4-922	Road Name:	ANGLY	Inspection Date:	2021/07/09
KM:	9.00	User km:	9.00	Crossing Name:	Un-named	Next Inspection Date:	2021/08/08
Project File ID #:	1795	Br.	08	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Steel I-beam				Right	Sill -Temporary Materials	
Total Length (metres):	18.3	# Spans:	1	Span Width:			Span Length(s) (metres): 18.3
UTM Zone:	10	UTM Easting:	394763	UTM Northing:	6012971		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2009		
Access:	Travel up the Sutherland FSR to 17 km and turn right onto the Sutherland Angly FSR. Travel to 9 km.						

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 165 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-147	Structure Name:	G4-922	Road Name:	ANGLY	Inspection Date:	2021/07/09
---------	--------	-----------------	--------	------------	-------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Good
----------------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Good
----------------	------

Sub Deck	Good
----------	------

Ties	Good
------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	2.0
Estimated High Water Level Clearance:	1.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 166 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-147	Structure Name:	G4-922	Road Name:	ANGLY	Inspection Date:	2021/07/09
GENERAL	Inspector's Comment:	No pics up/down stream, no pics of ballast walls (to be monitored)					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2024	Estimated Replacement (year):		2024	
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Rejected By IDIR\GZSOMBOR on 2022/01/10 12:27:34			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 167 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-210	Structure Name:	G4-933	Road Name:	ANGLY 900 FSR	Inspection Date:	2020/09/04
KM:	4.60	User km:	4.60	Crossing Name:	Unnamed Creek	Next Inspection Date:	2022/09/04
Project File ID #:	1795	Br.	12	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:			Span Length(s) (metres): 12.2
UTM Zone:	10		UTM Easting:	391581		UTM Northing:	6015035
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2014		
Access:							

ABUTMENTS

Bearings	Good	not centered on sill
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Log/Timber Cribs	Unrated	does not have
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Tie-backs	Not Applicable	
Wing Wall	Good	right downstream

APPROACHES

Alignment	Good	hill on left side
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	fire damage Shovle Lake fire

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 168 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-210	Structure Name:	G4-933	Road Name:	ANGLY 900 FSR	Inspection Date:	2020/09/04			
Posted Load Rating (Enter 0 if sign missing)	68									
Road Surface	Fair									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Fair									
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Good									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 169 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-210	Structure Name:	G4-933	Road Name:	ANGLY 900 FSR	Inspection Date:	2020/09/04
MONITORS	#	Description					
GENERAL	Inspector's Comment:	remove reference to Log/Timber Cribs					
GENERAL	PEng's Comment:	looks ok					
GENERAL	Estimated Load Restriction (year):		2030		Estimated Replacement (year):		
	Current Inspection Load Rating:		68		Design Load GVW (tonnes):		68
	Design Vehicle Config.:						
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/02/18 13:33:50			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 170 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-131	Structure Name:	G4-909	Road Name:	DUNCAN	Inspection Date:	2018/09/27
KM:	4.20	User km:	0.00	Crossing Name:	Duncan Creek	Next Inspection Date:	2022/10/01
Project File ID #:	1795	Br.	13	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Sill - Permanent Materials	
Superstructure:	Steel I-beam				Right	Sill - Permanent Materials	
Total Length (metres):	12.0	# Spans:	1	Span Width:			Span Length(s) (metres): 12
UTM Zone:	10		UTM Easting:	381584		UTM Northing:	6017179
Inspector Name:	Adam Mathison, GradTech			Year Superstructure Installed:	2011		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	Existing piles and timbers from old bridge retaining fill
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	Reattach
Delineator Missing Right (approaching structure)	0	Reattach
Fender Condition	Fair	Sections not connected, need to be flared more
Road Surface	Good	

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 171 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-131	Structure Name:	G4-909	Road Name:	DUNCAN	Inspection Date:	2018/09/27
---------	--------	-----------------	--------	------------	--------	------------------	------------

Span 1

Curb Rail/Blocks/Posts	Fair	Starting to rot, some damage to steel risers
Deck to Girder Bolts	Good	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Fair	
Running Planks	Good	
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.3	Estimated Present Water Level Width:	3.0
Estimated High Water Level Clearance:	1.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:	Beaver dam on upstream side								

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	High	\$ 500.00	Install bridge ahead signs and reattach delineators
2	Required	Medium	\$	Remove accumulated material at bridge corners
3	Required	Low	\$	Reposition fenders

MONITORS

#	Description
1	Monitor beaver dam upstream of bridge

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 172 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-131	Structure Name:	G4-909	Road Name:	DUNCAN	Inspection Date:	2018/09/27
GENERAL	Inspector's Comment:	Bridge is in overall fair condition due to signage and fenders.					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2019/02/05 09:05:48			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 173 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-135	Structure Name:	G4-923	Road Name:	DUNCAN	Inspection Date:	2020/05/13
KM:	0.30	User km:	0.30	Crossing Name:	No Name Creek	Next Inspection Date:	2023/05/13
Project File ID #:	1795	Br.	13	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	18.3	# Spans:	1	Span Width:	Span Length(s) (metres):		18.3
UTM Zone:	10		UTM Easting:	375123	UTM Northing:	6024091	
Inspector Name:	Sey Choi			Year Superstructure Installed:	2000		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Fair	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	
Fill	Fair	
Hardware	Fair	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Poor	slope erosion to be monitored in future

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Road Surface	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 174 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-135	Structure Name:	G4-923	Road Name:	DUNCAN	Inspection Date:	2020/05/13
---------	--------	-----------------	--------	------------	--------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Good
----------------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Good
---------------------	------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Not Applicable
----------------	----------------

Sub Deck	Good
----------	------

Ties	Good
------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	5.0
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	1.0
---------------------------------------	-----

HAZARDS

High Water:	Yes	Scour:	No	Ice:	Yes	Debris:	Yes	Aggradation:	No
-------------	-----	--------	----	------	-----	---------	-----	--------------	----

Comment:

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 175 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-135	Structure Name:	G4-923	Road Name:	DUNCAN	Inspection Date:	2020/05/13
MONITORS	#	Description					
	1	Fender Condition					
	2	Fill Behind Ballast Walls					
GENERAL	Inspector's Comment:	Overall good condition. Actual Structure ID was G4-922, but it is an identical structure to G4-923. The current Structure Id will be kept and the structure will be remarked as G4-923. Structure ID will be G4-922. Site G4-147 structure will be renamed to G4-923. GZ					
GENERAL	PEng's Comment:	Good for L-100					
GENERAL	Estimated Load Restriction (year):		2025		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2021/05/20 12:32:29

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 176 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-134	Structure Name:	G4-134	Road Name:	DUNCAN	Inspection Date:	2021/07/09
KM:	14.70	User km:	43.50	Crossing Name:	unnamed	Next Inspection Date:	2024/07/09
Project File ID #:	1795	Br.	13	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	3,000			Outlet Cover (mm):	3,000		
Footing Type:	Precast Concrete Footing			Gradient (%):	4.0		
Culvert Length (metres):	22.0	Opening Height (mm):	1,840	Opening Width (mm):	4,270		
UTM Zone:	10	UTM Easting:	375282	UTM Northing:	6023159		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2009		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Good	
Fill	Good	
Floor	Not Applicable	
Footing	Not Applicable	
Head Wall	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 177 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-134	Structure Name:	G4-134	Road Name:	DUNCAN	Inspection Date:	2021/07/09
Inlet	Good						
Outlet	Good						
Overall	Good						
Riprap	Good						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						

CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Poor pictures but no issues. GZ								
GENERAL	PEng's Comment:	No concerns. BH								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 178 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-134	Structure Name:	G4-134	Road Name:	DUNCAN	Inspection Date:	2021/07/09
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:		64	Design Load GVW (tonnes):		64	Design Vehicle Config.: BCL62
	Professional Inspection Required?		No	Report Status: Reviewed By Bruce Henderson on 2022/02/02 14:05:48			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 179 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-230	Structure Name:	G5-810	Road Name:	SUTHERLAND	Inspection Date:	2020/10/08
KM:	5.88	User km:	0.00	Crossing Name:	Unknown	Next Inspection Date:	2023/10/08
Project File ID #:	1795	Br.	17	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	24.4	# Spans:	1	Span Width:	Span Length(s) (metres):		24.4
UTM Zone:	10	UTM Easting:	379313	UTM Northing:	6027629		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2018		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Fair	
Hardware	Good	
Piles or Posts	Unrated	not observable
Riprap	Not Applicable	
Wing Wall	Good	

APPROACHES

Alignment	Fair	Hill and Corners
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	63	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 180 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-230	Structure Name:	G5-810	Road Name:	SUTHERLAND	Inspection Date:	2020/10/08			
Road Surface		Fair								
DECK										
Span 1										
Concrete Deck		Good								
Curb Rail/Blocks/Posts		Good								
Deck Joints		Good								
Grout Pockets		Not Applicable								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Overall Deck Condition		Good								
Running Surface		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Good								
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		5.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 181 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-230	Structure Name:	G5-810	Road Name:	SUTHERLAND	Inspection Date:	2020/10/08
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	looks good					
GENERAL	Estimated Load Restriction (year):		2026	Estimated Replacement (year):			
	Current Inspection Load Rating:	64	Design Load GVW (tonnes):	64	Design Vehicle Config.:	BCL62	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/02 08:36:49			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 182 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-231	Structure Name:	G1-910	Road Name:	SUTHERLAND	Inspection Date:	2020/10/08
KM:	8.10	User km:	0.00	Crossing Name:	Unknown	Next Inspection Date:	2023/10/08
Project File ID #:	1795	Br.	17	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	20.3	# Spans:	1	Span Width:	Span Length(s) (metres):		20
UTM Zone:	10	UTM Easting:	377949	UTM Northing:	6028232		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2019		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Fair	left side blocks are leaning in towards stream, right side blocks have bulging
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Fair	

APPROACHES

Alignment	Poor	hills and S corners pothe sides
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	100	should be L75

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 183 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-231	Structure Name:	G1-910	Road Name:	SUTHERLAND	Inspection Date:	2020/10/08			
Road Surface		Fair								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Deck to Girder Bolts		Good								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Good								
Running Planks		Good								
Sub Deck		Good								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Good								
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 184 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-231	Structure Name:	G1-910	Road Name:	SUTHERLAND	Inspection Date:	2020/10/08
MONITORS	#	Description					
GENERAL	Inspector's Comment:	Left Lock Block wall is leaning in. Ed Folk from Celtic Engineering was on site for the duration of this bridge installation and acted as POR. The lean in the lock block abutment occurred during the installation, not after. Sean Baumann was on site most of the time as well and expressed some concern to Ed about the lean in the lock blocks, but Ed assured us that this was OK, and he had no issue approving the installation as it was. (comments from Ken Yorston)					
GENERAL	PEng's Comment:	bridge appears in ok condition.					
GENERAL	Estimated Load Restriction (year):		2029		Estimated Replacement (year):		
	Current Inspection Load Rating:		68		Design Load GVW (tonnes):		91
					Design Vehicle Config.:		L100
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/01/22 15:08:10			

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 185 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-232	Structure Name:	G5-298	Road Name:	SUTHERLAND	Inspection Date:	2020/10/08
KM:	10.50	User km:	0.00	Crossing Name:	Unknown	Next Inspection Date:	2023/10/08
Project File ID #:	1795	Br.	17	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	10	UTM Easting:	377027	UTM Northing:	6029840		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2018		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	bottom of hill
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	100	
Road Surface	Fair	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 186 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-232	Structure Name:	G5-298	Road Name:	SUTHERLAND	Inspection Date:	2020/10/08
---------	--------	-----------------	--------	------------	------------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Good
----------------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Not Applicable
----------------	----------------

Sub Deck	Good
----------	------

Ties	Good
------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Excellent
----------	-----------

Under Trussing	Good
----------------	------

CHANNEL

Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	1.0
Estimated High Water Level Clearance:	0.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 187 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-232	Structure Name:	G5-298	Road Name:	SUTHERLAND	Inspection Date:	2020/10/08
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Looks ok					
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/02 08:42:42			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 188 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-161	Structure Name:	G5-161	Road Name:	HAT	Inspection Date:	2020/10/09
KM:	5293.00	User km:	5.20	Crossing Name:	Un-named	Next Inspection Date:	2023/10/09
Project File ID #:	6057	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,900			Outlet Cover (mm):	2,100		
Footing Type:	Steel Footing			Gradient (%):	2.0		
Culvert Length (metres):	28.0	Opening Height (mm):	2,500	Opening Width (mm):	3,400		
UTM Zone:	10	UTM Easting:	420713	UTM Northing:	6069554		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	2019		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Excellent	
Embedment Materials	Good	
Fill	Good	
Floor	Not Applicable	
Footing	Unrated	Buried
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 189 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-161	Structure Name:	G5-161	Road Name:	HAT	Inspection Date:	2020/10/09			
Inlet	Good									
Outlet	Good									
Overall	Good									
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	3.0						
	Estimated High Water Level Clearance:	0.6								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	Beaver activity								
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Culvert looks good. Need to get certification documents from industry. Conceptual drawings indicate L100								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 190 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-161	Structure Name:	G5-161	Road Name:	HAT	Inspection Date:	2020/10/09	
GENERAL	Estimated Load Restriction (year):		2064	Estimated Replacement (year):				
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/03/19 12:06:11		

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 191 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-160	Structure Name:	G5-160A	Road Name:	HAT	Inspection Date:	2019/09/05
KM:	4.00	User km:	42.90	Crossing Name:	Tezzeron Creek	Next Inspection Date:	2022/09/05
Project File ID #:	6057	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	36.6	# Spans:	1	Span Width:	Span Length(s) (metres):		36
UTM Zone:	10	UTM Easting:	421930	UTM Northing:	6070343		
Inspector Name:	dawson smith			Year Superstructure Installed:	2015		
Access:	42.9 km Germanson Hat FSR @ 39 km North Road						

ABUTMENTS

Bearings Good

Bracing Good

Ballast Wall Good

Corrosion Protection Not Applicable

Caps or Sills Good

Fill Good

Hardware Not Applicable

Piles or Posts Good

Riprap Good

Wing Wall Good

APPROACHES

Alignment Good

Bridge Ahead Signs Missing 0

Brushing Required No

Delineator Missing Left (approaching structure) 0

Delineator Missing Right (approaching structure) 0

Fender Condition Good

Road Surface Good

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 192 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-160	Structure Name:	G5-160A	Road Name:	HAT	Inspection Date:	2019/09/05
---------	--------	-----------------	---------	------------	-----	------------------	------------

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Good
---------------	------

Hardware	Not Applicable
----------	----------------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Not Applicable
----------	----------------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	5.0
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	4.0
---------------------------------------	-----

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$ 400.00	ADD LOAD LIMIT SIGN

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 193 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-160	Structure Name:	G5-160A	Road Name:	HAT	Inspection Date:	2019/09/05
GENERAL	Inspector's Comment:	BRIDGE AHEAD SIGNS BUT NO LOAD LIMIT					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2060	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/11 15:41:43			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 194 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-150	Structure Name:	G5-150	Road Name:	CRIPPLE	Inspection Date:	2019/09/11
KM:	13.00	User km:	413.00	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/09/11
Project File ID #:	6057	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	19.0	Opening Height (mm):	3,000	Opening Width (mm):	3,000		
UTM Zone:	10	UTM Easting:	436365	UTM Northing:	6082216		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1984		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Not Applicable	
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Fair	NEEDS BRUSHING
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 195 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-150	Structure Name:	G5-150	Road Name:	CRIPPLE	Inspection Date:	2019/09/11			
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	NEEDS BRUSHING								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):		2034		Estimated Replacement (year):					
	Current Inspection Load Rating:		68		Design Load GVW (tonnes):		54		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/01/27 12:40:19			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 196 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-151	Structure Name:	G5-151A	Road Name:	CRIPPLE	Inspection Date:	2020/05/21
KM:	26.50	User km:	426.50	Crossing Name:	Salmon River	Next Inspection Date:	2023/05/21
Project File ID #:	6057	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	16.7	# Spans:	1	Span Width:			Span Length(s) (metres): 16
UTM Zone:	10		UTM Easting:	448687	UTM Northing:	6084435	
Inspector Name:	Vince Sewell			Year Superstructure Installed:	2016		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Unrated	can't see
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	faded, replce
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	High chane downstream pulled apart but still in place
Posted Load Rating (Enter 0 if sign missing)	100	
Road Surface	Good	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 197 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-151	Structure Name:	G5-151A	Road Name:	CRIPPLE	Inspection Date:	2020/05/21
---------	--------	-----------------	---------	------------	---------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Fair	soled but showing wear
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	1.2	Estimated Present Water Level Width:	10.0
Estimated High Water Level Clearance:	1.2		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
3	Required	High		high chain downstream

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 198 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-151	Structure Name:	G5-151A	Road Name:	CRIPPLE	Inspection Date:	2020/05/21
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	looks good					
GENERAL	Estimated Load Restriction (year):		2051	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):		Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/01 11:34:46			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 199 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-170	Structure Name:	G5-170	Road Name:	INDATA	Inspection Date:	2021/09/22
KM:	2.40	User km:	0.00	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/09/22
Project File ID #:	6057	Br.	04	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	2,000			Outlet Cover (mm):	2,000		
Footing Type:				Gradient (%):	1.0		
Culvert Length (metres):	21.0	Opening Height (mm):	2,000	Opening Width (mm):	2,000		
UTM Zone:	10	UTM Easting:	417676	UTM Northing:	6121617		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1990		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Not Applicable	
Footing	Not Applicable	
Head Wall	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 200 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-170	Structure Name:	G5-170	Road Name:	INDATA	Inspection Date:	2021/09/22
Inlet	Good	overflow pipe plugged					
Outlet	Good						
Overall	Fair						
Riprap	Not Applicable						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Good						

CHANNEL	Estimated Present Water Level Depth:		1.5		Estimated Present Water Level Width:		1.5			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	3	Required	Medium	\$	Clean inlet of overflow pipe					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	overflow pipe plugged by beavers Unable to confirm culvert ratings due to flooded channel. Note heavy rust in pictures on inside and outside of pipes. GZ								
GENERAL	PEng's Comment:	No major concerns. BH								

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 201 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-170	Structure Name:	G5-170	Road Name:	INDATA	Inspection Date:	2021/09/22
---------	--------	-----------------	--------	------------	--------	------------------	------------

GENERAL

Estimated Load Restriction (year):	2030	Estimated Replacement (year):	
Current Inspection Load Rating:	54	Design Load GVW (tonnes):	54
Design Vehicle Config.:			
Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/05 11:22:51

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 202 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-174	Structure Name:	G5-174-2	Road Name:	INDATA	Inspection Date:	2021/09/08
KM:	13.10	User km:	12.30	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/09/08
Project File ID #:	6057	Br.	04	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Pipe Arch			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,500			Outlet Cover (mm):	1,600		
Footing Type:				Gradient (%):	1.0		
Culvert Length (metres):	16.0	Opening Height (mm):	1,500	Opening Width (mm):	1,500		
UTM Zone:	10	UTM Easting:	408418	UTM Northing:	6121009		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1990		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Unrated	None
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Head Wall	Not Applicable	
Inlet	Fair	Large piece of riprap in front of inlet
Outlet	Good	
Overall	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 203 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-174	Structure Name:	G5-174-2	Road Name:	INDATA	Inspection Date:	2021/09/08			
Riprap	Fair									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		3.2			
	Estimated High Water Level Clearance:		0.4							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	Yes
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	3	Required	Medium		Remove large rock from inlet					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	No major concerns.								
GENERAL	Estimated Load Restriction (year):			2025		Estimated Replacement (year):				
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		Design Vehicle Config.:		L100	
	Professional Inspection Required?		No		Report Status:		Reviewed By Bruce Henderson on 2022/02/06 09:01:47			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 204 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-174	Structure Name:	G5-174	Road Name:	INDATA	Inspection Date:	2021/09/08
KM:	13.10	User km:	12.30	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/09/08
Project File ID #:	6057	Br.	04	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):	1.0		
Culvert Length (metres):	16.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	408418	UTM Northing:	6121009		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1990		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Unrated	None
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Unrated	Buried
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 205 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-174	Structure Name:	G5-174	Road Name:	INDATA	Inspection Date:	2021/09/08			
Overall	Good									
Riprap	Fair									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	3.2						
	Estimated High Water Level Clearance:	0.4								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	Yes
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	No major issues. BH								
GENERAL	Estimated Load Restriction (year):	2026	Estimated Replacement (year):							
	Current Inspection Load Rating:	54	Design Load GVW (tonnes):	54	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/06 13:58:11						

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 206 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-175	Structure Name:	G5-175	Road Name:	INDATA	Inspection Date:	2021/09/22
KM:	15.50	User km:	16.00	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/09/22
Project File ID #:	6057	Br.	04	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	800			Outlet Cover (mm):	800		
Footing Type:				Gradient (%):			
Culvert Length (metres):	15.0	Opening Height (mm):	2,400	Opening Width (mm):	2,400		
UTM Zone:	10	UTM Easting:	406998	UTM Northing:	6118776		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1999		
Access:							

APPROACHES		
Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT		
Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Not Applicable	
Footing	Not Applicable	
Head Wall	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 207 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-175	Structure Name:	G5-175	Road Name:	INDATA	Inspection Date:	2021/09/22
Inlet	Good						
Outlet	Good						
Overall	Good						
Riprap	Not Applicable						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						

CHANNEL	Estimated Present Water Level Depth:			0.5		Estimated Present Water Level Width:			0.5	
	Estimated High Water Level Clearance:			1.0						
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	3	monitor beaver activity upstream								
GENERAL	Inspector's Comment:	beaver dam approx. 10 yards up stream No issues. GZ								
GENERAL	PEng's Comment:									

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 208 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-175	Structure Name:	G5-175	Road Name:	INDATA	Inspection Date:	2021/09/22
GENERAL	Estimated Load Restriction (year):		2040	Estimated Replacement (year):			
	Current Inspection Load Rating:		54	Design Load GVW (tonnes):		54	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/06 09:24:14	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 209 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-171	Structure Name:	G5-171	Road Name:	INDATA	Inspection Date:	2021/09/22
KM:	18.80	User km:	18.80	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/09/22
Project File ID #:	6057	Br.	04	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	15.7	# Spans:	1	Span Width:	Span Length(s) (metres):		15.7
UTM Zone:	10	UTM Easting:	404918	UTM Northing:	6118072		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1999		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	some out of place
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Fair	needs grading

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 210 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-171	Structure Name:	G5-171	Road Name:	INDATA	Inspection Date:	2021/09/22
---------	--------	-----------------	--------	------------	--------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	need replaced
Deck Joints	Good	
Grout Pockets	Not Applicable	deck muddy
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Poor	riser blocks need replaced

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	2.0
	Estimated High Water Level Clearance:	2.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	4	Required	High		Replace riser blocks
	5	Required	Medium		Install bridge ahead signs both sides
	7	Required	Medium		Install 1 delineator
	8	Required	Medium		Reposition fenders

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 211 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-171	Structure Name:	G5-171	Road Name:	INDATA	Inspection Date:	2021/09/22
---------	--------	-----------------	--------	------------	--------	------------------	------------

MONITORS

#	Description

GENERAL

Inspector's Comment:	Riser blocks show significant decay, they need to be replaced No significant issues other than rotten riser blocks. GZ
----------------------	---

GENERAL

PEng's Comment:	
-----------------	--

GENERAL

Estimated Load Restriction (year):	2040	Estimated Replacement (year):			
Current Inspection Load Rating:	68	Design Load GVW (tonnes):	68	Design Vehicle Config.:	L75
Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/05 11:42:29		

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 212 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-172	Structure Name:	G5-172	Road Name:	INDATA	Inspection Date:	2021/09/08
KM:	19.10	User km:	19.10	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/09/08
Project File ID #:	6057	Br.	04	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Pipe Arch			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	2,000			Outlet Cover (mm):	2,200		
Footing Type:				Gradient (%):	2.0		
Culvert Length (metres):	15.0	Opening Height (mm):	1,000	Opening Width (mm):	1,550		
UTM Zone:	10	UTM Easting:	410310	UTM Northing:	6122282		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1990		
Access:	Minor culvert on Apollo Permit R09277.I						

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Fair	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Fair	
Floor	Fair	
Head Wall	Not Applicable	
Inlet	Fair	
Outlet	Good	
Overall	Good	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 213 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-172	Structure Name:	G5-172	Road Name:	INDATA	Inspection Date:	2021/09/08			
Riprap	Not Applicable									
Roof	Good									
Side Walls	Fair									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		0.6			
	Estimated High Water Level Clearance:		0.3							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	Beavers have a dam around inlet. Does not block inlet.								
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	A minor pipe arch. Set to do not inspect.								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):			2040		Estimated Replacement (year):				
	Current Inspection Load Rating:		54		Design Load GVW (tonnes):		54		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Bruce Henderson on 2022/02/10 16:41:50			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 214 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-173	Structure Name:	G5-173	Road Name:	INDATA	Inspection Date:	2001/09/12
KM:	26.20	User km:	23.00	Crossing Name:	Unnamed creek	Next Inspection Date:	2030/01/01
Project File ID #:	6057	Br.	04	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	500			Outlet Cover (mm):	500		
Footing Type:				Gradient (%):	1.5		
Culvert Length (metres):	18.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	417252	UTM Northing:	6121918		
Inspector Name:	Tim Silbernagel			Year Superstructure Installed:	1990		
Access:	Stay left at 25.1 km Junction with Chuchi Road. Minor culvert						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Good	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 215 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-173	Structure Name:	G5-173	Road Name:	INDATA	Inspection Date:	2001/09/12			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	2	Suggested	Medium	\$ 0.00	Span: 1.0. Debris removal. Remove log at inlet.					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	nullCulvert: 1)log at inlet 2) 15 cm drop to small plunge pool.								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):			2040	Estimated Replacement (year):					
	Current Inspection Load Rating:		54	Design Load GVW (tonnes):		54	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/12 14:46:08				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 216 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-190	Structure Name:	G5-190	Road Name:	TSILCOH	Inspection Date:	2021/09/21
KM:	11.80	User km:	11.80	Crossing Name:	Tsilcoh River	Next Inspection Date:	2024/09/21
Project File ID #:	6057	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	18.3	# Spans:	1	Span Width:	Span Length(s) (metres):		18.3
UTM Zone:	10	UTM Easting:	435597	UTM Northing:	6072016		
Inspector Name:	Dawson Smith		Year Superstructure Installed:	2002			
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	some out of place or missing
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Fair	needs grading

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 217 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-190	Structure Name:	G5-190	Road Name:	TSILCOH	Inspection Date:	2021/09/21
---------	--------	-----------------	--------	------------	---------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Good	
Deck Joints	Good	
Grout Pockets	Not Applicable	(Rate as GOOD. GZ)
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	2.0
	Estimated High Water Level Clearance:	2.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
4	Required	High	\$ 0.00	Realign approach fenders
5	Required	Medium		Install all 4 delineators
6	Required	High		Install both bridge ahead signs
8	Required	Medium	\$ 0.00	Grade approaches

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 218 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-190	Structure Name:	G5-190	Road Name:	TSILCOH	Inspection Date:	2021/09/21
MONITORS	#	Description					
GENERAL	Inspector's Comment:	No issues. GZ					
GENERAL	PEng's Comment:	No concerns. BH					
GENERAL	Estimated Load Restriction (year):		2045		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:		L100				
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/06 14:32:32			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 219 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-207	Structure Name:	G5-302	Road Name:	NORTH SALMON	Inspection Date:	2020/05/12
KM:	4.50	User km:	10.50	Crossing Name:	Unnamed	Next Inspection Date:	2022/05/12
Project File ID #:	6057	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Steel I-beam				Right	Crib, Log or Untreated Timber	
Total Length (metres):	9.1	# Spans:	1	Span Width:			Span Length(s) (metres): 9.1
UTM Zone:	10		UTM Easting:	447065	UTM Northing:	6094073	
Inspector Name:	Vince Sewell			Year Superstructure Installed:	2020		
Access:	Bridge is on BR. 36. update once RRS-CBR issues resolved. LNH						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Good	log sills
Fill	Good	
Hardware	Good	
Log/Timber Cribs	Unrated	N/A
Piles or Posts	Not Applicable	
Riprap	Good	
Tie-backs	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 220 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-207	Structure Name:	G5-302	Road Name:	NORTH SALMON	Inspection Date:	2020/05/12			
Posted Load Rating (Enter 0 if sign missing)	0									
Road Surface	Fair									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Excellent									
Running Planks	Good									
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Not Applicable									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		0.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 221 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-207	Structure Name:	G5-302	Road Name:	NORTH SALMON	Inspection Date:	2020/05/12
MONITORS	#	Description					
GENERAL	Inspector's Comment:	change user kms location to 10.5km					
GENERAL	PEng's Comment:	looks ok					
GENERAL	Estimated Load Restriction (year):		2034		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:		L100				
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/02 09:43:22			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 222 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-180	Structure Name:	G5-180	Road Name:	NORTH SALMON	Inspection Date:	2021/07/07
KM:	4.70	User km:	604.70	Crossing Name:	Salmon River	Next Inspection Date:	2024/07/07
Project File ID #:	6057	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Binwall	
Superstructure:	Steel I-beam				Right	Binwall	
Total Length (metres):	16.0	# Spans:	1	Span Width:			Span Length(s) (metres): 16
UTM Zone:	10		UTM Easting:	446165	UTM Northing:	6088323	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1991		
Access:							

ABUTMENTS		
Bearings	Good	
Binwall	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES		
Alignment	Fair	Right Side corner, left side hill and corner
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	
Posted Load Rating (Enter 0 if sign missing)	68	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 223 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-180	Structure Name:	G5-180	Road Name:	NORTH SALMON	Inspection Date:	2021/07/07			
Road Surface		Fair								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Fair		Broken curb and post. Damaged curb						
Deck to Girder Bolts		Good								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Fair								
Running Planks		Good		Some wear from trucks with chains						
Sub Deck		Good		Creosode						
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Good								
CHANNEL	Estimated Present Water Level Depth:		0.6		Estimated Present Water Level Width:		4.0			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 224 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-180	Structure Name:	G5-180	Road Name:	NORTH SALMON	Inspection Date:	2021/07/07
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	No concerns. BH					
GENERAL	Estimated Load Restriction (year):		2031	Estimated Replacement (year):			
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		54	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/06 14:13:18	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 225 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-183	Structure Name:	G5-919	Road Name:	S SIDE TEZZERON	Inspection Date:	2021/09/22
KM:	6.30	User km:	6.30	Crossing Name:	Unnamed	Next Inspection Date:	2024/09/22
Project File ID #:	6057	Br.	14	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:			Span Length(s) (metres): 12.2
UTM Zone:	10		UTM Easting:	412526	UTM Northing:	6057091	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1999		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Concrete Precast	Unrated	Lock blocks, good
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 226 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-183	Structure Name:	G5-919	Road Name:	S SIDE TEZZERON	Inspection Date:	2021/09/22
---------	--------	-----------------	--------	------------	-----------------	------------------	------------

Posted Load Rating (Enter 0 if sign missing)	68	
--	----	--

Road Surface	Fair	needs grading
--------------	------	---------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Good	
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.0	Estimated Present Water Level Width:	0.0
	Estimated High Water Level Clearance:	1.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	beaver dam under structure								

REPAIRS	#	Status	Priority	Estimate	Description
	2	Required	Medium	\$ 0.00	Remove Beaver dam
	3	Required	Medium	\$ 0.00	Repair approach fill.

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 227 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-183	Structure Name:	G5-919	Road Name:	S SIDE TEZZERON	Inspection Date:	2021/09/22	
MONITORS	#	Description						
GENERAL	Inspector's Comment:	beaver dam under structure No significant issues other than beaver dam. GZ						
GENERAL	PEng's Comment:	No concerns. BH						
GENERAL	Estimated Load Restriction (year):		2025		Estimated Replacement (year):		2025	
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.:	L75
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/01/24 13:37:47		

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 228 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-005	Structure Name:	G5-921	Road Name:	OLD CINNABAR	Inspection Date:	2021/09/22
KM:	0.60	User km:	0.60	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/09/22
Project File ID #:	6057	Br.	15	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:	Span Length(s) (metres):		12.2
UTM Zone:	10		UTM Easting:	413298	UTM Northing:	6056752	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1999		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	some out of place
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 229 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-005	Structure Name:	G5-921	Road Name:	OLD CINNABAR	Inspection Date:	2021/09/22			
Road Surface	Fair	needs grading								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Poor	(Rate as poor for rot. GZ)								
Deck to Girder Bolts	Good									
Hardware	Fair									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Fair									
Running Planks	Fair	(rated as FAIR. GZ)								
Sub Deck	Good	(none)								
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		1.0		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 230 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-005	Structure Name:	G5-921	Road Name:	OLD CINNABAR	Inspection Date:	2021/09/22	
REPAIRS	#	Status	Priority	Estimate	Description			
	7	Required	Medium	\$ 0.00	Brushing required.			
	8	Required	Medium	\$ 0.00	Install bridge ahead signs.			
	9	Required	Medium	\$ 0.00	Cap and grade approaches			
	10	Required	Medium	\$ 0.00	Realign approach fenders			
	11	Required	High		Replace rotten sections of curbs.			
MONITORS	#	Description						
	4	monitor guardrail and riser blocks for decay, see pics						
	5	Monitor deck and subdeck for rot.						
GENERAL	Inspector's Comment:	Deck and rails look rotten. Suggest load restrictions. Flagged for in-house inspection next summer. GZ						
GENERAL	PEng's Comment:	Repairs should be done to rails and deck. Down rating is possible at any time. Flagged for P.Eng Inspection 2022. BH						
GENERAL	Estimated Load Restriction (year):			2025	Estimated Replacement (year):			
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.:	L75
	Professional Inspection Required?		Yes	Report Status:		Reviewed By Bruce Henderson on 2022/01/20 14:27:38		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 231 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-194	Structure Name:	G5-194	Road Name:	A74600	Inspection Date:	2010/06/23
KM:	1.00	User km:		Crossing Name:	unnamed	Next Inspection Date:	2012/06/23
Project File ID #:	6057	Br.	25	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.0	# Spans:	1	Span Width:	Span Length(s) (metres):		9
UTM Zone:	10	UTM Easting:	426866	UTM Northing:	6066919		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:			
Access:	Note: Bridge Deactivated as identified by Warren Wilkinson August 29, 2012.						

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	both approaches come off corners
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 232 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-194	Structure Name:	G5-194	Road Name:	A74600	Inspection Date:	2010/06/23
---------	--------	-----------------	--------	------------	--------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Not Applicable	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Not Applicable	
Sub Deck	Unrated	cover with dirt
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.0
Estimated High Water Level Clearance:	1.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:	No Flow - Still water								

REPAIRS

#	Status	Priority	Estimate	Description

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 233 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-194	Structure Name:	G5-194	Road Name:	A74600	Inspection Date:	2010/06/23
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments					
GENERAL	Estimated Load Restriction (year):		2020	Estimated Replacement (year):			
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):		Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Accepted By Raymond Getzlaf on 2012/04/12 00:00:00			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 234 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-199	Structure Name:	G5-979	Road Name:	COHO	Inspection Date:	2016/07/07
KM:	1.20	User km:	1.20	Crossing Name:	Unknown	Next Inspection Date:	2016/07/07
Project File ID #:	6057	Br.	32	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):				Outlet Cover (mm):			
Footing Type:				Gradient (%):			
Culvert Length (metres):	14.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	444673	UTM Northing:	6088200		
Inspector Name:	Donovan J. A. Melin			Year Superstructure Installed:			
Access:	Minor culvert						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	minor rust
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	minor rust
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 235 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-199	Structure Name:	G5-979	Road Name:	COHO	Inspection Date:	2016/07/07			
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Culvert is in good condition.								
GENERAL	PEng's Comment:	Need to verify if this is a culvert or a bridge at the location.								
GENERAL	Estimated Load Restriction (year):			2030		Estimated Replacement (year):				
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		Design Vehicle Config.:			
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2017/01/19 10:01:43			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 236 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-181	Structure Name:	G5-181	Road Name:	COHO	Inspection Date:	2021/07/07
KM:	3.90	User km:	3.90	Crossing Name:	unnamed	Next Inspection Date:	2024/07/07
Project File ID #:	6057	Br.	32	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:			Span Length(s) (metres): 12.2
UTM Zone:	10		UTM Easting:	443529	UTM Northing:	6089428	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2009		
Access:							

ABUTMENTS

Bearings	Poor	Due to shifting of blocks not level on concrete
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Poor	Shifted
Corrosion Protection	Not Applicable	
Caps or Sills	Unrated	No sill
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Fair	Needs more to lock in
Wing Wall	Good	

APPROACHES

Alignment	Poor	Bottom of steep hill both sides
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 237 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-181	Structure Name:	G5-181	Road Name:	COHO	Inspection Date:	2021/07/07			
Road Surface		Good								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Deck to Girder Bolts		Good								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Fair								
Running Planks		Good								
Sub Deck		Good								
Ties		Fair		Ties have been reused rotated 180?						
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Fair		Girders resting on edge of blocks						
Hardware		Good								
Under Trussing		Good								
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 238 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-181	Structure Name:	G5-181	Road Name:	COHO	Inspection Date:	2021/07/07
---------	--------	-----------------	--------	------------	------	------------------	------------

MONITORS

#	Description

GENERAL

Inspector's Comment:	Professional Inspection required Active logging on road proposed BCTS blocks past bridge possible Canfor blocks
----------------------	--

GENERAL

PEng's Comment:	Good condition. BH
-----------------	--------------------

GENERAL

Estimated Load Restriction (year):	2030	Estimated Replacement (year):			
Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100
Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/06 14:19:03		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 239 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-200	Structure Name:	G5-980	Road Name:	COHO	Inspection Date:	2021/07/07
KM:	5.40	User km:	5.40	Crossing Name:	Unknown	Next Inspection Date:	2024/07/07
Project File ID #:	6057	Br.	32	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	18.0	# Spans:	1	Span Width:	Span Length(s) (metres):		18
UTM Zone:	10	UTM Easting:	443781	UTM Northing:	6090623		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2008		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Fair	Washing right upstream between fender and bridge
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Good	

APPROACHES

Alignment	Poor	Steep Hill both sides corner at top of one
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 240 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-200	Structure Name:	G5-980	Road Name:	COHO	Inspection Date:	2021/07/07			
Road Surface		Fair	Wilderness							
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Deck to Girder Bolts		Good								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Good								
Running Planks		Good								
Sub Deck		Good								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Good								
CHANNEL	Estimated Present Water Level Depth:		0.2	Estimated Present Water Level Width:		1.5				
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 241 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-200	Structure Name:	G5-980	Road Name:	COHO	Inspection Date:	2021/07/07
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	No concerns. BH					
GENERAL	Estimated Load Restriction (year):		2048	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/06 14:37:19	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 242 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-202	Structure Name:	G5-981	Road Name:	COHO	Inspection Date:	2021/07/07
KM:	5.70	User km:	5.70	Crossing Name:	Unnamed Creek	Next Inspection Date:	2024/07/07
Project File ID #:	6057	Br.	32	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.0	# Spans:	1	Span Width:			Span Length(s) (metres): 12
UTM Zone:	10		UTM Easting:	443985	UTM Northing:	6091142	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2010		
Access:							

ABUTMENTS		
Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	Settling
Corrosion Protection	Not Applicable	Sheet Rust
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Good	
APPROACHES		
Alignment	Poor	Bottom of hill with corners both sides
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	Left side nose cones knocked off road surface
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Fair	Wilderness level.

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 243 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-202	Structure Name:	G5-981	Road Name:	COHO	Inspection Date:	2021/07/07
---------	--------	-----------------	--------	------------	------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Good
----------------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Good
----------------	------

Sub Deck	Good
----------	------

Ties	Good
------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good	Rust Forming
---------	------	--------------

Hardware	Good
----------	------

Under Trussing	Good
----------------	------

CHANNEL

Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.5
Estimated High Water Level Clearance:	1.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 244 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-202	Structure Name:	G5-981	Road Name:	COHO	Inspection Date:	2021/07/07
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	No concerns. BH					
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:	68	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/06 14:43:16			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 245 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-201	Structure Name:	G5-982	Road Name:	COHO	Inspection Date:	2018/09/25
KM:	5.90	User km:	5.90	Crossing Name:	Unknown	Next Inspection Date:	2022/09/01
Project File ID #:	6057	Br.	32	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:	Span Length(s) (metres):		12.2
UTM Zone:	10		UTM Easting:	443910	UTM Northing:	6091022	
Inspector Name:	Adam Mathison, GradTech			Year Superstructure Installed:	2008		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Good	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Fair	Not in line with guardrails
Road Surface	Fair	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 246 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-201	Structure Name:	G5-982	Road Name:	COHO	Inspection Date:	2018/09/25
---------	--------	-----------------	--------	------------	------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	Starting to rot
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Fair	Rotting
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	0.4
Estimated High Water Level Clearance:	2.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	High	\$	Install 2 bridge ahead signs and 4 delineators
2	Required	Medium	\$	Reposition fenders
3	Required	High	\$	Replace wear deck prior to industrial use

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 247 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-201	Structure Name:	G5-982	Road Name:	COHO	Inspection Date:	2018/09/25
MONITORS	#	Description					
GENERAL	Inspector's Comment:	Bridge is in overall fair condition. Requires all delineators. Replace wear deck prior to industrial use. Stand up fallen bridge ahead signs. Structure is at 5.7km on unknown road off the North Salmon FSR. Structure G5-982 is at this site, not G5-981.					
GENERAL	PEng's Comment:	Inspector is correct, this is structure G5-982. Comments and repairs from this inspection are for this site.					
GENERAL	Estimated Load Restriction (year):		2045	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Ross Hyam on 2018/12/10 11:15:52			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 248 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-205	Structure Name:	G4-952	Road Name:	KILNER CREEK	Inspection Date:	2019/09/11
KM:	0.20	User km:	0.20	Crossing Name:	UNNAMED	Next Inspection Date:	2022/09/11
Project File ID #:	6057	Br.	35	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	10		UTM Easting:	436142	UTM Northing:	6082392	
Inspector Name:	Dawson SMITH			Year Superstructure Installed:			
Access:							

ABUTMENTS

Bearings	Good
----------	------

Bracing	Good
---------	------

Ballast Wall	Good
--------------	------

Concrete Lock Blocks	Good
----------------------	------

Corrosion Protection	Not Applicable
----------------------	----------------

Caps or Sills	Good
---------------	------

Fill	Good
------	------

Hardware	Not Applicable
----------	----------------

Piles or Posts	Not Applicable
----------------	----------------

Riprap	Fair
--------	------

Wing Wall	Not Applicable
-----------	----------------

APPROACHES

Alignment	Good
-----------	------

Bridge Ahead Signs Missing	0
----------------------------	---

Brushing Required	Yes
-------------------	-----

Delineator Missing Left (approaching structure)	0
---	---

Delineator Missing Right (approaching structure)	0
--	---

Fender Condition	Good
------------------	------

Road Surface	Good
--------------	------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 249 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-205	Structure Name:	G4-952	Road Name:	KILNER CREEK	Inspection Date:	2019/09/11
---------	--------	-----------------	--------	------------	--------------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Not Applicable	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Fair	NEEDS REDECKING
Running Planks	Fair	NEEDS REDECKING
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.0	Estimated Present Water Level Width:	0.0
Estimated High Water Level Clearance:	2.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$ 250.00	ADD LOAD LIMIT SIGN
2	Required	Medium	\$	RE DECK
3	Required	Low	\$ 500.00	BRUSHING

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 250 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-205	Structure Name:	G4-952	Road Name:	KILNER CREEK	Inspection Date:	2019/09/11
---------	--------	-----------------	--------	------------	--------------	------------------	------------

MONITORS

#	Description

GENERAL

Inspector's Comment:	BRIDGE AHEAD SIGNS BUT NO LOAD LIMITS, NEEDS RE DECKED AND BRUSHING, TOO BRUSHED IN TO GET GOOD CROSSING PICTURES
----------------------	---

GENERAL

PEng's Comment:	
-----------------	--

GENERAL

Estimated Load Restriction (year):	2032	Estimated Replacement (year):	
Current Inspection Load Rating:	64	Design Load GVW (tonnes):	64
Design Vehicle Config.:	CL625	Professional Inspection Required?	No
Report Status:	Reviewed By Jason Olmsted on 2020/03/06 13:55:46		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 251 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-206	Structure Name:	G5-994	Road Name:	KILNER CREEK	Inspection Date:	2019/09/11
KM:	1.70	User km:	1.70	Crossing Name:	UNNAMED	Next Inspection Date:	2022/09/11
Project File ID #:	6057	Br.	35	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.0	# Spans:	1	Span Width:			Span Length(s) (metres): 12
UTM Zone:	10		UTM Easting:	435915		UTM Northing:	6083719
Inspector Name:	dawson smith			Year Superstructure Installed:			
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Not Applicable	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	
Fill	Fair	BOTH APPROACHES HAVE MINOR SLUFFING
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	LOG FENDERS
Road Surface	Fair	SLUFFED AT BOTH ENDS OF STRUCTURE

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 252 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-206	Structure Name:	G5-994	Road Name:	KILNER CREEK	Inspection Date:	2019/09/11
---------	--------	-----------------	--------	------------	--------------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	MONITOR ROT
------------------------	------	-------------

Deck to Girder Bolts	Not Applicable
----------------------	----------------

Hardware	Not Applicable
----------	----------------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Nails	Fair
-------	------

Overall Deck Condition	Fair
------------------------	------

Running Planks	Fair
----------------	------

Sub Deck	Fair
----------	------

Ties	Fair
------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Not Applicable
----------	----------------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	0.1
Estimated High Water Level Clearance:	2.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$ 250.00	ADD LOAD LIMIT SIGN
2	Required	Low	\$ 500.00	BRUSH

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 253 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-206	Structure Name:	G5-994	Road Name:	KILNER CREEK	Inspection Date:	2019/09/11
---------	--------	-----------------	--------	------------	--------------	------------------	------------

MONITORS

#	Description
1	MONITOR GUARD RAIL ROT

GENERAL

Inspector's Comment:	LOG FENDERS, GUARDRAILS HAVE SOME DECAY, NEEDS BRUSHING, LOAD LIMIT SIGN AND COULD BE GRADED
----------------------	--

GENERAL

PEng's Comment:	
-----------------	--

GENERAL

Estimated Load Restriction (year):			2032	Estimated Replacement (year):					
Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68		Design Vehicle Config.:		L75
Professional Inspection Required?		No	Report Status:	Reviewed By Jason Olmsted on 2020/03/06 13:53:10					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 254 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-204	Structure Name:	G5-924	Road Name:	WAMPUM	Inspection Date:	2021/07/07
KM:	3.10	User km:	3.10	Crossing Name:	Unnamed	Next Inspection Date:	2024/07/07
Project File ID #:	6057	Br.	36	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	15.0	# Spans:	1	Span Width:			Span Length(s) (metres): 15
UTM Zone:	10		UTM Easting:	446820	UTM Northing:	6092971	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2014		
Access:							

ABUTMENTS

Bearings	Fair	left side not sitting flat on sill
Bracing	Not Applicable	
Ballast Wall	Fair	Rot found i un-pealed logs
Concrete Lock Blocks	Fair	Some settling. gaps between sill timbers, uneven gaps between blocks
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Fair	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Good	

APPROACHES

Alignment	Poor	Steep hills and corners both sides
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	
Posted Load Rating (Enter 0 if sign missing)	68	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 255 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-204	Structure Name:	G5-924	Road Name:	WAMPUM	Inspection Date:	2021/07/07			
Road Surface		Fair	wilderness level							
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Deck to Girder Bolts		Good	Clips							
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Good								
Running Planks		Not Applicable								
Sub Deck		Fair								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Not Applicable								
Under Trussing		Good								
CHANNEL	Estimated Present Water Level Depth:		0.4	Estimated Present Water Level Width:		2.5				
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	5	Required	High		Install both bridge ahead signs.					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 256 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-204	Structure Name:	G5-924	Road Name:	WAMPUM	Inspection Date:	2021/07/07
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	No concerns. BH					
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.: L75
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/06 15:21:49	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 257 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-470	Structure Name:	G5-470-2	Road Name:	TEARDROP	Inspection Date:	2021/09/21
KM:	47.50	User km:	450.20	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/09/01
Project File ID #:	6480	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,300			Outlet Cover (mm):	1,300		
Footing Type:				Gradient (%):			
Culvert Length (metres):	21.0	Opening Height (mm):	1,200	Opening Width (mm):	1,200		
UTM Zone:	10	UTM Easting:	463645	UTM Northing:	6023597		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1972		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	
Footing	Not Applicable	
Head Wall	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 258 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-470	Structure Name:	G5-470-2	Road Name:	TEARDROP	Inspection Date:	2021/09/21			
Inlet	Fair									
Outlet	Fair									
Overall	Fair									
Riprap	Not Applicable									
Roof	Fair									
Side Walls	Fair									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	culvert is showing rust								
REPAIRS	#	Status	Priority	Estimate	Description					
	3	Suggested	Medium	\$	remove log from inlet					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Poor pics, no mention of slumping fill or plunge pool. GZ								
GENERAL	PEng's Comment:									

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 259 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-470	Structure Name:	G5-470-2	Road Name:	TEARDROP	Inspection Date:	2021/09/21
GENERAL	Estimated Load Restriction (year):		2020	Estimated Replacement (year):			
	Current Inspection Load Rating:		See footnote	Design Load GVW (tonnes):		Design Vehicle Config.:	
	Professional Inspection Required?		No	Report Status: Rejected By IDIR\GZSOMBOR on 2022/01/06 07:59:13			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 260 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-470	Structure Name:	G5-470	Road Name:	TEARDROP	Inspection Date:	2021/09/21
KM:	47.50	User km:	450.20	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/09/01
Project File ID #:	6480	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	2,000			Outlet Cover (mm):	2,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	21.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	463645	UTM Northing:	6023597		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1972		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 261 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-470	Structure Name:	G5-470	Road Name:	TEARDROP	Inspection Date:	2021/09/21			
Inlet	Good									
Outlet	Good									
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.0	Estimated Present Water Level Width:	0.0						
	Estimated High Water Level Clearance:	1.5								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	beavers have inlet plugged , pipe is dry								
REPAIRS	#	Status	Priority	Estimate	Description					
	4	Suggested	High	\$	remove beaver dam, inlet					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Poor pics, outlet rated good:no mention of plunge pool. GZ								
GENERAL	PEng's Comment:									

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 262 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-470	Structure Name:	G5-470	Road Name:	TEARDROP	Inspection Date:	2021/09/21
GENERAL	Estimated Load Restriction (year):		2020	Estimated Replacement (year):			
	Current Inspection Load Rating:		See footnote	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Rejected By IDIR\GZSOMBOR on 2022/01/06 07:52:20	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 263 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-471	Structure Name:	G5-471	Road Name:	TEARDROP	Inspection Date:	2002/07/25
KM:	50.20	User km:	452.90	Crossing Name:	Unnamed creek	Next Inspection Date:	2005/07/25
Project File ID #:	6480	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	3,700			Outlet Cover (mm):	3,700		
Footing Type:				Gradient (%):	2.0		
Culvert Length (metres):	18.0	Opening Height (mm):	1,200	Opening Width (mm):	1,200		
UTM Zone:	10	UTM Easting:	465812	UTM Northing:	6023735		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1972		
Access:	minor culvert 1200 2nd 1200 @ 123-30-34, 54-21-45. GZ 2019 design in G Drive. to be install when CMP washes out. GZ 2020						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Fair	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Fair	No Comment Available -Converter.RNI
Coating	Fair	No Comment Available -Converter.RNI
Fill	Fair	No Comment Available -Converter.RNI
Floor	Fair	No Comment Available -Converter.RNI
Inlet	Poor	No Comment Available -Converter.RNI
Outlet	Fair	No Comment Available -Converter.RNI
Roof	Fair	No Comment Available -Converter.RNI
Side Walls	Fair	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 264 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-471	Structure Name:	G5-471	Road Name:	TEARDROP	Inspection Date:	2002/07/25			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.8							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	5	Suggested	Medium	\$ 0.00	Span: 1.0. Lengthen Culvert. Lengthen culvert..					
MONITORS	#	Description								
	1	ALSO ONE 800mm AND ONE 500mm CULVERT AT THE SAME SITE. Monitor debris at inlet of 800 pipe. (building up - beaver dam)								
GENERAL	Inspector's Comment:	nullCulvert: 1) too short. Extend by 2 m..								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2022		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/12 09:39:15			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 265 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-469	Structure Name:	G5-469	Road Name:	TEARDROP	Inspection Date:	2020/10/21
KM:	51.60	User km:	454.30	Crossing Name:	Un-Named Creek	Next Inspection Date:	2023/10/21
Project File ID #:	6480	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	18.2	# Spans:	1	Span Width:	Span Length(s) (metres):		18
UTM Zone:	10	UTM Easting:	466911	UTM Northing:	6024023		
Inspector Name:	Warren Wilkinson		Year Superstructure Installed:	2019			
Access:	Structure installed at this site was originally supposed to be installed at Site G5-035. Structure information on Site file.						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	sills
Fill	Good	
Hardware	Good	
Piles or Posts	Good	posts
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	hills and corners both sides
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	100	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 266 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-469	Structure Name:	G5-469	Road Name:	TEARDROP	Inspection Date:	2020/10/21
---------	--------	-----------------	--------	------------	----------	------------------	------------

DECK

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Good
---------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Good
----------------	------

CHANNEL

Estimated Present Water Level Depth:	0.4	Estimated Present Water Level Width:	2.0
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	1.0
---------------------------------------	-----

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 267 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-469	Structure Name:	G5-469	Road Name:	TEARDROP	Inspection Date:	2020/10/21
GENERAL	Inspector's Comment:	Approaches re-aligned 2020					
GENERAL	PEng's Comment:	looks good					
GENERAL	Estimated Load Restriction (year):		2064	Estimated Replacement (year):		2066	
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status: Reviewed By Jason Olmsted on 2021/03/02 12:21:55			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 268 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-472	Structure Name:	G5-472	Road Name:	TEARDROP	Inspection Date:	2002/07/25
KM:	55.70	User km:	458.50	Crossing Name:	Unnamed creek	Next Inspection Date:	2005/07/25
Project File ID #:	6480	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	700			Outlet Cover (mm):	700		
Footing Type:				Gradient (%):	2.0		
Culvert Length (metres):	12.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	470825	UTM Northing:	6025740		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1972		
Access:	Minor culvert 2019 design in G Drive. to be install when CMP washes out. GZ 2020						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Fair	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Poor	No Comment Available -Converter.RNI
Floor	Fair	No Comment Available -Converter.RNI
Inlet	Fair	No Comment Available -Converter.RNI
Outlet	Fair	No Comment Available -Converter.RNI
Roof	Fair	No Comment Available -Converter.RNI
Side Walls	Fair	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 269 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-472	Structure Name:	G5-472	Road Name:	TEARDROP	Inspection Date:	2002/07/25			
CHANNEL	Estimated Present Water Level Depth:			Estimated Present Water Level Width:						
	Estimated High Water Level Clearance:		1.3							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	6	Suggested	Medium	\$ 0.00	Span: 1.0. Add Headwall/cutoff wall.					
	7	Suggested	Medium	\$ 0.00	Span: 1.0. Lengthen Culvert. Lengthen CMP or install headwalls or aprons to retain road fill..					
MONITORS	#	Description								
	1	ALSO ONE 1200mm CULVERT AT THE SAME SITE. (Fair condition & some beaver activity chinch99) Pipe may need to be replaced because it may be sagged and split - check at low flows. (NO chinch99) Monitor road shoulder erosion (chinch99)								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):			2022	Estimated Replacement (year):					
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/12 09:40:19				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 270 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-473	Structure Name:	G5-473-2	Road Name:	TEARDROP	Inspection Date:	2021/09/21
KM:	59.80	User km:	462.50	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/09/21
Project File ID #:	6480	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,500			Outlet Cover (mm):	1,500		
Footing Type:				Gradient (%):	2.0		
Culvert Length (metres):	17.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	471525	UTM Northing:	6029494		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1972		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	end section
Coupled Connections	Fair	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Not Applicable	
Footing	Not Applicable	
Head Wall	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 271 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-473	Structure Name:	G5-473-2	Road Name:	TEARDROP	Inspection Date:	2021/09/21			
Inlet	Fair	Beaver has built a dam around inlet								
Outlet	Good									
Overall	Fair									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	High	\$	remove beaver dam around inlet					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	beavers have partially dammed inlet Costing overrated. no significant issues. GZ.								
GENERAL	PEng's Comment:	No concerns. BH								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 272 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-473	Structure Name:	G5-473-2	Road Name:	TEARDROP	Inspection Date:	2021/09/21
---------	--------	-----------------	----------	------------	----------	------------------	------------

GENERAL

Estimated Load Restriction (year):	2025	Estimated Replacement (year):	
Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91
Design Vehicle Config.:			
Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/10 13:47:40

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 273 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-473	Structure Name:	G5-473	Road Name:	TEARDROP	Inspection Date:	2021/09/21
KM:	59.80	User km:	462.50	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/09/21
Project File ID #:	6480	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,500			Outlet Cover (mm):	1,500		
Footing Type:				Gradient (%):	2.0		
Culvert Length (metres):	17.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	471525	UTM Northing:	6029494		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1972		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Not Applicable	
Footing	Not Applicable	
Head Wall	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 274 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-473	Structure Name:	G5-473	Road Name:	TEARDROP	Inspection Date:	2021/09/21			
Inlet	Fair	Beaver has built a dam around inlet								
Outlet	Good									
Overall	Fair									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	2	Required	High	\$	around inlet					
MONITORS	#	Description								
	4	Monito beaver activity								
GENERAL	Inspector's Comment:	beaver have dammed (partially inlets)								
GENERAL	PEng's Comment:	No concerns. BH								

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 275 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-473	Structure Name:	G5-473	Road Name:	TEARDROP	Inspection Date:	2021/09/21
---------	--------	-----------------	--------	------------	----------	------------------	------------

GENERAL

Estimated Load Restriction (year):	2025	Estimated Replacement (year):	
Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91
Design Vehicle Config.:			
Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/10 13:42:40

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 276 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-474	Structure Name:	G5-474	Road Name:	TEARDROP	Inspection Date:	2021/09/21
KM:	61.10	User km:	463.90	Crossing Name:	Salmon River	Next Inspection Date:	2024/09/21
Project File ID #:	6480	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	39.0	# Spans:	1	Span Width:	Span Length(s) (metres):		39
UTM Zone:	10	UTM Easting:	471724	UTM Northing:	6030686		
Inspector Name:	Dawson Smith		Year Superstructure Installed:	1989			
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Fair	some out of place
Posted Load Rating (Enter 0 if sign missing)	91	(5 tonne signs not posted. GZ)
Road Surface	Fair	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 277 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-474	Structure Name:	G5-474	Road Name:	TEARDROP	Inspection Date:	2021/09/21
---------	--------	-----------------	--------	------------	----------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	need replaced see pics
Deck Joints	Good	
Grout Pockets	Not Applicable	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	guard rails need replaced see pics
Running Surface	Good	(Good GZ)

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	5.0
Estimated High Water Level Clearance:	3.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
9	Required	High	\$ 0.00	Replace all curbs and risers.
10	Required	Medium		Install 3 delineators.
11	Required	Medium	\$ 0.00	Realign approach fenders.
12	Required	High	\$ 0.00	Post load rating signs (5 tonnes)

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 278 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-474	Structure Name:	G5-474	Road Name:	TEARDROP	Inspection Date:	2021/09/21
MONITORS	#	Description					
GENERAL	Inspector's Comment:	guardrails and blocks need to be replaced Not a great inspection but noted major defects. Load restriction signs not posted. GZ					
GENERAL	PEng's Comment:	Install 5 tonne rating sign. Complete repairs as soon as possible. Bridge could be closed at any time due to failing curbs and user safety. BH					
GENERAL	Estimated Load Restriction (year):		2029	Estimated Replacement (year):			
	Current Inspection Load Rating:		5	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/10 14:05:12	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 279 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-490	Structure Name:	G5-490	Road Name:	TEARDROP	Inspection Date:	2019/09/05
KM:	13.30	User km:	480.80	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/09/05
Project File ID #:	6480	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Concrete Precast	
Superstructure:	Concrete Box Beam				Right	Concrete Precast	
Total Length (metres):	14.0	# Spans:	1	Span Width:	Span Length(s) (metres):		14
UTM Zone:	10	UTM Easting:	480605	UTM Northing:	6040321		
Inspector Name:	dawson smith		Year Superstructure Installed:	2000			
Access:	Can also be accessed from km 50 branch road off Davie-Muskeg (400 road). Stay left at km 410 fork.						

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Precast	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 280 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-490	Structure Name:	G5-490	Road Name:	TEARDROP	Inspection Date:	2019/09/05
---------	--------	-----------------	--------	------------	----------	------------------	------------

DECK

Span 1

Concrete Deck	Good
---------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Not Applicable
---------------	----------------

Grout Pockets	Not Applicable
---------------	----------------

Hardware	Not Applicable
----------	----------------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

SUPERSTRUCTURE

Span 1

Bracing	Not Applicable
---------	----------------

Hardware	Not Applicable
----------	----------------

Welded/grouted shear connectors	Not Applicable
---------------------------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	2.5
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	2.5
---------------------------------------	-----

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$ 250.00	REMOVE BEAVER ACTIVITY
2	Required	Low	\$ 500.00	BRUSH

MONITORS

#	Description
1	MONITOR GUARD RAILS

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 281 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-490	Structure Name:	G5-490	Road Name:	TEARDROP	Inspection Date:	2019/09/05
GENERAL	Inspector's Comment:	GOOD, GUARDRAILS DEGRADING, BEAVER ACTIVITY 5M UPSTREAM, NEEDS BRUSHING					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2050	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/03/05 12:17:13			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 282 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-477	Structure Name:	G5-477	Road Name:	CARRIER	Inspection Date:	2021/09/21
KM:	28.00	User km:	138.00	Crossing Name:	UNNAMED	Next Inspection Date:	2024/09/21
Project File ID #:	6480	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.5	# Spans:	1	Span Width:			Span Length(s) (metres): 12.5
UTM Zone:	10		UTM Easting:	446590	UTM Northing:	6052042	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2004		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Poor	some out of place
Posted Load Rating (Enter 0 if sign missing)	68	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 283 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-477	Structure Name:	G5-477	Road Name:	CARRIER	Inspection Date:	2021/09/21			
Road Surface		Fair								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Fair		showing decay, see pic						
Deck to Girder Bolts		Good								
Hardware		Fair								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Fair								
Running Planks		Good								
Sub Deck		Good								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	4	Required	Medium	\$	Replace fenders					
	5	Required	Medium	\$ 0.00	Replace missing delineators					

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 284 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-477	Structure Name:	G5-477	Road Name:	CARRIER	Inspection Date:	2021/09/21
MONITORS	#	Description					
	3	guardrail decay , see pics					
GENERAL	Inspector's Comment:	beaver dam under structure, missing 2 del, guardrails out of place No significant issues. GZ					
GENERAL	PEng's Comment:	No concerns					
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.: L75
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/01/18 13:29:19	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 285 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-478	Structure Name:	G5-478-2	Road Name:	CARRIER	Inspection Date:	2021/10/15
KM:	32.30	User km:	142.70	Crossing Name:	O'Cock Creek	Next Inspection Date:	2024/10/15
Project File ID #:	6480	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	850			Outlet Cover (mm):	400		
Footing Type:				Gradient (%):			
Culvert Length (metres):	17.0	Opening Height (mm):	1,500	Opening Width (mm):	1,500		
UTM Zone:	10	UTM Easting:	447397	UTM Northing:	6056446		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1977		
Access:							

APPROACHES

Alignment	Fair	Curve
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Unrated	could not inspect due to inlet plugged by beavers
Coating	Poor	Heavy rust
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Unrated	could not inspect due to inlet plugged by beavers
Footing	Unrated	could not inspect
Head Wall	Not Applicable	
Inlet	Poor	inlet plugged by beavers
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 286 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-478	Structure Name:	G5-478-2	Road Name:	CARRIER	Inspection Date:	2021/10/15			
Overall	Poor	not functional due to inlet blockage								
Riprap	Not Applicable									
Roof	Unrated	could not inspect due to inlet plugged by beavers								
Side Walls	Unrated	could not inspect due to inlet plugged by beavers								
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:									
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	could not take measurements due to beaver activity								
REPAIRS	#	Status	Priority	Estimate	Description					
	3	Required	High		Inlet plugged by beavers					
	4	Required	High		Culverts rusting out					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Need to replace crossing								
GENERAL	PEng's Comment:	Consider replacing both culverts soon.								
GENERAL	Estimated Load Restriction (year):			2024		Estimated Replacement (year):				
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Bruce Henderson on 2022/01/18 15:01:06			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 287 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-478	Structure Name:	G5-478	Road Name:	CARRIER	Inspection Date:	2021/10/15
KM:	32.30	User km:	142.70	Crossing Name:	O'Cock Creek	Next Inspection Date:	2024/10/15
Project File ID #:	6480	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	17.0	Opening Height (mm):	1,500	Opening Width (mm):	1,500		
UTM Zone:	10	UTM Easting:	447397	UTM Northing:	6056446		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1977		
Access:							

APPROACHES

Alignment	Fair	Curve
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Poor	Heavy rust
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Poor	perferated with rust
Footing	Unrated	can not inspect
Head Wall	Not Applicable	
Inlet	Fair	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 288 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-478	Structure Name:	G5-478	Road Name:	CARRIER	Inspection Date:	2021/10/15			
Overall	Poor	needs replacement								
Riprap	Not Applicable									
Roof	Fair									
Side Walls	Poor	perferated with rust								
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:									
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	unable to assess due to beaver activity								
REPAIRS	#	Status	Priority	Estimate	Description					
	5	Required	High	\$ 0.00	Culverts rusting out, need to be replaced					
MONITORS	#	Description								
	3	monitor rust and perforations of culvert walls and floor								
GENERAL	Inspector's Comment:	Heavy rust, perforated pipe walls								
GENERAL	PEng's Comment:	Consider replacing both culverts.								
GENERAL	Estimated Load Restriction (year):			2024	Estimated Replacement (year):					
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/01/18 15:08:12				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 289 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-680	Structure Name:	G1-680	Road Name:	CHIEF	Inspection Date:	2021/09/01
KM:	6.40	User km:	206.40	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/09/01
Project File ID #:	6480	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	800			Outlet Cover (mm):	800		
Footing Type:				Gradient (%):	1.0		
Culvert Length (metres):	13.0	Opening Height (mm):	1,500	Opening Width (mm):	1,500		
UTM Zone:	10	UTM Easting:	496202	UTM Northing:	5999671		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1975		
Access:							

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Poor	Rusting through
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	
Overall	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 290 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-680	Structure Name:	G1-680	Road Name:	CHIEF	Inspection Date:	2021/09/01			
Riprap	Fair									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.0		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		0.3							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	Beaver activity								
REPAIRS	#	Status	Priority	Estimate	Description					
	6	Required	Medium		Culvert floor rusting through					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	No concerns. BH								
GENERAL	Estimated Load Restriction (year):			2025		Estimated Replacement (year):				
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Bruce Henderson on 2022/02/10 14:13:01			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 291 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-680	Structure Name:	G1-680-2	Road Name:	CHIEF	Inspection Date:	2021/09/01
KM:	6.40	User km:	206.40	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/09/01
Project File ID #:	6480	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	800			Outlet Cover (mm):	800		
Footing Type:				Gradient (%):	1.0		
Culvert Length (metres):	13.0	Opening Height (mm):	1,500	Opening Width (mm):	1,500		
UTM Zone:	10	UTM Easting:	496202	UTM Northing:	5999671		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1975		
Access:							

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Fair	Eroding into inlet
Floor	Poor	Rust holes
Head Wall	Not Applicable	
Inlet	Fair	Gravel and beavers impairing capacity
Outlet	Good	
Overall	Fair	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 292 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-680	Structure Name:	G1-680-2	Road Name:	CHIEF	Inspection Date:	2021/09/01			
Riprap	Fair									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.0	Estimated Present Water Level Width:	1.0						
	Estimated High Water Level Clearance:	0.3								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	Beaver activity								
REPAIRS	#	Status	Priority	Estimate	Description					
	3	Required	Medium		Culvert floor rusting through					
MONITORS	#	Description								
	2	Monitor corrosion in culvert floor								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	No major concerns. BH								
GENERAL	Estimated Load Restriction (year):	2025	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/10 14:19:04						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 293 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-681	Structure Name:	G1-681	Road Name:	CHIEF	Inspection Date:	2021/09/01
KM:	11.20	User km:	211.20	Crossing Name:	Crocker Creek	Next Inspection Date:	2024/09/01
Project File ID #:	6480	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Concrete Box Beam				Right	Pile -Permanent Materials	
Total Length (metres):	18.0	# Spans:	1	Span Width:	Span Length(s) (metres):		18
UTM Zone:	10	UTM Easting:	496256	UTM Northing:	6003964		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1986		
Access:							

ABUTMENTS

Bearings	Good
Bracing	Not Applicable
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Fair
Hardware	Not Applicable
Piles or Posts	Good
Riprap	Fair
Wing Wall	Not Applicable

APPROACHES

Alignment	Good
Bridge Ahead Signs Missing	0
Brushing Required	No
Delineator Missing Left (approaching structure)	1
Delineator Missing Right (approaching structure)	0
Fender Condition	Fair
Road Surface	Fair

DECK

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 294 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-681	Structure Name:	G1-681	Road Name:	CHIEF	Inspection Date:	2021/09/01
---------	--------	-----------------	--------	------------	-------	------------------	------------

Span 1

Concrete Deck	Fair	
Curb Rail/Blocks/Posts	Poor	All 4 corners require replacement
Deck Joints	Good	
Gravel Deck Depth (metres)	0	
Grout Pockets	Not Applicable	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	
Running Surface	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Not Applicable	
Hardware	Not Applicable	
Welded/grouted shear connectors	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	7.5
Estimated High Water Level Clearance:	2.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:	Creek dammed by beavers, back watering structure								

REPAIRS

#	Status	Priority	Estimate	Description
11	Required	Medium	\$ 0.00	Some fill escaping on deck corner
12	Required	High	\$ 0.00	Replace all 4 corners. Damaged and rotten. Remaining rails likely have rot.
13	Required	High	\$ 0.00	Replace no posts on left upstream corner
14	Required	Medium	\$ 0.00	Replace missing delineator

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 295 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-681	Structure Name:	G1-681	Road Name:	CHIEF	Inspection Date:	2021/09/01
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Complete all required repair items. Bridge could be downrated at any time due to deteriorating curbs. BH					
GENERAL	Estimated Load Restriction (year):		2035	Estimated Replacement (year):			
	Current Inspection Load Rating:	68	Design Load GVW (tonnes):	68	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/10 14:40:47			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 296 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-682	Structure Name:	G1-682A	Road Name:	CHIEF	Inspection Date:	2021/09/01
KM:	15.90	User km:	215.90	Crossing Name:	Docs Creek	Next Inspection Date:	2024/09/01
Project File ID #:	6480	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	42.6	# Spans:	1	Span Width:	Span Length(s) (metres):		42.65
UTM Zone:	10	UTM Easting:	495743	UTM Northing:	6007846		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	2020		
Access:	Bridge is on the Chief. Currently on a short section of RP road. District to take over that section, so continue to inspect.						

ABUTMENTS

Bearings	Good
Bracing	Not Applicable
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Not Applicable
Piles or Posts	Good
Riprap	Good
Wing Wall	Not Applicable

APPROACHES

Alignment	Good
Bridge Ahead Signs Missing	0
Brushing Required	No
Delineator Missing Left (approaching structure)	0
Delineator Missing Right (approaching structure)	0
Fender Condition	Good
Road Surface	Good

DECK

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 297 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-682	Structure Name:	G1-682A	Road Name:	CHIEF	Inspection Date:	2021/09/01
---------	--------	-----------------	---------	------------	-------	------------------	------------

Span 1

Concrete Deck	Good
Curb Rail/Blocks/Posts	Good
Deck Joints	Good
Grout Pockets	Good
Hardware	Good
Hand Rails/Walkouts	Not Applicable
Overall Deck Condition	Good
Running Surface	Good

SUPERSTRUCTURE

Span 1

Bracing	Good
Diaphragms	Good
Girders	Good
Hardware	Good
Under Trussing	Not Applicable

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	14.0
Estimated High Water Level Clearance:	3.9		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:	Structure back-watered by beaver dam								

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 298 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-682	Structure Name:	G1-682A	Road Name:	CHIEF	Inspection Date:	2021/09/01
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	No concerns. New bridge in 2020. BH					
GENERAL	Estimated Load Restriction (year):		2065	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/10 14:49:09			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 299 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-683	Structure Name:	G1-683	Road Name:	CHIEF	Inspection Date:	2017/05/29
KM:	43.60	User km:		Crossing Name:	Unnamed	Next Inspection Date:	2022/05/02
Project File ID #:	6480	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	900			Outlet Cover (mm):	930		
Footing Type:				Gradient (%):			
Culvert Length (metres):	42.0	Opening Height (mm):	1,120	Opening Width (mm):	2,800		
UTM Zone:	10	UTM Easting:	479756	UTM Northing:	6023207		
Inspector Name:	Al Kennedy			Year Superstructure Installed:			
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	N/A (Culvert)
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	N/A (Culvert)
Delineator Missing Right (approaching structure)	0	N/A (Culvert)
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	None	N/A (Culvert)
Road Surface	Fair	Some rough sections, and several soft spots where fine material was used

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Unrated	No access for inspection due to trash racks
Coating	Good	Minor loss of galvanized coating at water level throughout length of pipe
Embedment Materials	Good	
Fill	Good	Scour evident from roadway drainage, outlet end, shown in photos
Floor	Unrated	No access for inspection
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 300 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-683	Structure Name:	G1-683	Road Name:	CHIEF	Inspection Date:	2017/05/29			
Inlet	Fair	Small accumulation of wood debris on trash rack								
Outlet	Good									
Overall	Good									
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Good									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Low	\$	Fill in scour trench on roadway embankment at outlet end.					
MONITORS	#	Description								
	1	Monitor woody debris accumulation at inlet end of culvert.								
GENERAL	Inspector's Comment:	Overall condition of culvert is good. Slight loss of galvanized coating at base of pipe near water level. Small amount of woody debris at inlet end of culvert. Scouring of the culvert fill at the edge of road shoulder, due to roadway surface drainage. No significant issues. GZ								
GENERAL	PEng's Comment:									

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 301 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-683	Structure Name:	G1-683	Road Name:	CHIEF	Inspection Date:	2017/05/29
GENERAL	Estimated Load Restriction (year):		2042	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2018/03/21 09:10:53	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 302 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-690	Structure Name:	G1-690	Road Name:	UNNAMED 1	Inspection Date:	2017/05/29	
KM:	19.00	User km:	618.60	Crossing Name:	Salmon River	Next Inspection Date:	2022/05/02	
Project File ID #:	6480	Br.	10	Forest District:	Stuart Nechako Natural Resource District			
Deck Type:	Timber - Untreated			Running Surface:	Gravel			
Curb Type:				Abutments (looking downstream)	Left	Other		
Superstructure:	Steel I-beam				Right	Other		
Total Length (metres):	68.0	# Spans:	3	Span Width:			Span Length(s) (metres):	17, 34, 17
UTM Zone:	10		UTM Easting:	496687		UTM Northing:	6009577	
Inspector Name:	Al Kennedy			Year Superstructure Installed:	1981			
Access:								

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Fair	
Caps or Sills	Unrated	No caps or sills present
Fill	Good	
General Abutment Condition	Good	Minor scouring of abutment fill at both left and right abutments due to road runoff.
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	1	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	2	Replace broken delineators
Fender Condition	Fair	Woods end upstream corner, missaligned and missing bulbnose

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 303 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-690	Structure Name:	G1-690	Road Name:	UNNAMED 1	Inspection Date:	2017/05/29
---------	--------	-----------------	--------	------------	-----------	------------------	------------

Posted Load Rating (Enter 0 if sign missing)	None	
Road Surface	Good	
DECK		
Span 1		
Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Good	
Gravel Surface	Unrated	No gravel surface
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Good	
Sub Deck	Good	
Ties	Good	
Span 2		
Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Good	
Gravel Surface	Unrated	no gravel surface
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Good	
Sub Deck	Good	
Ties	Good	
Span 3		
Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Good	
Gravel Surface	Unrated	no gravel surface
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 304 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-690	Structure Name:	G1-690	Road Name:	UNNAMED 1	Inspection Date:	2017/05/29
---------	--------	-----------------	--------	------------	-----------	------------------	------------

Nails	Good	
Overall Deck Condition	Good	
Running Planks	Good	
Sub Deck	Good	
Ties	Good	

PIERS

Pier 1

Bearings	Good	
Bracing or Sheathing	Not Applicable	
Caps	Unrated	No pier caps
Cribs	Not Applicable	
Dolphins	Not Applicable	
Hardware	Good	
Overall	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wall	Good	

Pier 2

Bearings	Good	
Bracing or Sheathing	Not Applicable	
Caps	Unrated	No pier caps
Cribs	Not Applicable	
Dolphins	Not Applicable	
Hardware	Good	
Overall	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wall	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
---------	------	--

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 305 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-690	Structure Name:	G1-690	Road Name:	UNNAMED 1	Inspection Date:	2017/05/29			
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
Span 2										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
Span 3										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		3.0		Estimated Present Water Level Width:		30.0			
	Estimated High Water Level Clearance:		6.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Medium	\$ 250.00	add bridge ahead sign					
	2	Required	High	\$ 400.00	add 2 right and 1 left delineator					
MONITORS	#	Description								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 306 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-690	Structure Name:	G1-690	Road Name:	UNNAMED 1	Inspection Date:	2017/05/29
GENERAL	Inspector's Comment:	Concrete repairs on both piers and abutment location has been completed. Timber running deck has been replaced. The remainder of the repair items previously identified have not been completed.					
GENERAL	PEng's Comment:	No Issues. GZ					
GENERAL	Estimated Load Restriction (year):		2021	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2018/03/21 09:12:37			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 307 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-691	Structure Name:	G1-691A	Road Name:	UNNAMED 1	Inspection Date:	2021/09/07
KM:	28.00	User km:	646.60	Crossing Name:	Muskeg River	Next Inspection Date:	2024/09/07
Project File ID #:	6480	Br.	10	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	27.4	# Spans:	1	Span Width:			Span Length(s) (metres): 27.43
UTM Zone:	10	UTM Easting:	490308	UTM Northing:	6029666		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	2020		
Access:							

ABUTMENTS

Bearings	Good	
----------	------	--

Bracing	Good	
---------	------	--

Ballast Wall	Good	
--------------	------	--

Corrosion Protection	Not Applicable	
----------------------	----------------	--

Caps or Sills	Unrated	none
---------------	---------	------

Fill	Good	
------	------	--

Hardware	Good	
----------	------	--

Piles or Posts	Good	
----------------	------	--

Riprap	Good	
--------	------	--

Wing Wall	Not Applicable	
-----------	----------------	--

APPROACHES

Alignment	Good	
-----------	------	--

Bridge Ahead Signs Missing	0	
----------------------------	---	--

Brushing Required	No	
-------------------	----	--

Delineator Missing Left (approaching structure)	0	
---	---	--

Delineator Missing Right (approaching structure)	0	
--	---	--

Fender Condition	Good	
------------------	------	--

Road Surface	Good	
--------------	------	--

DECK

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 308 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-691	Structure Name:	G1-691A	Road Name:	UNNAMED 1	Inspection Date:	2021/09/07
---------	--------	-----------------	---------	------------	-----------	------------------	------------

Span 1

Concrete Deck	Good
Curb Rail/Blocks/Posts	Good
Deck Joints	Good
Grout Pockets	Good
Hardware	Good
Hand Rails/Walkouts	Not Applicable
Overall Deck Condition	Good
Running Surface	Good

SUPERSTRUCTURE

Span 1

Bracing	Good
Diaphragms	Good
Girders	Good
Hardware	Good
Under Trussing	Not Applicable

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	16.0
Estimated High Water Level Clearance:	1.8		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 309 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G1-691	Structure Name:	G1-691A	Road Name:	UNNAMED 1	Inspection Date:	2021/09/07
GENERAL	Inspector's Comment:	New install, no issues					
GENERAL	PEng's Comment:	No concerns. BH					
GENERAL	Estimated Load Restriction (year):		2065	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/10 14:58:05			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 310 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-540	Structure Name:	G4-934	Road Name:	OWEN	Inspection Date:	2020/08/04
KM:	10.50	User km:	10.50	Crossing Name:	Un-named Creek	Next Inspection Date:	2023/08/04
Project File ID #:	6480	Br.	29	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Sill - Permanent Materials	
Superstructure:	Steel I-beam				Right	Sill - Permanent Materials	
Total Length (metres):	15.2	# Spans:	1	Span Width:	Span Length(s) (metres):		15.2
UTM Zone:	10	UTM Easting:	457252	UTM Northing:	6021841		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2015		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Fair	signs of rot
Corrosion Protection	Not Applicable	
Caps or Sills	Good	3 12x12
Fill	Good	
Hardware	Good	
Log/Timber Cribs	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Tie-backs	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	1	up chain
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Fair	logs sitting on ground, left upstream knocked of RW

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 311 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-540	Structure Name:	G4-934	Road Name:	OWEN	Inspection Date:	2020/08/04			
Posted Load Rating (Enter 0 if sign missing)	0									
Road Surface	Poor	large pot holes, no surface								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Good									
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Good									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		0.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	natural channel								
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 312 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-540	Structure Name:	G4-934	Road Name:	OWEN	Inspection Date:	2020/08/04
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	looks ok					
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/02/25 15:16:18	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 313 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-541	Structure Name:	G5-915	Road Name:	OWEN	Inspection Date:	2020/08/04
KM:	10.80	User km:	10.80	Crossing Name:	Un-named Creek	Next Inspection Date:	2022/08/04
Project File ID #:	6480	Br.	29	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Steel I-beam				Right	Sill -Temporary Materials	
Total Length (metres):	10.0	# Spans:	1	Span Width:	Span Length(s) (metres):		10
UTM Zone:	10	UTM Easting:	456916	UTM Northing:	6021852		
Inspector Name:	Warren Wiilkinson			Year Superstructure Installed:	2015		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Fair	
Corrosion Protection	Good	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Excellent	
Bridge Ahead Signs Missing	1	Upchian
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	loggs sitting on ground
Posted Load Rating (Enter 0 if sign missing)	75	
Road Surface	Poor	large pot holes, no surface

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 314 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-541 Structure Name: G5-915 Road Name: OWEN Inspection Date: 2020/08/04

DECK

Span 1

Curb Rail/Blocks/Posts Good

Deck to Girder Bolts Good

Hardware Good

Hand Rails/Walkouts Not Applicable

Nails Good

Overall Deck Condition Good

Running Planks Good covered in mus and dirt

Sub Deck Good

Ties Good

SUPERSTRUCTURE

Span 1

Bracing Good

Diaphragms Good

Girders Good

Hardware Good

Under Trussing Good

CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	0.3
	Estimated High Water Level Clearance:	0.4		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	Natural stream bed								

REPAIRS	#	Status	Priority	Estimate	Description
	4	Required	High	\$	up-chain bridge ahead sign
	5	Required	High	\$	L75 weight sign

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 315 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-541	Structure Name:	G5-915	Road Name:	OWEN	Inspection Date:	2020/08/04
MONITORS	#	Description					
	1	Rot in ballast walls					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	looks ok					
GENERAL	Estimated Load Restriction (year):		2030		Estimated Replacement (year):		
	Current Inspection Load Rating:		68		Design Load GVW (tonnes):		68
	Design Vehicle Config.:		L75				
GENERAL	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/19 12:17:02			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 316 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-476	Structure Name:	G4-920	Road Name:	OWEN	Inspection Date:	2021/09/21
KM:	2.70	User km:		Crossing Name:	Un-named Creek	Next Inspection Date:	2023/09/21
Project File ID #:	6480	Br.	29	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Steel I-beam				Right	Crib, Log or Untreated Timber	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	10		UTM Easting:	464057	UTM Northing:	6020966	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2014		
Access:							

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	
Fill	Good	
Hardware	Fair	
Log/Timber Cribs	Fair	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Tie-backs	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	1	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	log fenders

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 317 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-476	Structure Name:	G4-920	Road Name:	OWEN	Inspection Date:	2021/09/21			
Posted Load Rating (Enter 0 if sign missing)	0									
Road Surface	Fair	needs grading								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Poor	missing 1 running plank, see pics								
Running Planks	Poor	missing 1 running plank, see pics								
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		1.0		Estimated Present Water Level Width:		4.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 318 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-476	Structure Name:	G4-920	Road Name:	OWEN	Inspection Date:	2021/09/21	
REPAIRS	#	Status	Priority	Estimate	Description			
	5	Required	Low		Needs 1 running plank			
	7	Required	Medium		Add approach fenders			
	8	Required	Medium		Grade approaches to encourage proper drainage.			
MONITORS	#	Description						
GENERAL	Inspector's Comment:	No rip rap, deck missing 1 running plank, needs approaches graded No significant issues. GZ						
GENERAL	PEng's Comment:	No concerns. JDS						
GENERAL	Estimated Load Restriction (year):			2030	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Jordan Smith on 2022/02/10 12:49:04		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 319 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-479	Structure Name:	JH-93	Road Name:	46 ROAD	Inspection Date:	2021/09/07
KM:	2.40	User km:	2.40	Crossing Name:	Unnamed	Next Inspection Date:	2024/09/07
Project File ID #:	6480	Br.	30	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	7.3	# Spans:	1	Span Width:			Span Length(s) (metres): 7.3
UTM Zone:	10		UTM Easting:	445975	UTM Northing:	6058634	
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	2009		
Access:	Structure installed G5-988 = JH-93 LNH (2020-05-05)						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Poor	Settled
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	Left corner pushed over
Road Surface	Poor	Approach fill settled

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 320 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-479	Structure Name:	JH-93	Road Name:	46 ROAD	Inspection Date:	2021/09/07
---------	--------	-----------------	-------	------------	---------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Good
----------------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Good
----------------	------

Sub Deck	Good
----------	------

Ties	Good
------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Not Applicable
----------	----------------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.2
Estimated High Water Level Clearance:	0.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Medium		Add additional material to bring road grade to deck elevation
2	Required	Medium		Reset left upstream corner
3	Required	Medium		Add signs

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 321 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-479	Structure Name:	JH-93	Road Name:	46 ROAD	Inspection Date:	2021/09/07
MONITORS	#	Description					
GENERAL	Inspector's Comment:	Swamp complex. Standing water with minimal flow to SE.					
GENERAL	PEng's Comment:	No concerns. JDS					
GENERAL	Estimated Load Restriction (year):		2024	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Jordan Smith on 2022/02/10 13:00:39	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 322 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-080	Structure Name:	G5-080	Road Name:	CUNNINGHAM	Inspection Date:	2019/08/12
KM:	23.30	User km:	23.30	Crossing Name:	Un-named	Next Inspection Date:	2022/08/12
Project File ID #:	7537	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Concrete Slab Girders				Right	Steel Pipe and Precast Pad	
Total Length (metres):	9.6	# Spans:	1	Span Width:			Span Length(s) (metres): 9.6
UTM Zone:	10	UTM Easting:	397629	UTM Northing:	6030468		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2012		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Excellent	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	FENDER OUT OF POSITION
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 323 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-080	Structure Name:	G5-080	Road Name:	CUNNINGHAM	Inspection Date:	2019/08/12
---------	--------	-----------------	--------	------------	------------	------------------	------------

DECK

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Not Applicable
---------------	----------------

Grout Pockets	Not Applicable
---------------	----------------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

SUPERSTRUCTURE

Span 1

Bracing	Not Applicable
---------	----------------

Hardware	Not Applicable
----------	----------------

Welded/grouted shear connectors	Good
---------------------------------	------

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	3.0
Estimated High Water Level Clearance:	3.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$ 250.00	PUT FENDER BACK IN PLACE

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 324 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-080	Structure Name:	G5-080	Road Name:	CUNNINGHAM	Inspection Date:	2019/08/12
GENERAL	Inspector's Comment:	ALL GOOD, FENDER OUT OF PLACE					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2057	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/11 16:04:47			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 325 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-084	Structure Name:	G5-084	Road Name:	CUNNINGHAM	Inspection Date:	2019/08/12
KM:	27.00	User km:	27.00	Crossing Name:	unnamed	Next Inspection Date:	2022/08/12
Project File ID #:	7537	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	500			Outlet Cover (mm):	500		
Footing Type:	Steel Footing			Gradient (%):			
Culvert Length (metres):	11.0	Opening Height (mm):	1,440	Opening Width (mm):	2,740		
UTM Zone:	10	UTM Easting:	394366	UTM Northing:	6032386		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2009		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Not Applicable	
Embedment Materials	Good	
Fill	Good	
Floor	Not Applicable	
Footing	Not Applicable	
Head Wall	Fair	ROAD FILL NEEDS TO BE PULLED BACK BOTH SIDES

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 326 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-084	Structure Name:	G5-084	Road Name:	CUNNINGHAM	Inspection Date:	2019/08/12			
Inlet	Good									
Outlet	Good									
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	2.0						
	Estimated High Water Level Clearance:	1.5								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Low	\$ 500.00	PULL FILL BACK ON THE ROAD AND CLEAN OUT INLET					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	ACTUALLY 27.4KMS								
GENERAL	PEng's Comment:									

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 327 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-084	Structure Name:	G5-084	Road Name:	CUNNINGHAM	Inspection Date:	2019/08/12
GENERAL	Estimated Load Restriction (year):		2059	Estimated Replacement (year):			
	Current Inspection Load Rating:		64	Design Load GVW (tonnes):		64	Design Vehicle Config.: BCL62
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/02/11 16:09:17	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 328 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-081	Structure Name:	G5-081	Road Name:	CUNNINGHAM	Inspection Date:	2019/08/12
KM:	29.80	User km:	29.80	Crossing Name:	Un-named	Next Inspection Date:	2022/08/12
Project File ID #:	7537	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Concrete Slab Girders				Right	Steel Pipe and Precast Pad	
Total Length (metres):	8.6	# Spans:	1	Span Width:	Span Length(s) (metres):		8.6
UTM Zone:	10	UTM Easting:	392690	UTM Northing:	6033955		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2012		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Excellent	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 329 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-081 Structure Name: G5-081 Road Name: CUNNINGHAM Inspection Date: 2019/08/12

DECK

Span 1

Concrete Deck Good

Curb Rail/Blocks/Posts Good

Deck Joints Good

Grout Pockets Not Applicable

Grout Pockets Not Applicable

Hardware Not Applicable

Hand Rails/Walkouts Not Applicable

Overall Deck Condition Good

Running Surface Good

SUPERSTRUCTURE

Span 1

Bracing Not Applicable

Hardware Not Applicable

Welded/grouted shear connectors Good

CHANNEL

Estimated Present Water Level Depth: 0.5 Estimated Present Water Level Width: 1.5
Estimated High Water Level Clearance: 2.5

HAZARDS

High Water: No Scour: No Ice: No Debris: No Aggradation: No
Comment:

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 330 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-081	Structure Name:	G5-081	Road Name:	CUNNINGHAM	Inspection Date:	2019/08/12
GENERAL	Inspector's Comment:	GOOD, SIGNS WITH WEIGHT AND 4 DELINEATORS					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2057	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/11 16:26:12			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 331 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-082	Structure Name:	G5-082	Road Name:	CUNNINGHAM	Inspection Date:	2019/08/12
KM:	62.20	User km:	62.20	Crossing Name:	unnamed	Next Inspection Date:	2022/08/12
Project File ID #:	7537	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	720			Outlet Cover (mm):	720		
Footing Type:				Gradient (%):			
Culvert Length (metres):	13.5	Opening Height (mm):	2,000	Opening Width (mm):	2,000		
UTM Zone:	10	UTM Easting:	366492	UTM Northing:	6043695		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2009		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Good	
Fill	Good	
Floor	Not Applicable	
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 332 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-082	Structure Name:	G5-082	Road Name:	CUNNINGHAM	Inspection Date:	2019/08/12				
Overall	Good										
Riprap	Not Applicable										
Roof	Good										
Side Walls	Good										
Trash Rack	Not Applicable										
Wiers/Backwater Structures	Not Applicable										
Wing Wall	Not Applicable										
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		0.3				
	Estimated High Water Level Clearance:		1.5								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No	
	Comment:										
REPAIRS	#	Status	Priority	Estimate	Description						
MONITORS	#	Description									
GENERAL	Inspector's Comment:	ALL GOOD									
GENERAL	PEng's Comment:										
GENERAL	Estimated Load Restriction (year):		2059		Estimated Replacement (year):						
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:		L100
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/02/11 16:28:31				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 333 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-083	Structure Name:	G5-083	Road Name:	CUNNINGHAM	Inspection Date:	2019/08/12
KM:	62.80	User km:	62.80	Crossing Name:	unnamed	Next Inspection Date:	2022/08/12
Project File ID #:	7537	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	940			Outlet Cover (mm):	940		
Footing Type:	Steel Footing			Gradient (%):	3.5		
Culvert Length (metres):	14.8	Opening Height (mm):	1,870	Opening Width (mm):	4,570		
UTM Zone:	10	UTM Easting:	366287	UTM Northing:	6043677		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2009		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Good	
Fill	Good	
Floor	Not Applicable	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 334 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-083	Structure Name:	G5-083	Road Name:	CUNNINGHAM	Inspection Date:	2019/08/12			
Overall	Good									
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.0						
	Estimated High Water Level Clearance:	1.5								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	ALL GOOD								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):	2059	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100				
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/11 16:30:20						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 335 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-001	Structure Name:	G5-001	Road Name:	CUNNINGHAM	Inspection Date:	2019/08/12
KM:	17.60	User km:	916.80	Crossing Name:	Sowchea Creek	Next Inspection Date:	2022/08/12
Project File ID #:	7537	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	21.0	# Spans:	1	Span Width:	Span Length(s) (metres):		21
UTM Zone:	10	UTM Easting:	400954	UTM Northing:	6026923		
Inspector Name:	dawson smith			Year Superstructure Installed:	2001		
Access:							

ABUTMENTS

Bearings	Good
Bracing	Good
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Not Applicable
Piles or Posts	Good
Riprap	Good
Wing Wall	Good

APPROACHES

Alignment	Good
Bridge Ahead Signs Missing	0
Brushing Required	No
Delineator Missing Left (approaching structure)	0
Delineator Missing Right (approaching structure)	0
Fender Condition	Good
Posted Load Rating (Enter 0 if sign missing)	91,000
Road Surface	Good

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 336 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-001 Structure Name: G5-001 Road Name: CUNNINGHAM Inspection Date: 2019/08/12

DECK

Span 1

Concrete Deck Good

Curb Rail/Blocks/Posts Good

Deck Joints Not Applicable

Grout Pockets Fair

Hardware Not Applicable

Hand Rails/Walkouts Not Applicable

Overall Deck Condition Good

SUPERSTRUCTURE

Span 1

Bracing Good

Diaphragms Good

Girders Good

Hardware Not Applicable

Under Trussing Not Applicable

CHANNEL

Estimated Present Water Level Depth: 0.5 Estimated Present Water Level Width: 3.0

Estimated High Water Level Clearance: 3.0

HAZARDS

High Water: No Scour: No Ice: No Debris: No Aggradation: No

Comment:

REPAIRS

Status Priority Estimate Description

MONITORS

Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 337 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-001	Structure Name:	G5-001	Road Name:	CUNNINGHAM	Inspection Date:	2019/08/12
GENERAL	Inspector's Comment:	GROUT POCKETS GOOD,, ALL 4 DELINEATORS					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2051	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/11 15:55:36			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 338 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-002	Structure Name:	G5-002	Road Name:	CUNNINGHAM	Inspection Date:	2002/08/09
KM:	64.00	User km:	964.90	Crossing Name:	Unnamed creek	Next Inspection Date:	2005/08/09
Project File ID #:	7537	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	4,000			Outlet Cover (mm):	4,000		
Footing Type:				Gradient (%):	2.0		
Culvert Length (metres):	34.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	364149	UTM Northing:	6043994		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1983		
Access:	Minor culvert						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Excellent	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 339 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-002	Structure Name:	G5-002	Road Name:	CUNNINGHAM	Inspection Date:	2002/08/09			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		1.2							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Monitor for scour as no rip rap is present. Monitor beaver dam surrounding inlet.								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2033		Estimated Replacement (year):					
	Current Inspection Load Rating:		54		Design Load GVW (tonnes):		54		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/10 09:21:51			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 340 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-003	Structure Name:	G5-003	Road Name:	CUNNINGHAM	Inspection Date:	2002/08/09
KM:	65.90	User km:	965.90	Crossing Name:	Larson's Leap Creek	Next Inspection Date:	2030/01/01
Project File ID #:	7537	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	9,000			Outlet Cover (mm):	9,000		
Footing Type:				Gradient (%):	3.0		
Culvert Length (metres):	61.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	363103	UTM Northing:	6043694		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1986		
Access:	Minor culvert 1600						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Excellent	No Comment Available -Converter.RNI
Outlet	Excellent	No Comment Available -Converter.RNI
Riprap	Good	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 341 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-003	Structure Name:	G5-003	Road Name:	CUNNINGHAM	Inspection Date:	2002/08/09			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.8							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2036		Estimated Replacement (year):					
	Current Inspection Load Rating:		54		Design Load GVW (tonnes):		54		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/10 09:24:31			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 342 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-RW001	Structure Name:	G5-RW001	Road Name:	CUNNINGHAM	Inspection Date:	2020/09/22
KM:	17.50	User km:		Crossing Name:	Retaining Wall	Next Inspection Date:	2023/09/22
Project File ID #:	7537	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):				Outlet Cover (mm):			
Footing Type:				Gradient (%):			
Culvert Length (metres):	5.0	Opening Height (mm):	300	Opening Width (mm):	300		
UTM Zone:	10	UTM Easting:	400979	UTM Northing:	6026746		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2002		

Access: This site is the location of a retaining wall, 917.5km Cunningham FSR.
** INSPECT THIS STRUCTURE ANNUALLY **

This is now part of the Retaining Wall Program - 2021 (JO)

APPROACHES

Alignment	Good
-----------	------

Bridge Ahead Signs Missing	2
----------------------------	---

Brushing Required	No
-------------------	----

Delineator Missing Left (approaching structure)	2
---	---

Delineator Missing Right (approaching structure)	2
--	---

Fender Condition	None
------------------	------

Road Surface	Good
--------------	------

CULVERT ELEMENT

Baffles	Not Applicable
---------	----------------

Bolted Connections	Not Applicable
--------------------	----------------

Coupled Connections	Not Applicable
---------------------	----------------

Coating	Not Applicable
---------	----------------

Embedment Materials	Not Applicable
---------------------	----------------

Fill	Unrated	retaining wall
------	---------	----------------

Floor	Not Applicable
-------	----------------

Footing	Not Applicable
---------	----------------

Head Wall	Not Applicable
-----------	----------------

Inlet	Unrated	retaining wall
-------	---------	----------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 343 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-RW001	Structure Name:	G5-RW001	Road Name:	CUNNINGHAM	Inspection Date:	2020/09/22			
Outlet	Unrated	retaining wall								
Overall	Unrated	retaining wall								
Riprap	Not Applicable									
Roof	Unrated	retaining wall								
Side Walls	Unrated	retaining wall								
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.0	Estimated Present Water Level Width:		0.0					
	Estimated High Water Level Clearance:	0.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	3	shifting of lock blocks								
GENERAL	Inspector's Comment:	some movement in lock Blocks no major issues noted. Ditch work completed 2020 including cleaning of culverts should keep majority of water coming down the upslope side of the road away from wall and help keep road \ hill side from slipping. requested that survey points be put on wall.								
GENERAL	PEng's Comment:	this is not part of the retaining wall inventory program and no longer part of the routine bridge inspections.								
GENERAL	Estimated Load Restriction (year):	2047	Estimated Replacement (year):							
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):			Design Vehicle Config.:				
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/22 13:27:47						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 344 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-006	Structure Name:	G5-006	Road Name:	ANTIMONY	Inspection Date:	2021/10/14
KM:	0.40	User km:	0.40	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/10/14
Project File ID #:	7537	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel Truss/Bailey/Acrow				Right	Concrete Lock Blocks	
Total Length (metres):	9.0	# Spans:	1	Span Width:	Span Length(s) (metres):		9
UTM Zone:	10	UTM Easting:	397201	UTM Northing:	6031028		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	2002		
Access:	Turn right at km 24 on the Cunningham FSR						

ABUTMENTS

Bearings	Poor	Crushing timber sill
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Good	
Caps or Sills	Poor	Showing rot and crushing under bearings
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 345 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-006	Structure Name:	G5-006	Road Name:	ANTIMONY	Inspection Date:	2021/10/14
---------	--------	-----------------	--------	------------	----------	------------------	------------

Road Surface	Fair	
--------------	------	--

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	200mm timbers
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Fair	
Sub Deck	Good	
Ties	Unrated	None

SUPERSTRUCTURE

Span 1

Bracing	Fair	Bent but not structural
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	0.5
	Estimated High Water Level Clearance:	1.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	4	Required	Medium	\$ 0.00	Install both bridge ahead signs
	5	Required	Medium	\$ 0.00	Minor brush removal
	6	Required	High	\$ 0.00	Remove beaver dam. Will flood approach if height increases
	7	Required	High		Replace timber sills

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 346 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-006	Structure Name:	G5-006	Road Name:	ANTIMONY	Inspection Date:	2021/10/14
---------	--------	-----------------	--------	------------	----------	------------------	------------

MONITORS

#	Description

GENERAL

Inspector's Comment:	Recommend load restriction
----------------------	----------------------------

GENERAL

PEng's Comment:	Replace timber sills before industrial use. May be downrated at any time due to poor sills. BH
-----------------	--

GENERAL

Estimated Load Restriction (year):	2025	Estimated Replacement (year):	
Current Inspection Load Rating:	68	Design Load GVW (tonnes):	68
Design Vehicle Config.:			
Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/04 12:10:47

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 347 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-007	Structure Name:	G5-007	Road Name:	ANTIMONY	Inspection Date:	2021/10/14
KM:	1.60	User km:	1.60	Crossing Name:	Ucausley Creek tributary	Next Inspection Date:	2024/10/14
Project File ID #:	7537	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel Truss/Bailey/Acrow				Right	Concrete Lock Blocks	
Total Length (metres):	12.0	# Spans:	1	Span Width:	Span Length(s) (metres):		12
UTM Zone:	10	UTM Easting:	397480	UTM Northing:	6032148		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	2002		
Access:	Turn right at km 24 on the Cunningham FSR.						

ABUTMENTS

Bearings	Poor	Crushing timber sill
Bracing	Not Applicable	
Ballast Wall	Fair	
Concrete Lock Blocks	Good	
Concrete Precast	Good	
Corrosion Protection	Good	
Caps or Sills	Poor	Show signs of decay and crushing under bearing
Fill	Fair	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 348 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-007	Structure Name:	G5-007	Road Name:	ANTIMONY	Inspection Date:	2021/10/14			
Posted Load Rating (Enter 0 if sign missing)	68									
Road Surface	Fair									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Fair	200mm x 200mm timbers								
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Fair									
Overall Deck Condition	Fair									
Running Planks	Fair	Showing some rot								
Sub Deck	Fair	Indicators of decay								
Ties	Unrated	N/A								
SUPERSTRUCTURE										
Span 1										
Bracing	Fair	One bent but not structural								
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		2.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 349 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-007	Structure Name:	G5-007	Road Name:	ANTIMONY	Inspection Date:	2021/10/14
REPAIRS	#	Status	Priority	Estimate	Description		
	4	Required	Medium	\$ 0.00	Install both bridge ahead signs		
	5	Required	Medium	\$ 0.00	Minor brushing around abutments		
	6	Required	Medium		Replace timber sills		
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Consider replacing sills. Indicating rot in decking. May be downrated at any time.					
GENERAL	Estimated Load Restriction (year):			2025	Estimated Replacement (year):		
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/06 13:31:21	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 350 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-055	Structure Name:	G4-055	Road Name:	KLUSKUS	Inspection Date:	2019/08/09
KM:	26.50	User km:	26.50	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/08/09
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Elliptical			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	20.7	Opening Height (mm):	1,630	Opening Width (mm):	2,240		
UTM Zone:	10	UTM Easting:	415341	UTM Northing:	5968528		
Inspector Name:	dawson smith			Year Superstructure Installed:	1998		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 351 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-055	Structure Name:	G4-055	Road Name:	KLUSKUS	Inspection Date:	2019/08/09			
Overall	Good									
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	1.5						
	Estimated High Water Level Clearance:	2.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	GOOD								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):	2048	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/22 10:40:16						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 352 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-056	Structure Name:	G4-056	Road Name:	KLUSKUS	Inspection Date:	2002/07/10
KM:	27.00	User km:	27.00	Crossing Name:	Unnamed creek	Next Inspection Date:	2030/01/01
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	2,500			Outlet Cover (mm):	2,500		
Footing Type:				Gradient (%):			
Culvert Length (metres):	20.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	415185	UTM Northing:	5967875		
Inspector Name:	Ed Cienciala			Year Superstructure Installed:	1998		
Access:							

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Good	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 353 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-056	Structure Name:	G4-056	Road Name:	KLUSKUS	Inspection Date:	2002/07/10			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		1.3							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2048		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/12 16:28:57			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 354 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-048	Structure Name:	G4-048	Road Name:	KLUSKUS	Inspection Date:	2019/08/08
KM:	33.50	User km:	33.50	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/08/08
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Elliptical			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,500			Outlet Cover (mm):	1,500		
Footing Type:				Gradient (%):			
Culvert Length (metres):	18.9	Opening Height (mm):	2,080	Opening Width (mm):	2,690		
UTM Zone:	10	UTM Easting:	412440	UTM Northing:	5962541		
Inspector Name:	dawson smith			Year Superstructure Installed:	1998		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 355 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-048	Structure Name:	G4-048	Road Name:	KLUSKUS	Inspection Date:	2019/08/08
Overall	Good						
Riprap	Not Applicable						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						
CHANNEL	Estimated Present Water Level Depth:	0.5			Estimated Present Water Level Width:	1.5	
	Estimated High Water Level Clearance:	1.2					
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Aggradation: No
	Comment:						
REPAIRS	#	Status	Priority	Estimate	Description		
	1	Not Required	Medium	\$ 250.00	inlet and outlet require brushing		
MONITORS	#	Description					
GENERAL	Inspector's Comment:	inlet and outlet require brushing..					
GENERAL	PEng's Comment:	Brushing NOT required.					
GENERAL	Estimated Load Restriction (year):	2048		Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/20 16:02:14			

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 356 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-061	Structure Name:	G4-061	Road Name:	KLUSKUS	Inspection Date:	2020/10/22
KM:	48.70	User km:	49.00	Crossing Name:	Un-named	Next Inspection Date:	2023/10/22
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Elliptical			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,500			Outlet Cover (mm):	1,500		
Footing Type:				Gradient (%):			
Culvert Length (metres):	37.0	Opening Height (mm):	1,869	Opening Width (mm):	2,590		
UTM Zone:	10	UTM Easting:	411423	UTM Northing:	5947289		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2007		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Good	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 357 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-061	Structure Name:	G4-061	Road Name:	KLUSKUS	Inspection Date:	2020/10/22			
Overall	Good									
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.0						
	Estimated High Water Level Clearance:	1.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	looks good								
GENERAL	Estimated Load Restriction (year):	2055	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/02/09 15:41:49						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 358 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-067	Structure Name:	G4-067	Road Name:	KLUSKUS	Inspection Date:	2020/10/22
KM:	60.10	User km:	61.00	Crossing Name:	Un-named	Next Inspection Date:	2023/10/22
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	3,000			Outlet Cover (mm):			
Footing Type:	Piles			Gradient (%):			
Culvert Length (metres):	30.0	Opening Height (mm):	3,000	Opening Width (mm):	5,000		
UTM Zone:	10	UTM Easting:	406898	UTM Northing:	5938177		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2006		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Not Applicable	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 359 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-067	Structure Name:	G4-067	Road Name:	KLUSKUS	Inspection Date:	2020/10/22			
Overall	Good									
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Good									
CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	3.0						
	Estimated High Water Level Clearance:	2.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	looks ok								
GENERAL	Estimated Load Restriction (year):	2056	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):		Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/02/09 16:00:41						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 360 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-050	Structure Name:	G4-050	Road Name:	KLUSKUS	Inspection Date:	2005/05/26
KM:	61.20	User km:	61.20	Crossing Name:	Roy Creek	Next Inspection Date:	2008/05/26
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:				Culvert Material:			
Inlet Cover (mm):	3			Outlet Cover (mm):	3		
Footing Type:				Gradient (%):			
Culvert Length (metres):	27.0	Opening Height (mm):	3	Opening Width (mm):	3		
UTM Zone:	10	UTM Easting:	406843	UTM Northing:	5938277		
Inspector Name:	Vince Sewell		Year Superstructure Installed:	1987			
Access:							

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Good	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 361 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-050	Structure Name:	G4-050	Road Name:	KLUSKUS	Inspection Date:	2005/05/26			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Monitor beaver dams up and down stream. (OK chinch99) (OK chinch02) OK U/S - May/05 Mntce 200B - Not required - Crossing to be removed 2005 - May/05								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):				Estimated Replacement (year):					
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Accepted By Raymond Getzlaf on 2012/04/13 00:00:00				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 362 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-051	Structure Name:	G4-051	Road Name:	KLUSKUS	Inspection Date:	2020/07/29
KM:	77.00	User km:	77.00	Crossing Name:	Big Bend Creek	Next Inspection Date:	2023/07/29
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	2,000			Outlet Cover (mm):	2,000		
Footing Type:	Piles			Gradient (%):			
Culvert Length (metres):	14.6	Opening Height (mm):	2,530	Opening Width (mm):	7,446		
UTM Zone:	10	UTM Easting:	394950	UTM Northing:	5932573		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1997		
Access:							

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	Rust along bottom edge
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Not Applicable	
Footing	Good	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 363 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-051	Structure Name:	G4-051	Road Name:	KLUSKUS	Inspection Date:	2020/07/29			
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Good									
CHANNEL	Estimated Present Water Level Depth:		1.0		Estimated Present Water Level Width:		5.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	scour along left footing top								
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	looks good								
GENERAL	Estimated Load Restriction (year):			2047		Estimated Replacement (year):				
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2021/02/09 14:37:28			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 364 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-057	Structure Name:	G4-057	Road Name:	KLUSKUS	Inspection Date:	2016/07/12
KM:	83.00	User km:	83.00	Crossing Name:	unknown	Next Inspection Date:	2019/07/12
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Elliptical			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):	1.0		
Culvert Length (metres):	26.0	Opening Height (mm):	1,400	Opening Width (mm):	2,130		
UTM Zone:	10	UTM Easting:	397599	UTM Northing:	5928242		
Inspector Name:	Donovan J. A. Melin			Year Superstructure Installed:	2007		
Access:	Minor culvert						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Excellent	beautiful with the spaced rocks and gravel.
Fill	Good	
Floor	Unrated	under gravel
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 365 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-057	Structure Name:	G4-057	Road Name:	KLUSKUS	Inspection Date:	2016/07/12				
Overall	Good										
Riprap	Not Applicable										
Roof	Good										
Side Walls	Good										
Trash Rack	Not Applicable										
Wiers/Backwater Structures	Not Applicable										
Wing Wall	Not Applicable										
CHANNEL	Estimated Present Water Level Depth:		0.0		Estimated Present Water Level Width:		0.0				
	Estimated High Water Level Clearance:		0.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No	
	Comment:	No water has touched this culvert.									
REPAIRS	#	Status	Priority	Estimate	Description						
MONITORS	#	Description									
GENERAL	Inspector's Comment:	This culvert is not here for a watercourse. It looks like it was built for animal migration. Culvert is in excellent condition. Wrong photos uploaded in 2013. MD									
GENERAL	PEng's Comment:										
GENERAL	Estimated Load Restriction (year):		2045		Estimated Replacement (year):						
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:		L100
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2016/12/19 09:30:09				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 366 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-052	Structure Name:	G4-052-2	Road Name:	KLUSKUS	Inspection Date:	2020/07/29
KM:	83.70	User km:	84.10	Crossing Name:	Big Bend Creek	Next Inspection Date:	2023/07/29
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	500			Outlet Cover (mm):	500		
Footing Type:				Gradient (%):			
Culvert Length (metres):	24.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	398740	UTM Northing:	5927463		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1979		
Access:							

APPROACHES

Alignment	Good	
Alignment	Good	
Bridge Ahead Signs Missing	2	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Fender Condition	None	
Road Surface	Good	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Baffles	Not Applicable	
Bolted Connections	Good	Rivets

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 367 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-052	Structure Name:	G4-052-2	Road Name:	KLUSKUS	Inspection Date:	2020/07/29
Bolted Connections	Good	Rivets					
Coupled Connections	Not Applicable						
Coupled Connections	Not Applicable						
Coating	Fair	Rust on bottom					
Coating	Fair	Rust on bottom					
Embedment Materials	Not Applicable						
Embedment Materials	Not Applicable						
Fill	Good						
Fill	Good						
Floor	Fair	rust					
Floor	Fair	rust					
Footing	Not Applicable						
Footing	Not Applicable						
Head Wall	Good						
Head Wall	Good						
Inlet	Good						
Inlet	Good						
Outlet	Good						
Outlet	Good						
Overall	Good						
Overall	Good						
Riprap	Not Applicable						
Riprap	Not Applicable						
Roof	Good						
Roof	Good						
Side Walls	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 368 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-052	Structure Name:	G4-052-2	Road Name:	KLUSKUS	Inspection Date:	2020/07/29			
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Good									
Wing Wall	Good									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	see structure 1 for photos								
GENERAL	PEng's Comment:	looks ok								
GENERAL	Estimated Load Restriction (year):			2030		Estimated Replacement (year):				
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2021/02/09 15:27:13			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 369 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-052	Structure Name:	G4-052	Road Name:	KLUSKUS	Inspection Date:	2020/09/29
KM:	83.70	User km:	84.10	Crossing Name:	Big Bend Creek	Next Inspection Date:	2023/09/29
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	500			Outlet Cover (mm):	500		
Footing Type:				Gradient (%):			
Culvert Length (metres):	24.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	398740	UTM Northing:	5927463		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1979		
Access:							

APPROACHES

Alignment	Good	
Alignment	Good	
Bridge Ahead Signs Missing	2	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Fender Condition	None	
Road Surface	Good	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Baffles	Not Applicable	
Bolted Connections	Good	Rivets

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 370 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-052	Structure Name:	G4-052	Road Name:	KLUSKUS	Inspection Date:	2020/09/29
Bolted Connections	Good	Rivets					
Coupled Connections	Not Applicable						
Coupled Connections	Not Applicable						
Coating	Fair	Rust on bottom					
Coating	Fair	Rust on bottom					
Embedment Materials	Not Applicable						
Embedment Materials	Not Applicable						
Fill	Good						
Fill	Good						
Floor	Fair	rust					
Floor	Fair	rust					
Footing	Not Applicable						
Footing	Not Applicable						
Head Wall	Not Applicable						
Head Wall	Not Applicable						
Inlet	Good						
Inlet	Good						
Outlet	Good						
Outlet	Good						
Overall	Good						
Overall	Good						
Riprap	Not Applicable						
Riprap	Not Applicable						
Roof	Good						
Roof	Good						
Side Walls	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 371 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-052	Structure Name:	G4-052	Road Name:	KLUSKUS	Inspection Date:	2020/09/29			
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		1.2			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Looks ok								
GENERAL	Estimated Load Restriction (year):			2030		Estimated Replacement (year):			2030	
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2021/02/09 15:17:42			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 372 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-052	Structure Name:	G4-052-3	Road Name:	KLUSKUS	Inspection Date:	2020/07/29
KM:	83.70	User km:	84.10	Crossing Name:	Big Bend Creek	Next Inspection Date:	2023/07/29
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	500			Outlet Cover (mm):	500		
Footing Type:				Gradient (%):			
Culvert Length (metres):	24.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	398740	UTM Northing:	5927463		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1979		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	Rivets
Coupled Connections	Not Applicable	
Coating	Good	Rust on floor
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	Rust
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 373 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-052	Structure Name:	G4-052-3	Road Name:	KLUSKUS	Inspection Date:	2020/07/29			
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	See culvert # 1 for photos								
GENERAL	PEng's Comment:	looks good								
GENERAL	Estimated Load Restriction (year):		2030		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2021/02/09 15:28:49			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 374 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-110	Structure Name:	G4-110A	Road Name:	KLUSKUS	Inspection Date:	2019/08/08
KM:	118.00	User km:	117.20	Crossing Name:	Chedakuz Creek	Next Inspection Date:	2022/08/08
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	21.3	# Spans:	1	Span Width:			Span Length(s) (metres): 21.3
UTM Zone:	10		UTM Easting:	383940		UTM Northing:	5909411
Inspector Name:	dawson smith			Year Superstructure Installed:	2008		
Access:							

ABUTMENTS

Bearings	Good
Bracing	Good
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Good
Piles or Posts	Good
Riprap	Excellent
Wing Wall	Not Applicable

APPROACHES

Alignment	Good
Bridge Ahead Signs Missing	0
Brushing Required	No
Delineator Missing Left (approaching structure)	0
Delineator Missing Right (approaching structure)	0
Fender Condition	Good
Posted Load Rating (Enter 0 if sign missing)	0
Road Surface	Good

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 375 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-110	Structure Name:	G4-110A	Road Name:	KLUSKUS	Inspection Date:	2019/08/08
---------	--------	-----------------	---------	------------	---------	------------------	------------

DECK

Span 1

Concrete Deck	Fair	
Curb Rail/Blocks/Posts	Good	new sections
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	4.5
	Estimated High Water Level Clearance:	4.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 376 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-110	Structure Name:	G4-110A	Road Name:	KLUSKUS	Inspection Date:	2019/08/08
GENERAL	Inspector's Comment:	good					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2050	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/20 15:47:39			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 377 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-114	Structure Name:	G4-114	Road Name:	KLUSKUS	Inspection Date:	2019/08/08
KM:	119.00	User km:	119.00	Crossing Name:	Unnamed Creek	Next Inspection Date:	2022/08/08
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	700			Outlet Cover (mm):	900		
Footing Type:	Precast Concrete Footing			Gradient (%):			
Culvert Length (metres):	14.0	Opening Height (mm):	1,360	Opening Width (mm):	3,350		
UTM Zone:	10	UTM Easting:	382946	UTM Northing:	5908529		
Inspector Name:	dawson smith			Year Superstructure Installed:	2005		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Not Applicable	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Not Applicable	
Head Wall	Good	
Inlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 378 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-114	Structure Name:	G4-114	Road Name:	KLUSKUS	Inspection Date:	2019/08/08				
Outlet	Poor	breaks in welds									
Overall	Fair										
Riprap	Not Applicable										
Roof	Unrated	CULVERT WAS FULL COULD NOT INSPECT									
Side Walls	Unrated	CULVERT WAS FULL COULD NOT INSPECT									
Trash Rack	Not Applicable										
Wing Wall	Not Applicable										
CHANNEL	Estimated Present Water Level Depth:		2.0		Estimated Present Water Level Width:		3.0				
	Estimated High Water Level Clearance:		0.5								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No	
	Comment:										
REPAIRS	#	Status	Priority	Estimate	Description						
	1	Required	Medium	\$	weld breaks						
MONITORS	#	Description									
GENERAL	Inspector's Comment:	fair, WELDS BROKEN ON RIGHT HAND HEADWALL.									
GENERAL	PEng's Comment:										
GENERAL	Estimated Load Restriction (year):			2050		Estimated Replacement (year):					
	Current Inspection Load Rating:		64		Design Load GVW (tonnes):		64		Design Vehicle Config.:		BCL62
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/01/24 14:23:01				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 379 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-111	Structure Name:	G4-111	Road Name:	KLUSKUS	Inspection Date:	2019/08/08
KM:	141.40	User km:	140.50	Crossing Name:	Fawnie Creek #1	Next Inspection Date:	2022/08/08
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Binwall	
Superstructure:	Steel I-beam				Right	Binwall	
Total Length (metres):	22.0	# Spans:	1	Span Width:			Span Length(s) (metres): 22
UTM Zone:	10		UTM Easting:	363856	UTM Northing:	5899306	
Inspector Name:	dawson smith			Year Superstructure Installed:	1996		
Access:	ROAD TENURE IS REQUIRES UPDATING						

ABUTMENTS

Bearings	Not Applicable	
Binwall	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	
Posted Load Rating (Enter 0 if sign missing)	91000	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 380 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-111	Structure Name:	G4-111	Road Name:	KLUSKUS	Inspection Date:	2019/08/08			
Road Surface		Good								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good		RECENT REPLACED						
Deck to Girder Bolts		Not Applicable								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Good								
Running Planks		Good								
Sub Deck		Good								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		1.0		Estimated Present Water Level Width:		3.0			
	Estimated High Water Level Clearance:		2.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 381 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-111	Structure Name:	G4-111	Road Name:	KLUSKUS	Inspection Date:	2019/08/08
MONITORS	#	Description					
GENERAL	Inspector's Comment:	good					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2036		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/01/20 14:58:31
Design Vehicle Config.: L100							

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 382 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-112	Structure Name:	G4-112	Road Name:	KLUSKUS	Inspection Date:	2019/08/08
KM:	143.00	User km:	142.00	Crossing Name:	Fawnie Creek #2	Next Inspection Date:	2022/08/08
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Glulam Girder				Right	Pile -Permanent Materials	
Total Length (metres):	13.0	# Spans:	1	Span Width:	Span Length(s) (metres):		13
UTM Zone:	10	UTM Easting:	362656	UTM Northing:	5898147		
Inspector Name:	dawson smith			Year Superstructure Installed:	1978		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Fair	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Poor	2 posts on up side have shifted a bit
Riprap	Fair	minimal on both sides
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	91000	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 383 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-112	Structure Name:	G4-112	Road Name:	KLUSKUS	Inspection Date:	2019/08/08
---------	--------	-----------------	--------	------------	---------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Not Applicable
----------------------	----------------

Hardware	Excellent
----------	-----------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Good
----------------	------

Sub Deck	Good
----------	------

Ties	Good
------	------

SUPERSTRUCTURE

Span 1

Bracing	Not Applicable
---------	----------------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	2.5
Estimated High Water Level Clearance:	5.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
1	monitor posts for movement

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 384 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-112	Structure Name:	G4-112	Road Name:	KLUSKUS	Inspection Date:	2019/08/08
GENERAL	Inspector's Comment:	good, LOAD RATING SIGNS AND DELINIATORS DONE					
GENERAL	PEng's Comment:	Close Proximity Inspection scheduled for 2020 to determine condition of bridge. That inspection could result in additional repairs or load rating reductions.					
GENERAL	Estimated Load Restriction (year):		2024		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:						
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/24 12:15:01			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 385 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-062	Structure Name:	G4-062	Road Name:	KLUSKUS	Inspection Date:	2021/09/09
KM:	148.50	User km:	148.50	Crossing Name:	Unknown	Next Inspection Date:	2024/09/09
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	18.3	# Spans:	1	Span Width:			Span Length(s) (metres): 18.3
UTM Zone:	10		UTM Easting:	362147		UTM Northing:	5892933
Inspector Name:	Vince Sewell			Year Superstructure Installed:	2006		
Access:							

ABUTMENTS

Bearings	Good
Bracing	Good
Ballast Wall	Good
Corrosion Protection	Good
Caps or Sills	Good
Fill	Good
Hardware	Good
Piles or Posts	Good
Riprap	Good
Wing Wall	Not Applicable

APPROACHES

Alignment	Fair
Bridge Ahead Signs Missing	0
Brushing Required	No
Delineator Missing Left (approaching structure)	0
Delineator Missing Right (approaching structure)	0
Fender Condition	Good
Posted Load Rating (Enter 0 if sign missing)	91
Road Surface	Good

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 386 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-062	Structure Name:	G4-062	Road Name:	KLUSKUS	Inspection Date:	2021/09/09
---------	--------	-----------------	--------	------------	---------	------------------	------------

DECK

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Good
---------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.3	Estimated Present Water Level Width:	3.0
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	1.5
---------------------------------------	-----

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 387 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-062	Structure Name:	G4-062	Road Name:	KLUSKUS	Inspection Date:	2021/09/09
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	No concerns					
GENERAL	Estimated Load Restriction (year):		2050	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/01/19 13:46:46			

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 388 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-064	Structure Name:	G4-064	Road Name:	KLUSKUS	Inspection Date:	2021/09/08
KM:	150.20	User km:	151.60	Crossing Name:	Unknown	Next Inspection Date:	2024/09/08
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Concrete Slab Girders				Right	Steel Pipe and Precast Pad	
Total Length (metres):	10.0	# Spans:	1	Span Width:			Span Length(s) (metres): 10
UTM Zone:	10		UTM Easting:	361361		UTM Northing:	5890287
Inspector Name:	Vince Sewell			Year Superstructure Installed:	2006		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	Not visible
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 389 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-064	Structure Name:	G4-064	Road Name:	KLUSKUS	Inspection Date:	2021/09/08
---------	--------	-----------------	--------	------------	---------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Fair	1 broken riser US side broken curb
Deck Joints	Good	
Grout Pockets	Not Applicable	
Grout Pockets	Not Applicable	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Not Applicable	
Hardware	Not Applicable	
Welded/grouted shear connectors	Unrated	Can't see

CHANNEL

Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	1.0
Estimated High Water Level Clearance:	1.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	Yes	Debris:	No	Aggradation:	No
Comment:	Ice builds up under bridge in some winters, no damage								

REPAIRS

#	Status	Priority	Estimate	Description
3	Required	High	\$ 0.00	Replace damaged riser, curb and mudboards.

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 390 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-064	Structure Name:	G4-064	Road Name:	KLUSKUS	Inspection Date:	2021/09/08
GENERAL	Inspector's Comment:	Good condition except curbs will require repairs soon if hit again, still solid					
GENERAL	PEng's Comment:	Repairs required for damaged riser, curbs and replace mud boards. BH					
GENERAL	Estimated Load Restriction (year):		2056		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:		L100				
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/01/19 14:19:52			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 391 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-113	Structure Name:	G4-113	Road Name:	KLUSKUS	Inspection Date:	2021/09/23
KM:	156.70	User km:	156.80	Crossing Name:	Rozek Creek	Next Inspection Date:	2024/09/23
Project File ID #:	7655	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Glulam Girder				Right	Pile -Permanent Materials	
Total Length (metres):	13.0	# Spans:	1	Span Width:	Span Length(s) (metres):		13
UTM Zone:	10	UTM Easting:	358283	UTM Northing:	5886472		
Inspector Name:	Kody Pepper			Year Superstructure Installed:	1977		
Access:							

ABUTMENTS

Bearings	Good	Galvanized steel angle clips. The visible portions of the clips were in good condition. Other portions covered in debris.
Bracing	Not Applicable	N/A
Ballast Wall	Fair	Some scour/erosion noted at the bottom of the left abutment wall
Corrosion Protection	Not Applicable	Creosote leaching
Caps or Sills	Good	Good during sounding. Debris on the cap beams, recommend removing the debris
Fill	Fair	No issues noted
Hardware	Not Applicable	N/A
Piles or Posts	Fair	Drilled one pile per abutment, both showed dry and no rot.
Riprap	Not Applicable	No rip rap present. Only high fines under the bridge with natural vegetation beside the bridge
Wing Wall	Fair	Some scour/erosion on all wing walls. Monitor wing wall piles for movement

APPROACHES

Alignment	Good	Slight raise in grade near the bridge, but adequate
Bridge Ahead Signs Missing	1	Right approach sign is knocked over
Brushing Required	No	No issues noted
Delineator Missing Left (approaching structure)	1	Missing upstream delineator
Delineator Missing Right (approaching structure)	0	Both still in place
Fender Condition	Fair	Right downstream corner is hanging off the ballast wall. Barriers need alignment and connection, general wear noted on barriers

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 392 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-113	Structure Name:	G4-113	Road Name:	KLUSKUS	Inspection Date:	2021/09/23			
Posted Load Rating (Enter 0 if sign missing)	0	No load rating signs								
Road Surface	Fair	Slight erosion on the right approach. Noticeable hole at center of roadway								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Fair	Good during sounding. Downstream curb is leaning but was still connected to the deck and functional. Some washers missing and loose nuts noted								
Deck to Girder Bolts	Good	Some washers missing and loose nuts noted								
Hardware	Not Applicable	N/A								
Hand Rails/Walkouts	Not Applicable	N/A								
Nails	Good	No issues noted								
Overall Deck Condition	Poor	Replace 30% of the wearing surface planks. Monitor remaining wearing surface for deterioration and the downstream curb for movement								
Running Planks	Poor	30% of the wearing planks were in poor condition, remaining planks were in fair condition								
Sub Deck	Fair	Subdeck noted to be soft during sounding. Drill sample near right abutment and left abutments were dry with no rot or moisture noted.								
Ties	Fair	Drill near midspan was very hard, no rot or moisture. Drill near left abutment similar to mid span. Remaining ties were good during sounding.								
SUPERSTRUCTURE										
Span 1										
Bracing	Not Applicable	N/A								
Diaphragms	Good	No issues noted								
Girders	Good	General checking noted with width 2mm or less and depth 30mm or less								
Hardware	Good	No issues noted								
Under Trussing	Not Applicable	N/A								
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	Present water clearance is 1.84m. High fines under the bridge with no rip rap								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 393 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-113	Structure Name:	G4-113	Road Name:	KLUSKUS	Inspection Date:	2021/09/23
REPAIRS	#	Status	Priority	Estimate	Description		
	6	Required	High	\$ 0.00	Replace 30% of the wearing surface		
	7	Required	Medium	\$ 0.00	Re-align and connect the approach barriers		
	8	Required	Low	\$ 0.00	Fix right approach bridge ahead sign		
	9	Required	Low	\$ 0.00	Install left upstream delineator and re-align the others		
MONITORS	#	Description					
	4	Monitor wear surface and subdeck for deterioration					
	6	Monitor approaches for erosion					
GENERAL	Inspector's Comment:	The bridge is generally in adequate condition, but some of the wearing surface planks were worn and soft during sounding. Approximately 30% of the wearing planks are required to be replaced. The approach barriers on all four corners were noted to be disconnected and the right approach downstream barrier was hanging off the ballast wall. The right downstream barrier should be realigned and all barriers should be re-connected. The approaches should be monitored for further erosion. The downstream curb was noted to be leaning outwards and should be monitored for future movement. The fourth bearing pile on the left abutment was wrapped with some tape material and partially coated with a mortar based material. This was later determined to be a repair that was approved by Scouten Engineering in 2019. For further details, see the 2021 Close Proximity Inspection Report. Concern with curbs and end fill. DA.					
GENERAL	PEng's Comment:	Bridge seems in fair condition overall. LH Replacement date extended till 2024. See Allnorth Sept 23 2021 CP inspection report in documents and photos for details. BH					
GENERAL	Estimated Load Restriction (year):			2024	Estimated Replacement (year):		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/01/21 13:42:27	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 394 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-065	Structure Name:	G4-065-3	Road Name:	CORKSCREW	Inspection Date:	2019/08/01
KM:	9.50	User km:	10.20	Crossing Name:	Corkscrew Creek	Next Inspection Date:	2022/08/01
Project File ID #:	7655	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	300			Outlet Cover (mm):	300		
Footing Type:				Gradient (%):			
Culvert Length (metres):	16.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	423730	UTM Northing:	5966028		
Inspector Name:	Dawson SMITH		Year Superstructure Installed:				
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	LOG ACROSS INLET SHOULD BE REMOVED
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 395 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-065	Structure Name:	G4-065-3	Road Name:	CORKSCREW	Inspection Date:	2019/08/01
Overall	Good						
Riprap	Not Applicable						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		2.0
	Estimated High Water Level Clearance:		1.0				
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Aggradation: No
	Comment:						
REPAIRS	#	Status	Priority	Estimate	Description		
	1	Required	Medium	\$ 250.00	REMOVE LOG ACROSS THE INLETS		
MONITORS	#	Description					
GENERAL	Inspector's Comment:	GOOD, PIPE ON THE LEFT IN THE INLET PICTURES. LOG ACROSS INLETS NEEDS TO BE REMOVED..					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):			2030	Estimated Replacement (year):		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/14 13:07:53			

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 396 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-065	Structure Name:	G4-065	Road Name:	CORKSCREW	Inspection Date:	2019/08/08
KM:	9.50	User km:	10.20	Crossing Name:	Corkscrew Creek	Next Inspection Date:	2022/08/08
Project File ID #:	7655	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	300			Outlet Cover (mm):	300		
Footing Type:				Gradient (%):			
Culvert Length (metres):	16.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	423730	UTM Northing:	5966028		
Inspector Name:	dawson smith			Year Superstructure Installed:	1983		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 397 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-065	Structure Name:	G4-065	Road Name:	CORKSCREW	Inspection Date:	2019/08/08			
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Medium	\$ 250.00	REMOVE LOG FROM INLET					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	good, LOG NEEDS TO BE REMOVED FROM INLET, PIPE IS ON THE RIGHT IN THE INLET PICTURE								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):			2030	Estimated Replacement (year):					
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/01/14 12:47:10				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 398 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-065	Structure Name:	G4-065-2	Road Name:	CORKSCREW	Inspection Date:	2019/08/01
KM:	9.50	User km:	10.20	Crossing Name:	Corkscrew Creek	Next Inspection Date:	2022/08/01
Project File ID #:	7655	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	300			Outlet Cover (mm):	300		
Footing Type:				Gradient (%):			
Culvert Length (metres):	16.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	423730	UTM Northing:	5966028		
Inspector Name:	Dawson SMITH		Year Superstructure Installed:	1983			
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 399 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-065	Structure Name:	G4-065-2	Road Name:	CORKSCREW	Inspection Date:	2019/08/01			
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Medium	\$ 250.00	REMOVE LOG FROM ACROSS INLET					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	GOOD, MIDDLE PIPE IN THE PICTURES.								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):			2030		Estimated Replacement (year):				
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.: L100	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/01/14 13:06:38			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 400 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-070	Structure Name:	G4-070	Road Name:	LAVOIE-GOLD	Inspection Date:	2020/10/22
KM:	3.00	User km:	2.50	Crossing Name:	Roy Creek	Next Inspection Date:	2023/10/22
Project File ID #:	7655	Br.	04	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,200			Outlet Cover (mm):	1,200		
Footing Type:				Gradient (%):			
Culvert Length (metres):	21.0	Opening Height (mm):	3,000	Opening Width (mm):	3,000		
UTM Zone:	10	UTM Easting:	409378	UTM Northing:	5937340		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1993		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	rust on floor
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	rust on floor
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 401 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-070	Structure Name:	G4-070	Road Name:	LAVOIE-GOLD	Inspection Date:	2020/10/22			
Overall	Good									
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.0						
	Estimated High Water Level Clearance:	1.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	looks good								
GENERAL	Estimated Load Restriction (year):	2033	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/02/09 16:03:23						

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 402 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-071	Structure Name:	G4-071-2	Road Name:	LAVOIE-GOLD	Inspection Date:	2020/10/22
KM:	3.50	User km:	3.50	Crossing Name:	Finger Creek	Next Inspection Date:	2023/10/22
Project File ID #:	7655	Br.	04	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,500			Outlet Cover (mm):	1,500		
Footing Type:				Gradient (%):			
Culvert Length (metres):	21.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	408572	UTM Northing:	5936852		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1983		
Access:							

--

CHANNEL	Estimated Present Water Level Depth:		Estimated Present Water Level Width:	
	Estimated High Water Level Clearance:			

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Medium	\$	beaver dam inlet culvert #2

MONITORS	#	Description

GENERAL	Inspector's Comment:	second culvert from left see culvert #1 for photos

GENERAL	PEng's Comment:	remove debris from culvert

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 403 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-071	Structure Name:	G4-071-2	Road Name:	LAVOIE-GOLD	Inspection Date:	2020/10/22
---------	--------	-----------------	----------	------------	-------------	------------------	------------

GENERAL

Estimated Load Restriction (year):	2030	Estimated Replacement (year):	
Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91
Design Vehicle Config.:			
Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/02/16 14:09:28

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 404 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-071	Structure Name:	G4-071	Road Name:	LAVOIE-GOLD	Inspection Date:	2020/10/22
KM:	3.50	User km:	3.50	Crossing Name:	Finger Creek	Next Inspection Date:	2023/10/22
Project File ID #:	7655	Br.	04	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,100			Outlet Cover (mm):	1,100		
Footing Type:				Gradient (%):			
Culvert Length (metres):	21.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	408572	UTM Northing:	5936852		
Inspector Name:	warren Wilkinson			Year Superstructure Installed:	1983		
Access:							

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Fair	Rust on floor
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	Rust on floor
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 405 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-071	Structure Name:	G4-071	Road Name:	LAVOIE-GOLD	Inspection Date:	2020/10/22
Overall	Fair						
Riprap	Fair						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						
CHANNEL	Estimated Present Water Level Depth:		1.5		Estimated Present Water Level Width:		2.0
	Estimated High Water Level Clearance:		1.7				
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Aggradation: No
	Comment:						
REPAIRS	#	Status	Priority	Estimate	Description		
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Remove debris from culvert.					
GENERAL	Estimated Load Restriction (year):		2030		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:						
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/02/16 14:07:22			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 406 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-072	Structure Name:	G4-072	Road Name:	LAVOIE-GOLD	Inspection Date:	2020/10/22
KM:	11.40	User km:	11.40	Crossing Name:	Tatuk Creek	Next Inspection Date:	2023/10/22
Project File ID #:	7655	Br.	04	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Binwall	
Superstructure:	Steel I-beam				Right	Binwall	
Total Length (metres):	9.0	# Spans:	1	Span Width:	Span Length(s) (metres):		9
UTM Zone:	10		UTM Easting:	411599	UTM Northing:	5931051	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1995		
Access:							

ABUTMENTS

Bearings	Good	
Binwall	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	cannot see
Riprap	Good	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 407 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-072	Structure Name:	G4-072	Road Name:	LAVOIE-GOLD	Inspection Date:	2020/10/22
---------	--------	-----------------	--------	------------	-------------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Good
----------------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Good
----------------	------

Sub Deck	Good
----------	------

Ties	Good
------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Good
----------------	------

CHANNEL

Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	2.0
Estimated High Water Level Clearance:	1.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 408 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-072	Structure Name:	G4-072	Road Name:	LAVOIE-GOLD	Inspection Date:	2020/10/22
GENERAL	Inspector's Comment:	New Deck has been put on bridge. BCTS.					
GENERAL	PEng's Comment:	looks good					
GENERAL	Estimated Load Restriction (year):		2035	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/02/16 14:12:05			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 409 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-073	Structure Name:	G4-924	Road Name:	LAVOIE-GOLD	Inspection Date:	2021/09/09
KM:	16.40	User km:	16.70	Crossing Name:	Unknown	Next Inspection Date:	2024/09/09
Project File ID #:	7655	Br.	04	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Steel			Running Surface:	Anti-skid		
Curb Type:				Abutments (looking downstream)	Left	Sill - Permanent Materials	
Superstructure:	Steel Box Beam				Right	Sill - Permanent Materials	
Total Length (metres):	7.6	# Spans:	1	Span Width:	Span Length(s) (metres):		0
UTM Zone:	10	UTM Easting:	410422	UTM Northing:	5926223		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	2006		
Access:	Travel down the Kluskus FSR to 59 km and turn south onto the Gold Road. Travel to 16 km to reach the bridge						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Poor	Treated timbers are undersized for soft ground
Fill	Fair	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Unrated	None
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 410 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-073	Structure Name:	G4-924	Road Name:	LAVOIE-GOLD	Inspection Date:	2021/09/09
---------	--------	-----------------	--------	------------	-------------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	
Running Surface	Poor	5cm of mud over deck
Steel Deck Plate	Good	

SUPERSTRUCTURE

Span 1

Bracing	Not Applicable	
Diaphragms	Unrated	Can not inspect. No clearance
Girders	Unrated	Can not inspect. No clearance
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	0.5
	Estimated High Water Level Clearance:	0.2		

HAZARDS	High Water:	Yes	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
2	Required	Medium	\$ 0.00	Brush obscuring bridge rails
3	Required	High	\$ 0.00	Replace sills with larger bearing surface or add mud sill
4	Required	Medium	\$ 0.00	Add two delineators
5	Required	High	\$ 0.00	Beaver Dam removal

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 411 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-073	Structure Name:	G4-924	Road Name:	LAVOIE-GOLD	Inspection Date:	2021/09/09	
GENERAL	Inspector's Comment:	Bridge has settled 3cm below ballast boards on both sides consistently. Need an abutment with a much larger bearing surface. Bridge should be raised 500 mm minimum. Load restriction required. Cannot take abutment pictures due to low clearance/high water.						
GENERAL	PEng's Comment:	Beaver activity and high water has submerged abutments and difficult to inspect. Poor sill bearing suspected. Bridge should be removed if not needed. Could be downrated at any time due to settlement of bridge. BH						
GENERAL	Estimated Load Restriction (year):		2030		Estimated Replacement (year):		2030	
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/01 18:17:44		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 412 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-100	Structure Name:	G4-100	Road Name:	NATALKUZ-500	Inspection Date:	2021/08/30
KM:	36.20	User km:	536.20	Crossing Name:	Lucas Creek	Next Inspection Date:	2024/08/30
Project File ID #:	7655	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	30.0	# Spans:	1	Span Width:	Span Length(s) (metres):		30
UTM Zone:	10	UTM Easting:	362694	UTM Northing:	5936258		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1999		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Fair	Left downstream Spalding at corner of girder
Corrosion Protection	Not Applicable	
Caps or Sills	Good	Sills
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	Can't see
Riprap	Good	None along stream and not required
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Fair	One nose cone knocked off
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 413 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-100	Structure Name:	G4-100	Road Name:	NATALKUZ-500	Inspection Date:	2021/08/30
---------	--------	-----------------	--------	------------	--------------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Good	
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Fair	One bolt broken by grader
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Good	

CHANNEL

Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	4.0
Estimated High Water Level Clearance:	2.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
5	Not Required	Medium	\$ 0.00	Add load limit signs
6	Required	Medium		Replace missing delineators 2 right 1 left
7	Required	High	\$ 0.00	Replace rotten curbs. Replace broken bolt in curb.

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 414 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-100	Structure Name:	G4-100	Road Name:	NATALKUZ-500	Inspection Date:	2021/08/30
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Some sections of curbs need replacement. Downrating may occur if repairs are not done as soon as possible. BH					
GENERAL	Estimated Load Restriction (year):		2049		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:		L100				
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/02 12:55:54			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 415 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-053	Structure Name:	G4-053-2	Road Name:	KLUSKUS BLUE	Inspection Date:	2019/08/08
KM:	21.50	User km:	0.00	Crossing Name:	Suscha Creek	Next Inspection Date:	2022/08/08
Project File ID #:	7655	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	900			Outlet Cover (mm):	900		
Footing Type:				Gradient (%):			
Culvert Length (metres):	18.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	407485	UTM Northing:	5898122		
Inspector Name:	dawson smith		Year Superstructure Installed:	1983			
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 416 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-053	Structure Name:	G4-053-2	Road Name:	KLUSKUS BLUE	Inspection Date:	2019/08/08
Overall	Good						
Riprap	Not Applicable						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		0.5
	Estimated High Water Level Clearance:		1.0				
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Aggradation: No
	Comment:						
REPAIRS	#	Status	Priority	Estimate	Description		
	1	Not Required	Medium	\$	inlet and outlet require brushing		
MONITORS	#	Description					
GENERAL	Inspector's Comment:	PIPE ON THE LEFT IN PICTURE 6072, THICK BRUSH MADE IT IMPOSSIBLE TO GET BETTER PICTURES, NEEDS BRUSHING					
GENERAL	PEng's Comment:	no brush issue					
GENERAL	Estimated Load Restriction (year):			2023	Estimated Replacement (year):		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status: Reviewed By Jason Olmsted on 2020/01/20 15:00:23			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 417 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-053	Structure Name:	G4-053	Road Name:	KLUSKUS BLUE	Inspection Date:	2019/08/08
KM:	21.50	User km:	0.00	Crossing Name:	Suscha Creek	Next Inspection Date:	2022/08/08
Project File ID #:	7655	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	500			Outlet Cover (mm):	500		
Footing Type:				Gradient (%):			
Culvert Length (metres):	18.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	407485	UTM Northing:	5898122		
Inspector Name:	dawson smith			Year Superstructure Installed:	1983		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 418 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-053	Structure Name:	G4-053	Road Name:	KLUSKUS BLUE	Inspection Date:	2019/08/08			
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.2							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Not Required	Medium	\$	inlet and outlet require brushing					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	GOOD, DOWNSTREAM SIDE BRUSHED IN								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):			2023	Estimated Replacement (year):					
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/01/20 14:55:59				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 419 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-054	Structure Name:	G4-054	Road Name:	KLUSKUS BLUE	Inspection Date:	2020/07/29
KM:	49.50	User km:	51.00	Crossing Name:	Unnamed creek	Next Inspection Date:	2023/07/29
Project File ID #:	7655	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	14.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	384128	UTM Northing:	5887208		
Inspector Name:	Vince Sewell			Year Superstructure Installed:	1993		
Access:	Site is located at 49.5 km of the Blue Road. Mainly winter access. culvert #1 left when facing downstream						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	too much water to walk through, appears good
Coating	Fair	some bottom rust
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 420 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-054	Structure Name:	G4-054	Road Name:	KLUSKUS BLUE	Inspection Date:	2020/07/29			
Inlet	Good	minor scour								
Outlet	Good	25cm drop, small fish trying to jump								
Overall	Good									
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		1.5			
	Estimated High Water Level Clearance:		5.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	looks good								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 421 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-054	Structure Name:	G4-054	Road Name:	KLUSKUS BLUE	Inspection Date:	2020/07/29
GENERAL	Estimated Load Restriction (year):		2033	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/02/09 15:34:37	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 422 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-054	Structure Name:	G4-054-2	Road Name:	KLUSKUS BLUE	Inspection Date:	2020/07/29
KM:	49.50	User km:	51.00	Crossing Name:	Unnamed creek	Next Inspection Date:	2023/07/29
Project File ID #:	7655	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	14.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	384128	UTM Northing:	5887208		
Inspector Name:	Vince Sewell			Year Superstructure Installed:	1993		
Access:	Site is located at 49.5 km of the Blue Road. Mainly winter access. culvert #1 left when facing downstream						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 423 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-054	Structure Name:	G4-054-2	Road Name:	KLUSKUS BLUE	Inspection Date:	2020/07/29			
Inlet	Good									
Outlet	Good									
Overall	Good									
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:		0.2					
	Estimated High Water Level Clearance:	0.6								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	culvert #2 right when facing downstream see culvert 1 2020 inspection for photos								
GENERAL	PEng's Comment:	looks good								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 424 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-054	Structure Name:	G4-054-2	Road Name:	KLUSKUS BLUE	Inspection Date:	2020/07/29
GENERAL	Estimated Load Restriction (year):		2033	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/02/09 15:32:58	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 425 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-090	Structure Name:	G4-090	Road Name:	MALAPUT	Inspection Date:	2001/07/12
KM:	3.60	User km:	3.60	Crossing Name:	Unnamed creek	Next Inspection Date:	2030/01/01
Project File ID #:	7655	Br.	09	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	21,000			Outlet Cover (mm):	21,000		
Footing Type:				Gradient (%):	7.0		
Culvert Length (metres):	89.4	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	360346	UTM Northing:	5897540		
Inspector Name:	Ed Cienciala			Year Superstructure Installed:	1989		
Access:	Minor culvert						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI
Trash Rack	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 426 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-090	Structure Name:	G4-090	Road Name:	MALAPUT	Inspection Date:	2001/07/12			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.9							
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Monitor scour at outlet and road fill erosion if not repaired.								
GENERAL	Inspector's Comment:	Approach: Medium potential for road surface erosion on D/S side.								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2039		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/12 16:35:25			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 427 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-091	Structure Name:	G4-091	Road Name:	MALAPUT	Inspection Date:	2002/06/26
KM:	16.70	User km:	16.70	Crossing Name:	Unnamed creek	Next Inspection Date:	2005/06/26
Project File ID #:	7655	Br.	09	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	700			Outlet Cover (mm):	700		
Footing Type:				Gradient (%):	3.0		
Culvert Length (metres):	18.0	Opening Height (mm):	1,400	Opening Width (mm):	1,400		
UTM Zone:	10	UTM Easting:	349257	UTM Northing:	5891544		
Inspector Name:	Tim Silbernagel			Year Superstructure Installed:	1989		
Access:	Minor culvert, 1400mm, leave as DNI. GZ 2020						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Good	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 428 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-091	Structure Name:	G4-091	Road Name:	MALAPUT	Inspection Date:	2002/06/26			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Windfall problem upstream to monitor. Monitor scour at outlet if not fixed. (no change - chinch 2002)								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2039		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/13 11:20:48			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 429 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-092	Structure Name:	G4-092	Road Name:	MALAPUT	Inspection Date:	2019/08/08
KM:	19.60	User km:	19.60	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/08/08
Project File ID #:	7655	Br.	09	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	10,700			Outlet Cover (mm):	10,700		
Footing Type:				Gradient (%):	7.0		
Culvert Length (metres):	48.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	346584	UTM Northing:	5892022		
Inspector Name:	dawson smith			Year Superstructure Installed:	1989		
Access:	Minor culvert						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	INLET SIDE
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Fair	MINOR SCOURING ON RIGHT SIDE OF ROAD

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Excellent	
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 430 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-092	Structure Name:	G4-092	Road Name:	MALAPUT	Inspection Date:	2019/08/08
Overall	Good						
Riprap	Not Applicable						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						
CHANNEL	Estimated Present Water Level Depth:	0.2			Estimated Present Water Level Width:	5.0	
	Estimated High Water Level Clearance:	1.0					
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Aggradation: No
	Comment:						
REPAIRS	#	Status	Priority	Estimate	Description		
	1	Not Required	Medium	\$	brush out inlet		
MONITORS	#	Description					
GENERAL	Inspector's Comment:	good, LOCK BLOCKS ON ROAD BED, INLET BRUSHED IN, MINOR SCOURING ON ROAD BED					
GENERAL	PEng's Comment:	From the pictures the brush is NOT in the stream or blocking the inlet. It appears to be just vegetation growing on the ground.					
GENERAL	Estimated Load Restriction (year):	2025		Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/20 14:52:44			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 431 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-059	Structure Name:	G4-059	Road Name:	BLACKWATER-	Inspection Date:	2019/08/08
KM:	6.30	User km:	6.30	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/08/08
Project File ID #:	7655	Br.	10	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	900			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):	1.0		
Culvert Length (metres):	20.0	Opening Height (mm):	2,000	Opening Width (mm):	2,000		
UTM Zone:	10	UTM Easting:	411445	UTM Northing:	5896792		
Inspector Name:	dawson smith			Year Superstructure Installed:	1988		
Access:	Road is posted as the 4000 Road						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Good	
Bolted Connections	Not Applicable	
Coupled Connections	Poor	seperation 1/3 way from outlet end
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 432 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-059	Structure Name:	G4-059	Road Name:	BLACKWATER-	Inspection Date:	2019/08/08
Overall	Fair						
Riprap	Not Applicable						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		0.5
	Estimated High Water Level Clearance:		1.0				
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris: No Aggradation: No
	Comment:						
REPAIRS	#	Status	Priority	Estimate	Description		
	1	Required	Low	\$	inlet and outlet require brushing		
MONITORS	#	Description					
	1	monitor seperation of coupler					
GENERAL	Inspector's Comment:	good, at 5.9 kms					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):			2028	Estimated Replacement (year):		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/24 08:30:54			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 433 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-058	Structure Name:	G4-926	Road Name:	BLACKWATER-	Inspection Date:	2020/07/22
KM:	16.00	User km:	16.00	Crossing Name:	Beamis Creek	Next Inspection Date:	2022/05/12
Project File ID #:	7655	Br.	10	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Steel I-beam				Right	Sill -Temporary Materials	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	10	UTM Easting:	419934	UTM Northing:	5896711		
Inspector Name:	Warren Wilkinson		Year Superstructure Installed:	2001			
Access:	Turn off at 100 km on Kluskus onto Blue Road. Turn left at 19 km onto Kluskus-Blackwater. Access control (concrete blocks) at 13.5 km.						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	a couple of board bowed
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	corner and hill
Bridge Ahead Signs Missing	0	badly brushed in
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Fair	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 434 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-058	Structure Name:	G4-926	Road Name:	BLACKWATER-	Inspection Date:	2020/07/22
---------	--------	-----------------	--------	------------	-------------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Good
----------------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Good
---------------------	------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Good
----------------	------

Sub Deck	Good
----------	------

Ties	Good
------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Good
----------------	------

CHANNEL

Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.5
Estimated High Water Level Clearance:	1.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 435 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-058	Structure Name:	G4-926	Road Name:	BLACKWATER-	Inspection Date:	2020/07/22
GENERAL	Inspector's Comment:	inspected earlier in the year by Gary Zsombor					
GENERAL	PEng's Comment:	see other inspection					
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/02/17 10:40:29			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 436 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-066	Structure Name:	G4-066	Road Name:	BLACKWATER-	Inspection Date:	2021/09/09
KM:	19.00	User km:	19.00	Crossing Name:	Fireguard Creek	Next Inspection Date:	2024/09/09
Project File ID #:	7655	Br.	10	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	18.3	# Spans:	1	Span Width:			Span Length(s) (metres): 18
UTM Zone:	10		UTM Easting:	420956	UTM Northing:	5894382	
Inspector Name:	Vince Sewell			Year Superstructure Installed:	2020		
Access:							

ABUTMENTS		
Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES		
Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 437 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-066	Structure Name:	G4-066	Road Name:	BLACKWATER-	Inspection Date:	2021/09/09
---------	--------	-----------------	--------	------------	-------------	------------------	------------

DECK

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Good
---------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	3.0
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	2.5
---------------------------------------	-----

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 438 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-066	Structure Name:	G4-066	Road Name:	BLACKWATER-	Inspection Date:	2021/09/09
GENERAL	Inspector's Comment:	New Bridge no industrial use very good condition					
GENERAL	PEng's Comment:	No concerns. BH					
GENERAL	Estimated Load Restriction (year):		2065	Estimated Replacement (year):		2065	
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status: Reviewed By Bruce Henderson on 2022/01/18 12:01:31			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 439 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-080	Structure Name:	G4-908	Road Name:	LUCAS	Inspection Date:	2021/08/30
KM:	1.30	User km:	1.20	Crossing Name:	Lucas Creek	Next Inspection Date:	2023/08/30
Project File ID #:	7655	Br.	14	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Steel I-beam				Right	Sill -Temporary Materials	
Total Length (metres):	12.0	# Spans:	1	Span Width:			Span Length(s) (metres): 12
UTM Zone:	10		UTM Easting:	363144		UTM Northing:	5935188
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1990		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Fair	Unpealed spruce/pne
Corrosion Protection	Not Applicable	
Caps or Sills	Good	Treated sills sitting on ground
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Poor	None on left side limited on right side
Wing Wall	Not Applicable	

APPROACHES

Alignment	Poor	Curves on both sides
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	Logs sitting on gravel
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Fair	Wilderness level

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 440 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-080	Structure Name:	G4-908	Road Name:	LUCAS	Inspection Date:	2021/08/30
---------	--------	-----------------	--------	------------	-------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Good	Clips
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Good	
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Fair	Loose bolts
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	4.0
	Estimated High Water Level Clearance:	0.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	8	Required	Medium	\$ 0.00	Add rip rap to left side.

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 441 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-080	Structure Name:	G4-908	Road Name:	LUCAS	Inspection Date:	2021/08/30	
GENERAL	Inspector's Comment:							
GENERAL	PEng's Comment:	Nearing end of life. Needs rip rap installed left side. Posted at 91 tonnes. BH						
GENERAL	Estimated Load Restriction (year):		2025		Estimated Replacement (year):		2025	
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/02 11:56:01		

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 442 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-060	Structure Name:	G4-060	Road Name:	CHEDAKUZ	Inspection Date:	2020/08/19
KM:	8.10	User km:	8.10	Crossing Name:	Unnamed creek	Next Inspection Date:	2023/08/19
Project File ID #:	7655	Br.	18	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,500			Outlet Cover (mm):	1,500		
Footing Type:				Gradient (%):			
Culvert Length (metres):	18.0	Opening Height (mm):	2,200	Opening Width (mm):	2,200		
UTM Zone:	10	UTM Easting:	369047	UTM Northing:	5909925		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1991		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Fair	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	Rust on floor
Embedment Materials	Not Applicable	
Fill	Good	1m
Floor	Fair	Rust
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	rip rap has rolled in to inlet
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 443 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-060	Structure Name:	G4-060	Road Name:	CHEDAKUZ	Inspection Date:	2020/08/19
Overall	Excellent						
Riprap	Fair	rip rap has rolled in to inlet					
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		1.0
	Estimated High Water Level Clearance:		1.0				
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris: No Aggradation: No
	Comment:	Scour at inlet					
REPAIRS	#	Status	Priority	Estimate	Description		
MONITORS	#	Description					
	2	Scour at inlet					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	looks good					
GENERAL	Estimated Load Restriction (year):			2031	Estimated Replacement (year):		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/02/09 15:37:01			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 444 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-095	Structure Name:	G4-915	Road Name:	NARCOSLI	Inspection Date:	2020/07/15
KM:	3.80	User km:	5.00	Crossing Name:	Beamis Creek	Next Inspection Date:	2023/07/15
Project File ID #:	7655	Br.	20	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	15.3	# Spans:	1	Span Width:			Span Length(s) (metres): 15.3
UTM Zone:	10		UTM Easting:	417615	UTM Northing:	5898444	
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1998		
Access:	Turn left at about km 10 on the Kluskus-Blackwater FSR (4000 road)						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Fair	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Fair	Graded. all small boulders
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Fair	
Road Surface	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 445 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-095	Structure Name:	G4-915	Road Name:	NARCOSLI	Inspection Date:	2020/07/15
---------	--------	-----------------	--------	------------	----------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Fair	
Overall Deck Condition	Fair	
Running Planks	Fair	
Sub Deck	Fair	Showing signs of decay on underside
Ties	Fair	Showing signs of decay on underside

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.4	Estimated Present Water Level Width:	6.0
Estimated High Water Level Clearance:	1.9		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
Comment:	Lots of blow down in stream								

REPAIRS

#	Status	Priority	Estimate	Description

MONITORS

#	Description
1	Monitor deck components for decay

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 446 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-095	Structure Name:	G4-915	Road Name:	NARCOSLI	Inspection Date:	2020/07/15
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	looks ok					
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):		2030	
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/02/17 14:28:08			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 447 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-094	Structure Name:	G4-911	Road Name:	MOOSE LAKE	Inspection Date:	2020/08/19
KM:	12.80	User km:	12.80	Crossing Name:	Unnamed creek	Next Inspection Date:	2023/08/19
Project File ID #:	7655	Br.	28	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	10.4	# Spans:	1	Span Width:			Span Length(s) (metres): 10.4
UTM Zone:	10	UTM Easting:	348085	UTM Northing:	5886716		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1999		
Access:	Gated at the start of the road - get key from District or Helicopter access						

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Poor	Right upstream side broken, letting fill fall through
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Poor	does not go to bank edge, some has fallen into stream
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Poor	post good, rot in treated logs
Posted Load Rating (Enter 0 if sign missing)	5	
Road Surface	Poor	Wilderness

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 448 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-094	Structure Name:	G4-911	Road Name:	MOOSE LAKE	Inspection Date:	2020/08/19
---------	--------	-----------------	--------	------------	------------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Poor	curbs soft and missing posts
Deck to Girder Bolts	Good	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Nails	Poor	rotting deck
Overall Deck Condition	Poor	rot
Running Planks	Not Applicable	
Sub Deck	Poor	Rotting with holes
Ties	Poor	good under deck but rotting where exposed

SUPERSTRUCTURE

Span 1

Bracing	Fair	one badly bent
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Fair	

CHANNEL

Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	2.0
Estimated High Water Level Clearance:	1.0		

HAZARDS

High Water:	No	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	No
Comment:	scour under bridge not protected by riprap								

REPAIRS

#	Status	Priority	Estimate	Description
9	Required	High	\$	replace all wood componence

MONITORS

#	Description
2	broken boards in ballast wall

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 449 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-094	Structure Name:	G4-911	Road Name:	MOOSE LAKE	Inspection Date:	2020/08/19
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Bridge deck needs replacing ASAP or else it might be closed to all traffic.					
GENERAL	Estimated Load Restriction (year):		2010	Estimated Replacement (year):			
	Current Inspection Load Rating:	5	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/02/17 14:10:28			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 450 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-127	Structure Name:	G4-127	Road Name:	BLACKFLY	Inspection Date:	2011/09/21
KM:	4.80	User km:	4.80	Crossing Name:	Un-named Creek	Next Inspection Date:	2013/09/21
Project File ID #:	7655	Br.	38	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Log Stringers				Right	Crib, Log or Untreated Timber	
Total Length (metres):	6.0	# Spans:	1	Span Width:			Span Length(s) (metres): 6
UTM Zone:	10		UTM Easting:	387129		UTM Northing:	5902659
Inspector Name:	Shane Goretzky			Year Superstructure Installed:			
Access:	Bridge was removed by BCTS in 2013. Travel south on the Kluskus to 124.5 km. Turn onto the Davidson Road and travel to 6 km. Turn left onto the Blackfly and travel to						

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	Signs of rot on downchain side
Fill	Fair	
Hardware	Not Applicable	
Log/Timber Cribs	Fair	
Piles or Posts	Not Applicable	
Riprap	Good	
Tie-backs	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 451 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-127	Structure Name:	G4-127	Road Name:	BLACKFLY	Inspection Date:	2011/09/21			
Road Surface		Fair								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Fair								
Deck to Girder Bolts		Not Applicable								
Hardware		Not Applicable								
Hand Rails/Walkouts		Not Applicable								
Nails		Fair								
Overall Deck Condition		Fair		fair to poor condition						
Running Planks		Not Applicable								
Sub Deck		Fair		Some planks showing rot and hole in deck						
Ties		Fair								
STRINGERS										
Span 1										
Log Curbs		Fair								
Needle Beam(s) and Shims		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.0		Estimated Present Water Level Width:		0.0			
	Estimated High Water Level Clearance:		0.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Medium	\$	Deck requires replacement prior to any industrial use					
MONITORS	#	Description								
	1	monitor rot in stringer, sill and ties								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 452 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-127	Structure Name:	G4-127	Road Name:	BLACKFLY	Inspection Date:	2011/09/21
GENERAL	Inspector's Comment:	Low to zero traffic, behind access management point Need Log stringer measurements. Bridge rated at 5 tonnes until structure data is completed and checked.					
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments					
GENERAL	Estimated Load Restriction (year):		2015		Estimated Replacement (year):		
	Current Inspection Load Rating:		5		Design Load GVW (tonnes):		Design Vehicle Config.:
	Professional Inspection Required?		No		Report Status: Accepted By Jason Olmsted on 2013/05/24 00:00:00		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 453 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-115	Structure Name:	G4-115A	Road Name:	SALAMANDER/BL	Inspection Date:	2021/09/09
KM:	6.40	User km:	1.50	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/09/09
Project File ID #:	7655	Br.	49	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:			Span Length(s) (metres): 12.2
UTM Zone:	10		UTM Easting:	408907	UTM Northing:	5908883	
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	2019		
Access:	Turn left off Kluskus FSR at 99.5 km (Blue Road) then turn left off Blue road at 8.8 km onto 2500 road then turn right at 2503 km.						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Fair	small dead timber logs
Concrete Lock Blocks	Fair	Corner block spalling from fire damage, gap under the front of the timber sill on left abutment
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	1	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 454 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-115	Structure Name:	G4-115A	Road Name:	SALAMANDER/BL	Inspection Date:	2021/09/09			
Posted Load Rating (Enter 0 if sign missing)	0									
Road Surface	Fair	Low on eaach side								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Good									
Sub Deck	Unrated	none								
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Not Applicable									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		1.6							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 455 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-115	Structure Name:	G4-115A	Road Name:	SALAMANDER/BL	Inspection Date:	2021/09/09
REPAIRS	#	Status	Priority	Estimate	Description		
	1	Required	Medium		Bush side missing		
	2	Required	Low				
	3	Required	Low		add fill to both approaches		
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Bridge is to be removed in 2022. BH					
GENERAL	Estimated Load Restriction (year):		2060		Estimated Replacement (year):		
	Current Inspection Load Rating:		68		Design Load GVW (tonnes):		Design Vehicle Config.: L75
	Professional Inspection Required?		No		Report Status: Reviewed By Bruce Henderson on 2022/02/04 11:22:44		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 456 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-122	Structure Name:	G1-927	Road Name:	VIGANO	Inspection Date:	2020/08/19
KM:	3.20	User km:	1.90	Crossing Name:	Matthews Creek	Next Inspection Date:	2023/08/19
Project File ID #:	7655	Br.	60	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Precast	
Superstructure:	Steel I-beam				Right	Concrete Precast	
Total Length (metres):	18.3	# Spans:	1	Span Width:			Span Length(s) (metres): 18.3
UTM Zone:	10		UTM Easting:	355058		UTM Northing:	5886964
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2016		
Access:	Turn right at km 156 on the Kluskus-Ootsa then turn left at km 1.0						

ABUTMENTS

Bearings	Good	skewed on Right upstream, sitting on sill
Bracing	Not Applicable	
Ballast Wall	Good	right side top timber not sitting square
Concrete Precast	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Fair	
Wing Wall	Good	some lock blocks skewed

APPROACHES

Alignment	Poor	hill and corners
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	30	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 457 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-122	Structure Name:	G1-927	Road Name:	VIGANO	Inspection Date:	2020/08/19			
Road Surface	Poor	wilderness								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Fair	rot in a couple of curbs								
Deck to Girder Bolts	Good									
Hardware	Not Applicable									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Good									
Sub Deck	Fair	ro tin some boards first pannel								
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Good									
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:									
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 458 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-122	Structure Name:	G1-927	Road Name:	VIGANO	Inspection Date:	2020/08/19
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	According to previous bridge inspection bridge deck needs to be replaced and it does not appeared to have happen. Keep bridge at 30 tonnes.					
GENERAL	Estimated Load Restriction (year):		2050	Estimated Replacement (year):			
	Current Inspection Load Rating:	30	Design Load GVW (tonnes):	68	Design Vehicle Config.:	L75	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/01/22 13:56:51			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 459 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-075	Structure Name:	G4-919	Road Name:	GOLD 5000	Inspection Date:	2021/10/06
KM:	1.70	User km:	1.70	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/10/06
Project File ID #:	7655	Br.	77	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Concrete Precast	
Superstructure:	Steel I-beam				Right	Concrete Precast	
Total Length (metres):	15.2	# Spans:	1	Span Width:	Span Length(s) (metres):		15.2
UTM Zone:	10	UTM Easting:	409777	UTM Northing:	5928545		
Inspector Name:	Warren Wilkinson		Year Superstructure Installed:	1999			
Access:	Turn left off Kluskus FSR at 59 km (Gold Road) then turn right of Gold Road at 13.8 km. Note: Coloured named roads have changed (RJ06)						

ABUTMENTS

Bearings	Poor	collapsing/rotting sills
Bracing	Not Applicable	
Ballast Wall	Fair	Starting to rot, unpeeled logs
Concrete Precast	Poor	Blocks, shifting
Corrosion Protection	Not Applicable	
Caps or Sills	Poor	Rotting and collapsing/compressing
Fill	Good	
Hardware	Poor	Missing nuts washers, some bent bolts
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	1	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	5	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 460 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-075	Structure Name:	G4-919	Road Name:	GOLD 5000	Inspection Date:	2021/10/06			
Road Surface	Poor	Wilderness level								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Poor	Rot								
Deck to Girder Bolts	Not Applicable	None seen								
Hardware	Poor	Missing fastenings								
Hand Rails/Walkouts	Not Applicable									
Nails	Poor	Coming out								
Overall Deck Condition	Poor	See all above								
Running Planks	Poor	Rotting rails coming off								
Sub Deck	Poor	Rotting								
Ties	Poor	Tops and ends rotting								
SUPERSTRUCTURE										
Span 1										
Bracing	Not Applicable	"								
Diaphragms	Good	Could not observe								
Girders	Good									
Hardware	Not Applicable	"								
Under Trussing	Not Applicable	"								
CHANNEL	Estimated Present Water Level Depth:		1.0		Estimated Present Water Level Width:		4.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	Yes	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	Beaver dams above and below water backed up under bridge								
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 461 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G4-075 Structure Name: G4-919 Road Name: GOLD 5000 Inspection Date: 2021/10/06

MONITORS

#	Description
3	Monitor sills and lock blocks
4	Monitor deck
5	Monitor beaver dams

GENERAL

Inspector's Comment:	
----------------------	--

GENERAL

PEng's Comment:	
-----------------	--

GENERAL

Estimated Load Restriction (year):			2025	Estimated Replacement (year):					
Current Inspection Load Rating:		5	Design Load GVW (tonnes):		91		Design Vehicle Config.:		L100
Professional Inspection Required?		No	Report Status:	Rejected By IDIR\BHENDERS on 2022/02/28 09:27:05					

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 462 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-085	Structure Name:	G4-085	Road Name:	88 ROAD	Inspection Date:	2021/10/06
KM:	3.20	User km:	3.20	Crossing Name:	Unnamed	Next Inspection Date:	2024/10/06
Project File ID #:	7655	Br.	91	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	700			Outlet Cover (mm):	700		
Footing Type:	Steel Footing			Gradient (%):			
Culvert Length (metres):	12.3	Opening Height (mm):	1,524	Opening Width (mm):	3,048		
UTM Zone:	10	UTM Easting:	401077	UTM Northing:	5922860		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2009		
Access:							

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Poor	Wilderness level

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Fair	Some rust
Embedment Materials	Not Applicable	
Fill	Fair	One third down stream side not covered by dirt
Floor	Not Applicable	
Footing	Fair	Scoured at inlet water running along and under left footing
Head Wall	Good	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 463 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-085	Structure Name:	G4-085	Road Name:	88 ROAD	Inspection Date:	2021/10/06
Inlet	Good	scour on left bank and under footing					
Outlet	Good	Water running under left footing					
Overall	Good						
Riprap	Not Applicable						
Roof	Good						
Side Walls	Fair	Rusting from bottom up					
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						

CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		0.2							
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	2	Inlet left footing scour								
GENERAL	Inspector's Comment:	Look to remove culvert. About 4 cross drains and the culvert.								
GENERAL	PEng's Comment:									

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 464 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-085	Structure Name:	G4-085	Road Name:	88 ROAD	Inspection Date:	2021/10/06	
GENERAL	Estimated Load Restriction (year):		2050	Estimated Replacement (year):				
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/02 12:38:13		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 465 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-209	Structure Name:	G5-209	Road Name:	LEO CREEK	Inspection Date:	2020/10/15
KM:	1.00	User km:	1.00	Crossing Name:	Un-named Creek	Next Inspection Date:	2023/10/15
Project File ID #:	7671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	28.0	Opening Height (mm):	3,600	Opening Width (mm):	3,600		
UTM Zone:	10	UTM Easting:	392440	UTM Northing:	6056394		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2019		
Access:							

APPROACHES

Alignment	Fair	middle of curve
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Good	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 466 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-209	Structure Name:	G5-209	Road Name:	LEO CREEK	Inspection Date:	2020/10/15			
Overall	Good									
Riprap	Excellent									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	beaver dams down stream backing water up past inlet of stream								
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Beaver dam activity								
GENERAL	Inspector's Comment:	2019 install								
GENERAL	PEng's Comment:	looks good								
GENERAL	Estimated Load Restriction (year):		2064		Estimated Replacement (year):			2075		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.: L100	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2021/03/01 11:07:52			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 467 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-210	Structure Name:	G5-210A	Road Name:	LEO CREEK	Inspection Date:	2019/10/03
KM:	20.80	User km:	20.80	Crossing Name:	Kuzkwa River	Next Inspection Date:	2022/10/03
Project File ID #:	7671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	73.3	# Spans:	3	Span Width:			Span Length(s) (metres): 12.2, 42.7, 18.3
UTM Zone:	10		UTM Easting:	391315		UTM Northing:	6073543
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2011		
Access:							

ABUTMENTS

Bearings	Good
Bracing	Good
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Good
Piles or Posts	Good
Riprap	Good
Wing Wall	Not Applicable

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Poor	FENDERS OUT OF PLACE
Road Surface	Good	

DECK

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 468 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-210	Structure Name:	G5-210A	Road Name:	LEO CREEK	Inspection Date:	2019/10/03
---------	--------	-----------------	---------	------------	-----------	------------------	------------

Span 1

Concrete Deck	Good
Curb Rail/Blocks/Posts	Good
Deck Joints	Good
Grout Pockets	Good
Hardware	Good
Hand Rails/Walkouts	Not Applicable
Overall Deck Condition	Good
Running Surface	Good

SUPERSTRUCTURE

Span 1

Bracing	Good
Diaphragms	Good
Girders	Good
Hardware	Good
Under Trussing	Not Applicable

Span 2

Bracing	Good
Diaphragms	Good
Girders	Good
Hardware	Good
Under Trussing	Not Applicable

Span 3

Bracing	Good
Diaphragms	Good
Girders	Good
Hardware	Good
Under Trussing	Not Applicable

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 469 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-210	Structure Name:	G5-210A	Road Name:	LEO CREEK	Inspection Date:	2019/10/03			
CHANNEL	Estimated Present Water Level Depth:		1.5		Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		4.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	OVERALL GOOD								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):		2060		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.: L100	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/02/10 12:33:46			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 470 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-265	Structure Name:	G5-211	Road Name:	LEO CREEK	Inspection Date:	2020/08/05
KM:	27.00	User km:	27.00	Crossing Name:	Un-named Creek	Next Inspection Date:	2023/08/05
Project File ID #:	7671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	21.3	# Spans:	1	Span Width:			Span Length(s) (metres): 21.3
UTM Zone:	10		UTM Easting:	357242	UTM Northing:	6091496	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2019		
Access:	Road is actually br 08, but no responsibility entered yet so road section gives error. Bridge is on Kazchek Cannot update GZ Jan 31/22						

ABUTMENTS

Bearings	Good	Right upstream 28mm gap at front 24mm gap at back
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	right side may have some twist, see photos
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Fair	right downstream nose missing
Posted Load Rating (Enter 0 if sign missing)	200	
Road Surface	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 471 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-265	Structure Name:	G5-211	Road Name:	LEO CREEK	Inspection Date:	2020/08/05
---------	--------	-----------------	--------	------------	-----------	------------------	------------

DECK

Span 1

Concrete Deck	Good	chipping at leading edges of deck and road
Curb Rail/Blocks/Posts	Good	
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	

SUPERSTRUCTURE

Span 1

Bracing	Fair	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Good	

CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.0
	Estimated High Water Level Clearance:	2.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	scour of stream downstream from bridge, cause from blowout of old culvert								

REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 472 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-265	Structure Name:	G5-211	Road Name:	LEO CREEK	Inspection Date:	2020/08/05
GENERAL	Inspector's Comment:	PEng to look at right upstream bearing					
GENERAL	PEng's Comment:	looks good					
GENERAL	Estimated Load Restriction (year):		2047	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/01 13:06:24			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 473 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-212	Structure Name:	G5-212	Road Name:	LEO CREEK	Inspection Date:	2019/10/03
KM:	43.10	User km:	43.10	Crossing Name:	Inzana Creek	Next Inspection Date:	2022/10/03
Project File ID #:	7671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	27.4	# Spans:	1	Span Width:			Span Length(s) (metres): 27.4
UTM Zone:	10	UTM Easting:	378608	UTM Northing:	6092810		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2002		
Access:							

ABUTMENTS

Bearings	Good
----------	------

Bracing	Not Applicable
---------	----------------

Ballast Wall	Good
--------------	------

Corrosion Protection	Not Applicable
----------------------	----------------

Fill	Good
------	------

Hardware	Not Applicable
----------	----------------

Riprap	Good
--------	------

Wing Wall	Good
-----------	------

APPROACHES

Alignment	Good
-----------	------

Bridge Ahead Signs Missing	0
----------------------------	---

Brushing Required	No
-------------------	----

Delineator Missing Left (approaching structure)	1
---	---

Delineator Missing Right (approaching structure)	2
--	---

Fender Condition	Poor	OUT OF POSITION
------------------	------	-----------------

Posted Load Rating (Enter 0 if sign missing)	91
--	----

Road Surface	Good
--------------	------

DECK

Span 1

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 474 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-212	Structure Name:	G5-212	Road Name:	LEO CREEK	Inspection Date:	2019/10/03			
Concrete Deck	Good									
Curb Rail/Blocks/Posts	Good									
Deck Joints	Good									
Grout Pockets	Good									
Hardware	Not Applicable									
Hand Rails/Walkouts	Not Applicable									
Overall Deck Condition	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Not Applicable									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		1.5		Estimated Present Water Level Width:		4.0			
	Estimated High Water Level Clearance:		5.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Low	\$ 250.00	INSTALL 2 DELINEATORS					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	NEEDS 2 DELINEATORS.								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 475 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-212	Structure Name:	G5-212	Road Name:	LEO CREEK	Inspection Date:	2019/10/03
---------	--------	-----------------	--------	------------	-----------	------------------	------------

GENERAL

PEng's
Comment:

GENERAL

Estimated Load Restriction (year):	2052	Estimated Replacement (year):	
Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91
Design Vehicle Config.:			
Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/10 12:28:45

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 476 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-211	Structure Name:	G5-211A	Road Name:	LEO CREEK	Inspection Date:	2019/11/03
KM:	46.10	User km:	46.10	Crossing Name:	Barbara-Anne Creek	Next Inspection Date:	2022/11/03
Project File ID #:	7671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15
UTM Zone:	10		UTM Easting:	376693		UTM Northing:	6095284
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2018		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Excellent	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 477 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-211	Structure Name:	G5-211A	Road Name:	LEO CREEK	Inspection Date:	2019/11/03
---------	--------	-----------------	---------	------------	-----------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Good	
Deck Joints	Fair	town side foam peeling
Grout Pockets	Good	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	because of foam strip otherwise good
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	3.0
	Estimated High Water Level Clearance:	4.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Medium	\$ 250.00	redo foam fill on town end deck gap

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 478 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-211	Structure Name:	G5-211A	Road Name:	LEO CREEK	Inspection Date:	2019/11/03
GENERAL	Inspector's Comment:	all around okay,town side expansion joint foam is peeling					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2063	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/07 12:26:12			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 479 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-213	Structure Name:	G5-213	Road Name:	LEO CREEK	Inspection Date:	2001/09/25
KM:	46.60	User km:	46.60	Crossing Name:	Unnamed creek	Next Inspection Date:	2004/09/25
Project File ID #:	7671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):	1.0		
Culvert Length (metres):	21.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	376730	UTM Northing:	6095750		
Inspector Name:	Tim Silbernagel			Year Superstructure Installed:	1979		
Access:	Minor culvert 1800 New arch design 2017 on file						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Poor	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Fair	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 480 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-213	Structure Name:	G5-213	Road Name:	LEO CREEK	Inspection Date:	2001/09/25			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	2	Suggested	High	\$ 0.00	Span: 1.0. Remove Beaver Dam. inlet totally blocked by dams.					
MONITORS	#	Description								
	1	MONITOR - Culvert has constant beaver problems. (totally plugged/submerged TS 2001)								
GENERAL	Inspector's Comment:	nullCulvert: 1) plugged by beavers, submerged 0.2 4,5,6,7) can't see due to high water, assume solid 12) no scour.								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):			2029	Estimated Replacement (year):					
	Current Inspection Load Rating:		54	Design Load GVW (tonnes):		54	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Accepted By Raymond Getzlaf on 2012/04/10 00:00:00				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 481 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-214	Structure Name:	G5-214	Road Name:	LEO CREEK	Inspection Date:	2020/09/22
KM:	74.50	User km:	74.50	Crossing Name:	Unnamed creek	Next Inspection Date:	2023/09/22
Project File ID #:	7671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	4,000			Outlet Cover (mm):	4,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	31.0	Opening Height (mm):	2,000	Opening Width (mm):	2,000		
UTM Zone:	10	UTM Easting:	357223	UTM Northing:	6111022		
Inspector Name:	Vine Sewell			Year Superstructure Installed:	1975		
Access:							

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Fair	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Fair	Down Stream end damaged at install
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 482 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-214	Structure Name:	G5-214	Road Name:	LEO CREEK	Inspection Date:	2020/09/22
Inlet	Good	lots of despri upstream, not in culvert					
Outlet	Fair	badly deformed, 60cm drop					
Overall	Fair						
Riprap	Fair						
Roof	Fair						
Side Walls	Good	several holes from install some deformation					
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						

CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		0.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	debris at inlet								
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Will look at this culvert this summer and determine what the next steps are.								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 483 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-214	Structure Name:	G5-214	Road Name:	LEO CREEK	Inspection Date:	2020/09/22
GENERAL	Estimated Load Restriction (year):		2015	Estimated Replacement (year):			
	Current Inspection Load Rating:		54	Design Load GVW (tonnes):		54	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/03/01 13:24:30	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 484 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-215	Structure Name:	G5-215	Road Name:	LEO CREEK	Inspection Date:	2019/10/04
KM:	77.50	User km:	77.50	Crossing Name:	Takatoot Creek	Next Inspection Date:	2022/10/04
Project File ID #:	7671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Concrete Precast	
Superstructure:	Steel I-beam				Right	Concrete Precast	
Total Length (metres):	12.0	# Spans:	1	Span Width:	Span Length(s) (metres):		12
UTM Zone:	10	UTM Easting:	355999	UTM Northing:	6108809		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1988		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Precast	Good	LOCK BLOCKS
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	DAMAGED/MISSING
Posted Load Rating (Enter 0 if sign missing)	91	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 485 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-215	Structure Name:	G5-215	Road Name:	LEO CREEK	Inspection Date:	2019/10/04			
Road Surface		Fair								
DECK										
Span 1										
Concrete Deck		Good								
Curb Rail/Blocks/Posts		Poor		DAMAGED						
Deck Joints		Good								
Grout Pockets		Good								
Hardware		Not Applicable								
Hand Rails/Walkouts		Not Applicable								
Overall Deck Condition		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Not Applicable								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		3.0			
	Estimated High Water Level Clearance:		3.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	High	\$	REPAIR DAMAGED FENDERS AND GUARD RAILS					
	2	Required	Medium	\$ 250.00	INSTALL LOAD RATE SIGNS					
MONITORS	#	Description								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 486 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-215	Structure Name:	G5-215	Road Name:	LEO CREEK	Inspection Date:	2019/10/04
GENERAL	Inspector's Comment:	DAMAGED FENDERS AND GUARD RAILS, NEEDS BRUSHING					
GENERAL	PEng's Comment:	curb needs to repaired					
GENERAL	Estimated Load Restriction (year):		2033	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/03/06 14:34:49			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 487 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-222	Structure Name:	G5-222	Road Name:	LEO CREEK	Inspection Date:	2021/11/04
KM:	98.50	User km:	348.40	Crossing Name:	UNNAMED	Next Inspection Date:	2022/09/01
Project File ID #:	7671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	20.9	# Spans:	1	Span Width:	Span Length(s) (metres):		20.9
UTM Zone:	10	UTM Easting:	340389	UTM Northing:	6104412		
Inspector Name:	Dawson Smith		Year Superstructure Installed:	2006			
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	(Rate as fair. Note exposed geotextile.GZ)
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	1	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Poor	sone broken and out of place
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Fair	approached need grading

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 488 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-222 Structure Name: G5-222 Road Name: LEO CREEK Inspection Date: 2021/11/04

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	guardrails rotten
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Poor	due to guardrails and fenders
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	0.5
	Estimated High Water Level Clearance:	3.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	7	Suggested	High	\$	
	8	Suggested	High	\$	
	9	Suggested	High	\$	
	10	Suggested	Medium	\$	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 489 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-222	Structure Name:	G5-222	Road Name:	LEO CREEK	Inspection Date:	2021/11/04
MONITORS	#	Description					
GENERAL	Inspector's Comment:	fenders need replaced, guardrails rotten Did not note significant scour of right abutment since last inspection. Load restrict to flag riser rail repairs not completed. GZ					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2050	Estimated Replacement (year):			
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Rejected By IDIR\GZSOMBOR on 2022/01/04 15:00:37			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 490 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-216	Structure Name:	G5-216	Road Name:	LEO CREEK	Inspection Date:	2020/08/05
KM:	101.90	User km:	352.00	Crossing Name:	Unnamed creek	Next Inspection Date:	2023/08/05
Project File ID #:	7671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	600			Outlet Cover (mm):	750		
Footing Type:				Gradient (%):			
Culvert Length (metres):	18.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	337468	UTM Northing:	6106984		
Inspector Name:	Warren wilkinson			Year Superstructure Installed:	1975		
Access:	Minor culvert						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	2m
Floor	Fair	one hole 3/4 from inlet
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 491 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-216	Structure Name:	G5-216	Road Name:	LEO CREEK	Inspection Date:	2020/08/05			
Inlet	Good	steep drop								
Outlet	Fair	perched								
Overall	Fair									
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		0.3			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	4	monitor hole in floor, 3/4 from inlet								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	This is a minor culvert that will be no longer scheduled for inspection as a major culvert. This will now be inspected by the district during their road inspections.								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 492 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-216	Structure Name:	G5-216	Road Name:	LEO CREEK	Inspection Date:	2020/08/05
GENERAL	Estimated Load Restriction (year):		2020	Estimated Replacement (year):			
	Current Inspection Load Rating:		54	Design Load GVW (tonnes):		54	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/03/01 13:17:53	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 493 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-217	Structure Name:	G5-217	Road Name:	LEO CREEK	Inspection Date:	2021/07/20
KM:	104.50	User km:	354.50	Crossing Name:	Leo Creek	Next Inspection Date:	2022/09/01
Project File ID #:	7671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	15.0	# Spans:	1	Span Width:	Span Length(s) (metres):		15
UTM Zone:	10	UTM Easting:	335286	UTM Northing:	6108035		
Inspector Name:	Dawson Smith		Year Superstructure Installed:	1996			
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	(N/A. GZ)
Fill	Good	
Hardware	Fair	loose bolts
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	?? Repair item. GZ
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	?? Repair item. GZ
Delineator Missing Right (approaching structure)	0	?? Repair item. GZ
Fender Condition	Poor	log fenders, some missing
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 494 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-217 Structure Name: G5-217 Road Name: LEO CREEK Inspection Date: 2021/07/20

DECK

Span 1

Concrete Deck Good

Curb Rail/Blocks/Posts Good

Deck Joints Good

Grout Pockets Fair

Hardware Good

Hand Rails/Walkouts Not Applicable

Overall Deck Condition Good

Running Surface Good

SUPERSTRUCTURE

Span 1

Bracing Good

Diaphragms Good

Girders Good

Hardware Good

Under Trussing Not Applicable

CHANNEL

Estimated Present Water Level Depth: 1.5 Estimated Present Water Level Width: 3.0

Estimated High Water Level Clearance: 4.0

HAZARDS

High Water: No Scour: No Ice: No Debris: No Aggradation: No

Comment:

REPAIRS

#	Status	Priority	Estimate	Description
4	Suggested	Medium	\$ 500.00	
6	Suggested	Medium		
7	Suggested	Medium	\$ 500.00	
8	Suggested	Medium	\$	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 495 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-217	Structure Name:	G5-217	Road Name:	LEO CREEK	Inspection Date:	2021/07/20
---------	--------	-----------------	--------	------------	-----------	------------------	------------

MONITORS

#	Description

GENERAL

Inspector's Comment:	Missing pictures, repair items don't match component ratings. GZ
----------------------	--

GENERAL

PEng's Comment:	
-----------------	--

GENERAL

Estimated Load Restriction (year):	2036	Estimated Replacement (year):	
Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):	91
Design Vehicle Config.:			
Professional Inspection Required?	No	Report Status:	Rejected By IDIR\GZSOMBOR on 2022/01/04 13:07:05

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 496 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-218	Structure Name:	G5-218	Road Name:	LEO CREEK	Inspection Date:	2001/09/25
KM:	106.40	User km:	358.10	Crossing Name:	Unnamed creek	Next Inspection Date:	2030/01/01
Project File ID #:	7671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	6,000			Outlet Cover (mm):	6,000		
Footing Type:				Gradient (%):	3.0		
Culvert Length (metres):	37.0	Opening Height (mm):	1,500	Opening Width (mm):	1,500		
UTM Zone:	10	UTM Easting:	333966	UTM Northing:	6109585		
Inspector Name:	Tim Silbernagel			Year Superstructure Installed:	1974		
Access:	Minor culvert, 1600, Coordinates approximate, based on Km.						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Poor	No Comment Available -Converter.RNI
Riprap	Fair	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 497 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-218	Structure Name:	G5-218	Road Name:	LEO CREEK	Inspection Date:	2001/09/25			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Monitor for scour as no rip rap is on site. Crossing is heavily vegetated.								
GENERAL	Inspector's Comment:	nullCulvert: 2) crushing, supports inside only temp fix, major piping at last joint/seperation,piping failure in road fill slope 12) minor scour at inlet 14) hole near outlet end.								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2024		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		Yes		Report Status:		Accepted By Raymond Getzlaf on 2012/04/10 00:00:00			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 498 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-219	Structure Name:	G5-219-2	Road Name:	LEO CREEK	Inspection Date:	2021/07/07
KM:	109.40	User km:	359.40	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/07/07
Project File ID #:	7671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	9,000			Outlet Cover (mm):	9,000		
Footing Type:				Gradient (%):	2.0		
Culvert Length (metres):	56.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	332510	UTM Northing:	6112563		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1974		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	
Footing	Fair	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 499 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-219	Structure Name:	G5-219-2	Road Name:	LEO CREEK	Inspection Date:	2021/07/07			
Inlet	Fair									
Outlet	Fair									
Overall	Fair									
Riprap	Not Applicable									
Roof	Fair									
Side Walls	Fair									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.0		Estimated Present Water Level Width:		0.0			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	2	Required	Medium	\$ 500.00	Clean debris from culvert.					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	No concerns. BH								

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 500 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-219	Structure Name:	G5-219-2	Road Name:	LEO CREEK	Inspection Date:	2021/07/07
GENERAL	Estimated Load Restriction (year):		2024	Estimated Replacement (year):		2024	
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/24 15:25:44	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 501 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-219	Structure Name:	G5-219	Road Name:	LEO CREEK	Inspection Date:	2021/07/20
KM:	109.40	User km:	359.40	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/09/01
Project File ID #:	7671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	10,000			Outlet Cover (mm):	10,000		
Footing Type:				Gradient (%):	2.0		
Culvert Length (metres):	56.0	Opening Height (mm):	1,500	Opening Width (mm):	1,500		
UTM Zone:	10	UTM Easting:	332510	UTM Northing:	6112563		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1974		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Poor	culvert has failed, last coupler has come apart
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Not Applicable	
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 502 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-219	Structure Name:	G5-219	Road Name:	LEO CREEK	Inspection Date:	2021/07/20			
Inlet	Fair									
Outlet	Poor	culvert has failed, last coupler has come apart								
Overall	Poor	culvert has failed								
Riprap	Not Applicable									
Roof	Fair									
Side Walls	Fair									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		0.1			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	8	monitor separation at outlet end								
GENERAL	Inspector's Comment:	Component items listed as poor but no repair items. Pictures are distorted: round pipe looks elliptical. GZ								
GENERAL	PEng's Comment:									

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 503 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-219	Structure Name:	G5-219	Road Name:	LEO CREEK	Inspection Date:	2021/07/20
GENERAL	Estimated Load Restriction (year):		2024	Estimated Replacement (year):		2024	
	Current Inspection Load Rating:		See footnote	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status: Rejected By IDIR\GZSOMBOR on 2022/01/04 13:38:51			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 504 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-220	Structure Name:	G5-220	Road Name:	LEO CREEK	Inspection Date:	2009/09/30
KM:	110.70	User km:	360.70	Crossing Name:	Unnamed creek	Next Inspection Date:	2030/01/01
Project File ID #:	7671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	9,000			Outlet Cover (mm):	9,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	56.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	331285	UTM Northing:	6112340		
Inspector Name:	Sue Forshner			Year Superstructure Installed:	1974		
Access:	Minor culvert 1800						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	None
Road Surface	Good	

CULVERT ELEMENT

Baffles	Fair	
Bolted Connections	Fair	
Coupled Connections	Fair	
Coating	Unrated	Not rated on inspection sheet
Embedment Materials	Not Applicable	
Fill	Unrated	Not rated on inspection sheet
Floor	Fair	Rust
Footing	Unrated	Not rated on inspection sheet
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 505 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-220	Structure Name:	G5-220	Road Name:	LEO CREEK	Inspection Date:	2009/09/30			
Inlet	Unrated	Plugged minimal drainage - beaver dam								
Outlet	Unrated	Perched								
Overall	Poor	No comments on inspection sheet								
Riprap	Unrated	Not rated on inspection sheet								
Roof	Unrated	Not rated on inspection sheet								
Side Walls	Unrated	Not rated on inspection sheet								
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		20.0		Estimated Present Water Level Width:		99.0			
	Estimated High Water Level Clearance:		99.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Beavers								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 506 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-220	Structure Name:	G5-220	Road Name:	LEO CREEK	Inspection Date:	2009/09/30
GENERAL	Estimated Load Restriction (year):		2024	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Accepted By Raymond Getzlaf on 2010/03/03 00:00:00	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 507 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-221	Structure Name:	G5-221	Road Name:	LEO CREEK	Inspection Date:	2021/07/20
KM:	111.70	User km:	361.70	Crossing Name:	Sandypoint Creek	Next Inspection Date:	2024/07/20
Project File ID #:	7671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Binwall	
Superstructure:	Steel I-beam				Right	Binwall	
Total Length (metres):	16.0	# Spans:	1	Span Width:			Span Length(s) (metres): 16
UTM Zone:	10		UTM Easting:	330473	UTM Northing:	6112727	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1992		
Access:							

ABUTMENTS

Bearings	Fair	
Binwall	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Poor	log fenders, some missing
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 508 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-221	Structure Name:	G5-221	Road Name:	LEO CREEK	Inspection Date:	2021/07/20
---------	--------	-----------------	--------	------------	-----------	------------------	------------

Road Surface	Good	
--------------	------	--

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	Riser blocks show decay
Deck Joints	Good	
Grout Pockets	Good	(Rate as GOOD. GZ)
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	3.0
	Estimated High Water Level Clearance:	2.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	9	Required	Medium	\$ 0.00	install bridge ahead signs
	11	Required	Medium	\$ 500.00	install delineators
	12	Required	Medium	\$	Replace missing fenders
	13	Required	Medium	\$	Replace rotten curbs and risers

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 509 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-221	Structure Name:	G5-221	Road Name:	LEO CREEK	Inspection Date:	2021/07/20
MONITORS	#	Description					
GENERAL	Inspector's Comment:	No significant issues. GZ					
GENERAL	PEng's Comment:	No major concerns. BH					
GENERAL	Estimated Load Restriction (year):		2032	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/01 15:54:57	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 510 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-310	Structure Name:	G5-310	Road Name:	PURVIS	Inspection Date:	2019/10/04
KM:	15.70	User km:	415.70	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/10/04
Project File ID #:	7671	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	18.0	Opening Height (mm):	2,000	Opening Width (mm):	2,000		
UTM Zone:	10	UTM Easting:	345434	UTM Northing:	6117625		
Inspector Name:	Dawson SMITH		Year Superstructure Installed:		1985		
Access:							

APPROACHES

Alignment	Good
Road Surface	Good

CULVERT ELEMENT

Coupled Connections	Good	
Inlet	Fair	MINOR BEND IN OUTER LIP
Outlet	Fair	MINOR BEND IN OUTER LIP
Overall	Good	

CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	0.8
	Estimated High Water Level Clearance:	1.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 511 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-310	Structure Name:	G5-310	Road Name:	PURVIS	Inspection Date:	2019/10/04
GENERAL	Inspector's Comment:	GOOD					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2025	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/07 14:02:33			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 512 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-311	Structure Name:	G5-311	Road Name:	PURVIS	Inspection Date:	2019/10/04	
KM:	20.40	User km:	419.80	Crossing Name:	Purvis Creek	Next Inspection Date:	2022/10/04	
Project File ID #:	7671	Br.	02	Forest District:	Stuart Nechako Natural Resource District			
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks			
Curb Type:				Abutments (looking downstream)	Left	Crib, Treated Timber		
Superstructure:	Steel I-beam				Right	Crib, Treated Timber		
Total Length (metres):	8.0	# Spans:	1	Span Width:			Span Length(s) (metres):	8
UTM Zone:	10		UTM Easting:	347767		UTM Northing:	6120836	
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1992			
Access:								

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Log/Timber Cribs	Fair	
Piles or Posts	Not Applicable	
Riprap	Good	
Tie-backs	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	LOG FENDERS
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 513 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-311	Structure Name:	G5-311	Road Name:	PURVIS	Inspection Date:	2019/10/04
---------	--------	-----------------	--------	------------	--------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Not Applicable
----------------------	----------------

Hardware	Not Applicable
----------	----------------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Good
----------------	------

Sub Deck	Good
----------	------

Ties	Fair
------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Not Applicable
----------	----------------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	3.0
Estimated High Water Level Clearance:	3.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Medium	\$ 250.00	INSTALL LOAD RATING SIGNS

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 514 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-311	Structure Name:	G5-311	Road Name:	PURVIS	Inspection Date:	2019/10/04
GENERAL	Inspector's Comment:	LOG FENDERS					
GENERAL	PEng's Comment:	Temporary certification of 91 tonnes expires in September 2020. Need to inspect the bridge to see what the load rating should be after September					
GENERAL	Estimated Load Restriction (year):		2027	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/03/05 12:09:37			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 515 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-312	Structure Name:	G5-312	Road Name:	PURVIS	Inspection Date:	2020/09/17
KM:	22.40	User km:	422.40	Crossing Name:	Unnamed creek	Next Inspection Date:	2023/09/17
Project File ID #:	7671	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Crib, Treated Timber	
Superstructure:	Steel I-beam				Right	Crib, Treated Timber	
Total Length (metres):	14.3	# Spans:	1	Span Width:	Span Length(s) (metres):		14
UTM Zone:	10		UTM Easting:	349651	UTM Northing:	6122471	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1992		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Fair	
Ballast Wall	Poor	broken boards and rot
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	
Fill	Fair	
Hardware	Fair	
Log/Timber Cribs	Fair	
Piles or Posts	Fair	
Riprap	Fair	
Tie-backs	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	1	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Poor	loggs sitting on ground

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 516 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-312	Structure Name:	G5-312	Road Name:	PURVIS	Inspection Date:	2020/09/17			
Posted Load Rating (Enter 0 if sign missing)	0									
Road Surface	Fair									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Fair									
Deck to Girder Bolts	Good									
Hardware	Fair									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Fair									
Running Planks	Good									
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5	Estimated Present Water Level Width:		3.0				
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	11	Required	High	\$						

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 517 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-312	Structure Name:	G5-312	Road Name:	PURVIS	Inspection Date:	2020/09/17
MONITORS	#	Description					
	4	Timber Abutments for rot					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	will look at this bridge this summer to determine the condition of the timber abutments.					
GENERAL	Estimated Load Restriction (year):		2019	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/03/02 09:57:18	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 518 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-320	Structure Name:	G5-320	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
KM:	0.80	User km:	900.80	Crossing Name:	Middle River	Next Inspection Date:	2022/10/03
Project File ID #:	7671	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	147.	# Spans:	7	Span Width:			Span Length(s) (metres): 21, 21, 21, 21, 21, 21,
UTM Zone:	10		UTM Easting:	340262	UTM Northing:	6103770	
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1988		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	RECENTLY REPLACED
Road Surface	Good	

DECK

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 519 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-320	Structure Name:	G5-320	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
---------	--------	-----------------	--------	------------	-----------	------------------	------------

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Not Applicable
----------------------	----------------

Hardware	Not Applicable
----------	----------------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Good
----------------	------

Sub Deck	Good
----------	------

Ties	Good
------	------

Span 2

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Not Applicable
----------------------	----------------

Hardware	Not Applicable
----------	----------------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Good
----------------	------

Sub Deck	Good
----------	------

Ties	Good
------	------

Span 3

Curb Rail/Blocks/Posts	Excellent
------------------------	-----------

Deck to Girder Bolts	Not Applicable
----------------------	----------------

Hardware	Not Applicable
----------	----------------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Good
----------------	------

Sub Deck	Good
----------	------

Ties	Good
------	------

Span 4

Curb Rail/Blocks/Posts	Good
------------------------	------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 520 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-320	Structure Name:	G5-320	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
Deck to Girder Bolts	Not Applicable						
Hardware	Not Applicable						
Hand Rails/Walkouts	Not Applicable						
Nails	Good						
Overall Deck Condition	Good						
Running Planks	Good						
Sub Deck	Good						
Ties	Good						
Span 5							
Curb Rail/Blocks/Posts	Good						
Deck to Girder Bolts	Not Applicable						
Hardware	Not Applicable						
Hand Rails/Walkouts	Not Applicable						
Nails	Good						
Overall Deck Condition	Good						
Running Planks	Good						
Sub Deck	Good						
Ties	Good						
Span 6							
Curb Rail/Blocks/Posts	Good						
Deck to Girder Bolts	Not Applicable						
Hardware	Not Applicable						
Hand Rails/Walkouts	Not Applicable						
Nails	Good						
Overall Deck Condition	Good						
Running Planks	Good						
Sub Deck	Good						
Ties	Good						
Span 7							
Curb Rail/Blocks/Posts	Good						
Deck to Girder Bolts	Not Applicable						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 521 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-320	Structure Name:	G5-320	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
Hardware	Not Applicable						
Hand Rails/Walkouts	Not Applicable						
Nails	Good						
Overall Deck Condition	Good						
Running Planks	Good						
Sub Deck	Good						
Ties	Good						
PIERS							
Pier 1							
Bearings	Good						
Bracing or Sheathing	Good						
Caps	Good						
Cribs	Not Applicable						
Dolphins	Not Applicable						
Hardware	Not Applicable						
Overall	Good						
Piles or Posts	Good						
Riprap	Not Applicable						
Wall	Not Applicable						
SUPERSTRUCTURE							
Span 1							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Not Applicable						
Under Trussing	Not Applicable						
Span 2							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Not Applicable						

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 522 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-320	Structure Name:	G5-320	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
Under Trussing	Not Applicable						
Span 3							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Not Applicable						
Under Trussing	Not Applicable						
Span 4							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Not Applicable						
Under Trussing	Not Applicable						
Span 5							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Not Applicable						
Under Trussing	Not Applicable						
Span 6							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Not Applicable						
Under Trussing	Not Applicable						
Span 7							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Not Applicable						
Under Trussing	Not Applicable						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 523 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-320	Structure Name:	G5-320	Road Name:	SAKENICHE	Inspection Date:	2019/10/03			
CHANNEL	Estimated Present Water Level Depth:			Estimated Present Water Level Width:		40.0				
	Estimated High Water Level Clearance:		10.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Low	\$ 500.00	INSTALL BRIDGE AHEAD AND LOAD RATING SIGNS					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	RECENT NEW DECK BOARDS AND FENDERS.								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):			2028	Estimated Replacement (year):					
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/01/28 12:36:54				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 524 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-321	Structure Name:	G5-321	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
KM:	2.00	User km:	902.00	Crossing Name:	Gluskie Creek	Next Inspection Date:	2022/10/03
Project File ID #:	7671	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Treated Timber	
Superstructure:	Steel I-beam				Right	Crib, Treated Timber	
Total Length (metres):	15.7	# Spans:	1	Span Width:			Span Length(s) (metres): 15
UTM Zone:	10		UTM Easting:	339435		UTM Northing:	6103608
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1992		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Log/Timber Cribs	Good	
Piles or Posts	Good	
Riprap	Poor	MINIMAL OR NONE
Tie-backs	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 525 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-321	Structure Name:	G5-321	Road Name:	SAKENICHE	Inspection Date:	2019/10/03			
Posted Load Rating (Enter 0 if sign missing)	63.5									
Road Surface	Good									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Fair									
Deck to Girder Bolts	Not Applicable									
Hardware	Not Applicable									
Hand Rails/Walkouts	Not Applicable									
Nails	Fair									
Overall Deck Condition	Poor	DECK BOARDS ROTTING AND FALLING APART								
Running Planks	Poor	BOARDS ROTTING AND FALLING APART								
Sub Deck	Fair									
Ties	Fair									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Not Applicable									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		1.0	Estimated Present Water Level Width:		2.5				
	Estimated High Water Level Clearance:		3.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Medium	\$	REPLACE GUARD RAILS					

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 526 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-321 Structure Name: G5-321 Road Name: SAKENICHE Inspection Date: 2019/10/03

MONITORS

#	Description
1	MONITOR DECK BOARDS

GENERAL

Inspector's Comment: DECK BOARDS AND GUARD RAILS ROTTEN.

GENERAL

PEng's Comment:

GENERAL

Estimated Load Restriction (year): 2021 Estimated Replacement (year):
Current Inspection Load Rating: 64 Design Load GVW (tonnes): 91 Design Vehicle Config.: L100
Professional Inspection Required? No Report Status: Reviewed By Jason Olmsted on 2020/03/05 12:02:19

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 527 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-322	Structure Name:	G5-322	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
KM:	6.50	User km:	906.50	Crossing Name:	Bivouac Creek	Next Inspection Date:	2022/10/03
Project File ID #:	7671	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Crib, Treated Timber	
Superstructure:	Steel I-beam				Right	Crib, Treated Timber	
Total Length (metres):	12.0	# Spans:	1	Span Width:	Span Length(s) (metres):		12
UTM Zone:	10	UTM Easting:	335575	UTM Northing:	6105574		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1981		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Log/Timber Cribs	Good	
Piles or Posts	Good	
Riprap	Fair	MINIMAL
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Good	
Road Surface	Good	

DECK

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 528 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-322	Structure Name:	G5-322	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
---------	--------	-----------------	--------	------------	-----------	------------------	------------

Span 1

Curb Rail/Blocks/Posts	Fair	MINOR DAMAGE
Deck to Girder Bolts	Not Applicable	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Planks	Good	
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good
Diaphragms	Good
Girders	Good
Hardware	Not Applicable
Under Trussing	Not Applicable

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	3.0
Estimated High Water Level Clearance:	4.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Medium	\$ 0.00	Curbs need replacing
2	Required	Low	\$ 200.00	REPLACE MISSING DELINEATOR

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 529 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-322	Structure Name:	G5-322	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
GENERAL	Inspector's Comment:	MINOR DAMAGE TO GUARDRAIL..					
GENERAL	PEng's Comment:	Curbs need to be replaced soon.					
GENERAL	Estimated Load Restriction (year):		2025		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:		L100				
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/28 12:31:40			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 530 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-323	Structure Name:	G5-323	Road Name:	SAKENICHE	Inspection Date:	2020/05/12
KM:	16.70	User km:	916.70	Crossing Name:	Hobo Creek	Next Inspection Date:	2022/05/12
Project File ID #:	7671	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Steel I-beam				Right	Crib, Log or Untreated Timber	
Total Length (metres):	9.0	# Spans:	1	Span Width:			Span Length(s) (metres): 9
UTM Zone:	10		UTM Easting:	327325	UTM Northing:	6111945	
Inspector Name:	Vince Sewell			Year Superstructure Installed:	1979		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Good	treated timber
Fill	Good	
Hardware	Good	
Log/Timber Cribs	Fair	old but still solid
Piles or Posts	Not Applicable	
Riprap	Good	Minor scower low chain
Tie-backs	Fair	
Wing Wall	Fair	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	road requires brushing
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 531 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-323	Structure Name:	G5-323	Road Name:	SAKENICHE	Inspection Date:	2020/05/12			
Posted Load Rating (Enter 0 if sign missing)	0									
Road Surface	Fair	rough								
DECK										
Span 1										
Concrete Deck	Good									
Curb Rail/Blocks/Posts	Poor	curbs and risers very old wit rot								
Deck Joints	Good									
Grout Pockets	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Overall Deck Condition	Good	deck needs cleaning								
SUPERSTRUCTURE										
Span 1										
Bracing	Not Applicable									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.7		Estimated Present Water Level Width:		4.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	14	Required	Medium		Replace Curbs					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 532 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-323 Structure Name: G5-323 Road Name: SAKENICHE Inspection Date: 2020/05/12

MONITORS

Description

GENERAL

Inspector's
Comment:

GENERAL

PEng's
Comment:

Curbs will need replacing soon or else the bridge will be down-rated.

GENERAL

Estimated Load Restriction (year):

2029

Estimated Replacement (year):

Current Inspection Load Rating:

91

Design Load GVW (tonnes):

91

Design Vehicle Config.:

Professional Inspection Required?

No

Report Status:

Reviewed By Jason Olmsted on 2021/03/02 11:53:01

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 533 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-324	Structure Name:	G5-324	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
KM:	22.40	User km:	922.40	Crossing Name:	Sakeniche River	Next Inspection Date:	2022/10/03
Project File ID #:	7671	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Treated Timber	
Superstructure:	Steel Truss/Bailey/Acrow				Right	Binwall	
Total Length (metres):	31.0	# Spans:	1	Span Width:			Span Length(s) (metres): 31
UTM Zone:	10	UTM Easting:	322622	UTM Northing:	6114064		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1974		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Binwall	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Poor	FAILING ON WOODS SIDE
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	91	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 534 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-324	Structure Name:	G5-324	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
---------	--------	-----------------	--------	------------	-----------	------------------	------------

Road Surface	Good	
--------------	------	--

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Not Applicable	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Good	
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Good	

CHANNEL	Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	4.0
	Estimated High Water Level Clearance:	4.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	High	\$	INSTALL RIP RAP ON UPSTREAM SIDE

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 535 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-324	Structure Name:	G5-324	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
MONITORS	#	Description					
GENERAL	Inspector's Comment:	WATER COURSE HAD SHIFTED TO WOODS SIDE (LEFT LOOKING DOWNSTREAM)AND IS UNDERMINING ABUTMENT					
GENERAL	PEng's Comment:	Will do an inspection this year to determine the severity of the HC scour.					
GENERAL	Estimated Load Restriction (year):		2020	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/03/05 11:55:56			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 536 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-325	Structure Name:	G5-325	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
KM:	24.20	User km:	924.20	Crossing Name:	Mule Chute Creek	Next Inspection Date:	2022/10/03
Project File ID #:	7671	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	12.0	# Spans:	1	Span Width:	Span Length(s) (metres):		12
UTM Zone:	10	UTM Easting:	321358	UTM Northing:	6113156		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1991		
Access:							

ABUTMENTS

Bearings	Good
----------	------

Bracing	Not Applicable
---------	----------------

Ballast Wall	Good
--------------	------

Corrosion Protection	Not Applicable
----------------------	----------------

Caps or Sills	Good
---------------	------

Fill	Good
------	------

Hardware	Not Applicable
----------	----------------

Piles or Posts	Good
----------------	------

Riprap	Poor	MINIMAL
--------	------	---------

Wing Wall	Not Applicable
-----------	----------------

APPROACHES

Alignment	Good
-----------	------

Bridge Ahead Signs Missing	2
----------------------------	---

Brushing Required	No
-------------------	----

Delineator Missing Left (approaching structure)	0
---	---

Delineator Missing Right (approaching structure)	1
--	---

Fender Condition	Good
------------------	------

Road Surface	Good
--------------	------

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 537 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-325	Structure Name:	G5-325	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
---------	--------	-----------------	--------	------------	-----------	------------------	------------

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	GUARD RAILS ROTTEN AND FALLING APART
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Poor	DECK GOOD GUARD RAILS NOT

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	1.5
Estimated High Water Level Clearance:	3.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Medium	\$ 500.00	INSTALL BRIDGE, LOAD RATING SIGNS AND MISSING DELINEATOR
2	Required	High	\$	REPLACE GUARD RAILS

MONITORS

#	Description
1	MONITOR BANKS WHERE THERE IS MINIMAL RIP RAP

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 538 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-325	Structure Name:	G5-325	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
GENERAL	Inspector's Comment:	MINIMAL OR NO RIP RAPP, GUARD RAILS ROTTEN NEED TO BE REPLACED.					
GENERAL	PEng's Comment:	Curbs need replacing soon or bridge will be down-rated.					
GENERAL	Estimated Load Restriction (year):		2031	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/28 08:42:55			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 539 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-326	Structure Name:	G5-326	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
KM:	43.60	User km:	943.60	Crossing Name:	McDougall Creek	Next Inspection Date:	2022/10/03
Project File ID #:	7671	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,440			Outlet Cover (mm):	1,440		
Footing Type:				Gradient (%):			
Culvert Length (metres):	23.0	Opening Height (mm):	2,400	Opening Width (mm):	2,400		
UTM Zone:	9	UTM Easting:	497285	UTM Northing:	6116013		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1992		
Access:							

APPROACHES

Alignment	Good
Brushing Required	No
Road Surface	Good

CULVERT ELEMENT

Baffles	Not Applicable
Bolted Connections	Not Applicable
Coupled Connections	Good
Coating	Good
Embedment Materials	Not Applicable
Fill	Good
Floor	Good
Footing	Not Applicable
Head Wall	Good
Inlet	Good
Outlet	Good
Overall	Good
Riprap	Not Applicable
Roof	Good
Side Walls	Good

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 540 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-326	Structure Name:	G5-326	Road Name:	SAKENICHE	Inspection Date:	2019/10/03			
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	GOOD								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):		2032		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/02/03 11:59:03			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 541 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-327	Structure Name:	G5-327	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
KM:	58.00	User km:	957.90	Crossing Name:	Rabbits Foot Creek	Next Inspection Date:	2022/10/03
Project File ID #:	7671	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,050			Outlet Cover (mm):	1,050		
Footing Type:				Gradient (%):			
Culvert Length (metres):	20.0	Opening Height (mm):	2,000	Opening Width (mm):	2,000		
UTM Zone:	9	UTM Easting:	494950	UTM Northing:	6127820		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1990		
Access:							

APPROACHES

Alignment	Good
Brushing Required	Yes
Road Surface	Good

CULVERT ELEMENT

Coupled Connections	Good
Coating	Good
Fill	Good
Inlet	Good
Outlet	Good
Overall	Good

CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	0.3
	Estimated High Water Level Clearance:	1.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Not Required	Medium	\$ 500.00	BRUSH BOTH SIDES

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 542 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-327	Structure Name:	G5-327	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
MONITORS	#	Description					
GENERAL	Inspector's Comment:	LOACATION IS ACTUALY 59.2 KM					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2030		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:						
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/07 13:42:15			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 543 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-328	Structure Name:	G5-328	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
KM:	61.80	User km:	961.80	Crossing Name:	Sinta Creek	Next Inspection Date:	2022/10/03
Project File ID #:	7671	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	15.0	# Spans:	1	Span Width:	Span Length(s) (metres):		15
UTM Zone:	9	UTM Easting:	684393	UTM Northing:	6135211		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1991		
Access:							

ABUTMENTS

Bearings	Good
----------	------

Ballast Wall	Good
--------------	------

Corrosion Protection	Not Applicable
----------------------	----------------

Caps or Sills	Good
---------------	------

Fill	Good
------	------

Piles or Posts	Good
----------------	------

Riprap	Fair
--------	------

APPROACHES

Alignment	Good
-----------	------

Bridge Ahead Signs Missing	2
----------------------------	---

Brushing Required	No
-------------------	----

Delineator Missing Left (approaching structure)	1
---	---

Delineator Missing Right (approaching structure)	0
--	---

Fender Condition	Poor	MISSING AND OUT OF PLACE
------------------	------	--------------------------

Road Surface	Good
--------------	------

DECK

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 544 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-328	Structure Name:	G5-328	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
---------	--------	-----------------	--------	------------	-----------	------------------	------------

Deck Joints	Good	
Grout Pockets	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	3.0
	Estimated High Water Level Clearance:	3.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Low	\$ 500.00	INSTALL MISSING DELINEATOR AND BRIDGE SIGNS
	2	Required	Medium	\$	REPLACE MISSING AND DAMAGED FENDERS

MONITORS	#	Description

GENERAL	Inspector's Comment:	FENDERS OUT OF PLACE, ACTUALLY AT 63.1KM

GENERAL	PEng's Comment:	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 545 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-328	Structure Name:	G5-328	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
GENERAL	Estimated Load Restriction (year):		2031	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/03/05 11:47:03	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 546 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-329	Structure Name:	G5-329	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
KM:	65.30	User km:	965.30	Crossing Name:	Tim Creek	Next Inspection Date:	2022/10/03
Project File ID #:	7671	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	18.0	# Spans:	1	Span Width:			Span Length(s) (metres): 18
UTM Zone:	9		UTM Easting:	493989		UTM Northing:	6134063
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1992		
Access:							

ABUTMENTS

Bearings	Good
Ballast Wall	Good
Caps or Sills	Good
Fill	Good
Piles or Posts	Good
Riprap	Good

APPROACHES

Alignment	Good
Bridge Ahead Signs Missing	2
Brushing Required	No
Delineator Missing Left (approaching structure)	0
Delineator Missing Right (approaching structure)	0
Fender Condition	None
Road Surface	Good

DECK

Span 1

Curb Rail/Blocks/Posts	Good
Hardware	Not Applicable
Hand Rails/Walkouts	Not Applicable

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 547 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-329	Structure Name:	G5-329	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
---------	--------	-----------------	--------	------------	-----------	------------------	------------

Nails	Good	
Overall Deck Condition	Good	
Running Planks	Good	
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	2.0
	Estimated High Water Level Clearance:	4.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Medium	\$	INSTALL FENDERS

MONITORS	#	Description

GENERAL	Inspector's Comment:	66.1 KMS, NO FENDERS.

GENERAL	PEng's Comment:	Need to inspect the bridge in 2020 to see if the 2016 missing bracing bolts have been repaired.

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 548 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-329	Structure Name:	G5-329	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
GENERAL	Estimated Load Restriction (year):		2032	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/02/03 11:57:11	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 549 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-330	Structure Name:	G5-330	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
KM:	66.00	User km:	966.60	Crossing Name:	Dust Creek	Next Inspection Date:	2022/10/03
Project File ID #:	7671	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	18.0	# Spans:	1	Span Width:			Span Length(s) (metres): 18
UTM Zone:	9		UTM Easting:	494016	UTM Northing:	6136057	
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1992		
Access:							

ABUTMENTS

Bearings	Good
----------	------

Ballast Wall	Good
--------------	------

Corrosion Protection	Not Applicable
----------------------	----------------

Fill	Good
------	------

Piles or Posts	Good
----------------	------

Riprap	Good
--------	------

APPROACHES

Alignment	Good
-----------	------

Bridge Ahead Signs Missing	2
----------------------------	---

Brushing Required	No
-------------------	----

Delineator Missing Left (approaching structure)	2
---	---

Delineator Missing Right (approaching structure)	2
--	---

Fender Condition	Poor	NO FENDERS
------------------	------	------------

Road Surface	Good
--------------	------

DECK

Span 1

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Good
----------------	------

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 550 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-330	Structure Name:	G5-330	Road Name:	SAKENICHE	Inspection Date:	2019/10/03			
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Not Applicable									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		4.0			
	Estimated High Water Level Clearance:		3.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Medium	\$ 250.00	INSTALL BRIDGE AND LOAD RATING SIGNS					
	2	Required	Medium	\$	INSTALL FENDERS					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	NO FENDERS, SIGNS OR DELINIATORS, 67.3KM								
	PEng's Comment:									

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 551 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-330	Structure Name:	G5-330	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
GENERAL	Estimated Load Restriction (year):		2032	Estimated Replacement (year):			
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/02/03 11:43:36	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 552 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-331	Structure Name:	G5-331	Road Name:	SAKENICHE	Inspection Date:	2019/10/03
KM:	73.00	User km:	967.40	Crossing Name:	Beaverdale Creek	Next Inspection Date:	2022/10/03
Project File ID #:	7671	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel Box Beam				Right	Pile -Permanent Materials	
Total Length (metres):	9.0	# Spans:	1	Span Width:	Span Length(s) (metres):		9
UTM Zone:	9	UTM Easting:	683959	UTM Northing:	6139139		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1991		
Access:							

ABUTMENTS

Ballast Wall	Fair	
Caps or Sills	Fair	
Piles or Posts	Poor	WATER POOLING AROUND POSTS, THEY ARE SHOWING ROT
Wing Wall	Fair	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Good	

DECK

Span 1

Nails	Poor	SOME ARE MISSING
Overall Deck Condition	Poor	DECK BOARDS CRACKED, BROKEN AND LOOSE
Running Planks	Poor	SHOWING DAMAGE
Sub Deck	Fair	
Ties	Fair	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 553 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-331 Structure Name: G5-331 Road Name: SAKENICHE Inspection Date: 2019/10/03

SUPERSTRUCTURE

Span 1

Girders Good

CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	4.0
	Estimated High Water Level Clearance:	2.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Medium	\$	REPLACE DECK

MONITORS	#	Description
	1	MONITOR WOODEN POSTS IN THE WATER

GENERAL	Inspector's Comment:	DECK IS IN POOR CONDITION, WATER POOLING AROUND POSTS, POST SHOWING ROT.

GENERAL	PEng's Comment:	Bridge deck needs replacing ASAP or it will be down-rated

GENERAL	Estimated Load Restriction (year):			2031	Estimated Replacement (year):			
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.:	L75
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/03/05 11:32:02		

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 554 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-291	Structure Name:	G5-291	Road Name:	MIDDLE	Inspection Date:	2019/10/18
KM:	5.60	User km:	5.60	Crossing Name:	unnamed	Next Inspection Date:	2021/10/18
Project File ID #:	7671	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Rail Car				Right	Sill -Temporary Materials	
Total Length (metres):	16.1	# Spans:	1	Span Width:	Span Length(s) (metres):		16.1
UTM Zone:	10	UTM Easting:	341650	UTM Northing:	6078778		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:			
Access:	FORT ST. JAMES FOREST PRODUCTS GENERAL PARTNER LTD. R01565.CG FSR Retired in 2021						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Excellent	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Poor	MISSING OR ROTTEN
Road Surface	Good	

DECK

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 555 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-291	Structure Name:	G5-291	Road Name:	MIDDLE	Inspection Date:	2019/10/18
---------	--------	-----------------	--------	------------	--------	------------------	------------

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Poor	NOT ATTACHED
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Fair	
Running Planks	Good	
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Hardware	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	3.0
	Estimated High Water Level Clearance:	3.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Medium	\$	INSTALL FENDERS
	2	Required	Medium	\$ 250.00	INSTALL DELINEATORS

MONITORS	#	Description

GENERAL	Inspector's Comment:	DOES NOT APPEAR TO BE SITTING CENTERED ON ABUTMENTS OR ATTACHED, NEEDS DELINEATORS, BRIDGE IS AT 25.5 ON THE AUSTIN FSR
---------	----------------------	---

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 556 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-291	Structure Name:	G5-291	Road Name:	MIDDLE	Inspection Date:	2019/10/18
GENERAL	PEng's Comment:	Will do a field trip this year and determine if bridge should be further down-rated.					
GENERAL	Estimated Load Restriction (year):			2020	Estimated Replacement (year):		
	Current Inspection Load Rating:		30	Design Load GVW (tonnes):		Design Vehicle Config.:	
	Professional Inspection Required?		No	Report Status: Reviewed By Jason Olmsted on 2020/03/06 15:11:34			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 557 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-289	Structure Name:	G5-289	Road Name:	MIDDLE	Inspection Date:	2020/09/09
KM:	40.20	User km:	31.90	Crossing Name:	Sydney Creek #2	Next Inspection Date:	2023/09/09
Project File ID #:	7671	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,400			Outlet Cover (mm):	1,500		
Footing Type:				Gradient (%):	4.0		
Culvert Length (metres):	20.0	Opening Height (mm):	2,700	Opening Width (mm):	2,700		
UTM Zone:	10	UTM Easting:	346371	UTM Northing:	6081639		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1993		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Poor	Wilderness

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	rust on floor
Embedment Materials	Not Applicable	
Fill	Good	1m
Floor	Fair	Rust on Floor
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 558 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-289	Structure Name:	G5-289	Road Name:	MIDDLE	Inspection Date:	2020/09/09
Inlet	Good						
Outlet	Good	some material washed down ro outlet					
Overall	Good						
Riprap	Good						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						

CHANNEL	Estimated Present Water Level Depth:			0.3		Estimated Present Water Level Width:			1.0	
	Estimated High Water Level Clearance:			1.0						
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	looks ok								

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 559 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-289	Structure Name:	G5-289	Road Name:	MIDDLE	Inspection Date:	2020/09/09
GENERAL	Estimated Load Restriction (year):		2033	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/03/01 12:15:02	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 560 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-289	Structure Name:	G5-289-2	Road Name:	MIDDLE	Inspection Date:	2020/09/09
KM:	40.20	User km:	31.90	Crossing Name:	Sydney Creek #2	Next Inspection Date:	2023/09/09
Project File ID #:	7671	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,400		
Footing Type:				Gradient (%):	4.0		
Culvert Length (metres):	20.0	Opening Height (mm):	2,700	Opening Width (mm):	2,700		
UTM Zone:	10	UTM Easting:	346371	UTM Northing:	6081639		
Inspector Name:	Warren wilkinson			Year Superstructure Installed:	1993		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Poor	wilderness

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	some rust on floor, culvert does not get large flow of water through it
Embedment Materials	Not Applicable	
Fill	Good	1m
Floor	Fair	some rust
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 561 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-289	Structure Name:	G5-289-2	Road Name:	MIDDLE	Inspection Date:	2020/09/09
Inlet	Good	some brush at inlet					
Outlet	Good	some brush at ioutlet					
Overall	Good						
Riprap	Good						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						

CHANNEL	Estimated Present Water Level Depth:			0.0		Estimated Present Water Level Width:			0.4	
	Estimated High Water Level Clearance:			1.0						
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	see culvert 1 for inspection photos								
GENERAL	PEng's Comment:									

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 562 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-289	Structure Name:	G5-289-2	Road Name:	MIDDLE	Inspection Date:	2020/09/09
GENERAL	Estimated Load Restriction (year):		2031	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/03/01 12:17:58	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 563 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-287	Structure Name:	G5-287	Road Name:	MIDDLE	Inspection Date:	2020/09/09
KM:	36.70	User km:	34.70	Crossing Name:	Upper Baptiste Creek	Next Inspection Date:	2023/09/09
Project File ID #:	7671	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	3,500			Outlet Cover (mm):	3,600		
Footing Type:				Gradient (%):			
Culvert Length (metres):	35.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	350380	UTM Northing:	6082286		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1991		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Poor	Wilderness

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Unrated	cannot get into culvert to examan
Coating	Fair	Rust
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Unrated	cannot get into culvert to examan
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 564 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-287	Structure Name:	G5-287	Road Name:	MIDDLE	Inspection Date:	2020/09/09
Inlet	Fair	Beaver dam					
Outlet	Poor	lifting					
Overall	Fair						
Riprap	Not Applicable						
Roof	Fair	Rust					
Side Walls	Unrated	cannot get into culvert to examan					
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						

CHANNEL	Estimated Present Water Level Depth:	2.0	Estimated Present Water Level Width:	2.0
	Estimated High Water Level Clearance:	2.0		

HAZARDS	High Water:	Yes	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	Beaver Dam at outlet, this culvert is always 3/4 full								

REPAIRS	#	Status	Priority	Estimate	Description
	2	Not Required	Medium	\$	Replace culvert
	3	Complete	High	\$ 0.00	Remove beaver dam

MONITORS	#	Description
	2	lifting of culvert at outlet

GENERAL	Inspector's Comment:	
---------	----------------------	--

GENERAL	PEng's Comment:	Beaver dam needs removing. Will look at this culvert in the summer to determine if it needs replacing and what priority it is for funding.
---------	-----------------	--

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 565 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-287	Structure Name:	G5-287	Road Name:	MIDDLE	Inspection Date:	2020/09/09
GENERAL	Estimated Load Restriction (year):		2031	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/03/01 12:26:24	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 566 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-280	Structure Name:	G5-280	Road Name:	MIDDLE	Inspection Date:	2020/09/09
KM:	3.50	User km:	703.50	Crossing Name:	Forfar Creek	Next Inspection Date:	2022/09/09
Project File ID #:	7671	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Steel I-beam				Right	Crib, Log or Untreated Timber	
Total Length (metres):	15.0	# Spans:	1	Span Width:	Span Length(s) (metres):		15
UTM Zone:	10	UTM Easting:	342035	UTM Northing:	6101130		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1980		
Access:							

ABUTMENTS

Bearings	Fair	Rot found under bearings
Bracing	Not Applicable	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Poor	soft spots found
Fill	Good	
Hardware	Fair	
Log/Timber Cribs	Poor	rot found in timber members
Piles or Posts	Not Applicable	
Riprap	Good	
Tie-backs	Poor	rot found in timber members
Wing Wall	Poor	rot found in timber members

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	1	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 567 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-280	Structure Name:	G5-280	Road Name:	MIDDLE	Inspection Date:	2020/09/09			
Posted Load Rating (Enter 0 if sign missing)	0									
Road Surface	Fair									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Good									
Sub Deck	Good									
Ties	Fair									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Good									
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 568 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-280	Structure Name:	G5-280	Road Name:	MIDDLE	Inspection Date:	2020/09/09
MONITORS	#	Description					
	8	Abutments for rot					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Will look at this bridge during the summer to determine the extent of the rot.					
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:		90	Design Load GVW (tonnes):		90	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/03/01 12:56:41	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 569 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-281	Structure Name:	G5-281	Road Name:	MIDDLE	Inspection Date:	2020/09/09
KM:	10.60	User km:	710.60	Crossing Name:	O'Ne-ell Creek	Next Inspection Date:	2023/09/09
Project File ID #:	7671	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Binwall	
Superstructure:	Steel I-beam				Right	Binwall	
Total Length (metres):	16.8	# Spans:	1	Span Width:			Span Length(s) (metres): 16.8
UTM Zone:	10		UTM Easting:	346426	UTM Northing:	6096689	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1981		
Access:							

ABUTMENTS

Bearings	Good	
Binwall	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Unrated	cannot see
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 570 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-281	Structure Name:	G5-281	Road Name:	MIDDLE	Inspection Date:	2020/09/09			
Road Surface		Poor	pot holes on approach							
DECK										
Span 1										
Concrete Deck		Good								
Curb Rail/Blocks/Posts		Good								
Deck Joints		Fair	joints between ballast wall broken out							
Grout Pockets		Fair								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Overall Deck Condition		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Good								
CHANNEL	Estimated Present Water Level Depth:		0.3	Estimated Present Water Level Width:		5.0				
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	11	Required	Low	\$ 0.00						
MONITORS	#	Description								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 571 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-281	Structure Name:	G5-281	Road Name:	MIDDLE	Inspection Date:	2020/09/09
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	bridge looks ok					
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/01 12:45:47			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 572 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-282	Structure Name:	G5-282	Road Name:	MIDDLE	Inspection Date:	2001/10/15
KM:	11.90	User km:	711.90	Crossing Name:	6 Creek Tributary	Next Inspection Date:	2030/01/01
Project File ID #:	7671	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	3,000			Outlet Cover (mm):	3,000		
Footing Type:				Gradient (%):	5.0		
Culvert Length (metres):	16.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	347395	UTM Northing:	6095347		
Inspector Name:	Brent Case			Year Superstructure Installed:	1981		
Access:	minor culvert 1800						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Fair	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 573 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-282	Structure Name:	G5-282	Road Name:	MIDDLE	Inspection Date:	2001/10/15			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		1.3							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	nullCulvert: 11) Minor rust on floor. 12) Little, but little scour..								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2031		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By Raymond Getzlaf on 2012/04/10 00:00:00			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 574 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-283	Structure Name:	G5-283	Road Name:	MIDDLE	Inspection Date:	2001/10/15
KM:	14.70	User km:	714.70	Crossing Name:	Unnamed creek	Next Inspection Date:	2030/01/01
Project File ID #:	7671	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1		
Footing Type:				Gradient (%):	2.0		
Culvert Length (metres):	18.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	349472	UTM Northing:	6093361		
Inspector Name:	Brent Case			Year Superstructure Installed:	1981		
Access:	minor culvert 1600						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Poor	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Fair	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 575 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-283	Structure Name:	G5-283	Road Name:	MIDDLE	Inspection Date:	2001/10/15			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	3	Suggested	High	\$ 0.00	Span: 1.0. Remove Beaver Dam. Remove beaver dam at inlet.					
MONITORS	#	Description								
	1	Monitor for scour as no rip rap is on site. Monitor for beaver activity, blocked in 2001 by beaver.								
GENERAL	Inspector's Comment:	nullCulvert: 1) Blocked by beaver. Remove debris - could top road in spring. 11) Some rust on floor. 12) Little, but no scour..								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):			2031	Estimated Replacement (year):					
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Accepted By Raymond Getzlaf on 2012/04/10 00:00:00				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 576 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-284	Structure Name:	G5-284	Road Name:	MIDDLE	Inspection Date:	2020/09/09
KM:	15.30	User km:	715.30	Crossing Name:	vanDecar Creek	Next Inspection Date:	2023/09/09
Project File ID #:	7671	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Binwall	
Superstructure:	Steel I-beam				Right	Binwall	
Total Length (metres):	19.0	# Spans:	1	Span Width:			Span Length(s) (metres): 19
UTM Zone:	10		UTM Easting:	350027		UTM Northing:	6093157
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1989		
Access:							

ABUTMENTS

Bearings	Good	hard to see
Binwall	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	covered in dirt
Fill	Fair	large hole left side, bridge edge
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	
Posted Load Rating (Enter 0 if sign missing)	75	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 577 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-284	Structure Name:	G5-284	Road Name:	MIDDLE	Inspection Date:	2020/09/09			
Road Surface	Poor	wilderness								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Good									
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Good									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		3.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	old decking with spikes								
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 578 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-284	Structure Name:	G5-284	Road Name:	MIDDLE	Inspection Date:	2020/09/09
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	looks ok					
GENERAL	Estimated Load Restriction (year):		2029	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/03/04 14:07:43	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 579 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-285	Structure Name:	G5-285	Road Name:	MIDDLE	Inspection Date:	2020/09/09
KM:	17.50	User km:	717.50	Crossing Name:	Unnamed creek	Next Inspection Date:	2023/09/09
Project File ID #:	7671	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,300			Outlet Cover (mm):	1,300		
Footing Type:				Gradient (%):			
Culvert Length (metres):	24.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	351215	UTM Northing:	6091295		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1989		
Access:	minor culvert						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Unrated	wlderness

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Fair	some gaps between culvert segments
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	1m
Floor	Good	
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 580 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-285	Structure Name:	G5-285	Road Name:	MIDDLE	Inspection Date:	2020/09/09
Inlet	Good						
Outlet	Good	pool at outlet					
Overall	Good						
Riprap	Fair	some has fallen into stream					
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						

CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	Pool at outlet								
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	looks ok								

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 581 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-285	Structure Name:	G5-285	Road Name:	MIDDLE	Inspection Date:	2020/09/09
GENERAL	Estimated Load Restriction (year):		2029	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/03/01 12:32:19	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 582 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-290	Structure Name:	G5-290	Road Name:	MIDDLE	Inspection Date:	2001/10/15
KM:	21.00	User km:	721.00	Crossing Name:	Unnamed creek	Next Inspection Date:	2030/01/01
Project File ID #:	7671	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,500			Outlet Cover (mm):	1,500		
Footing Type:				Gradient (%):			
Culvert Length (metres):	20.0	Opening Height (mm):	1,200	Opening Width (mm):	1,200		
UTM Zone:	10	UTM Easting:	352685	UTM Northing:	6088722		
Inspector Name:	Brent Case			Year Superstructure Installed:	1989		
Access:	minor culvert, twin 1200						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Good	No Comment Available -Converter.RNI
Roof	Fair	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 583 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-290	Structure Name:	G5-290	Road Name:	MIDDLE	Inspection Date:	2001/10/15			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.6							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	nullCulvert: 5) Minor deformations. 11) Minor rust on floor..								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2039		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By Raymond Getzlaf on 2012/04/12 00:00:00			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 584 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-286	Structure Name:	G5-286	Road Name:	MIDDLE	Inspection Date:	2020/09/09
KM:	28.80	User km:	728.80	Crossing Name:	Baptiste Creek	Next Inspection Date:	2023/09/09
Project File ID #:	7671	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Sill - Permanent Materials	
Superstructure:	Steel I-beam				Right	Sill - Permanent Materials	
Total Length (metres):	15.0	# Spans:	1	Span Width:	Span Length(s) (metres):		15
UTM Zone:	10	UTM Easting:	357302	UTM Northing:	6085235		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1990		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Unrated	can't see elements
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	can't see elements
Riprap	Fair	Steep banks, RipRap not to stream edge
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	1	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Poor	wilderness

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 585 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-286	Structure Name:	G5-286	Road Name:	MIDDLE	Inspection Date:	2020/09/09
---------	--------	-----------------	--------	------------	--------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	starting to show age, Rot Ants, one bracket broken
Deck Joints	Fair	
Grout Pockets	Fair	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.4	Estimated Present Water Level Width:	2.0
	Estimated High Water Level Clearance:	2.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	6	Required	Medium	\$	replace curb and posts

MONITORS	#	Description

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 586 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-286	Structure Name:	G5-286	Road Name:	MIDDLE	Inspection Date:	2020/09/09
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Rails should be replaced soon.					
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/01 12:29:58			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 587 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-288	Structure Name:	G5-288	Road Name:	MIDDLE	Inspection Date:	2020/09/09
KM:	40.00	User km:	740.00	Crossing Name:	Sydney Creek #1	Next Inspection Date:	2023/09/09
Project File ID #:	7671	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,300			Outlet Cover (mm):	1,500		
Footing Type:				Gradient (%):			
Culvert Length (metres):	18.0	Opening Height (mm):	2,400	Opening Width (mm):	2,400		
UTM Zone:	10	UTM Easting:	346546	UTM Northing:	6081719		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1993		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Unrated	Wilderness

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Fair	Gap in bottom of first connector
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 588 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-288	Structure Name:	G5-288	Road Name:	MIDDLE	Inspection Date:	2020/09/09
Inlet	Good						
Outlet	Fair	perched					
Overall	Good						
Riprap	Good						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						

CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	Scour at outlet								
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	looks good								

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 589 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-288	Structure Name:	G5-288	Road Name:	MIDDLE	Inspection Date:	2020/09/09
GENERAL	Estimated Load Restriction (year):		2033	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status: Reviewed By Jason Olmsted on 2021/03/01 12:20:12			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 590 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-365	Structure Name:	G5-365	Road Name:	TARNEZELL	Inspection Date:	2021/07/20
KM:	1.30	User km:	1.30	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/07/01
Project File ID #:	7671	Br.	06	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	10		UTM Easting:	389605		UTM Northing:	6073610
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1999		
Access:							

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Fair	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	1 missing. GZ
Delineator Missing Right (approaching structure)	0	1 missing. GZ
Fender Condition	Fair	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 591 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-365	Structure Name:	G5-365	Road Name:	TARNEZELL	Inspection Date:	2021/07/20
---------	--------	-----------------	--------	------------	-----------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	significant rot
Deck Joints	Good	
Grout Pockets	Not Applicable	Rate as GOOD. GZ
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	0.1
	Estimated High Water Level Clearance:	3.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	9	Suggested	High	\$	
	10	Suggested	Medium	\$	
	11	Suggested	Medium	\$ 250.00	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 592 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-365	Structure Name:	G5-365	Road Name:	TARNEZELL	Inspection Date:	2021/07/20
MONITORS	#	Description					
	7	monitor beaver activity					
GENERAL	Inspector's Comment:	Repair and monitoring items do not match component conditions. Insufficient pictures. GZ					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2040	Estimated Replacement (year):			
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):	68	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Rejected By IDIR\GZSOMBOR on 2022/01/04 15:22:14			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 593 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-366	Structure Name:	G5-366	Road Name:	TARNEZELL	Inspection Date:	2021/07/20
KM:	7.10	User km:	7.20	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/07/01
Project File ID #:	7671	Br.	06	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	2,000			Outlet Cover (mm):	2,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	19.0	Opening Height (mm):	2,000	Opening Width (mm):	2,000		
UTM Zone:	10	UTM Easting:	384993	UTM Northing:	6075070		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1981		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Poor	one side has failed

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Unrated	culvert has failed
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Poor	culvert has failed
Floor	Poor	culvert has failed
Footing	Not Applicable	
Head Wall	Poor	culvert has failed

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 594 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-366	Structure Name:	G5-366	Road Name:	TARNEZELL	Inspection Date:	2021/07/20
Inlet	Poor	culvert has failed					
Outlet	Poor	culvert has failed					
Overall	Poor	culvert has failed					
Riprap	Not Applicable						
Roof	Poor	culvert has failed					
Side Walls	Poor	culvert has failed					
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		0.1
	Estimated High Water Level Clearance:		1.5				
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Aggradation: No
	Comment:						
REPAIRS	#	Status	Priority	Estimate	Description		
	4	Suggested	High	\$	replace culvert		
MONITORS	#	Description					
GENERAL	Inspector's Comment:	No detailed pictures or descriptions of what failed. Restrict loading. GZ					
GENERAL	PEng's Comment:						

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 595 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-366	Structure Name:	G5-366	Road Name:	TARNEZELL	Inspection Date:	2021/07/20
GENERAL	Estimated Load Restriction (year):		2020	Estimated Replacement (year):			
	Current Inspection Load Rating:		See footnote	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Rejected By IDIR\GZSOMBOR on 2022/01/04 15:27:26	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 596 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-260	Structure Name:	G5-260	Road Name:	KAZCHEK	Inspection Date:	2019/10/03
KM:	18.00	User km:	318.00	Crossing Name:	Kazchek Creek	Next Inspection Date:	2022/10/03
Project File ID #:	7671	Br.	08	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Concrete Precast	
Superstructure:	Steel I-beam				Right	Concrete Cast in Place	
Total Length (metres):	30.0	# Spans:	1	Span Width:			Span Length(s) (metres): 30
UTM Zone:	10		UTM Easting:	364483		UTM Northing:	6092637
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1987		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Cast in Place	Good	
Concrete Precast	Good	
Corrosion Protection	Not Applicable	
Fill	Poor	UNDERMINING ON WOODS SIDE
Hardware	Not Applicable	
Riprap	Poor	MINIMAL
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	ROTTEN
Road Surface	Good	

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 597 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-260	Structure Name:	G5-260	Road Name:	KAZCHEK	Inspection Date:	2019/10/03
---------	--------	-----------------	--------	------------	---------	------------------	------------

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Good
-------------	------

Hardware	Not Applicable
----------	----------------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Not Applicable
----------	----------------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	4.0
Estimated High Water Level Clearance:	5.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$	REPLACE ROTTEN FENDERS

MONITORS

#	Description
1	MONITOR UNDERMINING OF RIGHT SIDE (WOODS) ABUTMENT

GENERAL

Inspector's Comment:	RIGHT SIDE(LOOKING DOWNSTREAM) ABUTMENT APPEARS TO BE UNDERMINING.
----------------------	--

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 598 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-260	Structure Name:	G5-260	Road Name:	KAZCHEK	Inspection Date:	2019/10/03
---------	--------	-----------------	--------	------------	---------	------------------	------------

GENERAL

PEng's
Comment:

GENERAL

Estimated Load Restriction (year):	2027	Estimated Replacement (year):	
Current Inspection Load Rating:	68	Design Load GVW (tonnes):	68
Design Vehicle Config.:			
Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/03/06 15:16:29

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 599 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-261	Structure Name:	G5-261	Road Name:	KAZCHEK	Inspection Date:	2020/08/05
KM:	37.40	User km:	337.40	Crossing Name:	Natazutlo Creek	Next Inspection Date:	2023/08/05
Project File ID #:	7671	Br.	08	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	4,000			Outlet Cover (mm):	4,000		
Footing Type:				Gradient (%):	1.0		
Culvert Length (metres):	28.0	Opening Height (mm):	5,230	Opening Width (mm):	5,230		
UTM Zone:	10	UTM Easting:	348379	UTM Northing:	6098042		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1990		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	2m
Floor	Fair	some rust
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 600 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-261	Structure Name:	G5-261	Road Name:	KAZCHEK	Inspection Date:	2020/08/05			
Inlet	Good									
Outlet	Good									
Overall	Good									
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	2.0						
	Estimated High Water Level Clearance:	3.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	PENG please review why structure is rated at 54,000kg								
GENERAL	PEng's Comment:	Culvert was originally defaulted to load rating the road, which was 54 tonnes in the 90s.								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 601 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-261	Structure Name:	G5-261	Road Name:	KAZCHEK	Inspection Date:	2020/08/05
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:		54	Design Load GVW (tonnes):		54	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/03/01 13:11:15	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 602 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-262	Structure Name:	G5-262	Road Name:	KAZCHEK	Inspection Date:	2021/07/20
KM:	42.80	User km:	342.80	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/07/20
Project File ID #:	7671	Br.	08	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	10,200			Outlet Cover (mm):	10,200		
Footing Type:				Gradient (%):	3.0		
Culvert Length (metres):	60.0	Opening Height (mm):	2,000	Opening Width (mm):	2,000		
UTM Zone:	10	UTM Easting:	344500	UTM Northing:	6101547		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1990		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 603 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-262	Structure Name:	G5-262	Road Name:	KAZCHEK	Inspection Date:	2021/07/20			
Inlet	Good									
Outlet	Good									
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Distorted photos but no issues. GZ								
GENERAL	PEng's Comment:	No concerns. BH								

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 604 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-262	Structure Name:	G5-262	Road Name:	KAZCHEK	Inspection Date:	2021/07/20
---------	--------	-----------------	--------	------------	---------	------------------	------------

GENERAL

Estimated Load Restriction (year):	2030	Estimated Replacement (year):	
Current Inspection Load Rating:	54	Design Load GVW (tonnes):	54
Design Vehicle Config.:			
Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/06 15:41:11

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 605 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-263	Structure Name:	G5-263	Road Name:	KAZCHEK	Inspection Date:	2002/07/15
KM:	44.70	User km:	344.70	Crossing Name:	Unnamed creek	Next Inspection Date:	2030/01/01
Project File ID #:	7671	Br.	08	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	7,000			Outlet Cover (mm):	7,000		
Footing Type:				Gradient (%):	6.0		
Culvert Length (metres):	37.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	343346	UTM Northing:	6102578		
Inspector Name:	Brent Case			Year Superstructure Installed:	1990		
Access:	Minor culvert, 1800						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Fair	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Good	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 606 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-263	Structure Name:	G5-263	Road Name:	KAZCHEK	Inspection Date:	2002/07/15			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Monitor road fill erosion on upstream side. Monitor last 2 connections near outlet.								
GENERAL	Inspector's Comment:	nullCulvert: 4) Last 2 connections near outlet have some separation. 11) Rusting on floor..								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2040		Estimated Replacement (year):					
	Current Inspection Load Rating:		54		Design Load GVW (tonnes):		54		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By Raymond Getzlaf on 2012/04/10 00:00:00			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 607 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-264	Structure Name:	G5-264	Road Name:	KAZCHEK	Inspection Date:	2021/07/20
KM:	45.40	User km:	345.40	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/07/20
Project File ID #:	7671	Br.	08	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	6,000			Outlet Cover (mm):	6,000		
Footing Type:				Gradient (%):	2.0		
Culvert Length (metres):	33.0	Opening Height (mm):	2,400	Opening Width (mm):	2,400		
UTM Zone:	10	UTM Easting:	342770	UTM Northing:	6102877		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1990		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 608 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-264	Structure Name:	G5-264	Road Name:	KAZCHEK	Inspection Date:	2021/07/20			
Inlet	Fair	Beaver has built a dam around inlet								
Outlet	Good									
Overall	Fair									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.0		Estimated Present Water Level Width:		0.0			
	Estimated High Water Level Clearance:		2.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	Beaver has built a dam around inlet								
REPAIRS	#	Status	Priority	Estimate	Description					
	4	Required	High		Remove beaver dam					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Beaver dam above inlet, not blocking pipe. No issues. GZ								
GENERAL	PEng's Comment:	No major concerns. BH								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 609 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-264	Structure Name:	G5-264	Road Name:	KAZCHEK	Inspection Date:	2021/07/20
---------	--------	-----------------	--------	------------	---------	------------------	------------

GENERAL

Estimated Load Restriction (year):	2030	Estimated Replacement (year):	
Current Inspection Load Rating:	54	Design Load GVW (tonnes):	54
Design Vehicle Config.:			
Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/06 15:50:26

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 610 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-240	Structure Name:	G5-240	Road Name:	AIRLINE	Inspection Date:	2019/10/04
KM:	6.50	User km:	6.60	Crossing Name:	Airline Creek	Next Inspection Date:	2022/10/04
Project File ID #:	7671	Br.	11	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Binwall	
Superstructure:	Steel I-beam				Right	Binwall	
Total Length (metres):	18.0	# Spans:	1	Span Width:	Span Length(s) (metres):		18
UTM Zone:	10	UTM Easting:	367344	UTM Northing:	6115750		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1992		
Access:	68 km on Leo Creek - 3 km on Driftwood - 6.5 km on Leo Airline. Ladder and two inspectors recommended - bin walls limit access to abutments.						

ABUTMENTS

Bearings	Good	
Binwall	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Unrated	COULDNT SEE
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Fair	MINIMAL
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 611 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-240	Structure Name:	G5-240	Road Name:	AIRLINE	Inspection Date:	2019/10/04
---------	--------	-----------------	--------	------------	---------	------------------	------------

DECK

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Good
---------------	------

Hardware	Not Applicable
----------	----------------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Not Applicable
----------	----------------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	3.0
Estimated High Water Level Clearance:	3.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 612 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-240	Structure Name:	G5-240	Road Name:	AIRLINE	Inspection Date:	2019/10/04
GENERAL	Inspector's Comment:	NO BRIDGE SIGNS, ALL GOOD					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2032	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/03 13:27:50			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 613 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-241	Structure Name:	G5-966	Road Name:	AIRLINE	Inspection Date:	2019/10/04
KM:	12.00	User km:	12.60	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/10/04
Project File ID #:	7671	Br.	11	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	10		UTM Easting:	373159	UTM Northing:	6115426	
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2009		
Access:	12.7km Leo Airline FSR.						

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 614 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-241	Structure Name:	G5-966	Road Name:	AIRLINE	Inspection Date:	2019/10/04
---------	--------	-----------------	--------	------------	---------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Not Applicable	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Nails	Fair	
Overall Deck Condition	Poor	DECK BOARD LEFT SIDE MISSING
Running Planks	Fair	
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	1.0
Estimated High Water Level Clearance:	3.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Medium	\$ 500.00	REPLACE MISSING DECK BOARD

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 615 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-241	Structure Name:	G5-966	Road Name:	AIRLINE	Inspection Date:	2019/10/04
GENERAL	Inspector's Comment:	DECK BOARD LEFT SIDE ON UP APPROACH IS DAMAGED/MISSING, SEE PICTURES					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2039	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/03 13:23:08			

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 616 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-235	Structure Name:	G5-943	Road Name:	TAKATOOT 1	Inspection Date:	2020/09/22
KM:	0.29	User km:	0.30	Crossing Name:	Unnamed	Next Inspection Date:	2023/09/22
Project File ID #:	7671	Br.	23	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel Truss/Bailey/Acrow				Right	Concrete Lock Blocks	
Total Length (metres):	3.0	# Spans:	1	Span Width:	Span Length(s) (metres):		3
UTM Zone:	10	UTM Easting:	356372	UTM Northing:	6107782		
Inspector Name:	Vince Sewell			Year Superstructure Installed:	1997		
Access:	This site was installed with Acrow pannels G5-943 and G5-944.						

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Poor	needs repair for industrial use
Concrete Lock Blocks	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Poor	Sill plank needs replacing if industrial use
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	6	5000kg

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 617 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-235	Structure Name:	G5-943	Road Name:	TAKATOOT 1	Inspection Date:	2020/09/22			
Road Surface		Fair								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Fair								
Deck to Girder Bolts		Not Applicable								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Fair								
Overall Deck Condition		Fair								
Running Planks		Not Applicable								
Sub Deck		Fair								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		1.5			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	5	Required	Medium		replace sills prior to industrial use					

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 618 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-235	Structure Name:	G5-943	Road Name:	TAKATOOT 1	Inspection Date:	2020/09/22
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2020	Estimated Replacement (year):			
	Current Inspection Load Rating:	5	Design Load GVW (tonnes):	68	Design Vehicle Config.:	L75	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/03 10:58:23			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 619 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-235	Structure Name:	G5-944	Road Name:	TAKATOOT 1	Inspection Date:	2020/09/22
KM:	0.29	User km:	0.30	Crossing Name:	Unnamed	Next Inspection Date:	2023/09/22
Project File ID #:	7671	Br.	23	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel Truss/Bailey/Acrow				Right	Concrete Lock Blocks	
Total Length (metres):	3.0	# Spans:	1	Span Width:	Span Length(s) (metres):		3
UTM Zone:	10	UTM Easting:	356372	UTM Northing:	6107782		
Inspector Name:	Vince Sewell			Year Superstructure Installed:	1997		
Access:	This site was installed with Acrow pannels G5-943 and G5-944.						

CHANNEL	Estimated Present Water Level Depth:			Estimated Present Water Level Width:						
	Estimated High Water Level Clearance:									
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	see structure G5-943 for photos								
GENERAL	PEng's Comment:	see G5-943								

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 620 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-235	Structure Name:	G5-944	Road Name:	TAKATOOT 1	Inspection Date:	2020/09/22	
GENERAL	Estimated Load Restriction (year):		2020	Estimated Replacement (year):				
	Current Inspection Load Rating:		5	Design Load GVW (tonnes):		68	Design Vehicle Config.:	L75
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/03/03 10:51:26		

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 621 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-236	Structure Name:	G5-945	Road Name:	TAKATOOT 1	Inspection Date:	2020/09/22
KM:	3.01	User km:	3.00	Crossing Name:	Unnamed Creek	Next Inspection Date:	2023/09/22
Project File ID #:	7671	Br.	23	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel Truss/Bailey/Acrow				Right	Concrete Lock Blocks	
Total Length (metres):	3.0	# Spans:	1	Span Width:			Span Length(s) (metres): 3
UTM Zone:	10	UTM Easting:	357120	UTM Northing:	6107981		
Inspector Name:	Vince Sewell		Year Superstructure Installed:	1997			
Access:	This site is installed with Acrow pannels G5-945, G5-946 and G5-947.						

APPROACHES

Alignment	Fair	ok for rec traffic
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Fair	

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Not Applicable	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Fair	
Running Planks	Not Applicable	Fungus found on bottom
Sub Deck	Fair	
Ties	Good	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 622 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-236 Structure Name: G5-945 Road Name: TAKATOOT 1 Inspection Date: 2020/09/22

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	1.0
	Estimated High Water Level Clearance:	1.2		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	7	Required	Medium		
	8	Required	Medium		
	9	Required	Medium		

MONITORS	#	Description

GENERAL	Inspector's Comment:	
---------	----------------------	--

GENERAL	PEng's Comment:	Will look at this bridge this summer to determine the condition it is in and if anything needs to be down-rated.
---------	-----------------	--

GENERAL	Estimated Load Restriction (year):			2020	Estimated Replacement (year):			
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.:	L75
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/03/03 11:30:57		

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 623 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-236	Structure Name:	G5-946	Road Name:	TAKATOOT 1	Inspection Date:	2020/09/22
KM:	3.01	User km:	3.00	Crossing Name:	Unnamed Creek	Next Inspection Date:	2023/09/22
Project File ID #:	7671	Br.	23	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel Truss/Bailey/Acrow				Right	Concrete Lock Blocks	
Total Length (metres):	3.0	# Spans:	1	Span Width:			Span Length(s) (metres): 3
UTM Zone:	10	UTM Easting:	357120	UTM Northing:	6107981		
Inspector Name:	Vince sewell			Year Superstructure Installed:	1997		
Access:	This site is installed with Acrow pannels G5-945, G5-946 and G5-947.						

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Poor	replace
Concrete Lock Blocks	Good	
Corrosion Protection	Good	
Caps or Sills	Poor	replace
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 624 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-236	Structure Name:	G5-946	Road Name:	TAKATOOT 1	Inspection Date:	2020/09/22			
Road Surface		Fair								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Deck to Girder Bolts		Not Applicable								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Fair								
Running Planks		Not Applicable								
Sub Deck		Fair		white fungus starting on bottom						
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.2							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	2	Required	Medium		Replace sills					
	3	Required	Medium							
	4	Required	Medium							

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 625 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-236	Structure Name:	G5-946	Road Name:	TAKATOOT 1	Inspection Date:	2020/09/22
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2020	Estimated Replacement (year):			
	Current Inspection Load Rating:	68	Design Load GVW (tonnes):	68	Design Vehicle Config.:	L75	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/22 13:25:32			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 626 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-236	Structure Name:	G5-947	Road Name:	TAKATOOT 1	Inspection Date:	2020/09/22
KM:	3.01	User km:	3.00	Crossing Name:	Unnamed Creek	Next Inspection Date:	2023/09/22
Project File ID #:	7671	Br.	23	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel Truss/Bailey/Acrow				Right	Concrete Lock Blocks	
Total Length (metres):	3.0	# Spans:	1	Span Width:			Span Length(s) (metres): 3
UTM Zone:	10	UTM Easting:	357120	UTM Northing:	6107981		
Inspector Name:	Vince Sewell			Year Superstructure Installed:	1997		
Access:	This site is installed with Acrow pannels G5-945, G5-946 and G5-947.						

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Poor	Shold be replaced
Concrete Lock Blocks	Good	
Corrosion Protection	Good	
Caps or Sills	Poor	should be replaced
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	ok for rec traffic
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 627 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-236	Structure Name:	G5-947	Road Name:	TAKATOOT 1	Inspection Date:	2020/09/22			
Road Surface		Fair								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Deck to Girder Bolts		Not Applicable								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Fair								
Running Planks		Not Applicable								
Sub Deck		Good		white fungus starting on bottom						
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.2							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	2	Required	Medium		replace sill timbers					
	3	Required	Medium							
	4	Required	Medium							

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 628 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-236	Structure Name:	G5-947	Road Name:	TAKATOOT 1	Inspection Date:	2020/09/22
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	See G5-945 for comments					
GENERAL	Estimated Load Restriction (year):		2020	Estimated Replacement (year):			
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.: L75
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/03/19 12:10:49	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 629 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-248	Structure Name:	G5-931	Road Name:	WILLY	Inspection Date:	2018/09/20
KM:	1.33	User km:	1.33	Crossing Name:	Unknown	Next Inspection Date:	2022/09/01
Project File ID #:	7671	Br.	50	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	18.0	# Spans:	1	Span Width:	Span Length(s) (metres):		18
UTM Zone:	10	UTM Easting:	358403	UTM Northing:	6084173		
Inspector Name:	Adam Mathison, GradTech			Year Superstructure Installed:	2007		
Access:							

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Poor	Blocks have settled on each end, more on the downstream side. Bridge is tilted downstream and slightly wracked.
Corrosion Protection	Good	
Caps or Sills	Fair	Treated 6"x12" (x2) Sill has deflected with lock blocks
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Good	
Road Surface	Poor	Rough road, large bumps at each end of bridge due to settlement

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 630 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-248	Structure Name:	G5-931	Road Name:	WILLY	Inspection Date:	2018/09/20
---------	--------	-----------------	--------	------------	-------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	Showing age, rot starting
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Fair	
Overall Deck Condition	Fair	
Running Planks	Poor	Rotting
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Fair	Uneven settlement has caused a slight wrack in the bridge
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	1.0
Estimated High Water Level Clearance:	2.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	High	\$	Rebuild lock block abutments and replace sills with 8"x16" treated timbers to remove wrack from bridge. Regrade approaches.
2	Required	High	\$	Replace wear deck prior to industrial use
3	Required	Medium	\$ 750.00	Brush approaches and around bridge
4	Required	High	\$ 400.00	Install delineators all four corners

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 631 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-248	Structure Name:	G5-931	Road Name:	WILLY	Inspection Date:	2018/09/20
---------	--------	-----------------	--------	------------	-------	------------------	------------

MONITORS

#	Description

GENERAL

Inspector's Comment:	Bridge is in overall fair condition due to uneven settlement in lock blocks causing wrack in the bridge. Repair prior to industrial use.
----------------------	--

GENERAL

PEng's Comment:	Bridge down-rated to 30 Tonnes until foundation repaired and re-certified.
-----------------	--

GENERAL

Estimated Load Restriction (year):	2057	Estimated Replacement (year):			
Current Inspection Load Rating:	30	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100
Professional Inspection Required?	No	Report Status:	Reviewed By Ross Hyam on 2018/11/23 11:40:50		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 632 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-255	Structure Name:	G5-255	Road Name:	HART	Inspection Date:	2019/10/03
KM:	1.10	User km:	1.10	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/10/03
Project File ID #:	7671	Br.	52	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel Truss/Bailey/Acrow				Right	Concrete Lock Blocks	
Total Length (metres):	9.1	# Spans:	1	Span Width:			Span Length(s) (metres): 9.1
UTM Zone:	10		UTM Easting:	386003		UTM Northing:	6063255
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2002		
Access:	Road starts at km 6.5 on the Tanizul FSR.						

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	68	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 633 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-255	Structure Name:	G5-255	Road Name:	HART	Inspection Date:	2019/10/03			
Road Surface		Fair	UP SIDE COULD USE CAPPING							
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Deck to Girder Bolts		Not Applicable								
Hardware		Not Applicable								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Good								
Running Planks		Good								
Sub Deck		Good								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Good								
CHANNEL	Estimated Present Water Level Depth:		0.0	Estimated Present Water Level Width:		0.0				
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 634 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-255	Structure Name:	G5-255	Road Name:	HART	Inspection Date:	2019/10/03
---------	--------	-----------------	--------	------------	------	------------------	------------

MONITORS

#	Description
1	MONITOR APPROACH FOR CAPPING

GENERAL

Inspector's Comment:	APPROACHES COULD USE CAPPING
----------------------	------------------------------

GENERAL

PEng's Comment:	
-----------------	--

GENERAL

Estimated Load Restriction (year):			2025	Estimated Replacement (year):				
Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.:		L75
Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/02/11 15:51:12			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 635 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-256	Structure Name:	G5-256	Road Name:	HART	Inspection Date:	2019/10/03
KM:	3.50	User km:	3.50	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/10/03
Project File ID #:	7671	Br.	52	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Precast	
Superstructure:	Steel Truss/Bailey/Acrow				Right	Concrete Precast	
Total Length (metres):	9.1	# Spans:	1	Span Width:			Span Length(s) (metres): 9.1
UTM Zone:	10	UTM Easting:	384950	UTM Northing:	6065284		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2002		
Access:	road is at km 6.5 on the Tanizul FSR.						

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Precast	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Fair	MINIMAL BUT SEEMS TO BE HIGH ENOUGH
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Good	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 636 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-256	Structure Name:	G5-256	Road Name:	HART	Inspection Date:	2019/10/03
---------	--------	-----------------	--------	------------	------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Not Applicable	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Nails	Poor	SOME NAILS HAVE CAME UP
Overall Deck Condition	Poor	BOARDS ARE COMING UP, NEED TO BE RENAILED
Running Planks	Poor	BOARDS ARE COMING UP, NEED TO BE RENAILED

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Good	

CHANNEL	Estimated Present Water Level Depth:	0.0	Estimated Present Water Level Width:	0.0
	Estimated High Water Level Clearance:	2.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Medium	\$ 250.00	NAIL DECK BOARDS
	2	Required	Low	\$ 750.00	INSTALL DELINEATORS AND BRIDGE SINGS

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 637 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-256	Structure Name:	G5-256	Road Name:	HART	Inspection Date:	2019/10/03
GENERAL	Inspector's Comment:	DECK BOARDS LOOSE.					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2020	Estimated Replacement (year):			
	Current Inspection Load Rating:	68	Design Load GVW (tonnes):	68	Design Vehicle Config.:	L75	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/03/06 15:19:37			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 638 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-231	Structure Name:	G5-231	Road Name:	CURTIS	Inspection Date:	2019/10/04
KM:	0.15	User km:	0.15	Crossing Name:	Unnamed	Next Inspection Date:	2022/10/04
Project File ID #:	7671	Br.	64	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):				Outlet Cover (mm):			
Footing Type:	Precast Concrete Footing			Gradient (%):			
Culvert Length (metres):	23.3	Opening Height (mm):	1,840	Opening Width (mm):	4,298		
UTM Zone:	10	UTM Easting:	372822	UTM Northing:	6106125		
Inspector Name:	Dawson SMITH		Year Superstructure Installed:		2010		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Good	
Fill	Good	
Floor	Not Applicable	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 639 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-231	Structure Name:	G5-231	Road Name:	CURTIS	Inspection Date:	2019/10/04			
Overall	Good									
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	2.5						
	Estimated High Water Level Clearance:	1.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	ALL GOOD								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):	2050	Estimated Replacement (year):							
	Current Inspection Load Rating:	68	Design Load GVW (tonnes):	68	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/11 16:32:57						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 640 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-230	Structure Name:	G5-230	Road Name:	CURTIS	Inspection Date:	2019/10/04
KM:	0.23	User km:	0.23	Crossing Name:	Unnamed	Next Inspection Date:	2022/10/04
Project File ID #:	7671	Br.	64	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	10		UTM Easting:	372877		UTM Northing:	6106186
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1998		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Poor	OUT OF POSITION
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 641 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-230	Structure Name:	G5-230	Road Name:	CURTIS	Inspection Date:	2019/10/04
---------	--------	-----------------	--------	------------	--------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Poor	DAMAGED AND ROTTEN
Deck to Girder Bolts	Not Applicable	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Poor	WORN
Running Planks	Poor	WORN
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	5.0
Estimated High Water Level Clearance:	3.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:	BEAVERS BUILDING A DAM APPROX 50M UPSTREAM								

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Medium	\$ 250.00	PUT FENDERS BACK IN PLACE

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 642 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-230	Structure Name:	G5-230	Road Name:	CURTIS	Inspection Date:	2019/10/04
---------	--------	-----------------	--------	------------	--------	------------------	------------

MONITORS

#	Description
1	MONITOR BEAVER ACTIVITY UPSTREAM
2	MONITOR RUNNING SURFACE OF DECK
3	MONITOR GUARD RAILS

GENERAL

Inspector's Comment:	DECK AND GUARD RAIL DAMAGE, BEAVERS BUILDING A DAM APPROX. 50M UPSTREAM.
----------------------	--

GENERAL

PEng's Comment:	Need to replace curbs and running deck soon or the bridge will be down-rated
-----------------	--

GENERAL

Estimated Load Restriction (year):	2043	Estimated Replacement (year):	
Current Inspection Load Rating:	68	Design Load GVW (tonnes):	
Design Vehicle Config.:	L75	Professional Inspection Required?	No
Report Status:	Reviewed By Jason Olmsted on 2020/03/05 11:19:28		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 643 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-840	Structure Name:	G5-952	Road Name:	ALEXANDER	Inspection Date:	2019/10/04
KM:	0.20	User km:	0.20	Crossing Name:	Unknown	Next Inspection Date:	2022/10/04
Project File ID #:	7671	Br.	65	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	15.2	# Spans:	1	Span Width:	Span Length(s) (metres):		15
UTM Zone:	10	UTM Easting:	373028	UTM Northing:	6107728		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2015		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	WATER SITTING AGAINST
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	OUT OF PLACE
Posted Load Rating (Enter 0 if sign missing)	63	ACTUALLY 63,500

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 644 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-840	Structure Name:	G5-952	Road Name:	ALEXANDER	Inspection Date:	2019/10/04			
Road Surface		Good								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Deck to Girder Bolts		Not Applicable								
Hardware		Not Applicable								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Good								
Running Planks		Good								
Sub Deck		Good								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Not Applicable								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		6.0			
	Estimated High Water Level Clearance:		0.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Not Required	Medium	\$ 250.00	PUT FENDERS INTO POSITION					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 645 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-840	Structure Name:	G5-952	Road Name:	ALEXANDER	Inspection Date:	2019/10/04
MONITORS	#	Description					
GENERAL	Inspector's Comment:	FENDERS OUT OF PLACE, WATER SITTING AGAINST LOCK BLOCKS..					
GENERAL	PEng's Comment:	Will look at bridge in 2020 to ensure no issues with bearing pressures at abutments.					
GENERAL	Estimated Load Restriction (year):		2025		Estimated Replacement (year):		
	Current Inspection Load Rating:		64		Design Load GVW (tonnes):		91
	Design Vehicle Config.:		L100				
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/03 13:17:52			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 646 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-841	Structure Name:	P025	Road Name:	ALEXANDER	Inspection Date:	2021/07/21
KM:	1.50	User km:	1.50	Crossing Name:	Unknown	Next Inspection Date:	2022/09/01
Project File ID #:	7671	Br.	65	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Steel I-beam				Right	Crib, Log or Untreated Timber	
Total Length (metres):	10.3	# Spans:	1	Span Width:			Span Length(s) (metres): 10
UTM Zone:	10		UTM Easting:	374051	UTM Northing:	6108302	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2015		
Access:							

ABUTMENTS

Bearings	Not Applicable	(Rate as FAIR. GZ)
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Log/Timber Cries	Good	N/A. GZ
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Tie-backs	Good	N/A. GZ
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	log fenders, some missing

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 647 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-841	Structure Name:	P025	Road Name:	ALEXANDER	Inspection Date:	2021/07/21			
Posted Load Rating (Enter 0 if sign missing)	0									
Road Surface	Good									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Fair									
Running Planks	Fair	showing rot								
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 648 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-841	Structure Name:	P025	Road Name:	ALEXANDER	Inspection Date:	2021/07/21
----------------	--------	------------------------	------	-------------------	-----------	-------------------------	------------

REPAIRS	#	Status	Priority	Estimate	Description
	5	Suggested	Medium	\$	
	7	Suggested	Medium	\$ 500.00	
	8	Suggested	Medium	\$	
	9	Suggested	Medium	\$	

MONITORS	#	Description
	2	guardrails and riser blocks

GENERAL	Inspector's Comment:	Poor pics, repairs do not match ratings, rated componets that do not exist, suspect rot in in all wood components. GZ
	PEng's Comment:	

GENERAL	Estimated Load Restriction (year):	2030	Estimated Replacement (year):	
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):	91
	Design Vehicle Config.:	L100		

Professional Inspection Required?	No	Report Status:	Rejected By IDIR\GZSOMBOR on 2022/01/06 10:59:43
--	----	-----------------------	--

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 649 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-570	Structure Name:	G5-570	Road Name:	JEAN MARIE	Inspection Date:	2021/09/22
KM:	1.70	User km:	1.70	Crossing Name:	Un-named Creek	Next Inspection Date:	2024/09/22
Project File ID #:	7671	Br.	68	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Steel			Running Surface:	Anti-skid		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel Box Beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:	Span Length(s) (metres):		12
UTM Zone:	10		UTM Easting:	391982	UTM Northing:	6109102	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2016		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	some out of place
Posted Load Rating (Enter 0 if sign missing)	91	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 650 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-570	Structure Name:	G5-570	Road Name:	JEAN MARIE	Inspection Date:	2021/09/22			
Road Surface		Good								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Hardware		Not Applicable								
Hand Rails/Walkouts		Not Applicable								
Overall Deck Condition		Good								
Running Surface		Good								
Steel Deck Plate		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Not Applicable								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		4.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Medium	\$ 0.00	Reposition approach fenders					
MONITORS	#	Description								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 651 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-570	Structure Name:	G5-570	Road Name:	JEAN MARIE	Inspection Date:	2021/09/22
GENERAL	Inspector's Comment:	water is against lock blocks No issues. GZ					
GENERAL	PEng's Comment:	No concerns. BH					
GENERAL	Estimated Load Restriction (year):		2041	Estimated Replacement (year):		2041	
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/10 17:18:49			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 652 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-571	Structure Name:	G5-571	Road Name:	JEAN MARIE	Inspection Date:	2019/10/30
KM:	2.10	User km:	2.10	Crossing Name:	Jean Marie Creek	Next Inspection Date:	2022/10/30
Project File ID #:	7671	Br.	68	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	18.3	# Spans:	1	Span Width:			Span Length(s) (metres): 18
UTM Zone:	10		UTM Easting:	392146		UTM Northing:	6109290
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2016		
Access:							

ABUTMENTS

Bearings	Good
Bracing	Good
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Not Applicable
Piles or Posts	Good
Riprap	Good
Wing Wall	Not Applicable

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	NO LOAD RATING
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Good	
Road Surface	Good	

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 653 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-571	Structure Name:	G5-571	Road Name:	JEAN MARIE	Inspection Date:	2019/10/30
---------	--------	-----------------	--------	------------	------------	------------------	------------

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Not Applicable	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Good	WAS FROZEN BUT APPEARED TO BE IN GOOD SHAPE
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	5.0
	Estimated High Water Level Clearance:	3.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Low	\$ 500.00	INSTALL 2 DELINEATORS AND LOAD RATING SIGNS

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 654 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-571	Structure Name:	G5-571	Road Name:	JEAN MARIE	Inspection Date:	2019/10/30
GENERAL	Inspector's Comment:	GOOD					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2061	Estimated Replacement (year):		2061	
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/03/09 08:20:24			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 655 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-572	Structure Name:	G5-572	Road Name:	JEAN MARIE	Inspection Date:	2021/09/22
KM:	3.20	User km:	3.20	Crossing Name:	Un-named Creek	Next Inspection Date:	2024/09/22
Project File ID #:	7671	Br.	68	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:	Span Length(s) (metres):		12
UTM Zone:	10		UTM Easting:	391950	UTM Northing:	6110334	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2016		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	some out of place and damaged
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 656 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-572	Structure Name:	G5-572	Road Name:	JEAN MARIE	Inspection Date:	2021/09/22			
Road Surface		Good								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Fair								
Deck to Girder Bolts		Good								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Good								
Running Planks		Good								
Sub Deck		Good								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	3	Required	High	\$						

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 657 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-572	Structure Name:	G5-572	Road Name:	JEAN MARIE	Inspection Date:	2021/09/22
MONITORS	#	Description					
GENERAL	Inspector's Comment:	No issues. GZ					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2041	Estimated Replacement (year):		2041	
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/10 17:23:31	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 658 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-573	Structure Name:	G5-573	Road Name:	JEAN MARIE	Inspection Date:	2021/09/22
KM:	3.80	User km:	3.80	Crossing Name:	Un-named Creek	Next Inspection Date:	2024/09/22
Project File ID #:	7671	Br.	68	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Steel			Running Surface:	Anti-skid		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel Box Beam				Right	Concrete Lock Blocks	
Total Length (metres):	9.1	# Spans:	1	Span Width:	Span Length(s) (metres):		9
UTM Zone:	10		UTM Easting:	392270	UTM Northing:	6110749	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2016		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	some out of place and damaged
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 659 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-573	Structure Name:	G5-573	Road Name:	JEAN MARIE	Inspection Date:	2021/09/22
---------	--------	-----------------	--------	------------	------------	------------------	------------

Road Surface	Fair	needs grading
--------------	------	---------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

Steel Deck Plate	Good
------------------	------

SUPERSTRUCTURE

Span 1

Bracing	Not Applicable
---------	----------------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	1.0
Estimated High Water Level Clearance:	1.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
3	Required	Medium		Reposition and repair approach fenders.

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 660 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-573	Structure Name:	G5-573	Road Name:	JEAN MARIE	Inspection Date:	2021/09/22
GENERAL	Inspector's Comment:	No issues. GZ					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2041	Estimated Replacement (year):		2041	
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/10 17:38:38			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 661 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-574	Structure Name:	P048	Road Name:	JEAN MARIE	Inspection Date:	2021/09/22
KM:	7.70	User km:	7.70	Crossing Name:	Un-named Creek	Next Inspection Date:	2024/09/22
Project File ID #:	7671	Br.	68	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	10		UTM Easting:	391068		UTM Northing:	6113775
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2017		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	up side sign is damaged
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	some out of place and damaged
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 662 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-574	Structure Name:	P048	Road Name:	JEAN MARIE	Inspection Date:	2021/09/22			
Road Surface	Fair	needs grading								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Good									
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	2	Required	Medium		Realign approach fenders					
	3	Required	Medium		Grade bridge approaches.					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 663 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-574	Structure Name:	P048	Road Name:	JEAN MARIE	Inspection Date:	2021/09/22
MONITORS	#	Description					
GENERAL	Inspector's Comment:	No issues. GZ					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2041	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/10 17:43:42	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 664 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-576	Structure Name:	G4-928	Road Name:	JEAN MARIE	Inspection Date:	2020/09/26
KM:	13.90	User km:	13.90	Crossing Name:	Un-named Creek	Next Inspection Date:	2023/09/26
Project File ID #:	7671	Br.	68	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:			Span Length(s) (metres): 12.2
UTM Zone:	10		UTM Easting:	386625	UTM Northing:	6117228	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2018		
Access:	Check road						

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Fair	limited
Wing Wall	Good	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	100	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 665 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-576	Structure Name:	G4-928	Road Name:	JEAN MARIE	Inspection Date:	2020/09/26			
Road Surface		Good								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Deck to Girder Bolts		Good								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Good								
Running Planks		Good								
Sub Deck		Good								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Good								
CHANNEL	Estimated Present Water Level Depth:		0.3		Estimated Present Water Level Width:		3.0			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 666 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-576	Structure Name:	G4-928	Road Name:	JEAN MARIE	Inspection Date:	2020/09/26
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	looks good					
GENERAL	Estimated Load Restriction (year):		2068	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/02/25 15:21:34	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 667 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-575	Structure Name:	P049	Road Name:	TAMASGALE	Inspection Date:	2020/09/23
KM:	4.20	User km:	4.20	Crossing Name:	Un-named Creek	Next Inspection Date:	2022/09/23
Project File ID #:	7671	Br.	70	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Steel			Running Surface:	Anti-skid		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Steel Box Beam				Right	Sill -Temporary Materials	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	10		UTM Easting:	389079		UTM Northing:	6112405
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:			
Access:	Check Coords and revise.						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	100	
Road Surface	Good	

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 668 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-575	Structure Name:	P049	Road Name:	TAMASGALE	Inspection Date:	2020/09/23
---------	--------	-----------------	------	------------	-----------	------------------	------------

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

Steel Deck Plate	Good
------------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Good
----------------	------

CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.0
	Estimated High Water Level Clearance:	0.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	2	Required	Low	\$ 0.00	replace delineators

MONITORS	#	Description

GENERAL	Inspector's Comment:	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 669 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-575	Structure Name:	P049	Road Name:	TAMASGALE	Inspection Date:	2020/09/23	
GENERAL	PEng's Comment:	looks good						
GENERAL	Estimated Load Restriction (year):			2057	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status: Reviewed By Jason Olmsted on 2021/03/04 14:46:39				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 670 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-270	Structure Name:	G5-270A	Road Name:	KEVE	Inspection Date:	2020/09/23
KM:	3.20	User km:	3.20	Crossing Name:	Upper Keve Creek	Next Inspection Date:	2023/09/23
Project File ID #:	7671	Br.	72	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	18.3	# Spans:	1	Span Width:			Span Length(s) (metres): 18
UTM Zone:	10		UTM Easting:	355152	UTM Northing:	6117477	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2009		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	left off corner
Bridge Ahead Signs Missing	1	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Fair	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 671 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-270	Structure Name:	G5-270A	Road Name:	KEVE	Inspection Date:	2020/09/23
---------	--------	-----------------	---------	------------	------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	Rot in curbs
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Poor	due to rot in running boards
Overall Deck Condition	Fair	
Running Planks	Poor	Rot
Sub Deck	Fair	fungus located under deck
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Good	

CHANNEL

Estimated Present Water Level Depth:	0.3	Estimated Present Water Level Width:	3.0
Estimated High Water Level Clearance:	1.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	High	\$	
2	Required	High	\$	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 672 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-270	Structure Name:	G5-270A	Road Name:	KEVE	Inspection Date:	2020/09/23
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Need to replace deck soon or else it will be down rated.					
GENERAL	Estimated Load Restriction (year):		2029		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:		L100				
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/01 13:01:14			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 673 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-271	Structure Name:	G5-965	Road Name:	KEVE	Inspection Date:	2019/10/04
KM:	5.80	User km:	5.80	Crossing Name:	Unnamed	Next Inspection Date:	2022/10/04
Project File ID #:	7671	Br.	72	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:			Span Length(s) (metres): 12.2
UTM Zone:	10		UTM Easting:	354235		UTM Northing:	6115393
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2009		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	OUT OF POSITION
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 674 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-271 Structure Name: G5-965 Road Name: KEVE Inspection Date: 2019/10/04

DECK

Span 1

Curb Rail/Blocks/Posts Good

Deck to Girder Bolts Not Applicable

Hardware Not Applicable

Hand Rails/Walkouts Not Applicable

Nails Good

Overall Deck Condition Good

Running Planks Good

Sub Deck Good

Ties Good

SUPERSTRUCTURE

Span 1

Bracing Good

Diaphragms Good

Girders Good

Hardware Not Applicable

Under Trussing Not Applicable

CHANNEL

Estimated Present Water Level Depth: 0.5 Estimated Present Water Level Width: 2.0
Estimated High Water Level Clearance: 1.0

HAZARDS

High Water: No Scour: No Ice: No Debris: No Aggradation: No
Comment:

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Medium	\$ 250.00	BRUSH

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 675 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-271	Structure Name:	G5-965	Road Name:	KEVE	Inspection Date:	2019/10/04
GENERAL	Inspector's Comment:	ALL GOOD, NEEDS BRUSHING					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/10 12:49:21			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 676 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-020	Structure Name:	G4-020	Road Name:	HOLY CROSS	Inspection Date:	2002/07/24
KM:	14.10	User km:	114.10	Crossing Name:	Irish Creek	Next Inspection Date:	2007/07/20
Project File ID #:	7724	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:				Culvert Material:			
Inlet Cover (mm):	6			Outlet Cover (mm):	6		
Footing Type:				Gradient (%):			
Culvert Length (metres):	39.0	Opening Height (mm):	1	Opening Width (mm):	1		
UTM Zone:	10	UTM Easting:	386321	UTM Northing:	5978062		
Inspector Name:	Tim Silbernagel		Year Superstructure Installed:	1981			
Access:							

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Good	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 677 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-020	Structure Name:	G4-020	Road Name:	HOLY CROSS	Inspection Date:	2002/07/24			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	nullCulvert: 4-7) minor sag under roadway, minor deformations.								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):				Estimated Replacement (year):					
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/12 16:24:40				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 678 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-021	Structure Name:	G4-021	Road Name:	HOLY CROSS	Inspection Date:	2021/06/13
KM:	15.10	User km:	115.10	Crossing Name:	Smith Creek	Next Inspection Date:	2022/09/01
Project File ID #:	7724	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	5,200			Outlet Cover (mm):	8,000		
Footing Type:				Gradient (%):	5.0		
Culvert Length (metres):	50.6	Opening Height (mm):	2,100	Opening Width (mm):	2,100		
UTM Zone:	10	UTM Easting:	386576	UTM Northing:	5977248		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1979		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	
Footing	Not Applicable	
Head Wall	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 679 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-021	Structure Name:	G4-021	Road Name:	HOLY CROSS	Inspection Date:	2021/06/13			
Inlet	Good									
Outlet	Fair									
Overall	Fair									
Riprap	Not Applicable									
Roof	Fair	some deformation								
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	monitor deformation in roof								
GENERAL	Inspector's Comment:	Insufficient pictures, coupled, not bolted.								
GENERAL	PEng's Comment:									

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 680 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-021	Structure Name:	G4-021	Road Name:	HOLY CROSS	Inspection Date:	2021/06/13
GENERAL	Estimated Load Restriction (year):		2029	Estimated Replacement (year):			
	Current Inspection Load Rating:		See footnote	Design Load GVW (tonnes):	91	Design Vehicle Config.:	
	Professional Inspection Required?	No	Report Status:	Rejected By IDIR\GZSOMBOR on 2021/12/02 09:12:21			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 681 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-022	Structure Name:	G4-022	Road Name:	HOLY CROSS	Inspection Date:	2020/05/06
KM:	31.10	User km:	131.10	Crossing Name:	Cabin Creek	Next Inspection Date:	2023/05/06
Project File ID #:	7724	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,400			Outlet Cover (mm):	1,400		
Footing Type:	Precast Concrete Footing			Gradient (%):			
Culvert Length (metres):	23.0	Opening Height (mm):	4,416	Opening Width (mm):	10,860		
UTM Zone:	10	UTM Easting:	378643	UTM Northing:	5966967		
Inspector Name:	Warren wilkinson			Year Superstructure Installed:	1995		
Access:							

APPROACHES

Alignment	Fair	corner right side
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	1.5m
Floor	Not Applicable	
Footing	Good	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	nateral drop

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 682 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-022	Structure Name:	G4-022	Road Name:	HOLY CROSS	Inspection Date:	2020/05/06
Overall	Good						
Riprap	Fair						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						
CHANNEL	Estimated Present Water Level Depth:		1.0		Estimated Present Water Level Width:		4.5
	Estimated High Water Level Clearance:		3.0				
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Aggradation: No
	Comment:	at outlet					
REPAIRS	#	Status	Priority	Estimate	Description		
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Looks good					
GENERAL	Estimated Load Restriction (year):		2035		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:						
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/01/22 11:04:56			

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 683 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-023	Structure Name:	G4-023	Road Name:	HOLY CROSS	Inspection Date:	2002/07/24
KM:	41.70	User km:	141.70	Crossing Name:	Targe Creek	Next Inspection Date:	2030/08/01
Project File ID #:	7724	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	5,000			Outlet Cover (mm):	5,000		
Footing Type:				Gradient (%):	2.0		
Culvert Length (metres):	24.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	374923	UTM Northing:	5958945		
Inspector Name:	Tim Silbernagel			Year Superstructure Installed:	1982		
Access:							

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Fair	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Fair	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 684 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-023	Structure Name:	G4-023	Road Name:	HOLY CROSS	Inspection Date:	2002/07/24			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Monitor scour at inlet. (very minor, no problems TS2002)								
GENERAL	Inspector's Comment:	nullCulvert: 9) large screen laying by outlet but not required 11) rusty bottom 12) no scour, slow creek.								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2032		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/12 16:25:39			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 685 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-024	Structure Name:	G4-024	Road Name:	HOLY CROSS	Inspection Date:	2019/08/08
KM:	59.80	User km:	158.80	Crossing Name:	Cheslatta River	Next Inspection Date:	2022/08/08
Project File ID #:	7724	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Asphalt		
Curb Type:				Abutments (looking downstream)	Left	Concrete Cast in Place	
Superstructure:	Steel I-beam				Right	Concrete Cast in Place	
Total Length (metres):	37.0	# Spans:	1	Span Width:	Span Length(s) (metres):		37
UTM Zone:	10	UTM Easting:	370955	UTM Northing:	5945487		
Inspector Name:	dawson smith			Year Superstructure Installed:	1982		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Good	
Ballast Wall	Good	
Concrete Cast in Place	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	end cap far side downstream missing
Posted Load Rating (Enter 0 if sign missing)	91000	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 686 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-024	Structure Name:	G4-024	Road Name:	HOLY CROSS	Inspection Date:	2019/08/08
---------	--------	-----------------	--------	------------	------------	------------------	------------

Road Surface	Fair	
--------------	------	--

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Good	
Deck Joints	Not Applicable	
Grout Pockets	Not Applicable	
Hardware	Good	
Hand Rails/Walkouts	Good	
Overall Deck Condition	Good	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	3.0	Estimated Present Water Level Width:	20.0
	Estimated High Water Level Clearance:	7.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Medium	\$	add fill and grade approaches

MONITORS	#	Description

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 687 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-024	Structure Name:	G4-024	Road Name:	HOLY CROSS	Inspection Date:	2019/08/08
GENERAL	Inspector's Comment:	good, BOTH APPROACHES NEED CAPPING AND GRADING, ALL DELINIATORS PRESENT.					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/23 14:58:03			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 688 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-025	Structure Name:	G4-025	Road Name:	HOLY CROSS	Inspection Date:	2020/05/26
KM:	65.00	User km:	165.00	Crossing Name:	Canyon Creek	Next Inspection Date:	2023/05/26
Project File ID #:	7724	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	56.0	Opening Height (mm):	3,700	Opening Width (mm):	3,700		
UTM Zone:	10	UTM Easting:	370584	UTM Northing:	5940568		
Inspector Name:	Vince Sewell			Year Superstructure Installed:	1982		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	minor rust
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 689 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-025	Structure Name:	G4-025	Road Name:	HOLY CROSS	Inspection Date:	2020/05/26
Inlet	Good						
Outlet	Good						
Overall	Good						
Riprap	Good						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						

CHANNEL	Estimated Present Water Level Depth:			0.4		Estimated Present Water Level Width:			1.5	
	Estimated High Water Level Clearance:			2.0						
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Looks good								

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 690 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-025	Structure Name:	G4-025	Road Name:	HOLY CROSS	Inspection Date:	2020/05/26
GENERAL	Estimated Load Restriction (year):		2035	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/01/22 11:08:42	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 691 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-030	Structure Name:	G4-030	Road Name:	HOLY CROSS	Inspection Date:	2002/07/16
KM:	11.10	User km:	223.00	Crossing Name:	Unnamed creek	Next Inspection Date:	2030/01/01
Project File ID #:	7724	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	8,000			Outlet Cover (mm):	8,000		
Footing Type:				Gradient (%):	2.0		
Culvert Length (metres):	43.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	376396	UTM Northing:	5978361		
Inspector Name:	Tim Silbernagel			Year Superstructure Installed:	1980		
Access:	Coordinates are approximate and based on Km measure. Field verify						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Head Wall	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Fair	No Comment Available -Converter.RNI
Riprap	Fair	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 692 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-030	Structure Name:	G4-030	Road Name:	HOLY CROSS	Inspection Date:	2002/07/16			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		1.3							
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Monitor scour at outlet (1.4M drop, TS2002)								
GENERAL	Inspector's Comment:	nullCulvert: 2) 1.4M drop at outlet 4-7) minor deformations 12) poor at outlet.								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2030		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/12 16:26:56			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 693 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-031	Structure Name:	G4-031	Road Name:	HOLY CROSS	Inspection Date:	2021/07/14
KM:	14.50	User km:	226.60	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/07/14
Project File ID #:	7724	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	4,500			Outlet Cover (mm):	5,000		
Footing Type:				Gradient (%):	5.0		
Culvert Length (metres):	26.6	Opening Height (mm):	1,750	Opening Width (mm):	1,750		
UTM Zone:	10	UTM Easting:	374044	UTM Northing:	5975391		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1980		
Access:	Minor culvert in good condition. Inspect every 10 years. GZ. 2021						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 694 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-031	Structure Name:	G4-031	Road Name:	HOLY CROSS	Inspection Date:	2021/07/14			
Overall	Good									
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	3.0						
	Estimated High Water Level Clearance:	1.2								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	No concerns.								
GENERAL	Estimated Load Restriction (year):	2030	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/01/19 13:11:34						

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 695 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-032	Structure Name:	G4-032	Road Name:	HOLY CROSS	Inspection Date:	2021/07/14
KM:	15.00	User km:	227.10	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/07/14
Project File ID #:	7724	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	6,300			Outlet Cover (mm):	7,000		
Footing Type:				Gradient (%):	4.0		
Culvert Length (metres):	37.0	Opening Height (mm):	2,130	Opening Width (mm):	2,130		
UTM Zone:	10	UTM Easting:	373566	UTM Northing:	5975286		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1980		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 696 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-032	Structure Name:	G4-032	Road Name:	HOLY CROSS	Inspection Date:	2021/07/14			
Overall	Good									
Riprap	Fair									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.0	Estimated Present Water Level Width:	1.1						
	Estimated High Water Level Clearance:	1.6								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	No concerns.								
GENERAL	Estimated Load Restriction (year):	2030	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/01/19 13:17:24						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 697 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-033	Structure Name:	G4-033	Road Name:	HOLY CROSS	Inspection Date:	2019/08/08
KM:	33.30	User km:	233.30	Crossing Name:	Nithi River	Next Inspection Date:	2022/08/08
Project File ID #:	7724	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	16.0	# Spans:	1	Span Width:	Span Length(s) (metres):		16
UTM Zone:	10	UTM Easting:	367549	UTM Northing:	5977677		
Inspector Name:	dawson smith			Year Superstructure Installed:	1979		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 698 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-033	Structure Name:	G4-033	Road Name:	HOLY CROSS	Inspection Date:	2019/08/08
---------	--------	-----------------	--------	------------	------------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Not Applicable
----------------------	----------------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Good
----------------	------

Sub Deck	Good
----------	------

Ties	Fair
------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Fair
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	6.0
Estimated High Water Level Clearance:	4.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$ 250.00	INSTALL LOAD RATING SIGN

MONITORS

#	Description
1	Rot in cross ties

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 699 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-033	Structure Name:	G4-033	Road Name:	HOLY CROSS	Inspection Date:	2019/08/08
GENERAL	Inspector's Comment:	good, MISSING LOAD RATING SIGN					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/22 10:54:38			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 700 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-034	Structure Name:	G4-034-A	Road Name:	HOLY CROSS	Inspection Date:	2020/05/06
KM:	34.50	User km:	246.50	Crossing Name:	Nithi River	Next Inspection Date:	2023/05/06
Project File ID #:	7724	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	24.4	# Spans:	1	Span Width:			Span Length(s) (metres): 24
UTM Zone:	10		UTM Easting:	355733		UTM Northing:	5976888
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2007		
Access:							

ABUTMENTS

Bearings	Good
Bracing	Good
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Good
Piles or Posts	Good
Riprap	Good
Wing Wall	Not Applicable

APPROACHES

Alignment	Good	corners on both sides
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 701 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-034	Structure Name:	G4-034-A	Road Name:	HOLY CROSS	Inspection Date:	2020/05/06
---------	--------	-----------------	----------	------------	------------	------------------	------------

DECK

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Good
---------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	8.0
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	2.0
---------------------------------------	-----

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 702 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-034	Structure Name:	G4-034-A	Road Name:	HOLY CROSS	Inspection Date:	2020/05/06
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	bridge in good condition					
GENERAL	Estimated Load Restriction (year):		2052	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/01/22 11:01:37			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 703 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-040	Structure Name:	G4-040	Road Name:	H. CROSS CABIN	Inspection Date:	2021/06/13
KM:	1.00	User km:	0.90	Crossing Name:	Nithi River	Next Inspection Date:	2024/06/13
Project File ID #:	7724	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	16.5	# Spans:	1	Span Width:	Span Length(s) (metres):		16
UTM Zone:	10	UTM Easting:	362837	UTM Northing:	5978166		
Inspector Name:	Dawson Smith		Year Superstructure Installed:	1995			
Access:	Turn left at km 38.5 on the Holy Cross-Binta FSR which is marked as Boreal Rec. site						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Excellent	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Fair	wood fenders
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 704 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-040	Structure Name:	G4-040	Road Name:	H. CROSS CABIN	Inspection Date:	2021/06/13
---------	--------	-----------------	--------	------------	----------------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Good	
Sub Deck	Unrated	one layer of running planks
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	5.0
Estimated High Water Level Clearance:	1.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
3	Required	Medium	\$	
4	Required	Medium	\$	install delineators

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 705 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-040	Structure Name:	G4-040	Road Name:	H. CROSS CABIN	Inspection Date:	2021/06/13
MONITORS	#	Description					
GENERAL	Inspector's Comment:	No significant issues. GZ					
GENERAL	PEng's Comment:	No concerns. BH					
GENERAL	Estimated Load Restriction (year):		2035	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/01/19 13:25:52	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 706 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-028	Structure Name:	004-13	Road Name:	HOLY CROSS	Inspection Date:	2018/09/27
KM:	0.30	User km:	0.30	Crossing Name:	Unnamed creek	Next Inspection Date:	2019/08/01
Project File ID #:	7724	Br.	12	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:			Span Length(s) (metres): 12.2
UTM Zone:	10		UTM Easting:	355765	UTM Northing:	5976447	
Inspector Name:	Adam Mathison, GradTech			Year Superstructure Installed:	2018		
Access:	Turn left at user km 247 on the Holy Cross-Binta FSR						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Good	
Caps or Sills	Good	Two 6"x6" timbers lagged to front of each sill to increase bearing area
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 707 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-028	Structure Name:	004-13	Road Name:	HOLY CROSS	Inspection Date:	2018/09/27
---------	--------	-----------------	--------	------------	------------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Good
----------------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Good
----------------	------

Sub Deck	Good
----------	------

Ties	Good
------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	1.0
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	1.5
---------------------------------------	-----

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 708 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-028	Structure Name:	004-13	Road Name:	HOLY CROSS	Inspection Date:	2018/09/27
GENERAL	Inspector's Comment:	Superstructure has been replaced since last inspection. Ruskin Construction Serial 004-13 L-100 load rating Lock block abutments and existing sills were left in place. Two 6"x6" timbers were stacked and lagged against the front of the existing sills to increase bearing area. Bridge is in good condition					
GENERAL	PEng's Comment:	Road has been transferred to West Fraser.					
GENERAL	Estimated Load Restriction (year):		2038	Estimated Replacement (year):		2038	
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Rejected By IDIR\JOLMSTED on 2020/02/10 12:46:42			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 709 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-060	Structure Name:	G5-060	Road Name:	FALL	Inspection Date:	2019/10/14
KM:	0.10	User km:	200.10	Crossing Name:	Teegee Creek #1	Next Inspection Date:	2022/10/14
Project File ID #:	7785	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	20.0	Opening Height (mm):	2,800	Opening Width (mm):	4,000		
UTM Zone:	9	UTM Easting:	496503	UTM Northing:	6163969		
Inspector Name:	Dawson SMITH		Year Superstructure Installed:	1980			
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 710 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-060	Structure Name:	G5-060	Road Name:	FALL	Inspection Date:	2019/10/14
Overall	Good						
Riprap	Not Applicable						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						
CHANNEL	Estimated Present Water Level Depth:	0.5			Estimated Present Water Level Width:	2.0	
	Estimated High Water Level Clearance:	2.0					
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Aggradation: No
	Comment:						
REPAIRS	#	Status	Priority	Estimate	Description		
MONITORS	#	Description					
GENERAL	Inspector's Comment:	GOOD, BOLTED CULVERT, SIGNS OF BEAVERS BUT NOTHING BUILT					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):	2030		Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/03/02 13:58:56			

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 711 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-061	Structure Name:	G5-061	Road Name:	FALL	Inspection Date:	2019/10/14
KM:	4.30	User km:	204.30	Crossing Name:	Teegee Creek #1	Next Inspection Date:	2022/10/14
Project File ID #:	7785	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Elliptical			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	2,000			Outlet Cover (mm):	2,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	22.0	Opening Height (mm):	2,500	Opening Width (mm):	4,000		
UTM Zone:	9	UTM Easting:	498911	UTM Northing:	6166651		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1980		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Fair	LOOKS LIKE THE LAST SECTION HAS BENT DOWNWARDS A BIT

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 712 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-061	Structure Name:	G5-061	Road Name:	FALL	Inspection Date:	2019/10/14			
Overall	Fair									
Riprap	Fair									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	2.0						
	Estimated High Water Level Clearance:	2.5								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	BOLTED CULVERT, THE LAST SECTION (DOWNSTREAM SIDE) LOOKS LIKE IT HAS SLUMPED DOWN A BIT, EVERYTHING ELSE LOOKS OKAY								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):	2030	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/03/02 14:00:42						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 713 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-062	Structure Name:	G5-062	Road Name:	FALL	Inspection Date:	2021/09/15
KM:	23.50	User km:	223.50	Crossing Name:	Fall River	Next Inspection Date:	2024/09/15
Project File ID #:	7785	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	21.3	# Spans:	1	Span Width:	Span Length(s) (metres):		21.3
UTM Zone:	10	UTM Easting:	324749	UTM Northing:	6180054		
Inspector Name:	Vince Sewell			Year Superstructure Installed:	1999		
Access:							

ABUTMENTS

Bearings	Good
Bracing	Good
Ballast Wall	Good
Corrosion Protection	Good
Caps or Sills	Good
Fill	Good
Hardware	Good
Piles or Posts	Good
Riprap	Good
Wing Wall	Not Applicable

APPROACHES

Alignment	Fair
Bridge Ahead Signs Missing	0
Brushing Required	No
Delineator Missing Left (approaching structure)	0
Delineator Missing Right (approaching structure)	0
Fender Condition	Good
Posted Load Rating (Enter 0 if sign missing)	91
Road Surface	Good

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 714 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-062	Structure Name:	G5-062	Road Name:	FALL	Inspection Date:	2021/09/15
---------	--------	-----------------	--------	------------	------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Fair	Some rot showing age
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.7	Estimated Present Water Level Width:	4.0
	Estimated High Water Level Clearance:	2.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 715 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-062	Structure Name:	G5-062	Road Name:	FALL	Inspection Date:	2021/09/15
GENERAL	Inspector's Comment:	Bridge in good condition except curbs					
GENERAL	PEng's Comment:	No concerns. BH					
GENERAL	Estimated Load Restriction (year):		2050	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/04 13:17:45			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 716 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-063	Structure Name:	G5-063	Road Name:	FALL	Inspection Date:	2019/10/14
KM:	31.20	User km:	231.30	Crossing Name:	Fall River	Next Inspection Date:	2022/10/14
Project File ID #:	7785	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	37.0	# Spans:	1	Span Width:	Span Length(s) (metres):		37
UTM Zone:	10	UTM Easting:	332180	UTM Northing:	6181958		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1998		
Access:							

ABUTMENTS

Bearings Fair

Bracing Not Applicable

Ballast Wall Good

Corrosion Protection Not Applicable

Caps or Sills Good

Fill Good

Hardware Not Applicable

Piles or Posts Good

Riprap Good

Wing Wall Good

APPROACHES

Alignment Good

Bridge Ahead Signs Missing 2

Brushing Required No

Delineator Missing Left (approaching structure) 1

Delineator Missing Right (approaching structure) 1

Fender Condition Fair

Road Surface Good

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 717 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-063	Structure Name:	G5-063	Road Name:	FALL	Inspection Date:	2019/10/14
---------	--------	-----------------	--------	------------	------	------------------	------------

Span 1

Concrete Deck	Fair	COULDN'T SEE DUE TO TO FROZEN GROUNDS AND SNOW
Curb Rail/Blocks/Posts	Fair	MINOR DAMAGE/ROT
Deck Joints	Unrated	COULDN'T SEE DUE TO TO FROZEN GROUNDS AND SNOW
Grout Pockets	Unrated	COULDN'T SEE DUE TO TO FROZEN GROUNDS AND SNOW
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	7.0
Estimated High Water Level Clearance:	3.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Medium	\$ 500.00	INSTALL 2 SIGNS W/LOAD RATING AND 2 DELINEATORS

MONITORS

#	Description
1	MONITOR BEAVER DAM UPSTREAM
2	MONITOR DAMAGED/ROTTEN GUARD RAILS

GENERAL

Inspector's Comment: GUARD RAILS HAVE ROT BUT ARE OKAY FOR NOW, MISSING BRIDGE AHEAD SIGNS AND 2 DELINEATORS, BEAVERS ARE BUIDLING A DAM APPROX 30 M UPSTREAM

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 718 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-063	Structure Name:	G5-063	Road Name:	FALL	Inspection Date:	2019/10/14
---------	--------	-----------------	--------	------------	------	------------------	------------

GENERAL

PEng's
Comment:

GENERAL

Estimated Load Restriction (year):	2048	Estimated Replacement (year):			
Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100
Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/30 15:48:47		

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 719 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-064	Structure Name:	G5-064	Road Name:	FALL	Inspection Date:	2021/09/15
KM:	36.00	User km:	236.00	Crossing Name:	Fall River	Next Inspection Date:	2024/09/15
Project File ID #:	7785	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	24.8	# Spans:	1	Span Width:	Span Length(s) (metres):		24.8
UTM Zone:	10	UTM Easting:	335961	UTM Northing:	6181752		
Inspector Name:	Vince Sewell			Year Superstructure Installed:	1999		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Fair	LC has lots of cracking
Corrosion Protection	Good	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Fair	adequate but may scour in high water
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 720 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-064	Structure Name:	G5-064	Road Name:	FALL	Inspection Date:	2021/09/15
---------	--------	-----------------	--------	------------	------	------------------	------------

DECK

Span 1

Concrete Deck	Good	Dirty
Curb Rail/Blocks/Posts	Fair	Rot and soft sections
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.8	Estimated Present Water Level Width:	5.0
	Estimated High Water Level Clearance:	1.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	6	Required	Medium	\$ 0.00	Replace rails/blocks/risers prior to industrial use

MONITORS	#	Description
	1	LC ballast wall cracking

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 721 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-064	Structure Name:	G5-064	Road Name:	FALL	Inspection Date:	2021/09/15
GENERAL	Inspector's Comment:	Overall good except curbs. look at LC ballast wall photos					
GENERAL	PEng's Comment:	Minor cracking in ballast wall. Replace curbs before industrial ude. BH					
GENERAL	Estimated Load Restriction (year):		2050	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/04 13:40:24			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 722 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-065	Structure Name:	G5-065	Road Name:	FALL	Inspection Date:	2019/10/14
KM:	36.70	User km:	236.70	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/10/14
Project File ID #:	7785	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	3,000			Outlet Cover (mm):	3,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	32.0	Opening Height (mm):	2,000	Opening Width (mm):	2,000		
UTM Zone:	10	UTM Easting:	336384	UTM Northing:	6181299		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1990		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 723 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-065	Structure Name:	G5-065	Road Name:	FALL	Inspection Date:	2019/10/14			
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		0.1			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Not Required	Medium	\$ 500.00	BRUSH BOTH SIDES					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	VERY BRUSHED IN, CULVERT IS GOOD								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):			2030	Estimated Replacement (year):					
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/03/02 14:03:01				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 724 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-066	Structure Name:	G5-066	Road Name:	FALL	Inspection Date:	2019/10/14
KM:	37.70	User km:	237.70	Crossing Name:	Buck Creek	Next Inspection Date:	2022/10/14
Project File ID #:	7785	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	22.0	# Spans:	1	Span Width:	Span Length(s) (metres):		22
UTM Zone:	10	UTM Easting:	337389	UTM Northing:	6181203		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1994		
Access:							

ABUTMENTS

Bearings	Fair	BULGING
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Fair	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	LOG FENDERS
Road Surface	Good	

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 725 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-066	Structure Name:	G5-066	Road Name:	FALL	Inspection Date:	2019/10/14
---------	--------	-----------------	--------	------------	------	------------------	------------

Span 1

Concrete Deck	Fair	COULD NOT SEE DECK DUE TO FROZEN MUD AND SNOW HOWEVER NO LEAKS
Curb Rail/Blocks/Posts	Good	
Deck Joints	Fair	COULD NOT SEE DECK DUE TO FROZEN MUD AND SNOW HOWEVER NO LEAKS
Grout Pockets	Fair	COULD NOT SEE DECK DUE TO FROZEN MUD AND SNOW HOWEVER NO LEAKS
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	COULD NOT SEE DECK DUE TO FROZEN MUD AND SNOW HOWEVER NO LEAKS

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	2.0
Estimated High Water Level Clearance:	5.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$ 500.00	BRUSH

MONITORS

#	Description
1	MONITOR BEARINGS

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 726 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-066	Structure Name:	G5-066	Road Name:	FALL	Inspection Date:	2019/10/14
GENERAL	Inspector's Comment:	BRIDGE IS IN GOOD SHAPE, COULD NOT SEE DECK DUE TO FROZEN MUD AND SNOW HOWEVER NO LEAKS UNDERNEATH, BEARINGS ARE BULGING,					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2034	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/30 15:45:23			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 727 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-067	Structure Name:	G5-067-2	Road Name:	FALL	Inspection Date:	2019/10/14
KM:	44.60	User km:	244.60	Crossing Name:	Teegee Creek #2	Next Inspection Date:	2022/10/14
Project File ID #:	7785	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	3,000			Outlet Cover (mm):	3,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	25.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	343397	UTM Northing:	6179828		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1993		
Access:	2 WDR						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 728 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-067	Structure Name:	G5-067-2	Road Name:	FALL	Inspection Date:	2019/10/14			
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Low	\$ 250.00	BOTH SIDES NEED BRUSHING					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	GOOD, VERY BRUSHED IN, INLET HAS A WEIRD PLYWOOD DEFLECTOR								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):			2033	Estimated Replacement (year):					
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/03/02 14:08:05				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 729 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-067	Structure Name:	G5-067	Road Name:	FALL	Inspection Date:	2019/10/14
KM:	44.60	User km:	244.60	Crossing Name:	Teegee Creek #2	Next Inspection Date:	2022/10/14
Project File ID #:	7785	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	3,000			Outlet Cover (mm):	3,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	25.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	343397	UTM Northing:	6179828		
Inspector Name:	Dawson SMITH		Year Superstructure Installed:	1993			
Access:	2 WDR						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 730 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-067	Structure Name:	G5-067	Road Name:	FALL	Inspection Date:	2019/10/14			
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Low	\$ 250.00	BRUSH BOTH SIDES					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	PIPE IS IN GOOD SHAPE, THERE IS A WEIRD PLYWOOD WATER DEFLECTOR AT INLET, NEEDS BRUSHING								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):			2033	Estimated Replacement (year):					
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/03/02 14:04:59				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 731 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-068	Structure Name:	G5-068	Road Name:	FALL	Inspection Date:	2019/10/14
KM:	46.00	User km:	246.00	Crossing Name:	Silver Creek	Next Inspection Date:	2022/10/14
Project File ID #:	7785	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	34.0	# Spans:	1	Span Width:	Span Length(s) (metres):		34
UTM Zone:	10	UTM Easting:	344767	UTM Northing:	6179379		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1993		
Access:							

ABUTMENTS

Bearings Good

Bracing Not Applicable

Ballast Wall Good

Corrosion Protection Not Applicable

Caps or Sills Good

Fill Good

Hardware Not Applicable

Piles or Posts Good

Riprap Good

Wing Wall Good

APPROACHES

Alignment Good

Bridge Ahead Signs Missing 2

Brushing Required No

Delineator Missing Left (approaching structure) 0

Delineator Missing Right (approaching structure) 0

Fender Condition Good

Road Surface Good

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 732 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-068	Structure Name:	G5-068	Road Name:	FALL	Inspection Date:	2019/10/14
---------	--------	-----------------	--------	------------	------	------------------	------------

Span 1

Concrete Deck	Unrated	DECK WAS FROZEN SO COULDN'T SEE IT ALL HOWEVER GAPS AT BOTH ENDS
Curb Rail/Blocks/Posts	Poor	ROTTEN
Deck Joints	Poor	DECK WAS FROZEN SO COULDN'T SEE IT ALL HOWEVER GAPS AT BOTH ENDS
Grout Pockets	Unrated	DECK WAS FROZEN SO COULDN'T SEE IT ALL HOWEVER GAPS AT BOTH ENDS
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Poor	POOR DUE TO GUARD RAILS

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	25.0
Estimated High Water Level Clearance:	3.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Medium	\$	GROUT DECK JOINTS
2	Required	Medium	\$ 500.00	INSTALL BRIDGE AHEAD AND LOAD RATING SIGNS
3	Required	Medium	\$	REPLACE GUARD RAILS

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 733 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-068	Structure Name:	G5-068	Road Name:	FALL	Inspection Date:	2019/10/14
GENERAL	Inspector's Comment:	NO BRIDGE AHEAD SIGNS, DECK WAS FROZEN SO COULDN'T SEE IT ALL HOWEVER GAPS AT BOTH ENDS, GUARD RAILS ROTTEN AND SHOULD BE REPLACED					
GENERAL	PEng's Comment:	Curbs need replacing soon or bridge will be down-rated. Other than the curbs, deck is in good condition from last inspection.					
GENERAL	Estimated Load Restriction (year):		2038		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:		L100				
GENERAL	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/30 15:14:06			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 734 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-069	Structure Name:	G5-069	Road Name:	FALL	Inspection Date:	2001/09/18
KM:	46.10	User km:	246.10	Crossing Name:	Silver Side Channel	Next Inspection Date:	2030/01/01
Project File ID #:	7785	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	3,500			Outlet Cover (mm):	3,600		
Footing Type:				Gradient (%):	1.0		
Culvert Length (metres):	26.5	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	344789	UTM Northing:	6179168		
Inspector Name:	Brent Case			Year Superstructure Installed:	1993		
Access:	Minor culvert, 1600						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Excellent	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Excellent	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 735 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-069	Structure Name:	G5-069	Road Name:	FALL	Inspection Date:	2001/09/18			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.8							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2038		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/10 14:34:19			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 736 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-140	Structure Name:	G5-140	Road Name:	TSAYTA	Inspection Date:	2019/10/14
KM:	1.70	User km:	1.70	Crossing Name:	Trout Lake Creek	Next Inspection Date:	2022/10/14
Project File ID #:	7785	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	12.6	# Spans:	1	Span Width:	Span Length(s) (metres):		12.6
UTM Zone:	10	UTM Easting:	331155	UTM Northing:	6150759		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1997		
Access:	Park boundary sign near Abut #1						

ABUTMENTS

Bearings Fair

Bracing Not Applicable

Ballast Wall Good

Corrosion Protection Not Applicable

Caps or Sills Good

Fill Good

Hardware Not Applicable

Piles or Posts Good

Riprap Good

Wing Wall Good

APPROACHES

Alignment Fair

Bridge Ahead Signs Missing 0

Brushing Required No

Delineator Missing Left (approaching structure) 0

Delineator Missing Right (approaching structure) 0

Fender Condition Fair

Road Surface Good

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 737 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-140	Structure Name:	G5-140	Road Name:	TSAYTA	Inspection Date:	2019/10/14
---------	--------	-----------------	--------	------------	--------	------------------	------------

Span 1

Concrete Deck	Good
Curb Rail/Blocks/Posts	Good
Deck Joints	Good
Grout Pockets	Fair
Hardware	Not Applicable
Hand Rails/Walkouts	Not Applicable
Overall Deck Condition	Fair

SUPERSTRUCTURE

Span 1

Bracing	Good
Diaphragms	Good
Girders	Good
Hardware	Not Applicable
Under Trussing	Not Applicable

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	
Estimated High Water Level Clearance:	2.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Medium	\$	REMOVE BEAVER DAM AND MATERIAL ON UPSTREAM SIDE

MONITORS

#	Description

GENERAL

Inspector's Comment:	NO LOAD RATING SIGNS, BEAVERS ARE BUILDING A DAM ALMOST UNDER THE BRIDGE
----------------------	--

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 738 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-140	Structure Name:	G5-140	Road Name:	TSAYTA	Inspection Date:	2019/10/14
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2047	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?		No	Report Status: Reviewed By Jason Olmsted on 2020/02/04 15:21:11			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 739 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-147	Structure Name:	G5-147	Road Name:	TSAYTA	Inspection Date:	2019/10/14
KM:	4.50	User km:	4.90	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/10/14
Project File ID #:	7785	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	19.0	Opening Height (mm):	3,000	Opening Width (mm):	3,000		
UTM Zone:	10	UTM Easting:	334061	UTM Northing:	6150367		
Inspector Name:	Dawson SMITH		Year Superstructure Installed:		1997		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	RUSTY
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 740 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-147	Structure Name:	G5-147	Road Name:	TSAYTA	Inspection Date:	2019/10/14			
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Fair									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		1.5			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	PIPE IS IN GOOD SHAPE, LOOKS A BIT RUSTY ON THE BOTTOM, SIGNS THAT THERE WAS BEAVER ACTIVITY								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):			2047		Estimated Replacement (year):				
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/02/03 13:36:49			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 741 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-141	Structure Name:	G5-141	Road Name:	TSAYTA	Inspection Date:	2020/10/06
KM:	15.60	User km:	15.60	Crossing Name:	West Kwanika Creek	Next Inspection Date:	2023/10/06
Project File ID #:	7785	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Concrete Precast	
Superstructure:	Concrete Slab Girders				Right	Concrete Precast	
Total Length (metres):	10.0	# Spans:	1	Span Width:	Span Length(s) (metres):		10
UTM Zone:	10	UTM Easting:	340699	UTM Northing:	6156046		
Inspector Name:	Warren Wilkinson		Year Superstructure Installed:	1998			
Access:							

APPROACHES

Alignment	Poor	90 corner on upchain side
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Fair	one nose cone needs to be re-set
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Fair	wilderness level

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	rotting and broken
Deck Joints	Good	
Grout Pockets	Not Applicable	
Grout Pockets	Not Applicable	
Hardware	Poor	due to curb condition
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	

SUPERSTRUCTURE

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 742 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-141	Structure Name:	G5-141	Road Name:	TSAYTA	Inspection Date:	2020/10/06			
Span 1										
Bracing	Unrated	cannot see components								
Hardware	Unrated	cannot see components								
Welded/grouted shear connectors	Unrated	cannot see components								
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	5	Required	High	\$						
	6	Required	High							
	7	Required	Low	\$						
	8	Required	Low	\$						
MONITORS	#	Description								
GENERAL	Inspector's Comment:	down rate bridge until all repairs made								
GENERAL	PEng's Comment:	Bridge to be posted at 30 tonnes. If any section of rail is missing, then the bridge is to be closed to all traffic.								
GENERAL	Estimated Load Restriction (year):			2048		Estimated Replacement (year):			2048	
	Current Inspection Load Rating:		30		Design Load GVW (tonnes):		91		Design Vehicle Config.: L100	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2021/03/01 11:47:08			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 743 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-143	Structure Name:	G5-143	Road Name:	TSAYTA	Inspection Date:	1999/09/15
KM:	16.80	User km:	16.80	Crossing Name:	Unnamed creek	Next Inspection Date:	2030/01/01
Project File ID #:	7785	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	500			Outlet Cover (mm):	500		
Footing Type:				Gradient (%):			
Culvert Length (metres):	14.0	Opening Height (mm):	1,200	Opening Width (mm):	1,200		
UTM Zone:	10	UTM Easting:	341699	UTM Northing:	6156505		
Inspector Name:	unknown			Year Superstructure Installed:	1987		
Access:	Minor culvert, 1200						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Fair	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Poor	No Comment Available -Converter.RNI
Roof	Fair	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 744 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-143	Structure Name:	G5-143	Road Name:	TSAYTA	Inspection Date:	1999/09/15			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.1							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	nullCulvert: 5) Minor deformations. 11) Some rust on floor. 12) No rip rap, but no scour..								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2033		Estimated Replacement (year):					
	Current Inspection Load Rating:		54		Design Load GVW (tonnes):		54		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/12 09:54:06			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 745 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-144	Structure Name:	G5-144	Road Name:	TSAYTA	Inspection Date:	2002/06/20
KM:	18.30	User km:	18.30	Crossing Name:	Trout Lake Creek	Next Inspection Date:	2030/01/01
Project File ID #:	7785	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	300			Outlet Cover (mm):	500		
Footing Type:				Gradient (%):			
Culvert Length (metres):	12.0	Opening Height (mm):	1,200	Opening Width (mm):	1,200		
UTM Zone:	10	UTM Easting:	342966	UTM Northing:	6157174		
Inspector Name:	Ed Cienciala			Year Superstructure Installed:	1987		
Access:	Minor culvert, twin 1200						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Poor	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Poor	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Poor	No Comment Available -Converter.RNI
Roof	Poor	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 746 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-144	Structure Name:	G5-144	Road Name:	TSAYTA	Inspection Date:	2002/06/20			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.4							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Monitor deformations in roof near center of culverts. No Industrial traffic								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2035		Estimated Replacement (year):					
	Current Inspection Load Rating:		54		Design Load GVW (tonnes):		54		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/12 09:52:34			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 747 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-148	Structure Name:	G5-148	Road Name:	TSAYTA	Inspection Date:	2019/10/14
KM:	38.40	User km:	38.40	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/10/14
Project File ID #:	7785	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	12.0	Opening Height (mm):	2,300	Opening Width (mm):	2,300		
UTM Zone:	10	UTM Easting:	357257	UTM Northing:	6160918		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1975		
Access:	Road has been transferred to an RP. Do not inspect - CP Oct 2020 Road currently wilderness maintained. MD Feb 2017						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Poor	SCOURED ON LEFT SIDE, WATER COMING DOWN THE ROAD WILL CONTINUE

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Poor	FAILING ABOUT 1/2 WAY ACROSS
Coating	Poor	RUST ON BOTTOM
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Poor	SHOWING FROST HEAVE
Footing	Not Applicable	
Head Wall	Fair	
Inlet	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 748 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-148	Structure Name:	G5-148	Road Name:	TSAYTA	Inspection Date:	2019/10/14			
Outlet	Fair									
Overall	Poor	FAILING ABOUT 1/2 WAY ACROSS								
Riprap	Not Applicable									
Roof	Poor	FAILING ABOUT 1/2 WAY ACROSS								
Side Walls	Fair									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	1.0						
	Estimated High Water Level Clearance:	1.5								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Low	\$	GRADE ROAD					
	2	Required	Medium	\$	REPLACE CULVERT					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	ROAD ON INLET SIDE (LEFT GOING UP) IS SCOURED, NEED TO BE GRADED OR ROAD WILL FAIL. THERE IS SIGN CULVERT ROOF IS FAILING ABOUT 1/2 WAY ACROSS (CANT SEE IN THE PICTURE)								
GENERAL	PEng's Comment:	Will look at the culvert in 2020 to determine the what is required.								

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 749 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-148	Structure Name:	G5-148	Road Name:	TSAYTA	Inspection Date:	2019/10/14
GENERAL	Estimated Load Restriction (year):		2025	Estimated Replacement (year):			
	Current Inspection Load Rating:		54	Design Load GVW (tonnes):		54	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/03/09 08:39:32	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 750 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-018	Structure Name:	G5-018	Road Name:	TSAYTA	Inspection Date:	2019/10/14
KM:	55.80	User km:	55.80	Crossing Name:	Nation River	Next Inspection Date:	2022/10/14
Project File ID #:	7785	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	18.3	# Spans:	1	Span Width:	Span Length(s) (metres):		18.3
UTM Zone:	10	UTM Easting:	330707	UTM Northing:	6150281		
Inspector Name:	Dawson SMITH		Year Superstructure Installed:	1994			
Access:	Turn right at approx km 55 on the Old Driftwood FSR - start of ugly road DB2004						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Fair	MINIMAL
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	NEED TO BE REPLACED
Road Surface	Good	

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 751 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-018	Structure Name:	G5-018	Road Name:	TSAYTA	Inspection Date:	2019/10/14
---------	--------	-----------------	--------	------------	--------	------------------	------------

Span 1

Concrete Deck	Unrated	DECK WAS COVERED IN FROZEN DIRT AND SNOW SO COULD NOT SEE WELL
Curb Rail/Blocks/Posts	Fair	
Deck Joints	Unrated	DECK WAS COVERED IN FROZEN DIRT AND SNOW SO COULD NOT SEE WELL
Grout Pockets	Unrated	DECK WAS COVERED IN FROZEN DIRT AND SNOW SO COULD NOT SEE WELL
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Unrated	DECK WAS COVERED IN FROZEN DIRT AND SNOW SO COULD NOT SEE WELL

SUPERSTRUCTURE

Span 1

Bracing	Good
Diaphragms	Good
Girders	Good
Hardware	Not Applicable
Under Trussing	Not Applicable

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	4.0
Estimated High Water Level Clearance:	4.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$	REMOVE BEAVER DAM UPSTREAM
2	Required	Low	\$ 250.00	INSTALL LOAD SIGNS AND 1 DELINEATOR
3	Required	Low	\$	REPLACE FENDERS

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 752 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-018	Structure Name:	G5-018	Road Name:	TSAYTA	Inspection Date:	2019/10/14
GENERAL	Inspector's Comment:	DECK WAS COVERED IN FROZEN DIRT AND SNOW SO COULD NOT SEE WELL, HOWEVER THERE IS NO STAINING ON UNDERSIDE TO SUGGEST LEAKS. WOOD FENDERS NEED TO BE REPLACED, BEAVER BUILDING A DAM 20M UPSTREAM					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2034		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:						
GENERAL	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/03/02 14:21:40			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 753 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-100	Structure Name:	G5-100	Road Name:	DREAM	Inspection Date:	2019/10/14
KM:	3.20	User km:	3.20	Crossing Name:	Canyon Creek	Next Inspection Date:	2022/10/14
Project File ID #:	7785	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Binwall	
Superstructure:	Steel I-beam				Right	Binwall	
Total Length (metres):	10.0	# Spans:	1	Span Width:			Span Length(s) (metres): 10
UTM Zone:	10		UTM Easting:	349538	UTM Northing:	6161808	
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1991		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Binwall	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Poor	NONE
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 754 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-100	Structure Name:	G5-100	Road Name:	DREAM	Inspection Date:	2019/10/14
---------	--------	-----------------	--------	------------	-------	------------------	------------

Span 1

Curb Rail/Blocks/Posts	Fair	
Deck to Girder Bolts	Not Applicable	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Nails	Unrated	FROZEN SNOW AND DIRT SO I COULDN'T SEE THE DECK BUT NO WATER WAS DRIPPING THOUGH
Overall Deck Condition	Unrated	FROZEN SNOW AND DIRT SO I COULDN'T SEE THE DECK BUT NO WATER WAS DRIPPING THOUGH
Running Planks	Unrated	FROZEN SNOW AND DIRT SO I COULDN'T SEE THE DECK BUT NO WATER WAS DRIPPING THOUGH
Sub Deck	Fair	
Ties	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	3.0
	Estimated High Water Level Clearance:	3.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Medium	\$ 250.00	INSTALL BRIDGE AHEAD AND LOAD RATING SIGNS

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 755 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-100	Structure Name:	G5-100	Road Name:	DREAM	Inspection Date:	2019/10/14
GENERAL	Inspector's Comment:	NO BRIDGE AHEAD SIGNS, NO RIP RAP, FROZEN SNOW AND DIRT SO I COULDN'T SEE THE DECK BUT NO WATER WAS DRIPPING THOUGH					
GENERAL	PEng's Comment:	Bridge deck will need replacing soon					
GENERAL	Estimated Load Restriction (year):		2031	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/01/27 12:37:19	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 756 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-102	Structure Name:	G5-102	Road Name:	DREAM	Inspection Date:	2019/10/14
KM:	16.20	User km:	16.20	Crossing Name:	Kenny Creek	Next Inspection Date:	2022/10/14
Project File ID #:	7785	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Sill - Permanent Materials	
Superstructure:	Steel I-beam				Right	Sill - Permanent Materials	
Total Length (metres):	20.0	# Spans:	1	Span Width:			Span Length(s) (metres): 20
UTM Zone:	10	UTM Easting:	344936	UTM Northing:	6171118		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1991		
Access:							

ABUTMENTS

Bearings	Not Applicable
Bracing	Not Applicable
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Not Applicable
Piles or Posts	Not Applicable
Riprap	Fair
Wing Wall	Not Applicable

APPROACHES

Alignment	Fair	NEED SIGNS TO SLOW TRAFFIC DOWN
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Poor	OUT OF POSITION
Road Surface	Fair	

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 757 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-102	Structure Name:	G5-102	Road Name:	DREAM	Inspection Date:	2019/10/14
---------	--------	-----------------	--------	------------	-------	------------------	------------

Span 1

Curb Rail/Blocks/Posts	Fair	
Deck to Girder Bolts	Not Applicable	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Nails	Unrated	DECK WAS COVERED IN FROZEN DIRT AND SNOW SO COULD NOT SEE IF WELL
Overall Deck Condition	Fair	DECK WAS COVERED IN FROZEN DIRT AND SNOW SO COULD NOT SEE IF WELL
Running Planks	Unrated	DECK WAS COVERED IN FROZEN DIRT AND SNOW SO COULD NOT SEE IF WELL
Sub Deck	Fair	
Ties	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	16.0
	Estimated High Water Level Clearance:	3.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Medium	\$	INSTALL FENDERS
	2	Required	Medium	\$ 750.00	INSTALL BRIDGE AHEAD, LOAD RATING AND DELINEATORS

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 758 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-102	Structure Name:	G5-102	Road Name:	DREAM	Inspection Date:	2019/10/14
MONITORS	#	Description					
	1	MONITOR GUARD RAIL ROT					
GENERAL	Inspector's Comment:	DECK WAS COVERED IN FROZEN DIRT AND SNOW SO COULD NOT SEE IF WELL, HOWEVER IT APPEARS TO BE SOUND NOTHING DRIPPING THROUGH, NO SIGNS DELINEATORS, ROTTEN GUARD RAILS, FENDERS POOR					
GENERAL	PEng's Comment:	deck replacement will need to be done soon.					
GENERAL	Estimated Load Restriction (year):		2031	Estimated Replacement (year):			
	Current Inspection Load Rating:		54	Design Load GVW (tonnes):		54	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/01/24 15:52:48	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 759 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-130	Structure Name:	G5-130	Road Name:	OMINECA	Inspection Date:	2021/09/15
KM:	2.80	User km:	2.80	Crossing Name:	Beaverpond Creek	Next Inspection Date:	2024/09/15
Project File ID #:	7785	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Glulam Girder				Right	Pile -Permanent Materials	
Total Length (metres):	11.0	# Spans:	1	Span Width:			Span Length(s) (metres): 11
UTM Zone:	10		UTM Easting:	326838	UTM Northing:	6181858	
Inspector Name:	Vince Sewell			Year Superstructure Installed:	1980		
Access:	Access is at kilometer 223 off Fall FSR.						

ABUTMENTS

Bearings	Not Applicable	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Fair	Center 3 posts on left side cracked
Riprap	Good	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	End of LC DS fender broken
Posted Load Rating (Enter 0 if sign missing)	30	
Road Surface	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 760 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-130	Structure Name:	G5-130	Road Name:	OMINECA	Inspection Date:	2021/09/15
---------	--------	-----------------	--------	------------	---------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Fair	Good except running deck
Running Planks	Poor	Rot
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.3	Estimated Present Water Level Width:	4.0
Estimated High Water Level Clearance:	2.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
9	Required	High		Replace running deck surface before industrial use.
10	Required	Medium		Install bridge ahead signs.
11	Required	Medium		Brush out both approaches.

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 761 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-130	Structure Name:	G5-130	Road Name:	OMINECA	Inspection Date:	2021/09/15
MONITORS	#	Description					
GENERAL	Inspector's Comment:	Bridge difficult to inspect, very high and hard to see. Glulam and everything except running deck is covered in creosote. Professional inspection prior to industrial use due to age.					
GENERAL	PEng's Comment:	Running deck needs replacing before industrial use. BH					
GENERAL	Estimated Load Restriction (year):		2025	Estimated Replacement (year):			
	Current Inspection Load Rating:		30	Design Load GVW (tonnes):		134	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/01/24 13:14:41	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 762 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-010	Structure Name:	G5-010	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/04
KM:	6.40	User km:	6.40	Crossing Name:	Keve Creek	Next Inspection Date:	2022/10/04
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Pipe Arch			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	2,000			Outlet Cover (mm):	2,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	22.0	Opening Height (mm):	2,000	Opening Width (mm):	4,000		
UTM Zone:	10	UTM Easting:	359575	UTM Northing:	6116574		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1988		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Good	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Fair	SHOWING RUST ON BOTTOM & SIDES
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	SHOWS SOME RUST
Footing	Not Applicable	
Head Wall	Good	
Inlet	Fair	
Outlet	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 763 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-010	Structure Name:	G5-010	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/04			
Overall	Fair									
Riprap	Fair	ARMOUR								
Roof	Fair	SOME DENTS FROM RIP RAP								
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.3		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	PIPE SHOWING RUST ON BOTTOM/SIDES								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):		2028		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/01/24 15:28:55			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 764 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-011	Structure Name:	G5-011	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/04
KM:	14.30	User km:	14.30	Crossing Name:	Purvis Creek	Next Inspection Date:	2022/10/04
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Pipe Arch			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	4,000			Outlet Cover (mm):	4,000		
Footing Type:				Gradient (%):	1.0		
Culvert Length (metres):	34.0	Opening Height (mm):	3,426	Opening Width (mm):	4,626		
UTM Zone:	10	UTM Easting:	355058	UTM Northing:	6122847		
Inspector Name:	Dawson SMITH		Year Superstructure Installed:		1991		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Fair	LOGS ON MOUTH OF PIPE
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 765 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-011	Structure Name:	G5-011	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/04			
Overall	Good									
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	3.0						
	Estimated High Water Level Clearance:	1.5								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	LOGS ON INLET								
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Medium	\$ 250.00	REMOVE LOGS ON INLET SIDE					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	ALL GOOD, SOME LOG DEBRIS ON INLET SIDE								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):	2039	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/24 15:33:41						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 766 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-034	Structure Name:	G5-034	Road Name:	DRIFTWOOD	Inspection Date:	2010/08/18
KM:	23.20	User km:	23.20	Crossing Name:	Unnamed creek	Next Inspection Date:	2030/08/01
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	4,000			Outlet Cover (mm):	4,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	36.0	Opening Height (mm):	1,000	Opening Width (mm):	1,000		
UTM Zone:	10	UTM Easting:	352405	UTM Northing:	6130298		
Inspector Name:	Susan Forshner			Year Superstructure Installed:	1991		
Access:	Minor culvert						

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coating	Good	
Fill	Good	
Floor	Good	Rust
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Fair	perched x 2
Overall	Good	
Riprap	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 767 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-034	Structure Name:	G5-034	Road Name:	DRIFTWOOD	Inspection Date:	2010/08/18			
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	0.7						
	Estimated High Water Level Clearance:	0.6								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Monitor outlets, both perched								
GENERAL	Inspector's Comment:	both outlets are perched - monitor								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):	2030	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Accepted By IDIR\RMGETZLA on 2012/04/10 09:32:35						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 768 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-013	Structure Name:	G5-013	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
KM:	23.40	User km:	23.40	Crossing Name:	Brule Creek	Next Inspection Date:	2022/10/13
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Elliptical			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	3,000			Outlet Cover (mm):	3,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	26.0	Opening Height (mm):	3,000	Opening Width (mm):	6,000		
UTM Zone:	10	UTM Easting:	352344	UTM Northing:	6130418		
Inspector Name:	Dawson SMITH		Year Superstructure Installed:		1991		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Good	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 769 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-013	Structure Name:	G5-013	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13			
Overall	Good									
Riprap	Fair									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	1.5						
	Estimated High Water Level Clearance:	1.5								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	GOOD..								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):	2031	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/24 15:26:55						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 770 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-014	Structure Name:	G5-014	Road Name:	DRIFTWOOD	Inspection Date:	2021/07/20
KM:	36.00	User km:	36.00	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/09/19
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Elliptical			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	350			Outlet Cover (mm):	350		
Footing Type:				Gradient (%):			
Culvert Length (metres):	26.0	Opening Height (mm):	2,540	Opening Width (mm):	4,140		
UTM Zone:	10	UTM Easting:	342912	UTM Northing:	6138856		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1992		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 771 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-014	Structure Name:	G5-014	Road Name:	DRIFTWOOD	Inspection Date:	2021/07/20			
Inlet	Good									
Outlet	Good									
Overall	Good									
Riprap	Not Applicable									
Roof	Fair									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:		0.1					
	Estimated High Water Level Clearance:	1.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Wrong site inspected								
GENERAL	PEng's Comment:									

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 772 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-014	Structure Name:	G5-014	Road Name:	DRIFTWOOD	Inspection Date:	2021/07/20
GENERAL	Estimated Load Restriction (year):		2032	Estimated Replacement (year):			
	Current Inspection Load Rating:		See footnote	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status: Rejected By IDIR\GZSOMBOR on 2021/12/02 14:42:33			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 773 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-015	Structure Name:	G5-015	Road Name:	DRIFTWOOD	Inspection Date:	2021/07/09
KM:	37.40	User km:	37.40	Crossing Name:	Andrea Creek	Next Inspection Date:	2024/07/09
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	21.0	# Spans:	1	Span Width:	Span Length(s) (metres):		21
UTM Zone:	10	UTM Easting:	341753	UTM Northing:	6139454		
Inspector Name:	Dawson Smith		Year Superstructure Installed:	1995			
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	log fenders, some missing
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 774 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-015	Structure Name:	G5-015	Road Name:	DRIFTWOOD	Inspection Date:	2021/07/09
---------	--------	-----------------	--------	------------	-----------	------------------	------------

DECK

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Not Applicable
---------------	----------------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	3.0
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	4.0
---------------------------------------	-----

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
6	Required	Medium	\$	Install missing fenders

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 775 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-015	Structure Name:	G5-015	Road Name:	DRIFTWOOD	Inspection Date:	2021/07/09
GENERAL	Inspector's Comment:	Approach fenders an issue. Removed BA signs and LL signs from repairs. GZ					
GENERAL	PEng's Comment:	No major issues. BH					
GENERAL	Estimated Load Restriction (year):		2035	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/01/20 14:34:54			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 776 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-035	Structure Name:	G5-035	Road Name:	DRIFTWOOD	Inspection Date:	2021/08/31
KM:	49.80	User km:	49.80	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/08/31
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	6,000			Outlet Cover (mm):	9,000		
Footing Type:				Gradient (%):	12.0		
Culvert Length (metres):	24.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	334555	UTM Northing:	6148157		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1990		
Access:							

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Unrated	NA
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Fair	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Fair	
Overall	Fair	CMP squashed from poor install but stable

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 777 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-035	Structure Name:	G5-035	Road Name:	DRIFTWOOD	Inspection Date:	2021/08/31			
Riprap	Good									
Roof	Fair									
Side Walls	Fair									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	0.5						
	Estimated High Water Level Clearance:	0.4								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	4	Required	Low		Culvert is stable. Replacement not required until road upgrade occurs.					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	5m x 1400 mm extension added to outlet @ 2% grade. Poor install.No urgency to replace. Install new CMP when upgrading road section								
GENERAL	PEng's Comment:	Replace during road upgrades. BH								
GENERAL	Estimated Load Restriction (year):	2030	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/01/24 11:33:41						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 778 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-036	Structure Name:	G5-036	Road Name:	DRIFTWOOD	Inspection Date:	2021/08/31
KM:	51.60	User km:	51.60	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/08/31
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	900			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):	4.0		
Culvert Length (metres):	19.0	Opening Height (mm):	1,500	Opening Width (mm):	1,500		
UTM Zone:	10	UTM Easting:	332888	UTM Northing:	6148699		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1990		
Access:	Minor culvert						

APPROACHES

Alignment	Good
-----------	------

Bridge Ahead Signs Missing	0
----------------------------	---

Brushing Required	No
-------------------	----

Delineator Missing Left (approaching structure)	0
--	---

Delineator Missing Right (approaching structure)	0
---	---

Fender Condition	None
------------------	------

Road Surface	Good
--------------	------

CULVERT ELEMENT

Baffles	Not Applicable
---------	----------------

Bolted Connections	Not Applicable
--------------------	----------------

Coupled Connections	Good
---------------------	------

Coating	Good
---------	------

Embedment Materials	Not Applicable
---------------------	----------------

Fill	Good
------	------

Floor	Good
-------	------

Head Wall	Not Applicable
-----------	----------------

Inlet	Good
-------	------

Outlet	Fair	0.6m plunge pool
--------	------	------------------

Overall	Good
---------	------

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 779 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-036	Structure Name:	G5-036	Road Name:	DRIFTWOOD	Inspection Date:	2021/08/31			
Riprap	Good									
Roof	Good									
Side Walls	Fair									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:		4.0					
	Estimated High Water Level Clearance:	0.6								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Replace with 9m slab bridge with future road upgrade								
GENERAL	PEng's Comment:	Consider replacement during road upgrades. BH								
GENERAL	Estimated Load Restriction (year):	2030		Estimated Replacement (year):						
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):		91	Design Vehicle Config.:				
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/01/24 12:52:34						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 780 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-016	Structure Name:	G5-016	Road Name:	DRIFTWOOD	Inspection Date:	2020/08/06
KM:	53.60	User km:	53.00	Crossing Name:	Unnamed creek	Next Inspection Date:	2023/08/06
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	500			Outlet Cover (mm):	1,300		
Footing Type:				Gradient (%):	9.0		
Culvert Length (metres):	21.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	331258	UTM Northing:	6149046		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1990		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Poor	compresion of roof
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	1m
Floor	Poor	rust
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Fair	
Outlet	Poor	purchd, aggtigation has reated large hole

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 781 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-016	Structure Name:	G5-016	Road Name:	DRIFTWOOD	Inspection Date:	2020/08/06			
Overall	Poor	as per other elements								
Riprap	Poor	at inlet								
Roof	Poor	deformation of roof								
Side Walls	Poor	deformation of sides								
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.3		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	Yes
	Comment:	has created deep hole at outlet								
REPAIRS	#	Status	Priority	Estimate	Description					
	6	Required	Medium	\$	replace					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Will look at this culvert this year and determine if it needs replacing								
GENERAL	Estimated Load Restriction (year):			2030		Estimated Replacement (year):				
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2021/02/22 13:21:39			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 782 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-017	Structure Name:	G5-017	Road Name:	DRIFTWOOD	Inspection Date:	2020/08/06
KM:	54.20	User km:	54.20	Crossing Name:	Unnamed creek	Next Inspection Date:	2023/08/06
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	24.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	330379	UTM Northing:	6149328		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1990		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	1m
Floor	Fair	Rust
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 783 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-017	Structure Name:	G5-017	Road Name:	DRIFTWOOD	Inspection Date:	2020/08/06
Inlet	Good	log jammed in at inlet					
Outlet	Fair						
Overall	Good						
Riprap	Good						
Roof	Good						
Side Walls	Good	no changes in deformations					
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						

CHANNEL	Estimated Present Water Level Depth:		0.3		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	Yes
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	looks ok								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 784 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-017	Structure Name:	G5-017	Road Name:	DRIFTWOOD	Inspection Date:	2020/08/06
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/02/18 13:47:39	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 785 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-017	Structure Name:	G5-017-2	Road Name:	DRIFTWOOD	Inspection Date:	2020/08/06
KM:	54.20	User km:	54.20	Crossing Name:	Unnamed creek	Next Inspection Date:	2023/08/06
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	18.0	Opening Height (mm):	1,000	Opening Width (mm):	1,000		
UTM Zone:	10	UTM Easting:	330379	UTM Northing:	6149328		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1990		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	1m
Floor	Fair	Rust
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 786 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-017	Structure Name:	G5-017-2	Road Name:	DRIFTWOOD	Inspection Date:	2020/08/06			
Inlet	Good									
Outlet	Fair									
Overall	Good									
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.0		Estimated Present Water Level Width:		0.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	overflow\high water culvert. see culver 1 for photos								
GENERAL	PEng's Comment:									

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 787 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-017	Structure Name:	G5-017-2	Road Name:	DRIFTWOOD	Inspection Date:	2020/08/06
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/02/18 13:50:09	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 788 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-040	Structure Name:	G5-040	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
KM:	59.70	User km:	59.70	Crossing Name:	Nation River	Next Inspection Date:	2022/10/13
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	16.0	# Spans:	1	Span Width:			Span Length(s) (metres): 16
UTM Zone:	10		UTM Easting:	326106		UTM Northing:	6151745
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1999		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Fair	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 789 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-040	Structure Name:	G5-040	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
---------	--------	-----------------	--------	------------	-----------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Good	
Deck Joints	Good	
Grout Pockets	Unrated	COULD NOT SEE DUE TO FROZEN MUD/SNOW
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	4.0
	Estimated High Water Level Clearance:	3.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 790 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-040	Structure Name:	G5-040	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
GENERAL	Inspector's Comment:	GOOD, COULD NOT SEE GROUT POCKETS DUE TO FROZEN MUD AND SNOW					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2049	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/21 14:04:48			

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 791 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-041	Structure Name:	G5-041	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
KM:	62.10	User km:	61.10	Crossing Name:	Un-named	Next Inspection Date:	2022/10/13
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	700			Outlet Cover (mm):	1,100		
Footing Type:	Steel Footing			Gradient (%):	3.9		
Culvert Length (metres):	15.2	Opening Height (mm):	1,524	Opening Width (mm):	3,048		
UTM Zone:	10	UTM Easting:	324059	UTM Northing:	6151805		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2012		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Good	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 792 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-041	Structure Name:	G5-041	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13	
Overall	Good							
Riprap	Not Applicable							
Roof	Good							
Side Walls	Good							
Trash Rack	Not Applicable							
Wiers/Backwater Structures	Not Applicable							
Wing Wall	Not Applicable							
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		2.0	
	Estimated High Water Level Clearance:		2.5					
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Aggradation: No	
	Comment:							
REPAIRS	#	Status	Priority	Estimate	Description			
MONITORS	#	Description						
GENERAL	Inspector's Comment:	GOOD						
GENERAL	PEng's Comment:							
GENERAL	Estimated Load Restriction (year):			2047	Estimated Replacement (year):			2047
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/21 14:07:34				

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 793 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-020	Structure Name:	G5-020	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/14
KM:	67.50	User km:	64.70	Crossing Name:	MacLaing Creek	Next Inspection Date:	2022/10/14
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	15.0	Opening Height (mm):	2,000	Opening Width (mm):	2,000		
UTM Zone:	10	UTM Easting:	320655	UTM Northing:	6153181		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1987		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	BIT RUSTY
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 794 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-020	Structure Name:	G5-020	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/14
Overall	Good						
Riprap	Not Applicable						
Roof	Good						
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		1.0
	Estimated High Water Level Clearance:		1.5				
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Aggradation: No
	Comment:						
REPAIRS	#	Status	Priority	Estimate	Description		
	1	Not Required	Medium	\$ 250.00	BRUSH		
MONITORS	#	Description					
GENERAL	Inspector's Comment:	CULVERTS ARE WORKING FINE, COULD BE BRUSHED OUT					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):			2027	Estimated Replacement (year):		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status: Reviewed By Jason Olmsted on 2020/02/21 14:10:17			

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 795 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-020	Structure Name:	G5-020-2	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/14
KM:	67.50	User km:	64.70	Crossing Name:	MacLaing Creek	Next Inspection Date:	2022/10/14
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	15.0	Opening Height (mm):	2,000	Opening Width (mm):	2,000		
UTM Zone:	10	UTM Easting:	320655	UTM Northing:	6153181		
Inspector Name:	Dawson SMITH		Year Superstructure Installed:		1987		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	SHOWING SOME RUST
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 796 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-020	Structure Name:	G5-020-2	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/14			
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	1.0						
	Estimated High Water Level Clearance:	1.5								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Not Required	Medium	\$ 250.00	BRUSH BOTH SIDES					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	CULVERT IS IN GOOD SHAPE, SITE COULD BE BRUSHED OUT								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):	2027	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/21 14:11:32						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 797 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-021	Structure Name:	G5-021	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/14
KM:	75.90	User km:	76.20	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/10/14
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	25.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	313001	UTM Northing:	6158085		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1979		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	FLOOR SHOWS A BIT OF RUST
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	FLOOR SHOWS A BIT OF RUST
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 798 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-021	Structure Name:	G5-021	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/14			
Overall	Fair	FLOOR SHOWS A BIT OF RUST								
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Not Required	Medium	\$ 250.00	NEEDS BRUSHED					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	GOOD								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):			2029		Estimated Replacement (year):				
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/02/21 14:31:00			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 799 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-021	Structure Name:	G5-021-2	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/14
KM:	75.90	User km:	76.20	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/10/14
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	25.0	Opening Height (mm):	1,500	Opening Width (mm):	1,500		
UTM Zone:	10	UTM Easting:	313001	UTM Northing:	6158085		
Inspector Name:	Dawson SMITH		Year Superstructure Installed:		1979		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 800 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-021	Structure Name:	G5-021-2	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/14			
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		0.2			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Low	\$ 250.00	NEEDS BRUSHING					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	WORKING GOOD								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):			2029	Estimated Replacement (year):					
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/03/09 09:33:03				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 801 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-022	Structure Name:	G5-022	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
KM:	77.10	User km:	78.70	Crossing Name:	Bernie Creek	Next Inspection Date:	2022/10/13
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	15.0	# Spans:	1	Span Width:	Span Length(s) (metres):		15
UTM Zone:	10	UTM Easting:	312866	UTM Northing:	6159322		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1996		
Access:							

ABUTMENTS

Bearings	Good
Bracing	Not Applicable
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Good
Piles or Posts	Good
Riprap	Good
Wing Wall	Good

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	TIMBER FENDERS
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 802 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-022	Structure Name:	G5-022	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
---------	--------	-----------------	--------	------------	-----------	------------------	------------

DECK

Span 1

Concrete Deck	Unrated	THE DECK WAS FROZEN SO COULD NOT SEE POCKETS OR JOINTS
Curb Rail/Blocks/Posts	Good	
Deck Joints	Unrated	THE DECK WAS FROZEN SO COULD NOT SEE POCKETS OR JOINTS
Grout Pockets	Unrated	THE DECK WAS FROZEN SO COULD NOT SEE POCKETS OR JOINTS
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	3.0
Estimated High Water Level Clearance:	3.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description

MONITORS

#	Description

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 803 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-022	Structure Name:	G5-022	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13	
GENERAL	Inspector's Comment:	BRIDGE IS IN GOOD CONDITION, THE DECK WAS FROZEN SO COULD NOT SEE POCKETS OR JOINTS BUT NO WATER WAS DRIPPING THROUGH, NEW GUARD RAILS						
GENERAL	PEng's Comment:							
GENERAL	Estimated Load Restriction (year):		2036	Estimated Replacement (year):		2036		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/03/02 13:46:40		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 804 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-023	Structure Name:	G5-023	Road Name:	DRIFTWOOD	Inspection Date:	2021/07/20
KM:	82.80	User km:	80.80	Crossing Name:	Hudson Bay Creek	Next Inspection Date:	2022/09/01
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	15.7	# Spans:	1	Span Width:			Span Length(s) (metres): 15.7
UTM Zone:	10	UTM Easting:	313194	UTM Northing:	6163376		
Inspector Name:	Dawson Smith		Year Superstructure Installed:	2001			
Access:	82.8 Km Driftwood FSR Bridge has been rebuilt in 2001.						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Fender Condition	Fair	some out of place
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

DECK

Span 1

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 805 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-023	Structure Name:	G5-023	Road Name:	DRIFTWOOD	Inspection Date:	2021/07/20			
Concrete Deck	Good									
Curb Rail/Blocks/Posts	Fair	showing decay								
Deck Joints	Good									
Grout Pockets	Not Applicable									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Overall Deck Condition	Good									
Running Surface	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		3.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	5	Suggested	Medium	\$ 250.00						
	7	Suggested	High	\$						
	8	Suggested	High	\$						
MONITORS	#	Description								
	6	Monitor rot in guardrails and riser blocks								

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 806 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-023	Structure Name:	G5-023	Road Name:	DRIFTWOOD	Inspection Date:	2021/07/20
GENERAL	Inspector's Comment:	No up/down stream pics, did not rate grout pockets, rail & riser rot not clearly identified.					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2051	Estimated Replacement (year):			
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Rejected By IDIR\GZSOMBOR on 2021/12/02 15:16:42			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 807 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-024	Structure Name:	G5-024A	Road Name:	DRIFTWOOD	Inspection Date:	2020/09/03
KM:	92.80	User km:	92.80	Crossing Name:	Teegee Creek #1	Next Inspection Date:	2022/09/03
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Steel I-beam				Right	Sill -Temporary Materials	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	9		UTM Easting:	495980		UTM Northing:	6163555
Inspector Name:	Bruce Henderson			Year Superstructure Installed:	2019		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Fair	Erosion and loss of material on low chain downstream ballast wall. Fabric not properly installed and approach fill not compacted properly.
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	Minor settlement of hemlock sill logs.
Fill	Fair	Losing fill on low chain side
General Abutment Condition	Fair	Neds repair and additional rip rap to protect abutment slopes.
Hardware	Good	At least 2 deck clips are loose. (high chain)
Piles or Posts	Not Applicable	
Riprap	Fair	Rip Rap is slightly smaller than required and not placed well.
Wing Wall	Not Applicable	

APPROACHES

Alignment	Poor	Blind corners on both approaches.
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	Brushing will improve SSD and improve visibility.
Delineator Missing Left (approaching structure)	1	Both low chain delinators misssing or damagerd
Delineator Missing Right (approaching structure)	1	
Fender Condition	Fair	No post concrete barriers need bull noses installed and one no post chipped and missing concrete

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 808 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-024	Structure Name:	G5-024A	Road Name:	DRIFTWOOD	Inspection Date:	2020/09/03			
Posted Load Rating (Enter 0 if sign missing)	91	Signs required								
Road Surface	Good									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Fair	Couple loose deck clips ion high chain side.								
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Good	4 deck modules - 12m span								
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		5.5			
	Estimated High Water Level Clearance:		3.0							
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 809 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-024	Structure Name:	G5-024A	Road Name:	DRIFTWOOD	Inspection Date:	2020/09/03
REPAIRS	#	Status	Priority	Estimate	Description		
	1	Required	Medium	\$ 100.00	Install delineators on low chain side.		
	2	Required	Medium	\$ 100.00	Repair approach fill and to prevent erosion behind ballast wall low chain side.		
	3	Required	Medium	\$ 100.00	Install reduce speed signs (30km max) both approaches		
MONITORS	#	Description					
	1	Monitor settling of sill logs.					
GENERAL	Inspector's Comment:	Structure was installed in 2019 and structurally is in good condition. The approaches and road alignment are poor and have sharp curves entering the bridge. Low chain side is a blind curve and reduce speed signs should be installed. Some erosion of road fill near ballast wall may introduce sediment into stream. Sill log placed over improperly compacted leveling course. Minor settlement observed and should be checked at next inspection.					
GENERAL	PEng's Comment:	Will look at this bridge again this summer to determine if there are any issues.					
GENERAL	Estimated Load Restriction (year):			2030	Estimated Replacement (year):		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		Design Vehicle Config.:	L100
	Professional Inspection Required?		Yes	Report Status:		Reviewed By Jason Olmsted on 2021/02/25 15:33:34	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 810 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-025	Structure Name:	G5-025	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
KM:	99.80	User km:	99.80	Crossing Name:	French Creek	Next Inspection Date:	2022/10/13
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	24.4	# Spans:	1	Span Width:	Span Length(s) (metres):		24.4
UTM Zone:	9	UTM Easting:	491982	UTM Northing:	6169310		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2003		
Access:							

ABUTMENTS

Bearings	Good
----------	------

Bracing	Not Applicable
---------	----------------

Ballast Wall	Good
--------------	------

Corrosion Protection	Not Applicable
----------------------	----------------

Caps or Sills	Good
---------------	------

Fill	Good
------	------

Hardware	Not Applicable
----------	----------------

Piles or Posts	Good
----------------	------

Riprap	Good
--------	------

Wing Wall	Good
-----------	------

APPROACHES

Alignment	Good
-----------	------

Bridge Ahead Signs Missing	0
----------------------------	---

Brushing Required	No
-------------------	----

Delineator Missing Left (approaching structure)	0
---	---

Delineator Missing Right (approaching structure)	0
--	---

Fender Condition	Fair
------------------	------

Posted Load Rating (Enter 0 if sign missing)	91
--	----

Road Surface	Good
--------------	------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 811 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-025	Structure Name:	G5-025	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
---------	--------	-----------------	--------	------------	-----------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Excellent	
Deck Joints	Good	WHAT I COULD SEE WAS GOOD
Grout Pockets	Unrated	COULD NOT INSPECT GROUT POCKETS DUE TO FROZEN DIRT/ICE
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	3.0
	Estimated High Water Level Clearance:	4.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 812 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-025	Structure Name:	G5-025	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
GENERAL	Inspector's Comment:	COULD NOT INSPECT GROUT POCKETS DUE TO FROZEN DIRT/ICE, RECENTLY REPLACED GUARD RAILS					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2053	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/03/02 13:49:06			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 813 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-026	Structure Name:	G5-026	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
KM:	106.50	User km:	106.50	Crossing Name:	Sitlika Creek	Next Inspection Date:	2022/10/13
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	15.0	# Spans:	1	Span Width:	Span Length(s) (metres):		15
UTM Zone:	9	UTM Easting:	676884	UTM Northing:	6178411		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1996		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Fair	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	MISSING 1 FENDER
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 814 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-026	Structure Name:	G5-026	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
---------	--------	-----------------	--------	------------	-----------	------------------	------------

DECK

Span 1

Concrete Deck	Fair	STAINING UNDERNEATH INDICATES WATER DRIPPING THROUGH
Curb Rail/Blocks/Posts	Good	
Deck Joints	Fair	STAINING UNDERNEATH INDICATES WATER DRIPPING THROUGH
Grout Pockets	Unrated	COULDN'T INSPECT DUE TO FROZEN MUD
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	STAINING UNDERNEATH INDICATES WATER DRIPPING THROUGH

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	3.0
Estimated High Water Level Clearance:	4.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 815 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-026	Structure Name:	G5-026	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13	
GENERAL	Inspector's Comment:	NEW GUARD RAILS, DECK WAS PARTIALLY FROZEN SO COULD SEE ALL THE POCKETS OR JOINTS , THERE IS STAINING ON UNDERSIDE INDICATING WATER SEEPING THROUGH						
GENERAL	PEng's Comment:							
GENERAL	Estimated Load Restriction (year):		2036	Estimated Replacement (year):		2036		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/03/02 13:52:30		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 816 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-027	Structure Name:	G5-027	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
KM:	109.70	User km:	109.70	Crossing Name:	Bates Creek	Next Inspection Date:	2022/10/13
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	18.0	# Spans:	1	Span Width:	Span Length(s) (metres):		18
UTM Zone:	9	UTM Easting:	673953	UTM Northing:	6179658		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1995		
Access:							

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	WOOD FENDERS SHOWING ROT
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 817 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-027 Structure Name: G5-027 Road Name: DRIFTWOOD Inspection Date: 2019/10/13

DECK

Span 1

Concrete Deck	Unrated	COULD NOT SEE POCKETS OR ALL THE DECK JOINT DUE TO FROZEN MUD
Curb Rail/Blocks/Posts	Good	
Deck Joints	Unrated	COULD NOT SEE POCKETS OR ALL THE DECK JOINT DUE TO FROZEN MUD
Grout Pockets	Unrated	COULD NOT SEE POCKETS OR ALL THE DECK JOINT DUE TO FROZEN MUD
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	COULD NOT SEE POCKETS OR ALL THE DECK JOINT DUE TO FROZEN MUD

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:		Estimated Present Water Level Width:	3.0
Estimated High Water Level Clearance:	4.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description

MONITORS

#	Description

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 818 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-027	Structure Name:	G5-027	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
GENERAL	Inspector's Comment:	ALL GOOD, COULD NOT SEE POCKETS OR ALL THE DECK JOINT DUE TO FROZEN MUD HOWEVER THERE IS SOME STAINING ON UNDERSIDE INDICATING LEAKS, NEW GUARD RAILS					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2035	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/03/02 13:56:55			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 819 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-045	Structure Name:	G5-045	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
KM:	118.50	User km:	118.50	Crossing Name:	Lion Creek	Next Inspection Date:	2022/10/13
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	70.4	# Spans:	2	Span Width:			Span Length(s) (metres): 35.2, 35.2
UTM Zone:	9		UTM Easting:	666687		UTM Northing:	6184285
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1999		
Access:	2 WDr 118.5 Driftwood FSR						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 820 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-045	Structure Name:	G5-045	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
---------	--------	-----------------	--------	------------	-----------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	SOME NEED TO BE REPLACED
Deck Joints	Fair	
Grout Pockets	Good	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	1.5	Estimated Present Water Level Width:	7.0
	Estimated High Water Level Clearance:	5.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Medium	\$	REPLACE ROTTEN GUARD RAILS

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 821 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-045	Structure Name:	G5-045	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
GENERAL	Inspector's Comment:	SOME OF THE GUARD RAILS ARE DAMAGED AND SHOULD BE REPLACED					
GENERAL	PEng's Comment:	Bridge curbs need replacing and deck joints need repaired. If these are not completed soon the bridge could be down-rated.					
GENERAL	Estimated Load Restriction (year):		2049	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/03/09 09:10:57			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 822 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-033	Structure Name:	G5-033	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
KM:	140.50	User km:	132.00	Crossing Name:	Driftwood River #3	Next Inspection Date:	2022/10/13
Project File ID #:	7822	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	48.0	# Spans:	3	Span Width:	Span Length(s) (metres):		16, 16, 16
UTM Zone:	9	UTM Easting:	469970	UTM Northing:	6191224		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1993		
Access:							

ABUTMENTS

Bearings	Fair
----------	------

Bracing	Not Applicable
---------	----------------

Ballast Wall	Good
--------------	------

Corrosion Protection	Not Applicable
----------------------	----------------

Caps or Sills	Good
---------------	------

Fill	Good
------	------

Hardware	Not Applicable
----------	----------------

Piles or Posts	Good
----------------	------

Riprap	Good
--------	------

Wing Wall	Good
-----------	------

APPROACHES

Alignment	Good
-----------	------

Bridge Ahead Signs Missing	2
----------------------------	---

Brushing Required	No
-------------------	----

Delineator Missing Left (approaching structure)	0
---	---

Delineator Missing Right (approaching structure)	0
--	---

Fender Condition	Poor	LOG FENDERS ROTTEN
------------------	------	--------------------

Road Surface	Fair
--------------	------

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 823 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-033	Structure Name:	G5-033	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
---------	--------	-----------------	--------	------------	-----------	------------------	------------

Span 1

Concrete Deck	Fair	
Curb Rail/Blocks/Posts	Fair	
Deck Joints	Fair	NEEDS GROUT
Grout Pockets	Fair	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	NEEDS GUARD RAILS AND GROUT
Running Surface	Fair	

PIERS

Pier 1

Bearings	Fair	
Bracing or Sheathing	Good	
Caps	Good	
Cribs	Good	
Dolphins	Not Applicable	
Hardware	Not Applicable	
Overall	Fair	
Piles or Posts	Good	
Riprap	Not Applicable	
Wall	Not Applicable	

Pier 2

Bearings	Fair	
Bracing or Sheathing	Good	
Caps	Good	
Cribs	Good	
Dolphins	Not Applicable	
Hardware	Not Applicable	
Overall	Fair	
Piles or Posts	Good	
Riprap	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 824 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-033	Structure Name:	G5-033	Road Name:	DRIFTWOOD	Inspection Date:	2019/10/13
---------	--------	-----------------	--------	------------	-----------	------------------	------------

Wall	Not Applicable
------	----------------

SUPERSTRUCTURE

Span 1

Bracing	Good
Diaphragms	Good
Girders	Good
Hardware	Not Applicable
Under Trussing	Not Applicable

Span 2

Bracing	Good
Diaphragms	Good
Girders	Good
Hardware	Not Applicable
Under Trussing	Not Applicable

Span 3

Bracing	Good
Diaphragms	Good
Girders	Good
Hardware	Not Applicable
Under Trussing	Not Applicable

CHANNEL	Estimated Present Water Level Depth:	2.0	Estimated Present Water Level Width:	10.0
	Estimated High Water Level Clearance:	7.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Medium	\$	GROUT DECK JOINTS
	2	Required	Medium	\$	REPLACE FENDERS
	3	Required	Medium	\$	REPLACE GUARD RAILS

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 825 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-033 Structure Name: G5-033 Road Name: DRIFTWOOD Inspection Date: 2019/10/13

MONITORS

Description

GENERAL

Inspector's Comment: GUARDRAILS AND FENDERS ROTTEN SHOULD BE REPLACED, GROUT POCKETS AND DECK JOINTS SHOULD BE REDONE, BEARINGS ARE FAIR

GENERAL

PEng's Comment:

GENERAL

Estimated Load Restriction (year): 2033 Estimated Replacement (year):
Current Inspection Load Rating: 91 Design Load GVW (tonnes): 91 Design Vehicle Config.:
Professional Inspection Required? No Report Status: Reviewed By Jason Olmsted on 2020/03/06 15:36:16

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 826 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-050	Structure Name:	G5-050	Road Name:	ANKWILL	Inspection Date:	2019/10/13
KM:	0.10	User km:	6.50	Crossing Name:	Blackwater Creek	Next Inspection Date:	2022/10/13
Project File ID #:	7822	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	15.0	# Spans:	1	Span Width:	Span Length(s) (metres):		15
UTM Zone:	9	UTM Easting:	480998	UTM Northing:	6175020		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1994		
Access:							

ABUTMENTS

Bearings Good

Bracing Not Applicable

Ballast Wall Good

Corrosion Protection Not Applicable

Caps or Sills Good

Fill Good

Hardware Not Applicable

Piles or Posts Good

Riprap Good

Wing Wall Good

APPROACHES

Alignment Good

Bridge Ahead Signs Missing 2

Brushing Required No

Delineator Missing Left (approaching structure) 1

Delineator Missing Right (approaching structure) 0

Fender Condition Poor ROTTEN

Road Surface Good

DECK

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 827 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-050	Structure Name:	G5-050	Road Name:	ANKWILL	Inspection Date:	2019/10/13
---------	--------	-----------------	--------	------------	---------	------------------	------------

Span 1

Concrete Deck	Unrated	THE MUD/GRAVEL WAS FROZEN SO COULD NOT SEE
Curb Rail/Blocks/Posts	Poor	ROTTEN
Deck Joints	Unrated	THE MUD/GRAVEL WAS FROZEN SO COULD NOT SEE
Grout Pockets	Unrated	THE MUD/GRAVEL WAS FROZEN SO COULD NOT SEE
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	FAIR DIE TO GUARD RAILS
Running Surface	Unrated	THE MUD/GRAVEL WAS FROZEN SO COULD NOT SEE

SUPERSTRUCTURE

Span 1

Bracing	Good
Diaphragms	Good
Girders	Good
Hardware	Not Applicable
Under Trussing	Not Applicable

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	4.0
Estimated High Water Level Clearance:	3.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Medium	\$	REPLACE GUARD RAILS AND FENDERS

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 828 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-050	Structure Name:	G5-050	Road Name:	ANKWILL	Inspection Date:	2019/10/13
GENERAL	Inspector's Comment:	GUARD RAILS AND FENDERS ARE ROTTEN AND SHOULD BE REPLACED					
GENERAL	PEng's Comment:	Curbs need replacing ASAP. Bridge could be down-rated at anytime.					
GENERAL	Estimated Load Restriction (year):		2034		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:						
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/27 12:52:16			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 829 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-051	Structure Name:	G5-051	Road Name:	ANKWILL	Inspection Date:	2021/07/20
KM:	10.50	User km:	17.00	Crossing Name:	Ankwill Creek	Next Inspection Date:	2021/10/11
Project File ID #:	7822	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Glulam Girder				Right	Pile -Permanent Materials	
Total Length (metres):	21.0	# Spans:	1	Span Width:	Span Length(s) (metres):		21
UTM Zone:	9	UTM Easting:	487936	UTM Northing:	6168009		
Inspector Name:	Dawson Smith		Year Superstructure Installed:	1979			
Access:	Road washed out at 6 km. No access to bridge site in 2021.						

--

CHANNEL	Estimated Present Water Level Depth:		Estimated Present Water Level Width:	
	Estimated High Water Level Clearance:			

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

GENERAL	Inspector's Comment:	Ankwill road washed out at approx 6kms, can't access bridge site.

GENERAL	PEng's Comment:	
---------	-----------------	--

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 830 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-051	Structure Name:	G5-051	Road Name:	ANKWILL	Inspection Date:	2021/07/20
GENERAL	Estimated Load Restriction (year):		2024	Estimated Replacement (year):			
	Current Inspection Load Rating:		See footnote	Design Load GVW (tonnes):	91	Design Vehicle Config.:	
	Professional Inspection Required?	No	Report Status:	Rejected By IDIR\BHENDERS on 2022/01/24 12:43:45			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 831 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-028	Structure Name:	G5-028	Road Name:	SOUTH	Inspection Date:	2016/07/02
KM:	114.90	User km:	4.90	Crossing Name:	Unnamed creek	Next Inspection Date:	2016/07/02
Project File ID #:	7822	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	4,000			Outlet Cover (mm):	4,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	24.0	Opening Height (mm):	1,000	Opening Width (mm):	1,000		
UTM Zone:	9	UTM Easting:	482089	UTM Northing:	6176320		
Inspector Name:	Donovan J. A. Melin			Year Superstructure Installed:	1991		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	rusting
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	rusting
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 832 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-028	Structure Name:	G5-028	Road Name:	SOUTH	Inspection Date:	2016/07/02			
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		1.0		Estimated Present Water Level Width:		20.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	Blocked by beavers, but the pond is empty.								
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	High	\$ 600.00	Remove beaver dam.					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	The inlet is blocked by beavers still. Culvert is in fair condition - but not very functional due to the plugging.								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):			2031		Estimated Replacement (year):				
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2017/02/16 14:11:02			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 833 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-029	Structure Name:	G5-029	Road Name:	SOUTH	Inspection Date:	2021/09/21
KM:	6.30	User km:	6.30	Crossing Name:	Driftwood River #1	Next Inspection Date:	2024/09/21
Project File ID #:	7822	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	64.6	# Spans:	4	Span Width:	Span Length(s) (metres):		8.8, 18.4, 18.4, 19
UTM Zone:	9		UTM Easting:	669704	UTM Northing:	6178886	
Inspector Name:	Kody Pepper			Year Superstructure Installed:	1991		
Access:							

ABUTMENTS

Bearings	Fair	Both abutment bearings had a slight rotation towards the channel
Bracing	Fair	No issues noted
Ballast Wall	Fair	Right abutment was pressure treated timber and left abutment was creosote timber. Both abutment walls were good during sounding but was notably deflected towards the channel. The tie back piles on the right abutment wall were bearing against the abutment pile bracing and pile cap. Left abutment upstream abutment wall pile was split and deteriorating
Corrosion Protection	Not Applicable	N/A
Caps or Sills	Good	Only the right abutment has a cap beam. Left abutment girders bear directly on piles.
Fill	Fair	Movement in the ballast wall towards the channel on both abutments
Hardware	Not Applicable	N/A
Piles or Posts	Good	2 piles for the left and 4 for the right abutment
Riprap	Fair	Minor rip rap but in adequate condition
Wing Wall	Not Applicable	N/A

APPROACHES

Alignment	Fair	Steep approach on both sides
Bridge Ahead Signs Missing	2	Both approaches are missing bridge ahead sign
Brushing Required	Yes	Brushing required at both approaches
Delineator Missing Left (approaching structure)	0	Both still in place
Delineator Missing Right (approaching structure)	0	Both still in place
Fender Condition	Poor	Approach barrier logs are deteriorated and rotten. 0.95m gap to the bridge and logs are placed on grade.

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 834 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-029	Structure Name:	G5-029	Road Name:	SOUTH	Inspection Date:	2021/09/21
Posted Load Rating (Enter 0 if sign missing)	0	No load rating signs					
Road Surface	Poor	Grading required at both approaches					
DECK							
Span 1							
Curb Rail/Blocks/Posts	Poor	Curbs were poor during sounding. Drill samples were very soft with rot and moisture noted.					
Deck to Girder Bolts	Poor	Loose curb to tie bolts were noted					
Hardware	Not Applicable	N/A					
Hand Rails/Walkouts	Not Applicable	N/A					
Nails	Fair	No issues noted					
Overall Deck Condition	Poor	Replace entire wearing surface and curbs. Monitor subdeck and deck ties for deterioration.					
Running Planks	Poor	Wearing surface was noted to be breaking down and in poor condition. Drill samples contained rot and moisture.					
Sub Deck	Fair	Some soft sounding spots. Drill samples were dry with no rot					
Ties	Fair	Drill samples were good with no rot					
Span 2							
Curb Rail/Blocks/Posts	Poor	Curbs were poor during sounding. Drill samples were very soft with rot and moisture noted.					
Deck to Girder Bolts	Poor	Loose curb to tie bolts were noted					
Hardware	Not Applicable	N/A					
Hand Rails/Walkouts	Not Applicable	N/A					
Nails	Fair	No issues noted					
Overall Deck Condition	Poor	Replace entire wearing surface and curbs. Monitor subdeck and deck ties for deterioration.					
Running Planks	Poor	Wearing surface was noted to be breaking down and in poor condition. Drill samples contained rot and moisture.					
Sub Deck	Fair	Some soft sounding spots. Drill samples were dry with no rot					
Ties	Fair	Drill samples were good with no rot					
Span 3							
Curb Rail/Blocks/Posts	Poor	Curbs were poor during sounding. Drill samples were very soft with rot and moisture noted.					
Deck to Girder Bolts	Poor	Loose curb to tie bolts were noted					
Hardware	Not Applicable	N/A					
Hand Rails/Walkouts	Not Applicable	N/A					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 835 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-029	Structure Name:	G5-029	Road Name:	SOUTH	Inspection Date:	2021/09/21
Nails	Fair	No issues noted					
Overall Deck Condition	Poor	Replace entire wearing surface and curbs. Monitor subdeck and deck ties for deterioration.					
Running Planks	Poor	Wearing surface was noted to be breaking down and in poor condition. Drill samples contained rot and moisture.					
Sub Deck	Fair	Some soft sounding spots. Drill samples were dry with no rot					
Ties	Fair	Drill samples were good with no rot. Multiple ties were misaligned or shifted, some cracked					
Span 4							
Curb Rail/Blocks/Posts	Poor	Curbs were poor during sounding. Drill samples were very soft with rot and moisture noted.					
Deck to Girder Bolts	Poor	Loose curb to tie bolts were noted					
Hardware	Not Applicable	N/A					
Hand Rails/Walkouts	Not Applicable	N/A					
Nails	Fair	No issues noted					
Overall Deck Condition	Poor	Replace entire wearing surface and curbs. Monitor subdeck and deck ties for deterioration.					
Running Planks	Poor	Wearing surface was noted to be breaking down and in poor condition. Drill samples contained rot and moisture.					
Sub Deck	Fair	Some soft sounding spots. Drill samples were dry with no rot					
Ties	Fair	Drill samples were good with no rot. Multiple ties were misaligned or shifted, some cracked					
PIERS							
Pier 1							
Bearings	Fair	No issues noted. Gusset plate brackets on the right side of each pier to support the next span					
Bracing or Sheathing	Good	No issues noted					
Caps	Unrated	Girders rest on bearings on the top of the piles					
Cribs	Not Applicable	N/A					
Dolphins	Not Applicable	N/A					
Hardware	Not Applicable	N/A					
Overall	Fair	Driftwood and debris must be removed. Piers must be monitored for movement and damage until driftwood is removed.					
Piles or Posts	Fair	Adequate condition with no damage noted					
Riprap	Not Applicable	N/A					
Wall	Not Applicable	N/A					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 836 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-029	Structure Name:	G5-029	Road Name:	SOUTH	Inspection Date:	2021/09/21
---------	--------	-----------------	--------	------------	-------	------------------	------------

Pier 2

Bearings	Fair	No issues noted. Gusset plate brackets on the right side of each pier to support the next span
Bracing or Sheathing	Good	No issues noted
Caps	Unrated	Girders rest on bearings on the top of the piles
Cribs	Not Applicable	N/A
Dolphins	Not Applicable	N/A
Hardware	Not Applicable	N/A
Overall	Fair	Driftwood and debris must be removed. Piers must be monitored for movement and damage until driftwood is removed.
Piles or Posts	Fair	Significant driftwood and debris against the upstream side
Riprap	Not Applicable	N/A
Wall	Not Applicable	N/A

Pier 3

Bearings	Fair	No issues noted. Gusset plate brackets on the right side of each pier to support the next span
Bracing or Sheathing	Good	No issues noted
Caps	Unrated	Girders rest on bearings on the top of the piles
Cribs	Not Applicable	N/A
Dolphins	Not Applicable	N/A
Hardware	Not Applicable	N/A
Overall	Fair	Driftwood and debris must be removed. Piers must be monitored for movement and damage until driftwood is removed.
Piles or Posts	Fair	Upstream pile has a dent near the bracket connection, Approximately 1300mm down from the bearing and 19mm inwards. Significant amount of driftwood and debris against the upstream pile
Riprap	Not Applicable	N/A
Wall	Not Applicable	N/A

SUPERSTRUCTURE

Span 1

Bracing	Good	No issues noted
Diaphragms	Good	No issues noted
Girders	Good	Light surface rust and minor debris/moss growth.
Hardware	Not Applicable	N/A

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 837 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-029	Structure Name:	G5-029	Road Name:	SOUTH	Inspection Date:	2021/09/21			
Under Trussing		Not Applicable		N/A						
Span 2										
Bracing		Good		No issues noted						
Diaphragms		Good		No issues noted						
Girders		Good		Light surface rust and minor debris/moss growth.						
Hardware		Not Applicable		N/A						
Under Trussing		Not Applicable		N/A						
Span 3										
Bracing		Good		No issues noted						
Diaphragms		Good		No issues noted						
Girders		Good		Light surface rust and minor debris/moss growth.						
Hardware		Not Applicable		N/A						
Under Trussing		Not Applicable		N/A						
Span 4										
Bracing		Good		No issues noted						
Diaphragms		Good		No issues noted						
Girders		Good		Light surface rust and minor debris/moss growth.						
Hardware		Not Applicable		N/A						
Under Trussing		Not Applicable		N/A						
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		4.9							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	Present water clearance was 6.9m. Significant amount of driftwood and debris accumulation upstream of the bridge. Driftwood is bearing on piers 2 and 3 and should be removed immediately. Smaller amounts of rip rap, natural vegetation, to be monitored for erosion								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 838 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-029	Structure Name:	G5-029	Road Name:	SOUTH	Inspection Date:	2021/09/21
----------------	--------	------------------------	--------	-------------------	-------	-------------------------	------------

REPAIRS	#	Status	Priority	Estimate	Description
	15	Required	High	\$ 0.00	Remove driftwood and debris from the upstream channel
	16	Required	High	\$ 0.00	Install 30 tonne GVW load rating signs
	17	Required	High	\$ 0.00	Replace entire wearing surface
	18	Required	High	\$ 0.00	Replace curbs
	19	Required	Medium	\$ 0.00	Replace approach barriers
	20	Required	Medium	\$ 0.00	Install bridge ahead signs on both approaches
	21	Required	Medium	\$ 0.00	Grade approaches
	22	Required	Medium	\$ 0.00	Brush approaches

MONITORS	#	Description
	5	Monitor movement of abutment walls
	6	Monitor piers for lateral/longitudinal movement and damage
	7	Monitor abutment bearings for further movement
	8	Monitor banks for erosion

GENERAL	Inspector's Comment:	<p>This bridge is in immediate need for removal of the driftwood and debris in the upstream portion of the channel; this must be completed before any heavy truck traffic usage and we recommend that the bridge be posted with 30 tonne GVW signs until the driftwood is removed. The wearing surface and the curbs were in poor condition and must be replaced. The barriers were also in poor condition and located too far from the ends of the bridge. The abutments were noted to be leaning towards the channel and the right abutment wall was bearing against the abutment pile cap and bracing system. The bearings at the abutments should be monitored for further movement or rotation. Access to the bridge was also poor, so grading of the road leading into the bridge is recommended. For further details, see the 2021 Close Proximity Inspection Report.</p> <p>Concern with debris build up, running surface and curbs. DA.</p>
	PEng's Comment:	Some debris and driftwood was removed in 2020 and continues to be an ongoing issue. Load rating is to remain at 30 tonnes and may be downrated further if significant movement of piers, bearings or abutments are observed. Consider removing bridge. BH

GENERAL	Estimated Load Restriction (year):		2031	Estimated Replacement (year):		
	Current Inspection Load Rating:	30	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/01/20 15:49:32		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 839 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-032	Structure Name:	G5-032	Road Name:	SOUTH	Inspection Date:	2021/07/20
KM:	20.20	User km:	20.20	Crossing Name:	Driftwood River #2	Next Inspection Date:	2024/07/20
Project File ID #:	7822	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Glulam Girder				Right	Pile -Permanent Materials	
Total Length (metres):	51.0	# Spans:	3	Span Width:			Span Length(s) (metres): 13.5, 24, 13.5
UTM Zone:	9	UTM Easting:	473708	UTM Northing:	6184385		
Inspector Name:	Dawson Smith		Year Superstructure Installed:	1977			
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	
Fill	Good	
Hardware	Fair	
Piles or Posts	Fair	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	Brushing required both approaches.
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	Post load rating 0 tonnes
Road Surface	Good	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 840 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-032	Structure Name:	G5-032	Road Name:	SOUTH	Inspection Date:	2021/07/20
---------	--------	-----------------	--------	------------	-------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Poor	significant decay
Deck to Girder Bolts	Not Applicable	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Nails	Fair	
Overall Deck Condition	Poor	significant decay
Running Planks	Poor	significant decay
Sub Deck	Fair	
Ties	Fair	

PIERS

Pier 1

Bearings	Not Applicable	
Bracing or Sheathing	Fair	
Caps	Fair	
Cribs	Fair	
Dolphins	Fair	
Hardware	Fair	
Overall	Fair	
Piles or Posts	Fair	
Riprap	Not Applicable	
Wall	Fair	

Pier 2

Bearings	Not Applicable	
Bracing or Sheathing	Fair	
Caps	Fair	
Cribs	Fair	
Dolphins	Fair	
Hardware	Fair	
Overall	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 841 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-032	Structure Name:	G5-032	Road Name:	SOUTH	Inspection Date:	2021/07/20
---------	--------	-----------------	--------	------------	-------	------------------	------------

Piles or Posts	Fair	
Riprap	Not Applicable	
Wall	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Fair	
Diaphragms	Fair	
Girders	Fair	
Hardware	Fair	
Under Trussing	Not Applicable	

Span 2

Bracing	Fair	
Diaphragms	Fair	
Girders	Fair	
Hardware	Fair	
Under Trussing	Fair	

Span 3

Bracing	Fair	
Diaphragms	Fair	
Girders	Fair	
Hardware	Fair	
Under Trussing	Fair	

CHANNEL	Estimated Present Water Level Depth:		3.0		Estimated Present Water Level Width:		20.0			
	Estimated High Water Level Clearance:		5.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 842 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-032	Structure Name:	G5-032	Road Name:	SOUTH	Inspection Date:	2021/07/20
REPAIRS	#	Status	Priority	Estimate	Description		
	17	Required	High		Replace curbs and risers.		
	18	Required	High		Replace decking and running planks.		
	19	Required	Medium		Install bridge ahead signs		
	20	Required	Medium		Install delineators as required.		
	22	Required	Medium		Brushing required both approaches		
MONITORS	#	Description					
GENERAL	Inspector's Comment:	Not a great inspection but captured the critical issues. Structure should be load restricted and closed. GZ					
GENERAL	PEng's Comment:	Significant wear to running deck and curbs deteriorating. Replace all decking and curbs. Bridge is down rated to 0 tonnes. BH					
GENERAL	Estimated Load Restriction (year):			2030	Estimated Replacement (year):		
	Current Inspection Load Rating:		0	Design Load GVW (tonnes):		113	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status: Reviewed By Bruce Henderson on 2022/01/24 11:16:33			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 843 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-030	Structure Name:	G5-030	Road Name:	SOUTH	Inspection Date:	2010/08/18
KM:	122.20	User km:	122.20	Crossing Name:	Unnamed creek	Next Inspection Date:	2016/08/16
Project File ID #:	7822	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Steel (non-corrugated)		
Inlet Cover (mm):	1,200			Outlet Cover (mm):	1,200		
Footing Type:				Gradient (%):			
Culvert Length (metres):	25.0	Opening Height (mm):	1,200	Opening Width (mm):	1,200		
UTM Zone:	9	UTM Easting:	477075	UTM Northing:	6178863		
Inspector Name:	wwilkinson			Year Superstructure Installed:	1977		
Access:	Structure removed as per 2016 inspection-SRW						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	Not Required
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	Not Required
Delineator Missing Right (approaching structure)	2	Not Required
Fender Condition	None	
Road Surface	Poor	Wilderness level , no through road

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Poor	See Photos Left culvert in poor condition right culvert in better condition
Coating	Poor	See Photos Left culvert in poor condition right culvert in better condition
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Poor	See Photos Left culvert in poor condition right culvert in better condition
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Fair	Perched

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 844 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-030	Structure Name:	G5-030	Road Name:	SOUTH	Inspection Date:	2010/08/18
Overall	Poor	See Photos Left culvert in poor condition right culvert in better condition					
Riprap	Not Applicable						
Roof	Poor	See Photos Left culvert in poor condition right culvert in better condition					
Side Walls	Poor	See Photos Left culvert in poor condition right culvert in better condition					
Trash Rack	Poor	Posts rotting See Photos					
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						
CHANNEL	Estimated Present Water Level Depth:		5.0		Estimated Present Water Level Width:		2.0
	Estimated High Water Level Clearance:		1.0				
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Aggradation: No
	Comment:	Bridge removed 3 km up road					
REPAIRS	#	Status	Priority	Estimate	Description		
	1	Required	High	\$ 0.00	Remove Culverts		
MONITORS	#	Description					
GENERAL	Inspector's Comment:	Left culvert in poor condition, bridge has been pulled on road system 3km up chain from culverts - last inspection of culverts 2001 when bridge removed. Suggest pulling culverts and deactivate road past culvert if/when activities are finished past this point. Field inspection may not be required by engineer. please have engineer make decision for field visit based on photos and information provided. - Recommend down-rating culverts to 30 tonnes - M.D.					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):			2017	Estimated Replacement (year):		
	Current Inspection Load Rating:		30	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		Yes	Report Status: Accepted By Jason Olmsted on 2015/11/25 11:15:36			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 845 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-055	Structure Name:	G5-916	Road Name:	NESABUT	Inspection Date:	2021/07/21
KM:	0.60	User km:	0.60	Crossing Name:	Unnamed creek	Next Inspection Date:	2023/07/21
Project File ID #:	7822	Br.	06	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Steel I-beam				Right	Crib, Log or Untreated Timber	
Total Length (metres):	6.3	# Spans:	1	Span Width:			Span Length(s) (metres): 6.3
UTM Zone:	10		UTM Easting:	351948		UTM Northing:	6129818
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1995		
Access:	Access at 23.3 kilometer on Driftwood FSR.						

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Poor	showing rot
Fill	Good	
Hardware	Not Applicable	
Log/Timber Crib	Poor	showing rot
Piles or Posts	Not Applicable	
Riprap	Good	
Tie-backs	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 846 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-055	Structure Name:	G5-916	Road Name:	NESABUT	Inspection Date:	2021/07/21			
Posted Load Rating (Enter 0 if sign missing)	5	(not posted at 0 Tonnes.GZ)								
Road Surface	Poor	road has been deactivated approx. 500m from site however can be passed with a 4x4								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Poor	showing decay								
Deck to Girder Bolts	Not Applicable									
Hardware	Fair									
Hand Rails/Walkouts	Not Applicable									
Nails	Fair									
Overall Deck Condition	Poor	rotten								
Running Planks	Poor	rotten								
Sub Deck	Fair									
Ties	Fair									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Fair									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		0.1			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	Road is deactivated (but passable) approx. 500 meter from bridge, bridge deck is rotten								
REPAIRS	#	Status	Priority	Estimate	Description					
	12	Required	High	\$	or deactivate					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 847 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-055	Structure Name:	G5-916	Road Name:	NESABUT	Inspection Date:	2021/07/21
MONITORS	#	Description					
GENERAL	Inspector's Comment:	road has been deactivated approx. 500m from site however can be passed with a 4x4					
GENERAL	PEng's Comment:	Bridge is closed and should be barricaded or deactivated. BH					
GENERAL	Estimated Load Restriction (year):		2005		Estimated Replacement (year):		2013
	Current Inspection Load Rating:		0		Design Load GVW (tonnes):		68
	Design Vehicle Config.:						
Professional Inspection Required?		No		Report Status:		Reviewed By Bruce Henderson on 2022/02/04 13:11:39	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 848 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-056	Structure Name:	G5-056	Road Name:	NESABUT	Inspection Date:	2020/09/17
KM:	3.10	User km:	3.10	Crossing Name:	Unnamed Creek	Next Inspection Date:	2023/09/17
Project File ID #:	7822	Br.	06	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,200		
Footing Type:				Gradient (%):			
Culvert Length (metres):	20.0	Opening Height (mm):	1,200	Opening Width (mm):	1,200		
UTM Zone:	10	UTM Easting:	350360	UTM Northing:	6129803		
Inspector Name:	Vince Sewell			Year Superstructure Installed:	1999		
Access:	Minor culvert						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Poor	wilderness, not drivable

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	rust on floor
Embedment Materials	Not Applicable	
Fill	Good	1.5m
Floor	Good	rust
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 849 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-056	Structure Name:	G5-056	Road Name:	NESABUT	Inspection Date:	2020/09/17			
Inlet	Good									
Outlet	Poor	15cm perched								
Overall	Fair									
Riprap	Fair									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		0.6			
	Estimated High Water Level Clearance:		0.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Not a major structure. DNI. this is now part of the district's road inspection								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 850 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-056	Structure Name:	G5-056	Road Name:	NESABUT	Inspection Date:	2020/09/17
GENERAL	Estimated Load Restriction (year):		2020	Estimated Replacement (year):			
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		Design Vehicle Config.:	
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/02/25 15:37:07	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 851 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-242	Structure Name:	G5-990	Road Name:	AIRLINE EAST	Inspection Date:	2020/07/23
KM:	1.39	User km:	1.39	Crossing Name:	Unnamed	Next Inspection Date:	2023/09/01
Project File ID #:	7822	Br.	10	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Other	
Superstructure:	Steel I-beam				Right	Other	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	10		UTM Easting:	374460	UTM Northing:	6115760	
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	2012		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	
Fill	Poor	Soils loose, likely uncompacted
General Abutment Condition	Poor	require P.Eng. inspection
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Poor	Wire forms not connected, forms tied back with cable, top row has no intermediate fabric layer

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 852 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-242	Structure Name:	G5-990	Road Name:	AIRLINE EAST	Inspection Date:	2020/07/23			
Road Surface		Fair								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Good									
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Not Applicable									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		3.0			
	Estimated High Water Level Clearance:		2.9							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Medium	\$	Reconstruction of abutments may be required. P.Eng to inspect and confirm.					

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 853 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-242 Structure Name: G5-990 Road Name: AIRLINE EAST Inspection Date: 2020/07/23

MONITORS

#	Description
1	Monitor abutments for settlement and rotation

GENERAL

Inspector's Comment:	Sketchy GRS construction, not constructed to typical GRS standards, compaction of soils is suspect. Requires P.Eng. inspection and load rating.
----------------------	---

GENERAL

PEng's Comment:	Bridge is to be posted at 30 tonnes until bridge certification is submitted and need to also inspect the GRS abutments this summer to see if those are an issue
-----------------	---

GENERAL

Estimated Load Restriction (year):			2030	Estimated Replacement (year):				
Current Inspection Load Rating:	30		Design Load GVW (tonnes):		91		Design Vehicle Config.:	L100
Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/19 12:42:57					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 854 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-243	Structure Name:	G5-991	Road Name:	AIRLINE EAST	Inspection Date:	2020/07/23
KM:	2.36	User km:	2.36	Crossing Name:	Unnamed	Next Inspection Date:	2023/09/01
Project File ID #:	7822	Br.	10	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Other	
Superstructure:	Steel I-beam				Right	Other	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	10	UTM Easting:	375322	UTM Northing:	6116169		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	2012		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Fair	
General Abutment Condition	Fair	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Fair	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	
Road Surface	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 855 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-243	Structure Name:	G5-991	Road Name:	AIRLINE EAST	Inspection Date:	2020/07/23
---------	--------	-----------------	--------	------------	--------------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	one riser damaged but solid
------------------------	------	-----------------------------

Deck to Girder Bolts	Good	
----------------------	------	--

Hardware	Good	
----------	------	--

Hand Rails/Walkouts	Not Applicable	
---------------------	----------------	--

Nails	Good	
-------	------	--

Overall Deck Condition	Good	
------------------------	------	--

Running Planks	Fair	Excessive wear on town side
----------------	------	-----------------------------

Sub Deck	Good	
----------	------	--

Ties	Good	
------	------	--

SUPERSTRUCTURE

Span 1

Bracing	Good	
---------	------	--

Diaphragms	Good	
------------	------	--

Girders	Good	
---------	------	--

Hardware	Not Applicable	
----------	----------------	--

Under Trussing	Not Applicable	
----------------	----------------	--

CHANNEL

Estimated Present Water Level Depth:	0.3	Estimated Present Water Level Width:	3.0
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	2.3		
---------------------------------------	-----	--	--

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 856 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-243	Structure Name:	G5-991	Road Name:	AIRLINE EAST	Inspection Date:	2020/07/23
GENERAL	Inspector's Comment:	Stream channel heavily brushed in					
GENERAL	PEng's Comment:	Bridge appears ok. Post bridge at 30 tonnes until we receive certification package indicating what this crossing was designed for. We will also take a look at the GRS abutments this summer					
GENERAL	Estimated Load Restriction (year):		2030		Estimated Replacement (year):		
	Current Inspection Load Rating:		30		Design Load GVW (tonnes):		91
	Design Vehicle Config.:		L100				
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/19 12:59:12			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 857 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-340	Structure Name:	G5-922	Road Name:	AIRLINE EAST	Inspection Date:	2020/09/23
KM:	3.98	User km:	3.98	Crossing Name:	Unnamed Creek	Next Inspection Date:	2022/09/23
Project File ID #:	7822	Br.	10	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Steel I-beam				Right	Crib, Log or Untreated Timber	
Total Length (metres):	12.0	# Spans:	1	Span Width:			Span Length(s) (metres): 12
UTM Zone:	10		UTM Easting:	376924	UTM Northing:	6116517	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2009		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Poor	logs, rot found, top log is broken on both sides
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	logs, rot found outsid bride covering
Fill	Good	
Hardware	Good	
Log/Timber Cribs	Fair	logs, rot found outsid bride covering
Piles or Posts	Not Applicable	
Riprap	Good	
Tie-backs	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	Hill
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	no nose cones

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 858 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-340	Structure Name:	G5-922	Road Name:	AIRLINE EAST	Inspection Date:	2020/09/23			
Posted Load Rating (Enter 0 if sign missing)	75									
Road Surface	Fair									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Not Applicable									
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Good									
CHANNEL	Estimated Present Water Level Depth:		0.3		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 859 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-340	Structure Name:	G5-922	Road Name:	AIRLINE EAST	Inspection Date:	2020/09/23
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	looks ok					
GENERAL	Estimated Load Restriction (year):		2030		Estimated Replacement (year):		
	Current Inspection Load Rating:		68		Design Load GVW (tonnes):		68
	Design Vehicle Config.:		L75				
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/04 14:18:03			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 860 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-341	Structure Name:	G5-917	Road Name:	AIRLINE EAST	Inspection Date:	2020/09/23
KM:	5.26	User km:	5.26	Crossing Name:	Unnamed	Next Inspection Date:	2022/09/23
Project File ID #:	7822	Br.	10	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Steel I-beam				Right	Crib, Log or Untreated Timber	
Total Length (metres):	9.1	# Spans:	1	Span Width:			Span Length(s) (metres): 9.1
UTM Zone:	10		UTM Easting:	378073	UTM Northing:	6117043	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2014		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Fair	log with rot and fungus
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	log with rot and fungus
Fill	Good	
Hardware	Good	
Log/Timber Cribs	Fair	some rot and fungus
Piles or Posts	Not Applicable	
Riprap	Good	
Tie-backs	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	repaired by inspector
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 861 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-341	Structure Name:	G5-917	Road Name:	AIRLINE EAST	Inspection Date:	2020/09/23			
Posted Load Rating (Enter 0 if sign missing)	0									
Road Surface	Fair									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Poor	several broken								
Deck to Girder Bolts	Good									
Hardware	Fair									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Not Applicable									
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good	bent members								
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Good									
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	2	Required	Medium		Fix damaged curbs					

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 862 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-341 Structure Name: G5-917 Road Name: AIRLINE EAST Inspection Date: 2020/09/23

MONITORS

#	Description
1	Sills for rot
2	Ballast wall for rot

GENERAL

Inspector's Comment:	
----------------------	--

GENERAL

PEng's Comment:	bridge curbs will need to be repaired soon or else the bridge could be down-rated
-----------------	---

GENERAL

Estimated Load Restriction (year):		2025	Estimated Replacement (year):		
Current Inspection Load Rating:	68	Design Load GVW (tonnes):	68	Design Vehicle Config.:	L75
Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/04 15:13:19		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 863 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-342	Structure Name:	G5-920	Road Name:	AIRLINE EAST	Inspection Date:	2020/09/23
KM:	5.75	User km:	5.75	Crossing Name:	Unnamed	Next Inspection Date:	2022/09/23
Project File ID #:	7822	Br.	10	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Steel I-beam				Right	Crib, Log or Untreated Timber	
Total Length (metres):	12.1	# Spans:	1	Span Width:			Span Length(s) (metres): 12.1
UTM Zone:	10		UTM Easting:	378387	UTM Northing:	6117311	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:			
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Fair	Logs unpealed, some fungus growing
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	Logs unpealed, some fungus growing
Fill	Good	
Hardware	Good	
Log/Timber Cribs	Fair	Logs unpealed, some fungus growing
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Tie-backs	Unrated	not found \ seen
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 864 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-342	Structure Name:	G5-920	Road Name:	AIRLINE EAST	Inspection Date:	2020/09/23			
Posted Load Rating (Enter 0 if sign missing)	75									
Road Surface	Fair	wilderness								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Not Applicable	required								
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Not Applicable									
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Good									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 865 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-342 Structure Name: G5-920 Road Name: AIRLINE EAST Inspection Date: 2020/09/23

MONITORS

#	Description
1	all log components for rot

GENERAL

Inspector's Comment:	
----------------------	--

GENERAL

PEng's Comment:	looks ok
-----------------	----------

GENERAL

Estimated Load Restriction (year):	2025	Estimated Replacement (year):	
Current Inspection Load Rating:	68	Design Load GVW (tonnes):	
Design Vehicle Config.:	L75	Professional Inspection Required?	No
Report Status:	Reviewed By Jason Olmsted on 2021/03/04 14:23:56		

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 866 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-430	Structure Name:	G5-430A	Road Name:	TANIZUL	Inspection Date:	2016/06/28	
KM:	9.00	User km:	9.00	Crossing Name:	Tachie River	Next Inspection Date:	2022/06/01	
Project File ID #:	7873	Br.	01	Forest District:	Stuart Nechako Natural Resource District			
Deck Type:	Concrete Composite			Running Surface:	Concrete			
Curb Type:				Abutments (looking downstream)	Left	Concrete Cast in Place		
Superstructure:	Steel I-beam				Right	Concrete Cast in Place		
Total Length (metres):	134.	# Spans:	4	Span Width:			Span Length(s) (metres):	27, 40, 40, 27
UTM Zone:	10		UTM Easting:	384117		UTM Northing:	6063048	
Inspector Name:	Donovan J. A. Melin			Year Superstructure Installed:	2010			
Access:								

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Cast in Place	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 867 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-430	Structure Name:	G5-430A	Road Name:	TANIZUL	Inspection Date:	2016/06/28
---------	--------	-----------------	---------	------------	---------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Excellent	HSS
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

Span 2

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Excellent	
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

Span 3

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Excellent	
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

Span 4

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Excellent	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 868 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-430	Structure Name:	G5-430A	Road Name:	TANIZUL	Inspection Date:	2016/06/28
Deck Joints	Good						
Grout Pockets	Good						
Hardware	Good						
Hand Rails/Walkouts	Not Applicable						
Overall Deck Condition	Good						
Running Surface	Good						
PIERS							
Pier 1							
Bearings	Good						
Bracing or Sheathing	Good						
Caps	Good						
Cribs	Not Applicable						
Dolphins	Good						
Hardware	Good						
Overall	Good						
Piles or Posts	Good						
Riprap	Not Applicable						
Wall	Not Applicable						
Pier 2							
Bearings	Good						
Bracing or Sheathing	Good						
Caps	Good						
Cribs	Not Applicable						
Dolphins	Good						
Hardware	Good						
Overall	Good						
Piles or Posts	Good						
Riprap	Not Applicable						
Wall	Not Applicable						
Pier 3							
Bearings	Good						

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 869 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-430	Structure Name:	G5-430A	Road Name:	TANIZUL	Inspection Date:	2016/06/28
Bracing or Sheathing	Good						
Caps	Good						
Cribs	Not Applicable						
Dolphins	Good						
Hardware	Good						
Overall	Good						
Piles or Posts	Good						
Riprap	Not Applicable						
Wall	Not Applicable						
SUPERSTRUCTURE							
Span 1							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Good						
Under Trussing	Not Applicable						
Span 2							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Good						
Under Trussing	Not Applicable						
Span 3							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Good						
Under Trussing	Not Applicable						
Span 4							
Bracing	Good						
Diaphragms	Good						

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 870 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-430	Structure Name:	G5-430A	Road Name:	TANIZUL	Inspection Date:	2016/06/28			
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	5.0	Estimated Present Water Level Width:	50.0						
	Estimated High Water Level Clearance:	8.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Low	\$ 500.00	Delineator turning apparatuses are not turning properly and need repairs.					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Bridge is in good condition. First inspection since bridge replacement. Structure in good condition. MD								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):	2050	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100				
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2017/04/27 13:12:48						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 871 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-430	Structure Name:	G5-430	Road Name:	TANIZUL	Inspection Date:	2019/10/03	
KM:	9.00	User km:	9.00	Crossing Name:	Tachie River	Next Inspection Date:	2022/09/01	
Project File ID #:	7873	Br.	01	Forest District:	Stuart Nechako Natural Resource District			
Deck Type:	Concrete			Running Surface:	Concrete			
Curb Type:				Abutments (looking downstream)	Left	Concrete Precast		
Superstructure:	Steel I-beam				Right	Concrete Precast		
Total Length (metres):	134.	# Spans:	4	Span Width:			Span Length(s) (metres):	27, 40, 40, 27
UTM Zone:	10		UTM Easting:	384117		UTM Northing:	6063048	
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2010			
Access:								

ABUTMENTS

Bearings	Good
Bracing	Good
Ballast Wall	Good
Concrete Precast	Good
Corrosion Protection	Not Applicable
Fill	Good
Hardware	Good
Piles or Posts	Good
Riprap	Good
Wing Wall	Good

APPROACHES

Alignment	Good
Bridge Ahead Signs Missing	0
Brushing Required	No
Delineator Missing Left (approaching structure)	1
Delineator Missing Right (approaching structure)	1
Fender Condition	Good
Road Surface	Good

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 872 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-430	Structure Name:	G5-430	Road Name:	TANIZUL	Inspection Date:	2019/10/03
---------	--------	-----------------	--------	------------	---------	------------------	------------

Span 1

Concrete Deck	Good
Curb Rail/Blocks/Posts	Good
Deck Joints	Good
Grout Pockets	Good
Hardware	Good
Hand Rails/Walkouts	Not Applicable
Overall Deck Condition	Good
Running Surface	Good

PIERS

Pier 1

Bearings	Good
Bracing or Sheathing	Good
Caps	Good
Cribs	Good
Dolphins	Not Applicable
Hardware	Not Applicable
Overall	Good
Piles or Posts	Good
Riprap	Not Applicable
Wall	Good

Pier 2

Bearings	Good
Bracing or Sheathing	Good
Caps	Good
Cribs	Good
Dolphins	Not Applicable
Hardware	Not Applicable
Overall	Good
Piles or Posts	Good
Riprap	Not Applicable

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 873 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-430	Structure Name:	G5-430	Road Name:	TANIZUL	Inspection Date:	2019/10/03
Wall	Good						
Pier 3							
Bearings	Good						
Bracing or Sheathing	Good						
Caps	Good						
Cribs	Good						
Dolphins	Not Applicable						
Hardware	Not Applicable						
Overall	Good						
Piles or Posts	Good						
Riprap	Not Applicable						
Wall	Good						
SUPERSTRUCTURE							
Span 1							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Not Applicable						
Under Trussing	Not Applicable						
Span 2							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Not Applicable						
Under Trussing	Not Applicable						
Span 3							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Not Applicable						
Under Trussing	Not Applicable						

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 874 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-430	Structure Name:	G5-430	Road Name:	TANIZUL	Inspection Date:	2019/10/03
---------	--------	-----------------	--------	------------	---------	------------------	------------

Span 4

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	20.0	Estimated Present Water Level Width:	2.0
	Estimated High Water Level Clearance:	10.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Suggested	Medium	\$ 250.00	INSTALL LOAD RATING SIGN

MONITORS	#	Description

GENERAL	Inspector's Comment:	GOOD , NO WEIGHT RATING
---------	----------------------	-------------------------

GENERAL	PEng's Comment:	
---------	-----------------	--

GENERAL	Estimated Load Restriction (year):	2060	Estimated Replacement (year):	
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):	91
	Design Vehicle Config.:			
	Professional Inspection Required?	No	Report Status:	Rejected By IDIR\JOLMSTED on 2020/03/12 12:27:01

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 875 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-431	Structure Name:	G5-431	Road Name:	TANIZUL	Inspection Date:	2021/07/20
KM:	18.00	User km:	18.00	Crossing Name:	Tarnezell Creek	Next Inspection Date:	2022/07/01
Project File ID #:	7873	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	5,000			Outlet Cover (mm):	5,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	37.0	Opening Height (mm):	2,400	Opening Width (mm):	2,400		
UTM Zone:	10	UTM Easting:	376049	UTM Northing:	6064715		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1983		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	monitor rust
Footing	Not Applicable	
Head Wall	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 876 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-431	Structure Name:	G5-431	Road Name:	TANIZUL	Inspection Date:	2021/07/20
Inlet	Good						
Outlet	Fair	damage to roof at outlet end					
Overall	Fair						
Riprap	Good						
Roof	Fair	damage to roof at outlet end					
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						

CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	0.1						
	Estimated High Water Level Clearance:	2.5								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	No bolted connections, no headwalls, no information on monitoring items, no pics up& downstream. GZ								
GENERAL	PEng's Comment:									

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 877 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-431	Structure Name:	G5-431	Road Name:	TANIZUL	Inspection Date:	2021/07/20
GENERAL	Estimated Load Restriction (year):		2023	Estimated Replacement (year):			
	Current Inspection Load Rating:		See footnote	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Rejected By IDIR\GZSOMBOR on 2022/01/06 07:28:26	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 878 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-432	Structure Name:	G5-432	Road Name:	TANIZUL	Inspection Date:	2000/08/31
KM:	22.90	User km:	22.90	Crossing Name:	Unnamed creek	Next Inspection Date:	2030/01/01
Project File ID #:	7873	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	3,500			Outlet Cover (mm):	3,500		
Footing Type:				Gradient (%):	6.0		
Culvert Length (metres):	24.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	371460	UTM Northing:	6068517		
Inspector Name:	Brent Case			Year Superstructure Installed:	1982		
Access:	coordinates from LRM. GZ Minor culvert 1800						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Good	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 879 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-432	Structure Name:	G5-432	Road Name:	TANIZUL	Inspection Date:	2000/08/31			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	nullCulvert: 4-7) Minor deformations, but solid..								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2032		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/12 08:54:44			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 880 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-433	Structure Name:	G5-433	Road Name:	TANIZUL	Inspection Date:	2021/07/20
KM:	25.00	User km:	25.00	Crossing Name:	West Tarnezell Creek	Next Inspection Date:	2022/07/01
Project File ID #:	7873	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	15.6	# Spans:	1	Span Width:	Span Length(s) (metres):		15
UTM Zone:	10	UTM Easting:	371095	UTM Northing:	6069147		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1993		
Access:							

ABUTMENTS

Bearings	Good
Bracing	Good
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Good
Piles or Posts	Good
Riprap	Good
Wing Wall	Not Applicable

APPROACHES

Alignment	Good
Bridge Ahead Signs Missing	2
Brushing Required	No recently brushed
Delineator Missing Left (approaching structure)	0
Delineator Missing Right (approaching structure)	0
Fender Condition	Good
Posted Load Rating (Enter 0 if sign missing)	0
Road Surface	Good

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 881 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-433	Structure Name:	G5-433	Road Name:	TANIZUL	Inspection Date:	2021/07/20
---------	--------	-----------------	--------	------------	---------	------------------	------------

DECK

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Fair
-------------	------

Grout Pockets	Good
---------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	3.0
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	2.0
---------------------------------------	-----

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
8	Suggested	Medium	\$	
9	Suggested	Medium	\$ 500.00	

MONITORS

#	Description
9	monitor beaver activity

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 882 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-433	Structure Name:	G5-433	Road Name:	TANIZUL	Inspection Date:	2021/07/20
GENERAL	Inspector's Comment:	Did not monitor bearings, deck/ballast wall connection label as deck joint, missing pics. GZ					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2033	Estimated Replacement (year):			
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Rejected By IDIR\GZSOMBOR on 2022/01/06 07:45:32			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 883 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-434	Structure Name:	G5-434	Road Name:	TANIZUL	Inspection Date:	2019/10/03
KM:	31.70	User km:	31.70	Crossing Name:	Tarnezell Creek	Next Inspection Date:	2022/10/03
Project File ID #:	7873	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	17.9	# Spans:	1	Span Width:	Span Length(s) (metres):		17.9
UTM Zone:	10	UTM Easting:	369354	UTM Northing:	6075265		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1999		

Access:	
---------	--

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Fill	Poor	FILL HAS FAILED ON DOWN SIDE
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Good	
Road Surface	Poor	FILL HAS FAILED ON DOWN SIDE

DECK

Span 1

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 884 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-434	Structure Name:	G5-434	Road Name:	TANIZUL	Inspection Date:	2019/10/03			
Concrete Deck	Good									
Curb Rail/Blocks/Posts	Poor	GUARDRAILS ROTTEN								
Deck Joints	Good									
Grout Pockets	Good									
Hardware	Not Applicable									
Hand Rails/Walkouts	Not Applicable									
Overall Deck Condition	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Not Applicable									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		2.0		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		4.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Medium	\$	FILL AND GRADE DOWN SIDE APPROACH					
	2	Required	Medium	\$ 500.00	INSTALL DELINEATORS AND BRIDGE SIGNS					
	3	Required	High	\$	REPLACE GUARD RAILS					
MONITORS	#	Description								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 885 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-434	Structure Name:	G5-434	Road Name:	TANIZUL	Inspection Date:	2019/10/03
GENERAL	Inspector's Comment:	GUARDRAILS REQUIRE REPLACEMENT, FILL HAS SLOUGHED AWAY FROM WINGWALL ON UPSTREAM SIDE, RIGHT SIDE APPROACH WHEN FACING DOWNSTREAM.					
GENERAL	PEng's Comment:	Bridge to be posted at 5 tonnes until the curbs are replaced and other outstanding items are addressed					
GENERAL	Estimated Load Restriction (year):		2049		Estimated Replacement (year):		
	Current Inspection Load Rating:		5		Design Load GVW (tonnes):		68
	Design Vehicle Config.:		L75				
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/04 15:41:12			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 886 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-513	Structure Name:	G5-912	Road Name:	ONJO	Inspection Date:	2019/09/11
KM:	12.00	User km:	0.00	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/09/11
Project File ID #:	8280	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Concrete Precast	
Superstructure:	Steel I-beam				Right	Concrete Precast	
Total Length (metres):	12.0	# Spans:	1	Span Width:	Span Length(s) (metres):		12
UTM Zone:	10	UTM Easting:	410710	UTM Northing:	6101467		
Inspector Name:	dawson smith			Year Superstructure Installed:	1997		
Access:	At 72km North Road (hwy 27 N), turn onto Witch FSR. Go to 12.5km.						

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Precast	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	ROTTEN AND MISSING
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 887 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-513	Structure Name:	G5-912	Road Name:	ONJO	Inspection Date:	2019/09/11
---------	--------	-----------------	--------	------------	------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Not Applicable	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Fair	
Running Planks	Fair	MINOR ROT
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	4.0
Estimated High Water Level Clearance:	3.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$	REPLACE FENDERS
2	Required	Low	\$ 500.00	INSTALL 2 DELINEATORS AND BRIDGE SIGNS

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 888 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-513	Structure Name:	G5-912	Road Name:	ONJO	Inspection Date:	2019/09/11
---------	--------	-----------------	--------	------------	------	------------------	------------

MONITORS

#	Description

GENERAL

Inspector's Comment:	NO DOWNSTREAM SIDE DELINIATERS OR BRIDGE SIGNS, LOG FENDERS ROTTEN , DECK FAIR
----------------------	--

GENERAL

PEng's Comment:	Curbs will need replacing soon
-----------------	--------------------------------

GENERAL

Estimated Load Restriction (year):	2025	Estimated Replacement (year):	
Current Inspection Load Rating:	68	Design Load GVW (tonnes):	68
Design Vehicle Config.:			
Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/07 14:09:10

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 889 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-512	Structure Name:	G5-512	Road Name:	ONJO	Inspection Date:	2021/09/22
KM:	10.00	User km:	10.00	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/09/22
Project File ID #:	8280	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Glulam Girder				Right	Concrete Lock Blocks	
Total Length (metres):	12.0	# Spans:	1	Span Width:	Span Length(s) (metres):		12
UTM Zone:	10	UTM Easting:	412592	UTM Northing:	6101064		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1997		
Access:	Turn onto the Witch FSR at 72km North Road (hwy 27N). 11km on witch FSR.						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Poor	log fenders, most missing
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 890 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-512	Structure Name:	G5-512	Road Name:	ONJO	Inspection Date:	2021/09/22
---------	--------	-----------------	--------	------------	------	------------------	------------

Road Surface	Good	
--------------	------	--

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Poor	significant decay, especially on approach ends, nails exposed , see pics
Overall Deck Condition	Poor	significant decay, especially on approach ends, nails exposed , see pics
Running Planks	Not Applicable	(Rate as POOR. GZ)
Sub Deck	Poor	significant decay, especially on approach ends, nails exposed , see pics (N/A. GZ)
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Unrated	glulam beams (rate as Good. GZ)
Girders	Good	glulam beams
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	3.0
	Estimated High Water Level Clearance:	2.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	6	Required	High		Replace worn deck.
	7	Required	High	\$ 0.00	Install Approach fenders
	8	Required	Medium	\$	Install bridge ahead signs
	9	Required	High		Install missing delineators

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 891 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-512	Structure Name:	G5-512	Road Name:	ONJO	Inspection Date:	2021/09/22
MONITORS	#	Description					
GENERAL	Inspector's Comment:	Running deck decay, nails exposed, needs fenders Consider load restriction to flag repair items. GZ					
GENERAL	PEng's Comment:	Downrated to 30 tonnes due to condition of deck. JDS					
GENERAL	Estimated Load Restriction (year):		2028		Estimated Replacement (year):		
	Current Inspection Load Rating:		30		Design Load GVW (tonnes):		68
	Design Vehicle Config.:						
	Professional Inspection Required?	No	Report Status:	Reviewed By Jordan Smith on 2022/02/28 14:31:18			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 892 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-510	Structure Name:	G5-510	Road Name:	ONJO NORTH	Inspection Date:	2020/09/02
KM:	0.60	User km:	0.60	Crossing Name:	Wittsichica Creek	Next Inspection Date:	2023/09/02
Project File ID #:	8280	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel Truss/Bailey/Acrow				Right	Concrete Lock Blocks	
Total Length (metres):	15.0	# Spans:	1	Span Width:			Span Length(s) (metres): 12
UTM Zone:	10	UTM Easting:	416349	UTM Northing:	6100762		
Inspector Name:	Warren Wilkinson		Year Superstructure Installed:	1996			
Access:	Road is located at km 6.0 of Witch FSR.						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Poor	Spruce logs 8" rotting
Concrete Lock Blocks	Good	
Corrosion Protection	Good	Galvanised
Caps or Sills	Good	sill
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	hill
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	
Posted Load Rating (Enter 0 if sign missing)	75	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 893 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-510	Structure Name:	G5-510	Road Name:	ONJO NORTH	Inspection Date:	2020/09/02			
Road Surface		Fair								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Deck to Girder Bolts		Good								
Hardware		Fair		missing 2 retaining C clipps La2 pannals upchain						
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Good								
Running Planks		Good								
Sub Deck		Good								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Fair		some damage, bent.						
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		1.5			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	9	Required	High	\$ 500.00	install 2 missing C Rings upper railing					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 894 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-510	Structure Name:	G5-510	Road Name:	ONJO NORTH	Inspection Date:	2020/09/02
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Make sure to install missing hardware					
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:		64	Design Load GVW (tonnes):		64	Design Vehicle Config.: BCL62
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/03/02 13:04:08	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 895 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-511	Structure Name:	G5-973	Road Name:	ONJO NORTH	Inspection Date:	2020/09/02
KM:	2.10	User km:	2.10	Crossing Name:	Unnamed creek	Next Inspection Date:	2023/09/02
Project File ID #:	8280	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	15.2	# Spans:	1	Span Width:	Span Length(s) (metres):		15
UTM Zone:	10	UTM Easting:	417044	UTM Northing:	6101895		
Inspector Name:	Warren Wilkinson, Scott			Year Superstructure Installed:	2008		
Access:	Road turns north at km 6.0 of Witch FSR Acrow panel is not in place it has been replaced by BCTS with G5-973 a 15 meter steel and timber portable bridge						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Poor	unpeeled spruce Logs 8", rotting
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Fair	not much
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	
Road Surface	Fair	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 896 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-511 Structure Name: G5-973 Road Name: ONJO NORTH Inspection Date: 2020/09/02

DECK

Span 1

Curb Rail/Blocks/Posts Poor Rot, replace curbs

Deck to Girder Bolts Good

Hardware Good

Hand Rails/Walkouts Not Applicable

Nails Good

Overall Deck Condition Fair

Running Planks Good

Sub Deck Good minor fungus on bottom

Ties Good

SUPERSTRUCTURE

Span 1

Bracing Good

Diaphragms Good

Girders Good

Hardware Not Applicable

Under Trussing Good

CHANNEL

Estimated Present Water Level Depth: 0.1 Estimated Present Water Level Width: 1.5

Estimated High Water Level Clearance: 1.0

HAZARDS

High Water: No Scour: No Ice: No Debris: No Aggradation: No

Comment:

REPAIRS

#	Status	Priority	Estimate	Description
4	Required	Medium		Replace curbs

MONITORS

#	Description
2	Monitor ballast wall for rot

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 897 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-511	Structure Name:	G5-973	Road Name:	ONJO NORTH	Inspection Date:	2020/09/02
GENERAL	Inspector's Comment:	Inspection supervised by Warren Wilkinson					
GENERAL	PEng's Comment:	Curbs need replacing soon or the bridge will be down-rated					
GENERAL	Estimated Load Restriction (year):		2025		Estimated Replacement (year):		
	Current Inspection Load Rating:		64		Design Load GVW (tonnes):		64
	Design Vehicle Config.:		BCL62				
GENERAL	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/04 14:30:58			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 898 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-518	Structure Name:	G5-950	Road Name:	TIA	Inspection Date:	2020/09/02
KM:	2.10	User km:	2.20	Crossing Name:	Unnamed Crossing	Next Inspection Date:	2023/09/02
Project File ID #:	8280	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.0	# Spans:	1	Span Width:	Span Length(s) (metres):		12
UTM Zone:	10		UTM Easting:	418637	UTM Northing:	6101591	
Inspector Name:	Warren Wilkinsons			Year Superstructure Installed:	2008		
Access:							

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Fair	pushing out in the middle when \ where two boards butt join
Concrete Lock Blocks	Poor	right side has shifted, toed out
Corrosion Protection	Not Applicable	
Caps or Sills	Good	2 boards pinned together to make up each sill
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Poor	corners both sides
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	
Road Surface	Poor	wilderness

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 899 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-518	Structure Name:	G5-950	Road Name:	TIA	Inspection Date:	2020/09/02
---------	--------	-----------------	--------	------------	-----	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Poor	due to rot and hole
Running Planks	Not Applicable	
Sub Deck	Poor	holes and wear
Ties	Poor	found rot in ends

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Good	

CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	2.0
	Estimated High Water Level Clearance:	0.6		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	5	Required	High		Replace deck

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 900 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-518	Structure Name:	G5-950	Road Name:	TIA	Inspection Date:	2020/09/02
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	bridge deck needs to be replaced and any other outstanding issues. Bridge to be posted at 30 tonnes.					
GENERAL	Estimated Load Restriction (year):		2023	Estimated Replacement (year):			
	Current Inspection Load Rating:	30	Design Load GVW (tonnes):	64	Design Vehicle Config.:	CL625	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/04 14:43:54			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 901 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-517	Structure Name:	G5-918	Road Name:	TIA	Inspection Date:	2020/09/02
KM:	0.70	User km:		Crossing Name:	Unnamed Creek	Next Inspection Date:	2023/09/02
Project File ID #:	8280	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:		Span Length(s) (metres):	12.2
UTM Zone:	10	UTM Easting:	417822	UTM Northing:	6102652		
Inspector Name:	Warren Wilkinson, Scott			Year Superstructure Installed:	1999		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Fair	
Piles or Posts	Not Applicable	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	hill and corners
Bridge Ahead Signs Missing	1	upshain
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	left upchain one no post sections knocked over
Road Surface	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 902 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-517	Structure Name:	G5-918	Road Name:	TIA	Inspection Date:	2020/09/02
---------	--------	-----------------	--------	------------	-----	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Good	
Sub Deck	Fair	fungus underneath deck
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Good	

CHANNEL

Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	3.0
Estimated High Water Level Clearance:	1.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 903 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-517	Structure Name:	G5-918	Road Name:	TIA	Inspection Date:	2020/09/02	
GENERAL	Inspector's Comment:	inspection supervised by Warren Wilkinson						
GENERAL	PEng's Comment:	looks ok						
GENERAL	Estimated Load Restriction (year):		2035	Estimated Replacement (year):				
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.:	L75
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2021/03/04 14:39:15		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 904 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-523	Structure Name:	G5-523	Road Name:	NEWLAND	Inspection Date:	2020/09/02
KM:	0.30	User km:	13.30	Crossing Name:	unnamed	Next Inspection Date:	2023/09/02
Project File ID #:	8280	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:	Span Length(s) (metres):		12.1
UTM Zone:	10	UTM Easting:	414988	UTM Northing:	6105701		
Inspector Name:	Warren Wilkinson, Scott			Year Superstructure Installed:	2008		
Access:							

ABUTMENTS

Bearings	Fair	right sill slopped back leaving gap at rear of bearing, not square to bridge
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Fair	some movement leaving gaps between blocks
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Fair	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	hill/corner
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	
Posted Load Rating (Enter 0 if sign missing)	75	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 905 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-523	Structure Name:	G5-523	Road Name:	NEWLAND	Inspection Date:	2020/09/02			
Road Surface		Fair								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Poor	curbs have substantial rot in some timbers							
Deck to Girder Bolts		Good								
Hardware		Fair								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Fair								
Running Planks		Good								
Sub Deck		Excellent								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Not Applicable								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.2	Estimated Present Water Level Width:		2.0				
	Estimated High Water Level Clearance:		0.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	5	Required	Medium		Replace Curbs					

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 906 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-523	Structure Name:	G5-523	Road Name:	NEWLAND	Inspection Date:	2020/09/02
MONITORS	#	Description					
	1	right bearing, sill and blocks for movement					
GENERAL	Inspector's Comment:	inspection done under supervision of Warren Wilkinson					
GENERAL	PEng's Comment:	Curbs will need replacing soon or else bridge will be down-rated					
GENERAL	Estimated Load Restriction (year):		2030		Estimated Replacement (year):		
	Current Inspection Load Rating:		68		Design Load GVW (tonnes):		68
	Design Vehicle Config.:		L75				
GENERAL	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/02 13:11:57			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 907 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-522	Structure Name:	G5-245	Road Name:	NEWLAND	Inspection Date:	2019/09/11
KM:	0.90	User km:	14.00	Crossing Name:	unnamed	Next Inspection Date:	2022/09/11
Project File ID #:	8280	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	25.0	# Spans:	1	Span Width:	Span Length(s) (metres):		25
UTM Zone:	10	UTM Easting:	414617	UTM Northing:	6106047		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	2010		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 908 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-522	Structure Name:	G5-245	Road Name:	NEWLAND	Inspection Date:	2019/09/11
---------	--------	-----------------	--------	------------	---------	------------------	------------

DECK

Span 1

Concrete Deck	Good
---------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Good
---------------	------

Hardware	Not Applicable
----------	----------------

Hand Rails/Walkouts	Fair
---------------------	------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Not Applicable
----------	----------------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	3.0
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	3.0
---------------------------------------	-----

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$ 250.00	INSTALL WEIGHT RATING SIGN

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 909 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-522	Structure Name:	G5-245	Road Name:	NEWLAND	Inspection Date:	2019/09/11
GENERAL	Inspector's Comment:	NEEDS WEIGH SIGN					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2052	Estimated Replacement (year):			
	Current Inspection Load Rating:	68	Design Load GVW (tonnes):	68	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/07 14:42:29			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 910 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-520	Structure Name:	G5-974	Road Name:	NEWLAND	Inspection Date:	2021/09/22
KM:	5.00	User km:	18.00	Crossing Name:	unnamed	Next Inspection Date:	2024/09/22
Project File ID #:	8280	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Other	
Superstructure:	Steel I-beam				Right	Other	
Total Length (metres):	12.1	# Spans:	1	Span Width:			Span Length(s) (metres): 12.1
UTM Zone:	10		UTM Easting:	413027	UTM Northing:	6108067	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2011		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
General Abutment Condition	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 911 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-520	Structure Name:	G5-974	Road Name:	NEWLAND	Inspection Date:	2021/09/22			
Posted Load Rating (Enter 0 if sign missing)	68									
Road Surface	Good									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good	recently been redecked								
Running Planks	Not Applicable									
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.0		Estimated Present Water Level Width:		0.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 912 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-520	Structure Name:	G5-974	Road Name:	NEWLAND	Inspection Date:	2021/09/22
MONITORS	#	Description					
GENERAL	Inspector's Comment:	No issues. GZ					
GENERAL	PEng's Comment:	No concerns. JDS					
GENERAL	Estimated Load Restriction (year):		2025	Estimated Replacement (year):			
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.: L75
	Professional Inspection Required?		No	Report Status:		Reviewed By Jordan Smith on 2022/02/10 15:43:33	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 913 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-521	Structure Name:	G5-913	Road Name:	NEWLAND	Inspection Date:	2021/09/22
KM:	6.30	User km:	19.20	Crossing Name:	unnamed	Next Inspection Date:	2024/09/22
Project File ID #:	8280	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Other	
Superstructure:	Steel I-beam				Right	Other	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	10		UTM Easting:	413334	UTM Northing:	6109134	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2011		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	wire gabion (Timber planks. GZ)
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
General Abutment Condition	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Fair	
Wing Wall	Good	wire gabion

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	missing end caps

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 914 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-521	Structure Name:	G5-913	Road Name:	NEWLAND	Inspection Date:	2021/09/22			
Posted Load Rating (Enter 0 if sign missing)	68									
Road Surface	Fair	needs grading								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Fair									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Fair									
Running Planks	Not Applicable									
Sub Deck	Fair	up section is narrower than the rest, see pics								
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	6	Required	High		Install approach fenders					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 915 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-521	Structure Name:	G5-913	Road Name:	NEWLAND	Inspection Date:	2021/09/22
MONITORS	#	Description					
GENERAL	Inspector's Comment:	No significant issues. GZ					
GENERAL	PEng's Comment:	No concerns. JDS					
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.: L75
	Professional Inspection Required?		No	Report Status:		Reviewed By Jordan Smith on 2022/02/10 15:49:10	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 916 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-524	Structure Name:	G4-913	Road Name:	NEWLAND	Inspection Date:	2021/09/22
KM:	9.00	User km:	22.21	Crossing Name:	Un-named Creek	Next Inspection Date:	2024/09/22
Project File ID #:	8280	Br.	05	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	15.2	# Spans:	1	Span Width:	Span Length(s) (metres):		15.2
UTM Zone:	10	UTM Easting:	412612	UTM Northing:	6110662		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2015		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 917 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-524	Structure Name:	G4-913	Road Name:	NEWLAND	Inspection Date:	2021/09/22			
Road Surface		Good								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Deck to Girder Bolts		Good								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Unrated		(Rate as GOOD. GZ)						
Overall Deck Condition		Fair		missing a few mud boards						
Running Planks		Not Applicable		(Rate as GOOD. GZ)						
Sub Deck		Good		missing a few mud boards (N/A)						
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		3.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	5	Required	Medium		Add bridge ahead signage.					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 918 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-524	Structure Name:	G4-913	Road Name:	NEWLAND	Inspection Date:	2021/09/22
---------	--------	-----------------	--------	------------	---------	------------------	------------

MONITORS

#	Description

GENERAL

Inspector's Comment:	No significant issues. GZ
----------------------	---------------------------

GENERAL

PEng's Comment:	No concerns. JDS
-----------------	------------------

GENERAL

Estimated Load Restriction (year):	2042	Estimated Replacement (year):			
Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100
Professional Inspection Required?	No	Report Status:	Reviewed By Jordan Smith on 2022/02/10 15:59:04		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 919 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-420	Structure Name:	G5-420	Road Name:	RAINBOW	Inspection Date:	2021/09/22
KM:	1.30	User km:	1.30	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/09/22
Project File ID #:	8287	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel Truss/Bailey/Acrow				Right	Concrete Lock Blocks	
Total Length (metres):	9.0	# Spans:	1	Span Width:	Span Length(s) (metres):		9
UTM Zone:	10	UTM Easting:	428454	UTM Northing:	6089332		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1999		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Unrated	(Rate as GOOD. GZ)
Concrete Precast	Unrated	Lock blocks
Corrosion Protection	Not Applicable	(Rate as FAIR. GZ)
Caps or Sills	Unrated	none, it is bolted to the lock blocks (N/A. GZ)
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	Rate as YES. GZ)
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 920 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-420	Structure Name:	G5-420	Road Name:	RAINBOW	Inspection Date:	2021/09/22			
Posted Load Rating (Enter 0 if sign missing)	0									
Road Surface	Good									
DECK										
Span 1										
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Good									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Good									
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Unrated	none								
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable	(N/A. GZ)								
CHANNEL	Estimated Present Water Level Depth:		1.0		Estimated Present Water Level Width:		3.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 921 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-420	Structure Name:	G5-420	Road Name:	RAINBOW	Inspection Date:	2021/09/22
MONITORS	#	Description					
GENERAL	Inspector's Comment:	Bailey/Acrow structure, usually they are green (Bailey) or galvanized (Acrow), the yellow paint is weird. This structure is bolted directly to lock blocks, there is no concrete precast. No issues. GZ					
GENERAL	PEng's Comment:	No concerns. BH					
GENERAL	Estimated Load Restriction (year):		2039	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/10 13:37:59	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 922 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-421	Structure Name:	G5-421	Road Name:	RAINBOW	Inspection Date:	2018/10/11
KM:	6.10	User km:	6.10	Crossing Name:	Unnamed creek	Next Inspection Date:	2020/01/01
Project File ID #:	8287	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	4,000			Outlet Cover (mm):	4,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	33.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	429718	UTM Northing:	6089457		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1985		
Access:	Minor culvert						

--

CHANNEL	Estimated Present Water Level Depth:		Estimated Present Water Level Width:	
	Estimated High Water Level Clearance:			

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

GENERAL	Inspector's Comment:	Minor culvert, do not inspect

GENERAL	PEng's Comment:	This culvert falls under the district normal road maintenance inspections and not major structure inspections.

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 923 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-421	Structure Name:	G5-421	Road Name:	RAINBOW	Inspection Date:	2018/10/11
GENERAL	Estimated Load Restriction (year):		2020	Estimated Replacement (year):			
	Current Inspection Load Rating:		54	Design Load GVW (tonnes):		54	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2019/02/07 13:50:36	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 924 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-390	Structure Name:	G5-390	Road Name:	NECOSLIE	Inspection Date:	2019/08/12
KM:	3.50	User km:	0.00	Crossing Name:	Necoslie River	Next Inspection Date:	2022/08/12
Project File ID #:	8303	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	15.3	# Spans:	1	Span Width:	Span Length(s) (metres):		15.3
UTM Zone:	10	UTM Easting:	429292	UTM Northing:	6023009		
Inspector Name:	dawson smith			Year Superstructure Installed:	1985		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Fair	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	BENT
Delineator Missing Right (approaching structure)	0	BENT
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	68	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 925 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-390	Structure Name:	G5-390	Road Name:	NECOSLIE	Inspection Date:	2019/08/12
---------	--------	-----------------	--------	------------	----------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Not Applicable
----------------------	----------------

Hardware	Not Applicable
----------	----------------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Good
----------------	------

Sub Deck	Good
----------	------

Ties	Good
------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Not Applicable
----------	----------------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	4.0
Estimated High Water Level Clearance:	4.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
2	Complete	Low	\$ 600.00	REPLACE ALL 4 DELINIATORS AND BRUSH AROUND THEM

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 926 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-390	Structure Name:	G5-390	Road Name:	NECOSLIE	Inspection Date:	2019/08/12
GENERAL	Inspector's Comment:	ALL 4 DELINIATORS ARE BENT OR BRUSHED IN					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2035	Estimated Replacement (year):			
	Current Inspection Load Rating:	68	Design Load GVW (tonnes):	41	Design Vehicle Config.:	L45	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/28 16:17:36			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 927 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-395	Structure Name:	G4-912	Road Name:	NECOSLIE-	Inspection Date:	2021/07/09
KM:	16.40	User km:	16.40	Crossing Name:	Un-named	Next Inspection Date:	2024/07/09
Project File ID #:	8303	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Sill -Temporary Materials	
Total Length (metres):	15.2	# Spans:	1	Span Width:			Span Length(s) (metres): 15.2
UTM Zone:	10		UTM Easting:	447559	UTM Northing:	6011058	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2017		
Access:							

ABUTMENTS		
Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Log/Timber Cribs	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Tie-backs	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES		
Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 928 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-395	Structure Name:	G4-912	Road Name:	NECOSLIE-	Inspection Date:	2021/07/09
---------	--------	-----------------	--------	------------	-----------	------------------	------------

Fender Condition	Poor	log fenders, some missing
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Fair	

DECK

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Not Applicable	
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 929 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-395	Structure Name:	G4-912	Road Name:	NECOSLIE-	Inspection Date:	2021/07/09
REPAIRS	#	Status	Priority	Estimate	Description		
	2	Required	Medium		Install approach fill		
	3	Required	Medium		Install fenders		
MONITORS	#	Description					
GENERAL	Inspector's Comment:	No significant issues. GZ					
GENERAL	PEng's Comment:	No concerns. BH					
GENERAL	Estimated Load Restriction (year):		2032		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:		L100				
GENERAL	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/06 19:48:24			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 930 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-391	Structure Name:	G5-391	Road Name:	NECOSLIE-	Inspection Date:	2019/08/12
KM:	4.00	User km:	704.00	Crossing Name:	Necoslie River	Next Inspection Date:	2022/08/12
Project File ID #:	8303	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	27.0	# Spans:	1	Span Width:			Span Length(s) (metres): 27
UTM Zone:	10		UTM Easting:	440170	UTM Northing:	6012036	
Inspector Name:	dawson smith			Year Superstructure Installed:	2004		
Access:	Special Equipment Requirement: This structure requires a ladder to inspect right abutment bearings.						

ABUTMENTS

Bearings	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Not Applicable	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	68	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 931 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-391 Structure Name: G5-391 Road Name: NECOSLIE- Inspection Date: 2019/08/12

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Good	
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	2.0	Estimated Present Water Level Width:	7.0
	Estimated High Water Level Clearance:	4.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Low	\$ 500.00	REPLACE DELINEATOR AND BRUSH

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 932 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-391	Structure Name:	G5-391	Road Name:	NECOSLIE-	Inspection Date:	2019/08/12
GENERAL	Inspector's Comment:	MISSING 1 DELINEATOR, GROUT GOOD, NEED BRUSHING					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2049	Estimated Replacement (year):			
	Current Inspection Load Rating:	68	Design Load GVW (tonnes):	68	Design Vehicle Config.:	L75	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/07 14:31:16			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 933 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-393	Structure Name:	G5-906	Road Name:	NECOSLIE-	Inspection Date:	2021/09/16
KM:	28.00	User km:		Crossing Name:	Necoslie	Next Inspection Date:	2024/09/16
Project File ID #:	8303	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:			Span Length(s) (metres): 12.2
UTM Zone:	10		UTM Easting:	443176		UTM Northing:	6014114
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	2006		
Access:							

ABUTMENTS

Bearings	Fair	Wood sill showing sign of crushing under girder
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	Wood sill showing sign of crushing under girder
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Road Surface	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 934 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-393	Structure Name:	G5-906	Road Name:	NECOSLIE-	Inspection Date:	2021/09/16
---------	--------	-----------------	--------	------------	-----------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Poor	rotting rails and riser blocks
Deck to Girder Bolts	Fair	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Nails	Fair	
Overall Deck Condition	Fair	
Running Planks	Fair	
Sub Deck	Fair	Fruiting bodies on sub deck
Ties	Fair	Some rotten on ends

SUPERSTRUCTURE

Span 1

Bracing	Fair	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.1
Estimated High Water Level Clearance:	1.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
10	Required	High		replace all mods rather than patch rails and risers

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 935 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-393	Structure Name:	G5-906	Road Name:	NECOSLIE-	Inspection Date:	2021/09/16
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Bridge in fair condition Significant rot in all wood components. Replace deck mods before industrial use. Could be downrated at any time until high priority repair items are completed. BH					
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:	68	Design Load GVW (tonnes):	68	Design Vehicle Config.:	L75	
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/06 20:53:31			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 936 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-392	Structure Name:	G5-905	Road Name:	NECOSLIE-	Inspection Date:	2021/09/16
KM:	27.80	User km:		Crossing Name:	Necoslie	Next Inspection Date:	2024/09/16
Project File ID #:	8303	Br.	07	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:	Span Length(s) (metres):		12.2
UTM Zone:	10	UTM Easting:	443056	UTM Northing:	6013270		
Inspector Name:	Dustin Anderberg			Year Superstructure Installed:	2005		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Fair	Lock blocks
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	Starting to crush under girder
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Fair	Only on left abutment
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	Chipped spalling
Posted Load Rating (Enter 0 if sign missing)	68	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 937 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-392	Structure Name:	G5-905	Road Name:	NECOSLIE-	Inspection Date:	2021/09/16			
Road Surface	Fair	Minor pot holing on both approaches								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Poor	Rotten and not functioning								
Deck to Girder Bolts	Not Applicable									
Hardware	Fair									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Fair									
Running Planks	Good									
Sub Deck	Fair	Fruiting bodies indicate rot								
Ties	Fair	Rotten ends								
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Not Applicable									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.0		Estimated Present Water Level Width:		0.0			
	Estimated High Water Level Clearance:		1.2							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	9	Required	High	\$ 1.00	Replace sub decking and cross ties.					
	10	Required	High	\$ 1.00	Replace curbs and risers. Rotting and non functional					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 938 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-392	Structure Name:	G5-905	Road Name:	NECOSLIE-	Inspection Date:	2021/09/16
---------	--------	-----------------	--------	------------	-----------	------------------	------------

MONITORS

#	Description
3	Left bank bearing sill for crushing under girder

GENERAL

Inspector's Comment:	
----------------------	--

GENERAL

PEng's Comment:	Significant rot in risers curbs and decking components. Downrate to 0 tonne to address high priority repairs.BH
-----------------	---

GENERAL

Estimated Load Restriction (year):			2040	Estimated Replacement (year):					
Current Inspection Load Rating:		0	Design Load GVW (tonnes):		68		Design Vehicle Config.:		L75
Professional Inspection Required?		No	Report Status:	Reviewed By Bruce Henderson on 2022/02/06 20:29:53					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 939 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-396	Structure Name:	G4-935	Road Name:	GORDON	Inspection Date:	2021/09/16
KM:	0.50	User km:	0.50	Crossing Name:	Un-named	Next Inspection Date:	2024/09/16
Project File ID #:	8303	Br.	23	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Steel I-beam				Right	Sill -Temporary Materials	
Total Length (metres):	18.3	# Spans:	1	Span Width:			Span Length(s) (metres): 18.3
UTM Zone:	10		UTM Easting:	445388	UTM Northing:	6014193	
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	2017		
Access:	Road deactivated. Short walk to bridge						

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	
Fill	Poor	Eroding. Hole in approach fill
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Fair	
Wing Wall	Poor	Leaning wall piles

APPROACHES

Alignment	Poor	In a hole
Bridge Ahead Signs Missing	1	High chain side
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	Reset and secure
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Poor	Eroding. Hole in left approach

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 940 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-396	Structure Name:	G4-935	Road Name:	GORDON	Inspection Date:	2021/09/16
---------	--------	-----------------	--------	------------	--------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	Minor damage on one rail and riser
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Good	
Sub Deck	Unrated	N/A
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	2.0
Estimated High Water Level Clearance:	1.2		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
4	Required	Low		add high chain sign
5	Required	Low		Replace small logs with proper sized logs and position correctly
6	Required	High		Wingwall piles to be replaced or fill to be pulled back and stream armoured.
7	Required	High		Reconstruct high chain approach and protect stream from sediment delivery

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 941 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-396	Structure Name:	G4-935	Road Name:	GORDON	Inspection Date:	2021/09/16
MONITORS	#	Description					
GENERAL	Inspector's Comment:	wingwall stability at issue.					
GENERAL	PEng's Comment:	Road approach eroding and needs re-constructing. Replace leaning wingwall or remove and armour stream with rip rap. BH					
GENERAL	Estimated Load Restriction (year):		2030		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Professional Inspection Required?		No		Report Status:		Reviewed By Bruce Henderson on 2022/02/06 21:12:30
Design Vehicle Config.:		L100					

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 942 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-018	Structure Name:	G4-018	Road Name:	BEVERLY LAKE	Inspection Date:	2002/07/23
KM:	5.60	User km:	5.60	Crossing Name:	Unnamed creek	Next Inspection Date:	2030/01/01
Project File ID #:	8671	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	500			Outlet Cover (mm):	600		
Footing Type:				Gradient (%):			
Culvert Length (metres):	12.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	466638	UTM Northing:	5976662		
Inspector Name:	Tim Silbernagel			Year Superstructure Installed:	1995		
Access:	This FSR is located 1.9 km off Highway 16 on Finmore Road. Minor culvert.						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Fair	No Comment Available -Converter.RNI
Floor	Fair	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Fair	No Comment Available -Converter.RNI
Riprap	Fair	No Comment Available -Converter.RNI
Roof	Fair	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 943 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-018	Structure Name:	G4-018	Road Name:	BEVERLY LAKE	Inspection Date:	2002/07/23			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Suggested	Medium	\$ 0.00	Span: 1.0. Debris removal. remove log from outlet.					
MONITORS	#	Description								
	1	Monitor for Beaver activity if culvert remains on register. (no beaver problems TS2002)								
GENERAL	Inspector's Comment:	nullCulvert: 2) remove log from outlet 5,6) sagged 0.2M under roadway 12) none, slow creek/swamp.								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):			2045	Estimated Replacement (year):					
	Current Inspection Load Rating:		54	Design Load GVW (tonnes):		54	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/12 16:16:58				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 944 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-400	Structure Name:	G5-400A	Road Name:	OCOCK	Inspection Date:	2020/08/18
KM:	3.60	User km:	3.60	Crossing Name:	Unnamed creek	Next Inspection Date:	2023/08/18
Project File ID #:	8722	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	18.3	# Spans:	1	Span Width:			Span Length(s) (metres): 18
UTM Zone:	10		UTM Easting:	443862	UTM Northing:	6054523	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2016		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	caps
Fill	Good	
Hardware	Good	
Piles or Posts	Good	post
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	100	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 945 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-400	Structure Name:	G5-400A	Road Name:	OCOCK	Inspection Date:	2020/08/18
---------	--------	-----------------	---------	------------	-------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Good
----------------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Nails	Good
-------	------

Overall Deck Condition	Good
------------------------	------

Running Planks	Good
----------------	------

Sub Deck	Good
----------	------

Ties	Good
------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Good
----------	------

Under Trussing	Good
----------------	------

CHANNEL

Estimated Present Water Level Depth:	0.3	Estimated Present Water Level Width:	2.0
Estimated High Water Level Clearance:	1.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:	beaver dam upstream								

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 946 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-400	Structure Name:	G5-400A	Road Name:	OCOCK	Inspection Date:	2020/08/18
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	looks good					
GENERAL	Estimated Load Restriction (year):		2050	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/02 11:57:48			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 947 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-404	Structure Name:	G5-404	Road Name:	OCOCK	Inspection Date:	2021/10/15
KM:	12.20	User km:	12.20	Crossing Name:	unknown	Next Inspection Date:	2024/10/15
Project File ID #:	8722	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	3,000			Outlet Cover (mm):	3,000		
Footing Type:	Steel Footing			Gradient (%):	1.7		
Culvert Length (metres):	29.0	Opening Height (mm):	1,910	Opening Width (mm):	3,660		
UTM Zone:	10	UTM Easting:	440059	UTM Northing:	6061490		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	2008		
Access:							

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Unrated	None
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Poor	Loosing material. Scoured below footings
Footing	Poor	Scoured under a 2m section. 8m above inlet
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Fair	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 948 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-404	Structure Name:	G5-404	Road Name:	OCOCK	Inspection Date:	2021/10/15			
Overall	Fair									
Riprap	Fair									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.3						
	Estimated High Water Level Clearance:	1.8								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	3	Required	Medium		Remove trees across the channel at outlet					
MONITORS	#	Description								
	1	Monitor scour and undermining of footing.								
GENERAL	Inspector's Comment:	Scour under footing goes to the back of the footing. Approximately 0.1m deep. It appears that the arch footing was installed above the stream thalweg								
GENERAL	PEng's Comment:	Monitor footing scour. Otherwise in good condition.BH								
GENERAL	Estimated Load Restriction (year):	2030	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100				
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/07 07:51:52						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 949 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-406	Structure Name:	G5-989	Road Name:	OCOCK	Inspection Date:	2021/09/21
KM:	13.90	User km:	13.90	Crossing Name:	Un-named Creek	Next Inspection Date:	2024/09/21
Project File ID #:	8722	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:	Span Length(s) (metres):		12
UTM Zone:	10		UTM Easting:	440081	UTM Northing:	6062856	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2016		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Poor	some out of place or missing
Posted Load Rating (Enter 0 if sign missing)	91	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 950 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-406	Structure Name:	G5-989	Road Name:	OCOCK	Inspection Date:	2021/09/21			
Road Surface		Fair	needs grading							
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Deck to Girder Bolts		Good								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Good								
Running Planks		Good								
Sub Deck		Good								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.1	Estimated Present Water Level Width:		0.1				
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	4	Required	Medium	\$ 0.00	Reposition and install missing fenders.					
	5	Required	Medium	\$ 0.00	Grade approaches					
	6	Required	Low	\$ 0.00	Add one delineator					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 951 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-406 Structure Name: G5-989 Road Name: OCOCK Inspection Date: 2021/09/21

MONITORS

Description

GENERAL

Inspector's
Comment:

needs approaches graded, end on fenders
Poor inspection but no significant issues. GZ

GENERAL

PEng's
Comment:

No concerns. BH

GENERAL

Estimated Load Restriction (year):

2030

Estimated Replacement (year):

Current Inspection Load Rating:

91

Design Load GVW (tonnes):

91

Design Vehicle Config.:

L100

Professional Inspection Required?

No

Report Status:

Reviewed By Bruce Henderson on 2022/02/07 10:19:00

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 952 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-401	Structure Name:	G5-401	Road Name:	OCOCK	Inspection Date:	2020/08/18
KM:	14.90	User km:	14.50	Crossing Name:	O'Cock River	Next Inspection Date:	2023/08/18
Project File ID #:	8722	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	900			Outlet Cover (mm):	900		
Footing Type:				Gradient (%):			
Culvert Length (metres):	49.0	Opening Height (mm):	2,400	Opening Width (mm):	2,400		
UTM Zone:	10	UTM Easting:	439842	UTM Northing:	6063725		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1991		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Poor	wilderness

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Fair	some rust, vegetation growing out of connections
Coating	Poor	floor
Embedment Materials	Not Applicable	
Fill	Good	10m, some scour
Floor	Poor	rust
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Fair	
Outlet	Poor	purchased, large water hole

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 953 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-401	Structure Name:	G5-401	Road Name:	OCOCK	Inspection Date:	2020/08/18			
Overall	Fair									
Riprap	Poor	hardly any								
Roof	Fair									
Side Walls	Poor	rust and holes at water edbe, inlet first segment								
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.0						
	Estimated High Water Level Clearance:	1.0								
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	Yes
	Comment:	scour and Aggradation at outlet								
REPAIRS	#	Status	Priority	Estimate	Description					
	2	Required	Medium		Consider replacing culvert					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	PEng. to review and recommend if PEng. inspection required. PEng inspection prior to hauling								
GENERAL	PEng's Comment:	Will look at this culvert in the summer to determine what is needed.								
GENERAL	Estimated Load Restriction (year):	2031	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100				
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/02 12:17:16						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 954 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-405	Structure Name:	G5-405	Road Name:	OCOCK	Inspection Date:	2021/09/21
KM:	21.30	User km:	21.30	Crossing Name:	Unknown	Next Inspection Date:	2024/09/21
Project File ID #:	8722	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated - Panels			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.0	# Spans:	1	Span Width:	Span Length(s) (metres):		12
UTM Zone:	10		UTM Easting:	439348	UTM Northing:	6065790	
Inspector Name:	Dawson Smith			Year Superstructure Installed:	2007		
Access:							

ABUTMENTS

Bearings	Poor	structure not sitting on sill correctly
Bracing	Not Applicable	
Ballast Wall	Poor	showing significant decay
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Poor	structure not sitting on sill correctly
Fill	Fair	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 955 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-405	Structure Name:	G5-405	Road Name:	OCOCK	Inspection Date:	2021/09/21
---------	--------	-----------------	--------	------------	-------	------------------	------------

Road Surface	Good	
--------------	------	--

DECK

Span 1

Curb Rail/Blocks/Posts	Poor	significant decay
Deck to Girder Bolts	Good	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Fair	
Running Planks	Good	
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	1.0
	Estimated High Water Level Clearance:	1.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	7	Required	High	\$	Replace curbs and risers
	8	Required	High	\$	Replace ballast walls
	9	Required	High	\$ 0.00	Install both bridge ahead signs
	10	Required	High	\$ 0.00	Brush around bridge.

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 956 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-405	Structure Name:	G5-405	Road Name:	OCOCK	Inspection Date:	2021/09/21
MONITORS	#	Description					
GENERAL	Inspector's Comment:	significant rot in guardrails and ballast walls, see pictures Load restrictions should be applied. GZ					
GENERAL	PEng's Comment:	Significant rot in curbs. Replace ballast walls and reposition sills. Bridge downrated to 10 tonnes until repairs completed. BH					
GENERAL	Estimated Load Restriction (year):		2040		Estimated Replacement (year):		
	Current Inspection Load Rating:		10		Design Load GVW (tonnes):		91
	Design Vehicle Config.:						
	Professional Inspection Required?	No	Report Status:	Reviewed By Bruce Henderson on 2022/02/07 08:35:00			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 957 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-410	Structure Name:	G5-410	Road Name:	WEST	Inspection Date:	2021/10/15
KM:	0.80	User km:	0.80	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/09/21
Project File ID #:	8722	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	19.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	440159	UTM Northing:	6058750		
Inspector Name:	Gary Zsombor			Year Superstructure Installed:	1991		
Access:	Two culverts (battery) are located on this site - culvert one is G5-410; culvert two is G5-410-2.						

APPROACHES

Alignment	Good
-----------	------

Bridge Ahead Signs Missing	0
----------------------------	---

Brushing Required	No
-------------------	----

Delineator Missing Left (approaching structure)	0
---	---

Delineator Missing Right (approaching structure)	0
--	---

CULVERT ELEMENT

Baffles	Not Applicable
---------	----------------

Bolted Connections	Not Applicable
--------------------	----------------

Coupled Connections	Good
---------------------	------

Coating	Fair
---------	------

Embedment Materials	Not Applicable
---------------------	----------------

Fill	Good
------	------

Floor	Fair
-------	------

Footing	Fair
---------	------

Head Wall	Not Applicable
-----------	----------------

Inlet	Fair	Plugged by beavers
-------	------	--------------------

Outlet	Good
--------	------

Overall	Fair	Plugged by beavers
---------	------	--------------------

Riprap	Not Applicable
--------	----------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 958 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-410	Structure Name:	G5-410	Road Name:	WEST	Inspection Date:	2021/10/15			
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:									
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	Cannot take measurements								
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Issues with Filemaker go. Cannot put in poor rating.								
GENERAL	PEng's Comment:	Used Solid soils inspection.								
GENERAL	Estimated Load Restriction (year):		2031		Estimated Replacement (year):					
	Current Inspection Load Rating:		See footnote	Design Load GVW (tonnes):		91	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Rejected By IDIR\BHENDERS on 2022/02/28 09:23:04				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 959 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-410	Structure Name:	G5-410-2	Road Name:	WEST	Inspection Date:	2021/09/21
KM:	0.80	User km:	0.80	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/09/21
Project File ID #:	8722	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	19.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	440159	UTM Northing:	6058750		
Inspector Name:	Dawson Smith			Year Superstructure Installed:	1991		
Access:	Two culverts (battery) are located on this site - culvert one is G5-410; culvert two is G5-410-2.						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 960 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-410	Structure Name:	G5-410-2	Road Name:	WEST	Inspection Date:	2021/09/21			
Inlet	Poor	Both inlets are plugged by beavers, the water has breached the road surface								
Outlet	Good									
Overall	Poor	Both inlets are plugged by beavers, the water has breached the road surface								
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.1		Estimated Present Water Level Width:	0.1					
	Estimated High Water Level Clearance:	1.5								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	Both inlets are plugged by beavers, the water has breached the road surface								
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	High	\$	Both inlets are plugged by beavers, the water has breached the road surface					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Both inlets are plugged by beavers, the water has breached the road surface								
GENERAL	PEng's Comment:	Clean both culverts. BH								

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 961 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-410	Structure Name:	G5-410-2	Road Name:	WEST	Inspection Date:	2021/09/21
GENERAL	Estimated Load Restriction (year):		2031	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Bruce Henderson on 2022/02/09 14:53:03	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 962 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-450	Structure Name:	G5-450	Road Name:	TCHEMLO	Inspection Date:	2019/10/04
KM:	5.40	User km:	5.40	Crossing Name:	Brule Creek	Next Inspection Date:	2022/10/04
Project File ID #:	9275	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	30.0	# Spans:	1	Span Width:	Span Length(s) (metres):		30
UTM Zone:	10	UTM Easting:	357797	UTM Northing:	6128033		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1992		
Access:							

ABUTMENTS

Bearings	Good
----------	------

Bracing	Not Applicable
---------	----------------

Ballast Wall	Good
--------------	------

Caps or Sills	Good
---------------	------

Fill	Good
------	------

Hardware	Not Applicable
----------	----------------

Piles or Posts	Good
----------------	------

Riprap	Good
--------	------

Wing Wall	Good
-----------	------

APPROACHES

Alignment	Good
-----------	------

Bridge Ahead Signs Missing	0
----------------------------	---

Brushing Required	No
-------------------	----

Delineator Missing Left (approaching structure)	0
---	---

Delineator Missing Right (approaching structure)	0
--	---

Fender Condition	Fair	OUT OF POSITION
------------------	------	-----------------

Posted Load Rating (Enter 0 if sign missing)	91
--	----

Road Surface	Good
--------------	------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 963 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-450	Structure Name:	G5-450	Road Name:	TCHENTLO	Inspection Date:	2019/10/04
---------	--------	-----------------	--------	------------	----------	------------------	------------

DECK

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Good
---------------	------

Hardware	Not Applicable
----------	----------------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Running Surface	Good
-----------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Not Applicable
----------	----------------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	6.0
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	3.0
---------------------------------------	-----

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
1	MONITOR BEAVER DAM BEING BUILD DOWNSTREAM

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 964 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-450	Structure Name:	G5-450	Road Name:	TCHENTLO	Inspection Date:	2019/10/04
GENERAL	Inspector's Comment:	ALL GOOD, BEAVERS HAVE STARTED A DAM APPROX. 150M DOWNSTREAM					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2032	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/04 15:34:09			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 965 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-451	Structure Name:	G5-451	Road Name:	TCHEMLO	Inspection Date:	2019/10/04
KM:	7.60	User km:	7.60	Crossing Name:	Nation River	Next Inspection Date:	2022/10/04
Project File ID #:	9275	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	55.0	# Spans:	1	Span Width:	Span Length(s) (metres):		55
UTM Zone:	10	UTM Easting:	358767	UTM Northing:	6129475		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1992		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	LOG FENDERS
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 966 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-451	Structure Name:	G5-451	Road Name:	TCHENTLO	Inspection Date:	2019/10/04
---------	--------	-----------------	--------	------------	----------	------------------	------------

DECK

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck Joints	Good
-------------	------

Grout Pockets	Good
---------------	------

Hardware	Not Applicable
----------	----------------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Not Applicable
----------	----------------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	10.0
Estimated High Water Level Clearance:	4.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 967 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-451	Structure Name:	G5-451	Road Name:	TCHENTLO	Inspection Date:	2019/10/04
GENERAL	Inspector's Comment:	ALL GOOD					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2032	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/04 15:31:46			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 968 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-452	Structure Name:	G5-452	Road Name:	TCHEMLO	Inspection Date:	2016/09/22
KM:	8.70	User km:	8.70	Crossing Name:	Unnamed creek	Next Inspection Date:	2019/09/22
Project File ID #:	9275	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	900			Outlet Cover (mm):	900		
Footing Type:				Gradient (%):			
Culvert Length (metres):	18.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	359606	UTM Northing:	6128610		
Inspector Name:	w.wilkinson			Year Superstructure Installed:	1992		
Access:	Minor culvert						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	rust on floor
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	Rust
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 969 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-452	Structure Name:	G5-452	Road Name:	TCHEMLO	Inspection Date:	2016/09/22			
Overall	Good									
Riprap	Fair									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	0.5						
	Estimated High Water Level Clearance:	1.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	No issues noted. Structure may have to switched to Do not inspect for several years. MD								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):	2032	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2017/05/02 15:24:16						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 970 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-453	Structure Name:	G5-453	Road Name:	TCHENTLO	Inspection Date:	2019/10/04
KM:	9.90	User km:	9.90	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/10/04
Project File ID #:	9275	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	16.0	Opening Height (mm):	2,000	Opening Width (mm):	2,000		
UTM Zone:	10	UTM Easting:	360026	UTM Northing:	6127650		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1992		
Access:	9.9 km T. Road						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 971 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-453	Structure Name:	G5-453	Road Name:	TCHENTLO	Inspection Date:	2019/10/04			
Overall	Good									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		0.5			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	ALL GOOD								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):		2032		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/02/07 12:29:35			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 972 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-454	Structure Name:	G5-454	Road Name:	TCHENTLO	Inspection Date:	2019/10/04
KM:	12.30	User km:	12.30	Crossing Name:	Unnamed creek	Next Inspection Date:	2022/10/04
Project File ID #:	9275	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	6,300			Outlet Cover (mm):	6,300		
Footing Type:				Gradient (%):	3.0		
Culvert Length (metres):	35.0	Opening Height (mm):	2,800	Opening Width (mm):	2,800		
UTM Zone:	10	UTM Easting:	361700	UTM Northing:	6125896		
Inspector Name:	Dawson SMITH		Year Superstructure Installed:		1992		
Access:	12.3 T. Road						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Fair	
Bolted Connections	Not Applicable	
Coupled Connections	Fair	
Coating	Fair	FLOOR HAS SOME RUST
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	FLOOR HAS SOME RUST
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 973 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-454	Structure Name:	G5-454	Road Name:	TCHENTLO	Inspection Date:	2019/10/04			
Overall	Fair									
Riprap	Not Applicable									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	1.0						
	Estimated High Water Level Clearance:	1.5								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):	2032	Estimated Replacement (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/04 15:27:53						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 974 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-455	Structure Name:	G5-455	Road Name:	TCHEMLO	Inspection Date:	2021/08/11
KM:	13.50	User km:	13.50	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/08/11
Project File ID #:	9275	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	6,700			Outlet Cover (mm):	6,700		
Footing Type:				Gradient (%):	3.0		
Culvert Length (metres):	42.0	Opening Height (mm):	3,200	Opening Width (mm):	3,200		
UTM Zone:	10	UTM Easting:	362068	UTM Northing:	6124882		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1992		
Access:							

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Good	Rust on baffles
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	Rust
Embedment Materials	Not Applicable	
Fill	Good	3m
Floor	Fair	Heavy rust
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 975 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-455	Structure Name:	G5-455	Road Name:	TCHENTLO	Inspection Date:	2021/08/11
Inlet	Good						
Outlet	Poor	Perched, scour					
Overall	Fair						
Riprap	Fair	Scour has moved riprap at outlet					
Roof	Good						
Side Walls	Fair	Rust					
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						

CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		1.5			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	Yes	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	Yes
	Comment:	High water flow has scoured outlet and created a perched outlet								
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Outlet scour does not appear to have worsened since last inspection. No concerns. JDS								

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 976 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-455	Structure Name:	G5-455	Road Name:	TCHEMLO	Inspection Date:	2021/08/11
GENERAL	Estimated Load Restriction (year):		2032	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jordan Smith on 2022/02/10 12:24:21	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 977 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-456	Structure Name:	G5-456	Road Name:	TCHENTLO	Inspection Date:	2002/06/20
KM:	17.70	User km:	17.70	Crossing Name:	Unnamed creek	Next Inspection Date:	2005/06/20
Project File ID #:	9275	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	2,000			Outlet Cover (mm):	2,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	18.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	365599	UTM Northing:	6122611		
Inspector Name:	Ed Cienciala			Year Superstructure Installed:	1992		
Access:	Minor culvert						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Good	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 978 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-456	Structure Name:	G5-456	Road Name:	TCHEMLO	Inspection Date:	2002/06/20			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Monitor for debris build-up at outlet. (OK - Chinch02)								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):		2032		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By IDIR\RMGETZLA on 2012/04/12 09:38:15			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 979 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-457	Structure Name:	G5-457	Road Name:	TCHEMLO	Inspection Date:	2021/08/11
KM:	19.60	User km:	19.60	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/08/11
Project File ID #:	9275	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	2,600			Outlet Cover (mm):	2,600		
Footing Type:				Gradient (%):	1.5		
Culvert Length (metres):	28.0	Opening Height (mm):	2,400	Opening Width (mm):	2,400		
UTM Zone:	10	UTM Easting:	367371	UTM Northing:	6122125		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1992		
Access:	19.6 km T Road						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	Could not walk through did not observe joint 1
Coating	Fair	Rust
Embedment Materials	Not Applicable	
Fill	Good	1m
Floor	Fair	Rust
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 980 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-457	Structure Name:	G5-457	Road Name:	TCHENTLO	Inspection Date:	2021/08/11			
Inlet	Fair	Beaver dam								
Outlet	Good									
Overall	Good									
Riprap	Fair	Not much								
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		1.5			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	Beaver dam at inlet								
REPAIRS	#	Status	Priority	Estimate	Description					
	5	Required	Medium	\$ 0.00	Beaver dam removal					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Beaver dam blocking inlet, debris is spilling into the inlet. Outlet partially blocked by displaced riprap. Little flow going through pipe. Consider removing dam and clearing inlet/outlet to prevent future issue. -JDS								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 981 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-457	Structure Name:	G5-457	Road Name:	TCHENTLO	Inspection Date:	2021/08/11
GENERAL	Estimated Load Restriction (year):		2032	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jordan Smith on 2022/02/10 12:32:25	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 982 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-458	Structure Name:	G5-458	Road Name:	TCHEMLO	Inspection Date:	2021/08/11
KM:	20.30	User km:	20.30	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/08/11
Project File ID #:	9275	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,660			Outlet Cover (mm):	1,660		
Footing Type:				Gradient (%):	4.0		
Culvert Length (metres):	23.0	Opening Height (mm):	2,800	Opening Width (mm):	2,800		
UTM Zone:	10	UTM Easting:	368143	UTM Northing:	6122164		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1992		
Access:							

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	1.5m
Floor	Good	some rust
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 983 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-458	Structure Name:	G5-458	Road Name:	TCHENTLO	Inspection Date:	2021/08/11
Inlet	Good						
Outlet	Poor	Perched					
Overall	Good						
Riprap	Fair						
Roof	Good	dent in roof					
Side Walls	Good						
Trash Rack	Not Applicable						
Wiers/Backwater Structures	Not Applicable						
Wing Wall	Not Applicable						

CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	Yes
	Comment:	Pool formed at outlet								
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	No concerns. JDS								

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 984 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-458	Structure Name:	G5-458	Road Name:	TCHENTLO	Inspection Date:	2021/08/11
GENERAL	Estimated Load Restriction (year):		2032	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jordan Smith on 2022/02/10 12:36:48	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 985 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-459	Structure Name:	G5-459	Road Name:	TCHENTLO	Inspection Date:	2021/08/11
KM:	24.10	User km:	24.10	Crossing Name:	Unnamed creek	Next Inspection Date:	2024/08/11
Project File ID #:	9275	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,150			Outlet Cover (mm):	1,150		
Footing Type:				Gradient (%):	4.0		
Culvert Length (metres):	21.0	Opening Height (mm):	2,400	Opening Width (mm):	2,400		
UTM Zone:	10	UTM Easting:	371452	UTM Northing:	6122670		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1992		
Access:							

APPROACHES

Alignment Fair

Bridge Ahead Signs Missing 2

Brushing Required Yes

Delineator Missing Left (approaching structure) 2

Fender Condition None

Posted Load Rating (Enter 0 if sign missing) 0

Road Surface Good

CULVERT ELEMENT

Baffles Not Applicable

Bolted Connections Not Applicable

Coupled Connections Good

Coating Fair

Embedment Materials Not Applicable

Fill Good 1m

Floor Fair Rust

Footing Not Applicable

Head Wall Not Applicable

Inlet Good Riprap in culvert

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 986 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-459	Structure Name:	G5-459	Road Name:	TCHENTLO	Inspection Date:	2021/08/11			
Outlet	Good	Material building up on outlet floor								
Overall	Good									
Riprap	Good	Some has fallen into culvert in past								
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	No concerns. JDS								
GENERAL	Estimated Load Restriction (year):		2032		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jordan Smith on 2022/02/10 12:39:02			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 987 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-460	Structure Name:	G5-460	Road Name:	TCHEMLO	Inspection Date:	2019/10/04
KM:	37.20	User km:	37.20	Crossing Name:	Ahdatay Creek	Next Inspection Date:	2022/10/04
Project File ID #:	9275	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	21.0	# Spans:	1	Span Width:	Span Length(s) (metres):		21
UTM Zone:	10	UTM Easting:	382557	UTM Northing:	6123218		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1993		
Access:	No load limit concerns. Nov/05						

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Fair	WHAT I COULD SEE
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Fair	
Wing Wall	Good	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	91	
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 988 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-460	Structure Name:	G5-460	Road Name:	TCHENTLO	Inspection Date:	2019/10/04
---------	--------	-----------------	--------	------------	----------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Excellent	SOME RECENTLY REPLACED
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	1.5	Estimated Present Water Level Width:	4.0
	Estimated High Water Level Clearance:	3.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 989 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-460	Structure Name:	G5-460	Road Name:	TCHENTLO	Inspection Date:	2019/10/04
GENERAL	Inspector's Comment:	NEW GUARDRAILS					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2033	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/04 15:25:49			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 990 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-182	Structure Name:	G5-101	Road Name:	Jess	Inspection Date:	2020/10/15
KM:	0.50	User km:		Crossing Name:	Unnamed Creek	Next Inspection Date:	2023/10/15
Project File ID #:	9305	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	10.3	# Spans:	1	Span Width:			Span Length(s) (metres): 10.3
UTM Zone:	10	UTM Easting:	410668	UTM Northing:	6046779		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:			
Access:	Structure found in 2019.						

ABUTMENTS

Bearings	Fair	sunk into sill timber or recessed into sill timber
Bracing	Not Applicable	
Ballast Wall	Fair	
Concrete Lock Blocks	Poor	movement of lock blocks on left abutment, some movement on right abutment
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	some soft spots, broken \ bent on left abutment, split on end on right abutment
Fill	Fair	settling at edge of bridge left side
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Poor	on corners both sides
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	30	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 991 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-182	Structure Name:	G5-101	Road Name:	Jess	Inspection Date:	2020/10/15
---------	--------	-----------------	--------	------------	------	------------------	------------

Road Surface	Poor	Wilderness
--------------	------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	rot found
Deck to Girder Bolts	Not Applicable	none found
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Poor	running deck rot
Overall Deck Condition	Fair	
Running Planks	Poor	Rotting
Sub Deck	Fair	Creosote treated
Ties	Fair	Creosote treated

SUPERSTRUCTURE

Span 1

Bracing	Fair	some bent
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Fair	

CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.0
	Estimated High Water Level Clearance:	0.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Low	\$ 100.00	Delineator
	2	Required	Low	\$	Bridge ahead signs
	3	Required	Low	\$	Replace Deck prior to hualing
	4	Required	Low	\$	Re-set lock blocks prior to hauling

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 992 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-182 Structure Name: G5-101 Road Name: Jess Inspection Date: 2020/10/15

MONITORS

#	Description
1	Sill timbers for rot and further bending \ breaks
2	Shifting of lock blocks

GENERAL

Inspector's Comment:	found bridge 2019, first inspection 2020
----------------------	--

GENERAL

PEng's Comment:	If lock blocks appear to be moving than the bridge should be closed.
-----------------	--

GENERAL

Estimated Load Restriction (year):	2020	Estimated Replacement (year):	
Current Inspection Load Rating:	10	Design Load GVW (tonnes):	
Design Vehicle Config.:			
Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/19 11:52:10

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 993 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-500	Structure Name:	G5-500	Road Name:	INZANA	Inspection Date:	2000/09/07
KM:	2.90	User km:	2.90	Crossing Name:	Inzana Creek Tributary	Next Inspection Date:	2030/01/01
Project File ID #:	9345	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):	1.5		
Culvert Length (metres):	21.0	Opening Height (mm):	1,400	Opening Width (mm):	1,400		
UTM Zone:	10	UTM Easting:	410806	UTM Northing:	6091153		
Inspector Name:	Brent Case			Year Superstructure Installed:	1993		
Access:	Coordinates from LRM twin 1400, minor crossing						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Riprap	Good	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 994 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-500	Structure Name:	G5-500	Road Name:	INZANA	Inspection Date:	2000/09/07			
CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		0.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	H.C. pipe has some separation at connection - Monitor.								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):			2043	Estimated Replacement (year):					
	Current Inspection Load Rating:		68	Design Load GVW (tonnes):		68	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Accepted By Raymond Getzlaf on 2012/04/10 00:00:00				

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 995 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-501	Structure Name:	G5-501	Road Name:	INZANA	Inspection Date:	2021/07/07
KM:	3.20	User km:	3.20	Crossing Name:	Inzana Creek	Next Inspection Date:	2023/07/07
Project File ID #:	9345	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Steel I-beam				Right	Crib, Log or Untreated Timber	
Total Length (metres):	16.2	# Spans:	1	Span Width:			Span Length(s) (metres): 9
UTM Zone:	10		UTM Easting:	410756	UTM Northing:	6091473	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2011		
Access:	Germansen North Road about km 58 Left onto Inzana Main km 69 right						

ABUTMENTS

Bearings	Poor	Sinking into rotting sill logs
Bracing	Not Applicable	
Ballast Wall	Poor	Logs rotting
Corrosion Protection	Not Applicable	
Caps or Sills	Poor	Logs rotting
Fill	Fair	
Hardware	Not Applicable	
Log/Timber Cribs	Unrated	N/A
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Tie-backs	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	Corner Right Side
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	1	
Fender Condition	None	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 996 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-501	Structure Name:	G5-501	Road Name:	INZANA	Inspection Date:	2021/07/07			
Posted Load Rating (Enter 0 if sign missing)	30	30000kg								
Road Surface	Fair	Wilderness								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Fair	Rot								
Deck to Girder Bolts	Good									
Hardware	Fair									
Hand Rails/Walkouts	Not Applicable									
Nails	Fair									
Overall Deck Condition	Poor	Large amounts of rot, missing running planks								
Running Planks	Not Applicable	Rotting - several holes in deck								
Sub Deck	Poor	Rotting - several holes in deck								
Ties	Fair									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Not Applicable									
Under Trussing	Good									
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		1.5			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	15	Required	High		Deck system and abutments need replacement.					

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 997 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-501	Structure Name:	G5-501	Road Name:	INZANA	Inspection Date:	2021/07/07
---------	--------	-----------------	--------	------------	--------	------------------	------------

MONITORS

#	Description

GENERAL

Inspector's Comment:	PEng to review recommend reduction to 5 ton
----------------------	---

GENERAL

PEng's Comment:	Downrated to 5 tonnes due to condition of deck system and rotten sill logs. JDS
-----------------	---

GENERAL

Estimated Load Restriction (year):	2025	Estimated Replacement (year):			
Current Inspection Load Rating:	5	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100
Professional Inspection Required?	No	Report Status:	Reviewed By Jordan Smith on 2022/02/10 13:07:41		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 998 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-482	Structure Name:	G5-482	Road Name:	SUSTUT	Inspection Date:	2019/06/25
KM:	2.00	User km:	0.20	Crossing Name:	Theresa Creek	Next Inspection Date:	2022/06/25
Project File ID #:	9388	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	12.0	# Spans:	1	Span Width:			Span Length(s) (metres): 12
UTM Zone:	9		UTM Easting:	421779	UTM Northing:	6244393	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1996		
Access:							

ABUTMENTS

Bearings	Good
Bracing	Not Applicable
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Good
Piles or Posts	Good
Riprap	Good
Wing Wall	Not Applicable

APPROACHES

Alignment	Fair
Bridge Ahead Signs Missing	2
Brushing Required	Yes
Delineator Missing Left (approaching structure)	2
Delineator Missing Right (approaching structure)	2
Fender Condition	Fair
Posted Load Rating (Enter 0 if sign missing)	0 None
Road Surface	Poor wilderness

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 999 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-482	Structure Name:	G5-482	Road Name:	SUSTUT	Inspection Date:	2019/06/25
---------	--------	-----------------	--------	------------	--------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	rot
Deck Joints	Fair	
Grout Pockets	Unrated	can not see do to dirt
Hardware	Fair	some bolts are loose from rot
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.3	Estimated Present Water Level Width:	1.0
Estimated High Water Level Clearance:	1.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$ 0.00	Curbs need replacing

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1000 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-482	Structure Name:	G5-482	Road Name:	SUSTUT	Inspection Date:	2019/06/25
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2036	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/03 11:26:34			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 1001 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-486	Structure Name:	G5-486	Road Name:	SUSTUT	Inspection Date:	2019/06/25
KM:	3.00	User km:	1.10	Crossing Name:	Boyd Creek	Next Inspection Date:	2022/06/25
Project File ID #:	9388	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	18.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	9	UTM Easting:	422793	UTM Northing:	6244406		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1996		
Access:	Minor culvert						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	0	None
Road Surface	Poor	wilderness

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Poor	rusty
Footing	Not Applicable	
Head Wall	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 1002 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-486	Structure Name:	G5-486	Road Name:	SUSTUT	Inspection Date:	2019/06/25			
Inlet	Good									
Outlet	Poor	perched								
Overall	Fair									
Riprap	Fair									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		0.3			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Culvert is being removed for Major Structure inspection list because under 2000mm. This culvert should be inspected during the road inspections.								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 1003 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-486	Structure Name:	G5-486	Road Name:	SUSTUT	Inspection Date:	2019/06/25
GENERAL	Estimated Load Restriction (year):		2036	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status: Reviewed By Jason Olmsted on 2020/02/07 12:45:35			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1004 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-480	Structure Name:	G5-480	Road Name:	SUSTUT	Inspection Date:	2019/06/25
KM:	1.80	User km:	1.80	Crossing Name:	Minaret Creek	Next Inspection Date:	2022/06/25
Project File ID #:	9388	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	15.0	# Spans:	1	Span Width:	Span Length(s) (metres):		15
UTM Zone:	9	UTM Easting:	420114	UTM Northing:	6245352		
Inspector Name:	Warren Wilinsons \ Scott			Year Superstructure Installed:	1996		
Access:							

ABUTMENTS

Bearings	Fair	right downstream bearing pad being compressed
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	none	
Road Surface	Poor	wilderness leavel road

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1005 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-480	Structure Name:	G5-480	Road Name:	SUSTUT	Inspection Date:	2019/06/25
---------	--------	-----------------	--------	------------	--------	------------------	------------

DECK

Span 1

Concrete Deck	Good	vegetation taking foot hold in dirt on deck
Curb Rail/Blocks/Posts	Poor	Some rot found, post and curbs, broken post
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	

SUPERSTRUCTURE

Span 1

Bracing	Not Applicable	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Good	

CHANNEL

Estimated Present Water Level Depth:		Estimated Present Water Level Width:	
Estimated High Water Level Clearance:			

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	High	\$ 0.00	Replace Curbs

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1006 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-480	Structure Name:	G5-480	Road Name:	SUSTUT	Inspection Date:	2019/06/25
GENERAL	Inspector's Comment:	Wilkinson Training Atkinson Limited or no traffic on this wilderness level Road, no access for vehicles to access this road system					
GENERAL	PEng's Comment:	Placing 30 Tonne Load Limit until curbs are replaced					
GENERAL	Estimated Load Restriction (year):		2036	Estimated Replacement (year):			
	Current Inspection Load Rating:	30	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/01/24 12:01:14			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1007 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-481	Structure Name:	G5-481	Road Name:	SUSTUT	Inspection Date:	2019/06/25
KM:	4.00	User km:	2.20	Crossing Name:	Islam Creek	Next Inspection Date:	2022/06/25
Project File ID #:	9388	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	18.0	# Spans:	1	Span Width:	Span Length(s) (metres):		18
UTM Zone:	9	UTM Easting:	423714	UTM Northing:	6244018		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1996		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	0	None
Road Surface	Poor	Wilderness

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1008 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-481	Structure Name:	G5-481	Road Name:	SUSTUT	Inspection Date:	2019/06/25
---------	--------	-----------------	--------	------------	--------	------------------	------------

DECK

Span 1

Concrete Deck	Fair	Dirt on deck and tress growing
Curb Rail/Blocks/Posts	Poor	broken and rotting
Deck Joints	Fair	Cracks
Grout Pockets	Good	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Good
Diaphragms	Good
Girders	Good
Hardware	Good
Under Trussing	Good

CHANNEL

Estimated Present Water Level Depth:	3.0	Estimated Present Water Level Width:	5.0
Estimated High Water Level Clearance:	1.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Medium	\$ 0.00	Fix Broken Curb Section or Replace all the Curbs

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1009 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-481	Structure Name:	G5-481	Road Name:	SUSTUT	Inspection Date:	2019/06/25
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2036	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/03 11:32:39			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1010 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-483	Structure Name:	G5-483	Road Name:	SUSTUT	Inspection Date:	2019/06/25
KM:	6.00	User km:	4.00	Crossing Name:	Chelsey Creek	Next Inspection Date:	2022/06/25
Project File ID #:	9388	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	18.0	# Spans:	1	Span Width:	Span Length(s) (metres):		18
UTM Zone:	9	UTM Easting:	425381	UTM Northing:	6244050		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1996		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	0	None
Road Surface	Poor	wilderness

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1011 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-483	Structure Name:	G5-483	Road Name:	SUSTUT	Inspection Date:	2019/06/25
---------	--------	-----------------	--------	------------	--------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	rotting
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Poor	loose from rot
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Good	

CHANNEL

Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	3.0
Estimated High Water Level Clearance:	1.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$ 0.00	Replace curbs

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1012 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-483	Structure Name:	G5-483	Road Name:	SUSTUT	Inspection Date:	2019/06/25
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2036	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/03 11:21:13			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 1013 of 1106

Date Printed: 2022/03/16

User Id: IDIR\WWILKINS

Database: PROD

Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-484	Structure Name:	G5-484	Road Name:	SUSTUT	Inspection Date:	2019/06/26
KM:	11.40	User km:	11.40	Crossing Name:	Laura Creek	Next Inspection Date:	2022/06/26
Project File ID #:	9388	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	18.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	9	UTM Easting:	431579	UTM Northing:	6242833		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1997		
Access:	Minor culvert						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Poor	Wilderness

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	
Embedment Materials	Not Applicable	culvert is naturally filling in with material
Fill	Good	
Floor	Fair	some rust \ filling with sediment
Footing	Not Applicable	
Head Wall	Good	
Inlet	Good	
Outlet	Good	partly restricted channel

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 1014 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-484	Structure Name:	G5-484	Road Name:	SUSTUT	Inspection Date:	2019/06/26			
Overall	Good									
Riprap	Good	limmited								
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Good									
CHANNEL	Estimated Present Water Level Depth:		0.0		Estimated Present Water Level Width:		0.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):		2037		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/01/14 15:14:45			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1015 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-485	Structure Name:	G5-485	Road Name:	SUSTUT	Inspection Date:	2019/06/26	
KM:	12.50	User km:	12.50	Crossing Name:	Birdflat Creek	Next Inspection Date:	2022/06/26	
Project File ID #:	9388	Br.	01	Forest District:	Stuart Nechako Natural Resource District			
Deck Type:	Concrete Composite			Running Surface:	Not Available			
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials		
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials		
Total Length (metres):	55.3	# Spans:	2	Span Width:			Span Length(s) (metres):	27.6, 27.6
UTM Zone:	9		UTM Easting:	432420		UTM Northing:	6242789	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1997			
Access:								

ABUTMENTS

Bearings	Good
Bracing	Good
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Excellent
Hardware	Good
Piles or Posts	Good
Riprap	Good
Wing Wall	Not Applicable

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Good	
Road Surface	Poor	Wilderness

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1016 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-485	Structure Name:	G5-485	Road Name:	SUSTUT	Inspection Date:	2019/06/26
---------	--------	-----------------	--------	------------	--------	------------------	------------

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	rotting
Deck Joints	Poor	Cracking and spalling
Grout Pockets	Good	
Hardware	Poor	loose from rotting timbers
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	

PIERS

Pier 1

Bearings	Good	
Bracing or Sheathing	Good	
Caps	Good	
Cribs	Not Applicable	
Dolphins	Good	
Hardware	Good	
Overall	Good	
Piles or Posts	Good	
Riprap	Not Applicable	
Wall	Not Applicable	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1017 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-485	Structure Name:	G5-485	Road Name:	SUSTUT	Inspection Date:	2019/06/26
CHANNEL	Estimated Present Water Level Depth:		1.0		Estimated Present Water Level Width:		6.0
	Estimated High Water Level Clearance:		3.0				
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris: No
	Aggradation:	No					
REPAIRS	Comment:						
	#	Status	Priority	Estimate	Description		
	1	Required	High	\$ 0.00	Repair grout joints		
	2	Required	High	\$ 0.00	Replace curbs		
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Load Rate to 5 tonnes until curbs are replaced and the grout joints are repaired.					
GENERAL	Estimated Load Restriction (year):			2037	Estimated Replacement (year):		
	Current Inspection Load Rating:		5	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status: Reviewed By Jason Olmsted on 2020/01/24 12:42:49			

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1018 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-487	Structure Name:	G5-487	Road Name:	SUSTUT	Inspection Date:	2019/06/25
KM:	19.00	User km:	19.00	Crossing Name:	February Creek	Next Inspection Date:	2022/06/25
Project File ID #:	9388	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	18.7	# Spans:	1	Span Width:			Span Length(s) (metres): 18.7
UTM Zone:	9		UTM Easting:	436917		UTM Northing:	6242426
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1999		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Good	sill
Fill	Good	
Hardware	Good	
Piles or Posts	Good	pile
Riprap	Good	some signs of scower
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	corner
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	
Posted Load Rating (Enter 0 if sign missing)	0	None
Road Surface	Poor	wilderness

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1019 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-487	Structure Name:	G5-487	Road Name:	SUSTUT	Inspection Date:	2019/06/25
---------	--------	-----------------	--------	------------	--------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	Rot left downstream missing bolt
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Good	

CHANNEL	Estimated Present Water Level Depth:	3.0	Estimated Present Water Level Width:	4.0
	Estimated High Water Level Clearance:	1.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Medium	\$ 0.00	Repair Curb or replace all curbs

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1020 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-487	Structure Name:	G5-487	Road Name:	SUSTUT	Inspection Date:	2019/06/25
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2049	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/03 11:16:37			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1021 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-491	Structure Name:	G5-491	Road Name:	SUSTUT	Inspection Date:	2019/06/26
KM:	19.40	User km:	19.40	Crossing Name:	Unnamed Creek	Next Inspection Date:	2022/06/26
Project File ID #:	9388	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	17.9	# Spans:	1	Span Width:	Span Length(s) (metres):		17.9
UTM Zone:	9	UTM Easting:	622762	UTM Northing:	6243586		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2001		
Access:	Fly-in only.						

ABUTMENTS

Bearings	Fair	left side may be compressing rubber pads
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	sill
Fill	Good	
Hardware	Good	
Piles or Posts	Good	piles
Riprap	Fair	Scour around ends
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Poor	wilderness

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1022 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #: G5-491 Structure Name: G5-491 Road Name: SUSTUT Inspection Date: 2019/06/26

DECK

Span 1

Concrete Deck	Good	dirt with organics
Curb Rail/Blocks/Posts	Fair	some rot found
Deck Joints	Good	
Grout Pockets	Fair	flaking of surface of grout
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Good	

CHANNEL	Estimated Present Water Level Depth:	0.3	Estimated Present Water Level Width:	3.0
	Estimated High Water Level Clearance:	1.0		

HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	dead pine under bridge								

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Low	\$	replace curbs
	2	Required	Low	\$	clean deck

MONITORS	#	Description
	1	Grout pockets

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1023 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-491	Structure Name:	G5-491	Road Name:	SUSTUT	Inspection Date:	2019/06/26
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2041	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/03/09 10:19:19			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1024 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-492	Structure Name:	G5-492	Road Name:	SUSTUT	Inspection Date:	2019/06/26
KM:	20.80	User km:	20.80	Crossing Name:	Unnamed Creek	Next Inspection Date:	2022/06/26
Project File ID #:	9388	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Steel Pipe and Precast Pad	
Superstructure:	Steel I-beam				Right	Steel Pipe and Precast Pad	
Total Length (metres):	15.6	# Spans:	1	Span Width:			Span Length(s) (metres): 15.6
UTM Zone:	9	UTM Easting:	623984	UTM Northing:	6242861		
Inspector Name:	Colton Polson			Year Superstructure Installed:	2001		
Access:	Fly-in only.						

ABUTMENTS

Bearings	Poor	left - delaminating / squished, right failed due to cap lean
Bracing	Not Applicable	
Ballast Wall	Good	some localized spalding at girder end
Corrosion Protection	Not Applicable	
Caps or Sills	Poor	right cap lean 12, left ok
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	one laying on ground one missing
Brushing Required	Yes	bridge completely overgrown
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Fair	missing transition nose
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Poor	wilderness, needs grading

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1025 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-492	Structure Name:	G5-492	Road Name:	SUSTUT	Inspection Date:	2019/06/26
---------	--------	-----------------	--------	------------	--------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	rotten
Deck Joints	Good	
Grout Pockets	Not Applicable	covered in moss
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	
Running Surface	Poor	moss on sides

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	welded
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.5
Estimated High Water Level Clearance:	1.8		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	High	\$	replace bearing pad
2	Required	High	\$	reset left abutment to plum

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1026 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-492	Structure Name:	G5-492	Road Name:	SUSTUT	Inspection Date:	2019/06/26
GENERAL	Inspector's Comment:	recommend 5 ton load, cap lean needs to be fixed prior to any use. may be a global soil move or terrain issue causing lean of sill cap\piles, bearing belt\pad damaged.					
GENERAL	PEng's Comment:	Bridge to be posted at 5 tonnes until all the repairs are completed. There is an structural issue with this bridge.					
GENERAL	Estimated Load Restriction (year):		2041	Estimated Replacement (year):			
	Current Inspection Load Rating:	5	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/07 12:37:40			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1027 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-488	Structure Name:	G5-488	Road Name:	SUSTUT NORTH	Inspection Date:	2019/06/25
KM:	0.70	User km:	0.70	Crossing Name:	Sustut River	Next Inspection Date:	2022/06/25
Project File ID #:	9388	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Sill - Permanent Materials	
Superstructure:	Steel I-beam				Right	Sill - Permanent Materials	
Total Length (metres):	173.	# Spans:	3	Span Width:	Span Length(s) (metres):		45.1, 65, 63.4
UTM Zone:	9	UTM Easting:	431790	UTM Northing:	6242025		
Inspector Name:	Colton Polson		Year Superstructure Installed:	2003			
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	0	None
Road Surface	Fair	Wilderness

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1028 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-488	Structure Name:	G5-488	Road Name:	SUSTUT NORTH	Inspection Date:	2019/06/25
---------	--------	-----------------	--------	------------	--------------	------------------	------------

DECK

Span 1

Concrete Deck	Fair	Moss on deck
Curb Rail/Blocks/Posts	Good	
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Good	
Hand Rails/Walkouts	Good	
Overall Deck Condition	Good	

Span 2

Concrete Deck	Fair	Moss on deck
Curb Rail/Blocks/Posts	Good	
Deck Joints	Good	Finger joint in good condition
Grout Pockets	Good	
Hardware	Good	
Hand Rails/Walkouts	Good	
Overall Deck Condition	Good	drain spouts broken, drains still fuction

Span 3

Concrete Deck	Fair	Moss on deck
Curb Rail/Blocks/Posts	Good	
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Good	
Hand Rails/Walkouts	Good	
Overall Deck Condition	Good	

PIERS

Pier 1

Bearings	Good	
Bracing or Sheathing	Good	
Caps	Good	
Cribs	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1029 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-488	Structure Name:	G5-488	Road Name:	SUSTUT NORTH	Inspection Date:	2019/06/25
Dolphins	Not Applicable						
Hardware	Good						
Overall	Good						
Piles or Posts	Good						
Riprap	Not Applicable						
Wall	Not Applicable						
Pier 2							
Bearings	Good						
Bracing or Sheathing	Good						
Caps	Good						
Cribs	Not Applicable						
Dolphins	Not Applicable						
Hardware	Good						
Overall	Good						
Piles or Posts	Good						
Riprap	Not Applicable						
Wall	Not Applicable						
SUPERSTRUCTURE							
Span 1							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Good						
Under Trussing	Not Applicable						
Span 2							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Good						
Under Trussing	Not Applicable						
Span 3							

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1030 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-488	Structure Name:	G5-488	Road Name:	SUSTUT NORTH	Inspection Date:	2019/06/25			
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		2.0		Estimated Present Water Level Width:		5.0			
	Estimated High Water Level Clearance:		20.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	Yes	Debris:	No	Aggradation:	No
	Comment:	Canyon								
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	bridge in good condition. schedule for drone inspection.								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):		2053		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2020/02/03 11:12:49			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1031 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-489	Structure Name:	G5-489	Road Name:	SUSTUT	Inspection Date:	2016/09/12
KM:	2.50	User km:		Crossing Name:	unknown	Next Inspection Date:	2022/08/01
Project File ID #:	9388	Br.	03	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	7.5	# Spans:	1	Span Width:	Span Length(s) (metres):		1
UTM Zone:	9	UTM Easting:	619233	UTM Northing:	6242008		
Inspector Name:	Vince Sewell			Year Superstructure Installed:	2009		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Poor	Untreated logs, soft with lots of fungus
Concrete Lock Blocks	Fair	High chain middle 2 blocks are low
Corrosion Protection	Good	
Caps or Sills	Good	
Fill	Good	
Hardware	Fair	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	prior to industrial use
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Fair	
Road Surface	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1032 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-489	Structure Name:	G5-489	Road Name:	SUSTUT	Inspection Date:	2016/09/12
---------	--------	-----------------	--------	------------	--------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Fair	
Overall Deck Condition	Fair	
Running Planks	Poor	Soft with fungus, replace prior to industrial use
Ties	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	1.5
Estimated High Water Level Clearance:	1.2		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Medium	\$ 1.00	Replace deck and ballast walls prior to industrial use. MD

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1033 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-489	Structure Name:	G5-489	Road Name:	SUSTUT	Inspection Date:	2016/09/12
GENERAL	Inspector's Comment:	Deck and ballast walls rotting, high chain lock blocks settling. Recommend assigning low load rating until structure loading is proven and repairs completed. MD					
GENERAL	PEng's Comment:	Need to confirm load capacity of structure.					
GENERAL	Estimated Load Restriction (year):		2020	Estimated Replacement (year):			
	Current Inspection Load Rating:	30	Design Load GVW (tonnes):		Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2017/05/02 15:29:32			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1034 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-493	Structure Name:	G5-493	Road Name:	SUSTUT SOUTH	Inspection Date:	2019/06/26
KM:	0.40	User km:	0.40	Crossing Name:	Unnamed Creek	Next Inspection Date:	2022/06/26
Project File ID #:	9388	Br.	04	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	27.0	# Spans:	1	Span Width:			Span Length(s) (metres): 17.9
UTM Zone:	9	UTM Easting:	616751	UTM Northing:	6242674		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2003		
Access:	Fly-in only.						

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Fair	some movement on right abutment
Corrosion Protection	Not Applicable	
Caps or Sills	Good	caps
Fill	Good	
Hardware	Good	
Piles or Posts	Good	piles
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Fair	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Fair	wilderness

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1035 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-493	Structure Name:	G5-493	Road Name:	SUSTUT SOUTH	Inspection Date:	2019/06/26
---------	--------	-----------------	--------	------------	--------------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Poor	Rotten, replace
Deck to Girder Bolts	Poor	most clips missing
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Nails	Poor	due to deck rot
Overall Deck Condition	Poor	rotting components
Running Planks	Poor	Rotten, replace
Sub Deck	Poor	Rotten, replace
Ties	Poor	Rotten, replace

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.0	Estimated Present Water Level Width:	1.0
Estimated High Water Level Clearance:	3.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	High	\$	replace all deck components, deck modules

MONITORS

#	Description
1	right abutment \ ballast wall

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1036 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-493	Structure Name:	G5-493	Road Name:	SUSTUT SOUTH	Inspection Date:	2019/06/26
GENERAL	Inspector's Comment:	down rate to 5 ton untill deck replacement					
GENERAL	PEng's Comment:	Bridge to be posted at 5 tonnes until deck is replaced.					
GENERAL	Estimated Load Restriction (year):		2043	Estimated Replacement (year):			
	Current Inspection Load Rating:	5	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/03/05 11:37:52			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1037 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-427	Structure Name:	G5-427	Road Name:	ROTTAKER	Inspection Date:	2019/10/04
KM:	1.40	User km:	1.40	Crossing Name:	Rottacker Creek	Next Inspection Date:	2022/10/04
Project File ID #:	9487	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete Removable			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	25.0	# Spans:	1	Span Width:	Span Length(s) (metres):		25
UTM Zone:	10	UTM Easting:	358885	UTM Northing:	6130631		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1994		
Access:							

ABUTMENTS

Bearings	Good
----------	------

Bracing	Not Applicable
---------	----------------

Ballast Wall	Good
--------------	------

Corrosion Protection	Not Applicable
----------------------	----------------

Caps or Sills	Good
---------------	------

Fill	Good
------	------

Hardware	Not Applicable
----------	----------------

Piles or Posts	Good
----------------	------

Riprap	Good
--------	------

Wing Wall	Good
-----------	------

APPROACHES

Alignment	Good
-----------	------

Bridge Ahead Signs Missing	2
----------------------------	---

Brushing Required	No
-------------------	----

Delineator Missing Left (approaching structure)	2
---	---

Delineator Missing Right (approaching structure)	2
--	---

Fender Condition	Fair	LOG FENDERS
------------------	------	-------------

Road Surface	Good
--------------	------

DECK

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1038 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-427	Structure Name:	G5-427	Road Name:	ROTTAKER	Inspection Date:	2019/10/04
---------	--------	-----------------	--------	------------	----------	------------------	------------

Span 1

Concrete Deck	Good
---------------	------

Curb Rail/Blocks/Posts	Good
------------------------	------

Deck to Girder Bolts	Not Applicable
----------------------	----------------

Deck Joints	Good
-------------	------

Grout Pockets	Good
---------------	------

Hardware	Not Applicable
----------	----------------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Not Applicable
----------	----------------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	4.0
Estimated High Water Level Clearance:	4.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$ 500.00	INSTALL BRIDGE SIGNS AND DELINEATEORS

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1039 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-427	Structure Name:	G5-427	Road Name:	ROTTAKER	Inspection Date:	2019/10/04
GENERAL	Inspector's Comment:	ALL GOOD EXCEPT NO SIGNS OR DELINIATORS					
GENERAL	PEng's Comment:	will do a field review this summer to see if there are any serious issues with the grout pockets and girders.					
GENERAL	Estimated Load Restriction (year):		2034	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2020/02/07 13:52:57			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1040 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-506	Structure Name:	G5-506	Road Name:	EAGLE	Inspection Date:	2020/09/22
KM:	16.50	User km:	16.50	Crossing Name:	Eagle Creek	Next Inspection Date:	2023/09/22
Project File ID #:	9532	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	21.0	# Spans:	1	Span Width:	Span Length(s) (metres):		21
UTM Zone:	10	UTM Easting:	393993	UTM Northing:	6093573		
Inspector Name:	vince Sewell		Year Superstructure Installed:	2000			
Access:	This structure was reported as deactivated, but is still installed at this site. 516.5 Km Inzana Lake west FSR.						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	1	High chain
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1041 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-506	Structure Name:	G5-506	Road Name:	EAGLE	Inspection Date:	2020/09/22
---------	--------	-----------------	--------	------------	-------	------------------	------------

DECK

Span 1

Concrete Deck	Good	some dirt, could be swept
---------------	------	---------------------------

Curb Rail/Blocks/Posts	Good	
------------------------	------	--

Deck Joints	Good	
-------------	------	--

Grout Pockets	Good	
---------------	------	--

Hardware	Good	
----------	------	--

Hand Rails/Walkouts	Not Applicable	
---------------------	----------------	--

Overall Deck Condition	Good	
------------------------	------	--

SUPERSTRUCTURE

Span 1

Bracing	Good	
---------	------	--

Diaphragms	Good	
------------	------	--

Girders	Good	
---------	------	--

Hardware	Good	
----------	------	--

Under Trussing	Not Applicable	
----------------	----------------	--

CHANNEL

Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	3.5
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	2.5		
---------------------------------------	-----	--	--

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
---	--------	----------	----------	-------------

MONITORS

#	Description
---	-------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1042 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-506	Structure Name:	G5-506	Road Name:	EAGLE	Inspection Date:	2020/09/22
GENERAL	Inspector's Comment:	5458'39.8" x 12439'23.6					
GENERAL	PEng's Comment:	looks good					
GENERAL	Estimated Load Restriction (year):		2050	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:		
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/02 12:36:44			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1043 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-505	Structure Name:	G5-505	Road Name:	EAGLE	Inspection Date:	2021/07/21
KM:	9.10	User km:	20.00	Crossing Name:	Un-named Creek	Next Inspection Date:	2024/07/21
Project File ID #:	9532	Br.	02	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Curb Type:				Abutments (looking downstream)	Left	Pile -Permanent Materials	
Superstructure:	Steel I-beam				Right	Pile -Permanent Materials	
Total Length (metres):	15.0	# Spans:	1	Span Width:	Span Length(s) (metres):		15
UTM Zone:	10	UTM Easting:	396670	UTM Northing:	6092255		
Inspector Name:	Warren Wilkinson		Year Superstructure Installed:	1996			
Access:	Deactivation planned for 2020, did not occur. GZ						

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	Post
Riprap	Fair	Loose not locked in together well
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	1	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	Rotted Away
Posted Load Rating (Enter 0 if sign missing)	0	
Road Surface	Poor	Wilderness level

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1044 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-505	Structure Name:	G5-505	Road Name:	EAGLE	Inspection Date:	2021/07/21
---------	--------	-----------------	--------	------------	-------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Fair	some rot, overall solid
Deck Joints	Good	gaps at ballast walls
Grout Pockets	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Unrated	Remove from this schedule only concrete deck

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Good	

CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	1.5
	Estimated High Water Level Clearance:	0.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	10	Required	High		Replace missing delineator
	11	Required	High		Install approach fenders
	12	Required	High		Add bridge ahead signage
	13	Required	Medium		Brush approaches

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1045 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-505	Structure Name:	G5-505	Road Name:	EAGLE	Inspection Date:	2021/07/21
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Curbs and risers are currently functional, but further deterioration will reduce load rating.					
GENERAL	Estimated Load Restriction (year):		2036	Estimated Replacement (year):			
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?		No	Report Status:		Reviewed By Jordan Smith on 2022/02/10 15:15:52	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 1046 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-058	Structure Name:	G5-058	Road Name:	DUST	Inspection Date:	2019/10/03
KM:	2.90	User km:	2.90	Crossing Name:	Dust Creek Tributary	Next Inspection Date:	2022/10/03
Project File ID #:	9534	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	3,000			Outlet Cover (mm):	3,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	20.1	Opening Height (mm):	3,000	Opening Width (mm):	3,000		
UTM Zone:	9	UTM Easting:	496870	UTM Northing:	6135683		
Inspector Name:	Dawson SMITH			Year Superstructure Installed:	1999		
Access:							

APPROACHES

Alignment	Good
Brushing Required	No
Road Surface	Good

CULVERT ELEMENT

Bolted Connections	Good
Coating	Good
Embedment Materials	Good
Fill	Good
Head Wall	Good
Inlet	Good
Outlet	Good
Overall	Good
Roof	Good
Side Walls	Good

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 1047 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-058	Structure Name:	G5-058	Road Name:	DUST	Inspection Date:	2019/10/03			
CHANNEL	Estimated Present Water Level Depth:		0.5		Estimated Present Water Level Width:		0.2			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	3.05 KM								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):		2049		Estimated Replacement (year):					
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/01/30 15:50:18				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1048 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-029	Structure Name:	G1-937	Road Name:	DAVIS	Inspection Date:	2018/09/27
KM:	6.52	User km:	6.52	Crossing Name:	Unknown	Next Inspection Date:	2022/09/01
Project File ID #:	9749	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Steel I-beam				Right	Sill -Temporary Materials	
Total Length (metres):	15.2	# Spans:	1	Span Width:	Span Length(s) (metres):		15
UTM Zone:	10	UTM Easting:	396205	UTM Northing:	6006918		
Inspector Name:	Adam Mathison, GradTech			Year Superstructure Installed:			
Access:							

ABUTMENTS

Bearings	Poor	Burned
Bracing	Not Applicable	
Ballast Wall	Poor	Burned
Corrosion Protection	Not Applicable	
Caps or Sills	Poor	Burned
Fill	Fair	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Good	
Road Surface	Fair	

DECK

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1049 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-029	Structure Name:	G1-937	Road Name:	DAVIS	Inspection Date:	2018/09/27
---------	--------	-----------------	--------	------------	-------	------------------	------------

Span 1

Curb Rail/Blocks/Posts	Poor	Burned
Deck to Girder Bolts	Not Applicable	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Nails	Poor	Burned
Overall Deck Condition	Poor	Burned
Running Planks	Poor	Burned
Sub Deck	Poor	Burned
Ties	Poor	Burned

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	0.3
Estimated High Water Level Clearance:	1.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	High	\$	Rebuild structure

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1050 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-029	Structure Name:	G1-937	Road Name:	DAVIS	Inspection Date:	2018/09/27
GENERAL	Inspector's Comment:	Structure burned in 2018 and is no longer passable.					
GENERAL	PEng's Comment:	Bridge should be barricaded. If bridge is no longer needed than it should be deactivated.					
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:		0	Design Load GVW (tonnes):		Design Vehicle Config.:	L75
	Professional Inspection Required?		Yes	Report Status:		Reviewed By Jason Olmsted on 2019/01/31 08:58:35	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1051 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-495	Structure Name:	G5-495	Road Name:	A50763	Inspection Date:	2005/10/02
KM:	1.10	User km:	1.10	Crossing Name:	Unnamed creek	Next Inspection Date:	2007/10/02
Project File ID #:	9930	Br.	01	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Precast	
Superstructure:					Right	Concrete Precast	
Total Length (metres):	12.0	# Spans:	1	Span Width:			Span Length(s) (metres): 12
UTM Zone:	10		UTM Easting:	357427	UTM Northing:	6147022	
Inspector Name:	Dave Burgess			Year Superstructure Installed:	2000		
Access:	Tchentlo FSR km 8 Left onto Rottacker FSR km 10.8 Left onto						

ABUTMENTS

Bracing	Good	No Comment Available -Converter.RNI
Ballast Wall	Good	No Comment Available -Converter.RNI
Caps or Sills	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Hardware	Good	No Comment Available -Converter.RNI
Riprap	Poor	No Comment Available -Converter.RNI

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	1	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	1	No Comment Available -Converter.RNI
Fender Condition	Good	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI
Road Surface	Poor	No Comment Available -Converter.RNI

DECK

Span 1

Deck to Girder Bolts	Excellent	No Comment Available -Converter.RNI
Hardware	Good	No Comment Available -Converter.RNI
Running Planks	Excellent	No Comment Available -Converter.RNI
Sub Deck	Excellent	No Comment Available -Converter.RNI

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1052 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-495	Structure Name:	G5-495	Road Name:	A50763	Inspection Date:	2005/10/02
Ties	Excellent	No Comment Available -Converter.RNI					

CHANNEL	Estimated Present Water Level Depth:				Estimated Present Water Level Width:					
	Estimated High Water Level Clearance:		2.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Suggested	High	\$ 0.00	Span: 0.0. Delineator maintenance. Add Delineators, 1 left and 1 right..					
	2	Suggested	High	\$ 0.00	Span: 0.0. Bridge Ahead Signs. Add 2 Bridge Ahead Signs.					
MONITORS	#	Description								
	1	Monitor LC abutment for scour as rip rap is light. (OK Chinch03) (No maintenance until hauling commences) No further inspections until notified by BCTS that structure being used.								
GENERAL	Inspector's Comment:	nullPerm_Span: Never hauled on yet.. Perm_Sup: 15) Visual not torqued.								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Estimated Load Restriction (year):				Estimated Replacement (year):					
	Current Inspection Load Rating:		68		Design Load GVW (tonnes):		68		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By Raymond Getzlaf on 2012/04/12 00:00:00			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 1053 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-142	Structure Name:	G5-142	Road Name:	A52153 CP 30	Inspection Date:	2017/06/15
KM:	26.90	User km:	26.90	Crossing Name:	Unnamed creek	Next Inspection Date:	2020/06/15
Project File ID #:	R13151	Br.	A	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Pipe Arch			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	600			Outlet Cover (mm):	600		
Footing Type:				Gradient (%):			
Culvert Length (metres):	12.0	Opening Height (mm):	1,270	Opening Width (mm):	1,900		
UTM Zone:	10	UTM Easting:	350297	UTM Northing:	6158991		
Inspector Name:	Justin Beveridge			Year Superstructure Installed:	1987		
Access:	Road has been transferred to an RP. Do not inspect - CP Oct 2020						

APPROACHES

Alignment	Fair	
Road Surface	Fair	potholes

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Poor	left culvert roof has collapsed approx. 30cm at connection
Coating	Fair	
Embedment Materials	Poor	not embedded properly
Fill	Fair	oversteepened d/s. ravelling from water off road
Floor	Fair	
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	
Overall	Fair	
Riprap	Good	
Roof	Poor	left culvert roof has collapsed approx. 30cm at connection. Right culvert is good.
Side Walls	Fair	
Trash Rack	Not Applicable	

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 1054 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-142	Structure Name:	G5-142	Road Name:	A52153 CP 30	Inspection Date:	2017/06/15			
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		4.5			
	Estimated High Water Level Clearance:		0.7							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	Yes
	Comment:	some minor aggradation at inlet.								
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	monitor left culvert for further collapse of roof.								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Monitor left culvert for further settlement.								
GENERAL	Estimated Load Restriction (year):			2027	Estimated Replacement (year):					
	Current Inspection Load Rating:		54	Design Load GVW (tonnes):		54	Design Vehicle Config.:			
	Professional Inspection Required?		No	Report Status:		Reviewed By Ross Hyam on 2018/04/30 17:08:54				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1055 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-185	Structure Name:	G4-185	Road Name:	R21455 SEC.AW	Inspection Date:	2019/08/08
KM:	1.00	User km:	1.00	Crossing Name:	Un-named	Next Inspection Date:	2019/08/08
Project File ID #:	R21455	Br.	AW	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Steel			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Steel Box Beam				Right	Sill -Temporary Materials	
Total Length (metres):	6.1	# Spans:	1	Span Width:	Span Length(s) (metres):		6.1
UTM Zone:	10	UTM Easting:	422270	UTM Northing:	6006618		
Inspector Name:	dawson smith			Year Superstructure Installed:	2011		
Access:	Vanderhoof Community Forest RP						

ABUTMENTS

Bearings	Not Applicable
Bracing	Not Applicable
Ballast Wall	Good
Corrosion Protection	Not Applicable
Caps or Sills	Good
Fill	Good
Hardware	Good
Piles or Posts	Not Applicable
Riprap	Not Applicable
Wing Wall	Not Applicable

APPROACHES

Alignment	Good
Bridge Ahead Signs Missing	0
Brushing Required	Yes
Delineator Missing Left (approaching structure)	0
Delineator Missing Right (approaching structure)	1
Fender Condition	None
Road Surface	Good

DECK

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1056 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-185	Structure Name:	G4-185	Road Name:	R21455 SEC.AW	Inspection Date:	2019/08/08
---------	--------	-----------------	--------	------------	---------------	------------------	------------

Span 1

Curb Rail/Blocks/Posts	Good
------------------------	------

Hardware	Good
----------	------

Hand Rails/Walkouts	Not Applicable
---------------------	----------------

Overall Deck Condition	Good
------------------------	------

Steel Deck Plate	Good
------------------	------

SUPERSTRUCTURE

Span 1

Bracing	Good
---------	------

Diaphragms	Good
------------	------

Girders	Good
---------	------

Hardware	Not Applicable
----------	----------------

Under Trussing	Not Applicable
----------------	----------------

CHANNEL

Estimated Present Water Level Depth:	0.0	Estimated Present Water Level Width:	0.0
--------------------------------------	-----	--------------------------------------	-----

Estimated High Water Level Clearance:	1.0
---------------------------------------	-----

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
-------------	----	--------	----	------	----	---------	----	--------------	----

Comment:	
----------	--

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	Low	\$ 250.00	INSTALL MISSING DELINEATORS AND LOAD RATING SIGN
2	Required	Low	\$ 500.00	brushing

MONITORS

#	Description
---	-------------

GENERAL

Inspector's Comment:	
----------------------	--

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1057 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-185	Structure Name:	G4-185	Road Name:	R21455 SEC.AW	Inspection Date:	2019/08/08
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:		64	Design Load GVW (tonnes):		64	Design Vehicle Config.: BCL62
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 2020/01/22 10:47:30	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 1058 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-170	Structure Name:	G4-170A	Road Name:	R21455 SEC.AX	Inspection Date:	2018/09/23
KM:	6.50	User km:	9.00	Crossing Name:	Unknown	Next Inspection Date:	2018/09/23
Project File ID #:	R21455	Br.	AX	Forest District:	Stuart Nechako Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	750			Outlet Cover (mm):	1,000		
Footing Type:	Precast Concrete Footing			Gradient (%):			
Culvert Length (metres):	20.0	Opening Height (mm):	2,360	Opening Width (mm):	5,790		
UTM Zone:	10	UTM Easting:	431081	UTM Northing:	6003786		
Inspector Name:	Adam Mathison, GradTech			Year Superstructure Installed:			
Access:	Vanderhoof Community Forest RP						

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	
Coupled Connections	Not Applicable	
Coating	Good	
Embedment Materials	Good	
Fill	Good	
Floor	Fair	Beaver dam under construction inside of culvert
Footing	Good	Exposed upstream right corner
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Major Culvert Inspection Report

Page: 1059 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001C

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-170	Structure Name:	G4-170A	Road Name:	R21455 SEC.AX	Inspection Date:	2018/09/23			
Overall	Good									
Riprap	Fair	Riprap too small over footings								
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		2.5			
	Estimated High Water Level Clearance:		1.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Monitor beaver activity in and around pipe								
	2	Monitor footing exposure								
GENERAL	Inspector's Comment:	Culvert in overall good condition. Beaver dam under construction in culvert. Monitor beaver activity.								
GENERAL	PEng's Comment:									
GENERAL	Estimated Load Restriction (year):			2040		Estimated Replacement (year):				
	Current Inspection Load Rating:		68		Design Load GVW (tonnes):		68		Design Vehicle Config.: CL625	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 2019/01/31 08:53:15			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1060 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-145	Structure Name:	G5-145	Road Name:	GERMANSEN	Inspection Date:	2020/10/06
KM:	48.30	User km:	48.30	Crossing Name:	Twin Creek	Next Inspection Date:	2022/10/06
Project File ID #:	R22292	Br.	DB	Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Log Stringers				Right	Crib, Log or Untreated Timber	
Total Length (metres):	11.0	# Spans:	1	Span Width:	Span Length(s) (metres):		11
UTM Zone:	10	UTM Easting:	363430	UTM Northing:	6164334		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1995		
Access:	Road has been transferred to an RP. Do not inspect. CP Oct 2020						

ABUTMENTS

Bearings	Fair	Several spacers between log sill and Log Strings are rotting and soft, made from plywood and 2x6
Bracing	Not Applicable	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	Surface Rot
Fill	Good	
Hardware	Fair	
Log/Timber Cribs	Fair	Surface Rot
Piles or Posts	Not Applicable	
Riprap	Fair	
Tie-backs	Fair	Surface Rot
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1061 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-145	Structure Name:	G5-145	Road Name:	GERMANSEN	Inspection Date:	2020/10/06
---------	--------	-----------------	--------	------------	-----------	------------------	------------

Posted Load Rating (Enter 0 if sign missing)	1	
--	---	--

Road Surface	Poor	wilderness
--------------	------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	log curbs, surface rot 5-10cm depth
Deck to Girder Bolts	Not Applicable	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Nails	Fair	
Overall Deck Condition	Fair	
Running Planks	Not Applicable	
Sub Deck	Fair	Rot Found, soft boards
Ties	Fair	all tested were solid

STRINGERS

Span 1

Stringer	Diameter or Width X Depth	Peeled	Rot Depth (Bottom)	Rot Depth (Side)	Rot Depth (Top)	Wood Species	Comments
1	570	No	0	0	0	sx	found to be solid
2	600	Yes	0	0	0	sx	found to be solid
3	560	Yes	0	0	0	sx	found to be solid
4	590	Yes	0	0	0	sx	found to be solid
5	510	Yes	0	0	0	sx	found to be solid
6	490	Yes	0	0	0	sx	found to be solid

Log Curbs	Fair	log curbs, surface rot 5-10cm depth
-----------	------	-------------------------------------

Needle Beam(s) and Shims	Not Applicable	
--------------------------	----------------	--

CHANNEL	Estimated Present Water Level Depth:	0.0	Estimated Present Water Level Width:	8.0
	Estimated High Water Level Clearance:	0.5		

HAZARDS	High Water:	Yes	Scour:	Yes	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	left abutment sitting in stream, fast water could be scouring under. logs under and pushed up against bridge.								

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1062 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-145	Structure Name:	G5-145	Road Name:	GERMANSEN	Inspection Date:	2020/10/06
REPAIRS	#	Status	Priority	Estimate	Description		
MONITORS	#	Description					
GENERAL	Inspector's Comment:	Bridge is not on FSR, FLNRO carries out inspection as it is on the land base but does not "own" this bridge. bridge re-posted from 45000kg to 5000kg					
GENERAL	PEng's Comment:	This bridge is on a RP. Bridge will not be monitored anymore. RP holder is responsible for everything.					
GENERAL	Estimated Load Restriction (year):			2002	Estimated Replacement (year):		2015
	Current Inspection Load Rating:		5	Design Load GVW (tonnes):		45	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status: Reviewed By Jason Olmsted on 2021/03/01 11:39:53			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1063 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-036	Road Name:		Inspection Date:	2008/11/07
KM:		User km:		Crossing Name:	Vanderhoof District	Next Inspection Date:	2012/04/20
Project File ID #:		Br.		Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Steel I-beam				Right	Crib, Log or Untreated Timber	
Total Length (metres):	12.1	# Spans:	1	Span Width:		Span Length(s) (metres):	12.1
UTM Zone:	10		UTM Easting:	434873	UTM Northing:	5984828	
Inspector Name:	Vince Sewell			Year Superstructure Installed:	2007		
Access:	Vanderhoof District Office						

ABUTMENTS

Bearings	Unrated	na
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	
Fill	Good	
Hardware	Not Applicable	
Log/Timber Cries	Fair	still solid - but untreated 1.4 years old
Piles or Posts	Not Applicable	
Riprap	Not Applicable	none needed
Tie-backs	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1064 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-036	Road Name:		Inspection Date:	2008/11/07			
Road Surface		Fair								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Deck to Girder Bolts		Good								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Good								
Running Planks		Good								
Sub Deck		Good		treated						
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Not Applicable								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.3		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		0.8							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1065 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-036	Road Name:		Inspection Date:	2008/11/07
---------	---------	-----------------	--------	------------	--	------------------	------------

MONITORS

#	Description

GENERAL

Inspector's Comment:	The bridge itself is in very good condition. The untreated cribs are still solid but their age will soon start to show. No industrial use at this time and this bridge is behind G4-028 with a 10 tonne load rating.
----------------------	--

GENERAL

PEng's Comment:	Refer to Inspection Comments for historical PEng Comments
-----------------	---

GENERAL

Estimated Load Restriction (year):	2020	Estimated Replacement (year):	
Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):	
Design Vehicle Config.:			
Professional Inspection Required?	No	Report Status:	Accepted By IDIR\JOLMSTED on 2013/05/27 16:28:27

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1066 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-923	Road Name:		Inspection Date:	2020/09/09
KM:		User km:		Crossing Name:	Ft St James District	Next Inspection Date:	2023/09/09
Project File ID #:		Br.		Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:		Span Length(s) (metres):	12.2
UTM Zone:	10		UTM Easting:	418198	UTM Northing:	6031130	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2000		
Access:	Fort St. James bridge storage site - see individual structures for specific storage locations.						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	no rot 12x12
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	covered in dirt
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Fair	
Posted Load Rating (Enter 0 if sign missing)	0	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1067 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-923	Road Name:		Inspection Date:	2020/09/09			
Road Surface	Poor	wilderness								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Poor	rot in curbs, steel posts\risers attached to rotated ties								
Deck to Girder Bolts	Not Applicable									
Hardware	Fair									
Hand Rails/Walkouts	Not Applicable									
Nails	Fair									
Overall Deck Condition	Poor	bridge deck in poor condition due to rot in many structure elements.								
Running Planks	Poor	rot								
Sub Deck	Poor	Rot and fungus as seen from below								
Ties	Poor	Rot and fungus as seen from below								
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Good									
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		1.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	8	Required	High		Replace deck					
	9	Required	Medium		Brushing needed					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1068 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-923	Road Name:		Inspection Date:	2020/09/09
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Bridge deck needs replacing. Bridge to be posted at 30 tonnes until all repairs are completed					
GENERAL	Estimated Load Restriction (year):		2030		Estimated Replacement (year):		
	Current Inspection Load Rating:		30		Design Load GVW (tonnes):		68
	Design Vehicle Config.:		L75				
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/04 14:14:36			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1069 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-145	Road Name:		Inspection Date:	2011/07/19
KM:		User km:		Crossing Name:	Vanderhoof District	Next Inspection Date:	2014/07/19
Project File ID #:		Br.		Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	8.2	# Spans:	1	Span Width:		Span Length(s) (metres):	8.2
UTM Zone:	10		UTM Easting:	434873	UTM Northing:	5984828	
Inspector Name:	Vince Sewell			Year Superstructure Installed:	2002		
Access:	Vanderhoof District Office						

ABUTMENTS

Bearings	Not Applicable	
Bracing	Good	
Ballast Wall	Good	
Concrete Precast	Good	
Corrosion Protection	Good	
Caps or Sills	Fair	North side crushed - no change from last inspection
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Poor	North side not effective South side DS rotten
Posted Load Rating (Enter 0 if sign missing)	54	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1070 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-145	Road Name:		Inspection Date:	2011/07/19			
Road Surface		Fair								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Fair		starting to get soft but ok for now						
Deck to Girder Bolts		Not Applicable								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Good								
Running Planks		Good								
Sub Deck		Good								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.4		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		0.8							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1071 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-145	Road Name:		Inspection Date:	2011/07/19
---------	---------	-----------------	--------	------------	--	------------------	------------

MONITORS

#	Description
1	HC outside Lock Blocks appear to have settled.
2	curbs for rot

GENERAL

Inspector's Comment:	
----------------------	--

GENERAL

PEng's Comment:	Refer to Inspection Comments for historical PEng Comments
-----------------	---

GENERAL

Estimated Load Restriction (year):	2022	Estimated Replacement (year):	
Current Inspection Load Rating:	54	Design Load GVW (tonnes):	54
Design Vehicle Config.:			
Professional Inspection Required?	No	Report Status:	Accepted By Jason Olmsted on 2013/05/27 00:00:00

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1072 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-940	Road Name:		Inspection Date:	2010/05/13
KM:		User km:		Crossing Name:	Ft St James District	Next Inspection Date:	2012/05/13
Project File ID #:		Br.		Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Steel I-beam				Right	Sill -Temporary Materials	
Total Length (metres):	12.2	# Spans:	1	Span Width:		Span Length(s) (metres):	12.2
UTM Zone:	10	UTM Easting:	418198	UTM Northing:	6031130		
Inspector Name:	wwilkinson/sforshner			Year Superstructure Installed:	2006		
Access:	Fort St. James bridge storage site - see individual structures for specific storage locations.						

ABUTMENTS

Bearings	Fair	left bearing not centered on sill log
Bracing	Not Applicable	
Ballast Wall	Good	some materials coming down from top of ballast wall
Corrosion Protection	Not Applicable	
Caps or Sills	Good	un-pealed spruce logs
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Fender Condition	None	
Road Surface	Fair	

DECK

Span 1

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1073 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-940	Road Name:		Inspection Date:	2010/05/13			
Curb Rail/Blocks/Posts	Good									
Deck to Girder Bolts	Not Applicable									
Hardware	Good									
Hand Rails/Walkouts	Not Applicable									
Nails	Good									
Overall Deck Condition	Good									
Running Planks	Good									
Sub Deck	Good									
Ties	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.4		Estimated Present Water Level Width:		1.5			
	Estimated High Water Level Clearance:		1.2							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	right bearing not centered on sill log, right bearing the girder is seitting on sill log								

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1074 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-940	Road Name:		Inspection Date:	2010/05/13
GENERAL	Inspector's Comment:	bridge is longer then the abutment placements, bridge girder is sitting on sill log left abutment, bearing is not centered on right abutment.					
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments					
GENERAL	Estimated Load Restriction (year):		2020		Estimated Replacement (year):		
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91
	Design Vehicle Config.:						
	Professional Inspection Required?	No	Report Status:	Accepted By Raymond Getzlaf on 2011/04/28 00:00:00			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1075 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-250	Road Name:		Inspection Date:	2013/08/28
KM:		User km:		Crossing Name:	Ft St James District	Next Inspection Date:	2015/08/28
Project File ID #:		Br.		Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Crib, Log or Untreated Timber	
Superstructure:	Log Stringers				Right	Crib, Log or Untreated Timber	
Total Length (metres):	6.0	# Spans:	1	Span Width:		Span Length(s) (metres):	6
UTM Zone:	10		UTM Easting:	418198	UTM Northing:	6031130	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1988		
Access:	Fort St. James bridge storage site - see individual structures for specific storage locations.						

ABUTMENTS

Bearings	Fair	
Bracing	Fair	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	
Fill	Good	
Hardware	Not Applicable	
Log/Timber Cries	Poor	outside logs and logs on bottom row are in a rotting condition
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Tie-backs	Fair	some are rotting others appear reasonably sound
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1076 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-250	Road Name:		Inspection Date:	2013/08/28			
Road Surface	Poor	overgrown wilderness level road								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Poor	curp logs very rotten, spruce peeled								
Deck to Girder Bolts	Not Applicable									
Hardware	Poor	steel cables used to hold curbs t bridge are loose due to rotting curbs								
Hand Rails/Walkouts	Not Applicable									
Nails	Poor	loose and coming up								
Overall Deck Condition	Poor	log bridge long past planed lifespan 10 years over planned lifespan								
Running Planks	Poor	100% of boards were found to have rot								
Sub Deck	Poor	90% of boards have some rot\soft spots								
Ties	Poor	rot found in outside portion of ties not covered by deck								
STRINGERS										
Span 1										
Stringer	Diameter or Width X Depth	Peeled	Rot Depth (Bottom)	Rot Depth (Side)	Rot Depth (Top)	Wood Species	Comments			
1	520	Yes	0	0	20	FC	estimate of rot			
2	600	Yes	0	0	20	Fd	estimate of rot			
3	530	Yes	0	0	20	FD	estimate of rot			
4	690	Yes	0	0	20	Fd	estimate of rot			
5	530	Yes	0	0	20	fd	estimate of rot			
6	680	No	0	0	20	fD	estimate of rot			
CHANNEL	Estimated Present Water Level Depth:		0.1			Estimated Present Water Level Width:		1.0		
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	High	\$	replace abutments \ replace deck					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1077 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-250	Road Name:		Inspection Date:	2013/08/28
MONITORS	#	Description					
GENERAL	Inspector's Comment:	Pull or replace					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2000	Estimated Replacement (year):			
	Current Inspection Load Rating:		0	Design Load GVW (tonnes):		0	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Accepted By Jason Olmsted on 2014/05/12 14:24:35	

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1078 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-929	Road Name:		Inspection Date:	2013/08/29
KM:		User km:		Crossing Name:	Vanderhoof District	Next Inspection Date:	2015/08/29
Project File ID #:		Br.		Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated - Panels			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Steel I-beam				Right	Sill -Temporary Materials	
Total Length (metres):	15.2	# Spans:	1	Span Width:		Span Length(s) (metres):	15.2
UTM Zone:	10	UTM Easting:	434873	UTM Northing:	5984828		
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2018		
Access:	Vanderhoof District Office						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	un-pealed spruce logs
Corrosion Protection	Not Applicable	
Caps or Sills	Good	left pealed fir log, right un-pealed fir log
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	left off sharp corner
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Road Surface	Good	

DECK

Corporate Bridge Register (CBR)

- Disclaimer:
- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 - 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1079 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-929	Road Name:		Inspection Date:	2013/08/29
---------	---------	-----------------	--------	------------	--	------------------	------------

Span 1

Curb Rail/Blocks/Posts	Fair	one upstream one downstream with rot
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Fair	several have rot the rest are sound
Sub Deck	Fair	several have rot the rest are sound
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	1.0
Estimated High Water Level Clearance:	2.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:	very slow stream								

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	High	\$	replace rotting deck boards and post and curbs

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1080 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-929	Road Name:		Inspection Date:	2013/08/29
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2017	Estimated Replacement (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Accepted By Jason Olmsted on 2014/04/16 10:51:20			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1081 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-914	Road Name:		Inspection Date:	2013/09/19
KM:		User km:		Crossing Name:	Vanderhoof District	Next Inspection Date:	2016/09/19
Project File ID #:		Br.		Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	16.0	# Spans:	1	Span Width:		Span Length(s) (metres):	16
UTM Zone:	10		UTM Easting:	434873	UTM Northing:	5984828	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	1997		
Access:	Vanderhoof District Office						

ABUTMENTS

Bearings	Good	cannot se right side
Bracing	Good	
Ballast Wall	Good	
Concrete Precast	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Fair	

APPROACHES

Alignment	Fair	Hills and corners both sides
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Posted Load Rating (Enter 0 if sign missing)	50	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1082 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-914	Road Name:		Inspection Date:	2013/09/19			
Road Surface		Fair								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Deck to Girder Bolts		Good								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Fair								
Overall Deck Condition		Fair								
Running Planks		Good								
Sub Deck		Poor		soft and rotting						
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Good								
Diaphragms		Good								
Girders		Good								
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		2.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Medium	\$	replace deck					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1083 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-914	Road Name:		Inspection Date:	2013/09/19
MONITORS	#	Description					
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2035	Estimated Replacement (year):			
	Current Inspection Load Rating:	54	Design Load GVW (tonnes):	54	Design Vehicle Config.:	L60	
	Professional Inspection Required?	No	Report Status:	Accepted By Jason Olmsted on 2014/04/14 11:33:59			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1084 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-930	Road Name:		Inspection Date:	2006/01/01
KM:		User km:		Crossing Name:	Ft St James District	Next Inspection Date:	2006/06/01
Project File ID #:		Br.		Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Other	
Superstructure:	Steel I-beam				Right	Other	
Total Length (metres):	18.0	# Spans:	1	Span Width:		Span Length(s) (metres):	18
UTM Zone:	10	UTM Easting:	418198	UTM Northing:	6031130		
Inspector Name:	Unknown		Year Superstructure Installed:	2006			
Access:	Fort St. James bridge storage site - see individual structures for specific storage locations.						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating (Enter 0 if sign missing)	0.0	No Comment Available -Converter.RNI

CHANNEL

Estimated Present Water Level Depth:		Estimated Present Water Level Width:	
Estimated High Water Level Clearance:	0.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1085 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-930	Road Name:		Inspection Date:	2006/01/01
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):	100	Design Vehicle Config.:		
	Professional Inspection Required?	Yes	Report Status:	Rejected By IDIR\JOLMSTED on 2015/04/14 13:59:56			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1086 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-601	Road Name:		Inspection Date:	2012/06/15
KM:		User km:		Crossing Name:	Ft St James District	Next Inspection Date:	2014/06/15
Project File ID #:		Br.		Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	12.2	# Spans:	1	Span Width:		Span Length(s) (metres):	12.2
UTM Zone:	10		UTM Easting:	418198	UTM Northing:	6031130	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:			
Access:	Fort St. James bridge storage site - see individual structures for specific storage locations.						

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Fair	Left upstream top board broken on outside
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	Left upstream Sill showing rot on end and bearing wall side
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	one homemade, and one damaged
Delineator Missing Right (approaching structure)	0	one homemade, and one damaged
Fender Condition	Fair	
Road Surface	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1087 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-601	Road Name:		Inspection Date:	2012/06/15
---------	---------	-----------------	--------	------------	--	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	downstream curbs have splits in timbers
Deck to Girder Bolts	Good	only eight bolts
Hardware	Poor	rating due to deck condition
Hand Rails/Walkouts	Not Applicable	
Nails	Poor	Nails sticking up due to rot and ware of deck
Overall Deck Condition	Poor	rating due to deck condition
Running Planks	Not Applicable	
Sub Deck	Poor	many holes in deck, deck rotting, fungus on deck boards on underside
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Good	

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	3.0
Estimated High Water Level Clearance:	2.0		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Suggested	Medium	\$	relace broken curb timbers
2	Suggested	High	\$	Replace broken baring wall board at time of deck repair
3	Suggested	High	\$	replace all decking

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1088 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-601	Road Name:		Inspection Date:	2012/06/15
MONITORS	#	Description					
GENERAL	Inspector's Comment:	indications of tracked vehicle traffic on bridge Bridge down rated to 10 tonnes until deck is repaired and confirmation on steel capacity(need bridge file) on scheduled for inspection, but have had request to inspect from BCTS as planned use for this bridge in 2012					
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments					
GENERAL	Estimated Load Restriction (year):		2020	Estimated Replacement (year):			
	Current Inspection Load Rating:		10	Design Load GVW (tonnes):		Design Vehicle Config.:	
	Professional Inspection Required?		No	Report Status: Accepted By Jason Olmsted on 2013/04/17 00:00:00			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1089 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-903	Road Name:		Inspection Date:	2016/07/12
KM:		User km:		Crossing Name:	Vanderhoof District	Next Inspection Date:	2018/07/12
Project File ID #:		Br.		Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Sill -Temporary Materials	
Superstructure:	Steel I-beam				Right	Sill -Temporary Materials	
Total Length (metres):	12.0	# Spans:	1	Span Width:		Span Length(s) (metres):	12
UTM Zone:	10		UTM Easting:	434873	UTM Northing:	5984828	
Inspector Name:	Donovan J. A. Melin			Year Superstructure Installed:	1998		
Access:	Vanderhoof District Office						

ABUTMENTS

Bearings	Poor	not pinned to girders
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Poor	not pinned to girders
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Road Surface	Good	

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1090 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-903	Road Name:		Inspection Date:	2016/07/12
---------	---------	-----------------	--------	------------	--	------------------	------------

Span 1

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Fair	not tightened in a few places
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Not Applicable	
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.3	Estimated Present Water Level Width:	4.0
	Estimated High Water Level Clearance:	1.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	High	\$ 100.00	Post load limit of 41 tonnes sign.
	2	Required	High	\$ 500.00	Pin girders to timber sills.

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1091 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-903	Road Name:		Inspection Date:	2016/07/12
GENERAL	Inspector's Comment:	The timber sills are pinned to the lock blocks but the girders are not pinned to the timber sills. A load rating of 41 tonnes is a serious limiting factor on this road and that sign should be posted. Bridge is in fair condition.					
GENERAL	PEng's Comment:						
GENERAL	Estimated Load Restriction (year):		2018		Estimated Replacement (year):		
	Current Inspection Load Rating:		41		Design Load GVW (tonnes):		41
	Design Vehicle Config.:						
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2016/12/19 09:01:20			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1092 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-301	Road Name:		Inspection Date:	2015/12/18
KM:		User km:		Crossing Name:	Ft St James District	Next Inspection Date:	2017/12/18
Project File ID #:		Br.		Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	9.1	# Spans:	1	Span Width:		Span Length(s) (metres):	9.1
UTM Zone:	10		UTM Easting:	418198	UTM Northing:	6031130	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:			
Access:	Fort St. James bridge storage site - see individual structures for specific storage locations.						

ABUTMENTS

Bearings	Poor	Not centered on sill
Bracing	Not Applicable	
Ballast Wall	Good	Treated
Concrete Lock Blocks	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Excellent	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1093 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-301	Road Name:		Inspection Date:	2015/12/18
---------	---------	-----------------	--------	------------	--	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	Rot found
Deck to Girder Bolts	Not Applicable	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Nails	Poor	Lifting
Overall Deck Condition	Poor	Deck needs to be replaced
Running Planks	Poor	Rotting
Sub Deck	Poor	Rotting
Ties	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Fair	Rust
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	1.0
Estimated High Water Level Clearance:	0.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	High	\$	Replace deck and curbs

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1094 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-301	Road Name:		Inspection Date:	2015/12/18
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Need to confirm loading in the summer					
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2016/01/18 14:36:53			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1095 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-300	Road Name:		Inspection Date:	2015/09/18
KM:		User km:		Crossing Name:	Ft St James District	Next Inspection Date:	2017/09/18
Project File ID #:		Br.		Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Other	
Superstructure:	Steel I-beam				Right	Other	
Total Length (metres):	9.1	# Spans:	1	Span Width:		Span Length(s) (metres):	9.1
UTM Zone:	10		UTM Easting:	418198	UTM Northing:	6031130	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:			
Access:	Fort St. James bridge storage site - see individual structures for specific storage locations.						

ABUTMENTS

Bearings	Fair	Right side is not centered on sill
Bracing	Not Applicable	
Ballast Wall	Poor	Rotting, boards do not go up to deck edge
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
General Abutment Condition	Fair	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	Corner on right side
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Poor	Wilderness

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1096 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-300	Road Name:		Inspection Date:	2015/09/18
---------	---------	-----------------	--------	------------	--	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Poor	Rotting, curb broken
Deck to Girder Bolts	Not Applicable	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Nails	Poor	Lifting
Overall Deck Condition	Poor	Deck needs replacement
Running Planks	Poor	Rotting
Sub Deck	Poor	Rotting
Ties	Fair	Wet with fungus

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.0
Estimated High Water Level Clearance:	0.5		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description
1	Required	High	\$	Replace deck and curbs

MONITORS

#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1097 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-300	Road Name:		Inspection Date:	2015/09/18
GENERAL	Inspector's Comment:						
GENERAL	PEng's Comment:	Need to confirm loading this summer					
GENERAL	Estimated Load Restriction (year):		2030	Estimated Replacement (year):			
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2016/01/18 14:34:27			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1098 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G4-900	Road Name:		Inspection Date:	2015/07/24
KM:		User km:		Crossing Name:	Ft St James District	Next Inspection Date:	2017/07/24
Project File ID #:		Br.		Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	9.0	# Spans:	1	Span Width:		Span Length(s) (metres):	9
UTM Zone:	10		UTM Easting:	418198	UTM Northing:	6031130	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2014		
Access:	Fort St. James bridge storage site - see individual structures for specific storage locations.						

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Concrete Lock Blocks	Good	Some settling
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Fair	Settling
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	Off corners and hills both approaches
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating (Enter 0 if sign missing)	L40	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1099 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G4-900	Road Name:		Inspection Date:	2015/07/24			
Road Surface		Fair								
DECK										
Span 1										
Curb Rail/Blocks/Posts		Good								
Deck to Girder Bolts		Good								
Hardware		Good								
Hand Rails/Walkouts		Not Applicable								
Nails		Good								
Overall Deck Condition		Good								
Running Planks		Not Applicable								
Sub Deck		Good								
Ties		Good								
SUPERSTRUCTURE										
Span 1										
Bracing		Fair		Some bent						
Diaphragms		Good								
Girders		Good		Some damage from previous install						
Hardware		Good								
Under Trussing		Not Applicable								
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		0.3			
	Estimated High Water Level Clearance:		0.4							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:	Beaver dam upstream								
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Medium	\$	Road needs capping material					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1100 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G4-900	Road Name:		Inspection Date:	2015/07/24
---------	---------	-----------------	--------	------------	--	------------------	------------

MONITORS

#	Description
1	Monitor beaver activity upstream from crossing
2	Monitor settling of lock blocks

GENERAL

Inspector's Comment:	Recent PEng inspection done on behalf of John Prince Research Forest UNBC
----------------------	---

GENERAL

PEng's Comment:	Bridge to be replaced next year
-----------------	---------------------------------

GENERAL

Estimated Load Restriction (year):			2035	Estimated Replacement (year):				
Current Inspection Load Rating:		5	Design Load GVW (tonnes):		41	Design Vehicle Config.:		L45
Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2016/01/13 13:02:28					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1101 of 1106
 Date Printed: 2022/03/16
 User Id: IDIR\WWILKINS
 Database: PROD
 Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-959	Road Name:		Inspection Date:	2020/08/18
KM:		User km:		Crossing Name:	Ft St James District	Next Inspection Date:	2023/08/18
Project File ID #:		Br.		Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Not Available		
Curb Type:				Abutments (looking downstream)	Left	Concrete Precast	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	18.3	# Spans:	1	Span Width:		Span Length(s) (metres):	18.3
UTM Zone:	10		UTM Easting:	418198	UTM Northing:	6031130	
Inspector Name:	Warren Wilkinson			Year Superstructure Installed:	2004		
Access:	Fort St. James bridge storage site - see individual structures for specific storage locations.						

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Concrete Lock Blocks	Fair	blocks have slight lean towards stream
Concrete Precast	Fair	blocks leaning
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Fair	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Wing Wall	Poor	toes out on all 4 sides

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	may need 3rd sign at Y junction upchain
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Fair	

Corporate Bridge Register (CBR)

Disclaimer:
 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1102 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-959	Road Name:		Inspection Date:	2020/08/18			
Posted Load Rating (Enter 0 if sign missing)	5									
Road Surface	Poor	wilderness								
DECK										
Span 1										
Curb Rail/Blocks/Posts	Fair	rot								
Deck to Girder Bolts	Fair	need more as noted in previous inspection								
Hardware	Fair									
Hand Rails/Walkouts	Not Applicable									
Nails	Poor	rotting deck, nails lifting								
Overall Deck Condition	Poor	rotting deck with holes								
Running Planks	Poor	rot								
Sub Deck	Poor	rot with holes in deck								
Ties	Fair	wet with fungus growing								
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Good									
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		1.0			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	Yes	Scour:	Yes	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:	Flood event spring 2020								
REPAIRS	#	Status	Priority	Estimate	Description					

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Permanent Bridge Inspection Report

Page: 1103 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001A

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G5-STOR	Structure Name:	G5-959	Road Name:		Inspection Date:	2020/08/18
MONITORS	#	Description					
	2	watch lock blocks after flood event					
GENERAL	Inspector's Comment:	major flood event down stream, (posable beaver dam failure) Full PEng. inspection prior to hauling					
GENERAL	PEng's Comment:	all outstanding repairs need to be completed					
GENERAL	Estimated Load Restriction (year):		2030		Estimated Replacement (year):		
	Current Inspection Load Rating:		5		Design Load GVW (tonnes):		91
	Design Vehicle Config.:		L100				
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 2021/03/04 14:26:55			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1104 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-128	Road Name:		Inspection Date:	2011/09/21
KM:		User km:		Crossing Name:	Vanderhoof District	Next Inspection Date:	2013/09/21
Project File ID #:		Br.		Forest District:	Stuart Nechako Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Curb Type:				Abutments (looking downstream)	Left	Concrete Lock Blocks	
Superstructure:	Steel I-beam				Right	Concrete Lock Blocks	
Total Length (metres):	9.0	# Spans:	1	Span Width:		Span Length(s) (metres):	9
UTM Zone:	10		UTM Easting:	434873	UTM Northing:	5984828	
Inspector Name:	Shane Gorezky			Year Superstructure Installed:	2000		
Access:	Vanderhoof District Office						

ABUTMENTS

Bearings	Good
Ballast Wall	Good
Concrete Lock Blocks	Good
Caps or Sills	Good
Fill	Fair
Hardware	Good
Piles or Posts	Not Applicable
Riprap	Good
Wing Wall	Not Applicable

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Poor	no surfacing

DECK

Span 1

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1105 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-128	Road Name:		Inspection Date:	2011/09/21			
Curb Rail/Blocks/Posts	Fair									
Deck to Girder Bolts	Fair									
Hand Rails/Walkouts	Not Applicable									
Nails	Fair									
Overall Deck Condition	Fair	decking beginning to rot								
Running Planks	Not Applicable									
Sub Deck	Poor	Deck is showing sign of rot								
Ties	Fair									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Not Applicable									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.3		Estimated Present Water Level Width:		1.2			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Monitor deck for rot. Should be replaced prior to any industrial use								
GENERAL	Inspector's Comment:	Little to no traffic as bridge is behind access management point Need asbuilt information and confirmation on loading								

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests, Lands, and Natural Resource Operations

Log Stringer Bridge Inspection Report

Page: 1106 of 1106
Date Printed: 2022/03/16
User Id: IDIR\WWILKINS
Database: PROD
Report Id: CBR001B

Forest District: Stuart Nechako Natural Resource District Most Recent Inspections Only: Yes Sort By:

Site #:	G4-STOR	Structure Name:	G4-128	Road Name:		Inspection Date:	2011/09/21
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments					
	Estimated Load Restriction (year):	2015		Estimated Replacement (year):			
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):		Design Vehicle Config.:		
GENERAL	Professional Inspection Required?	No	Report Status:	Accepted By Jason Olmsted on 2013/05/24 00:00:00			

Corporate Bridge Register (CBR)

Disclaimer:
1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.