



BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 1 of 2
Date Printed: 2016/01/25
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001C
File:

Structure #:	G6-034-2	Site #:	G6-034	Road Name:	FINLAY FSR	Inspection Date:	2015/09/20
KM:	205.00	User km:	20.80	Crossing Name:	Unnamed creek	Next Inspection Date:	2018/09/20
Project File ID #:	7829	Br.	01	Forest District:	Mackenzie Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,500			Outlet Cover (mm):	1,500		
Footing Type:				Gradient (%):			
Culvert Length (metres):	19.0	Opening Height (mm):	1,800	Opening Width (mm):	1,800		
UTM Zone:	10	UTM Easting:	390020	UTM Northing:	6241161		
Inspector Name:	Edward Folk			Year Superstructure Installed:	1983		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	not applicable
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	not applicable
Delineator Missing Right (approaching structure)	0	not applicable
Fender Condition	None	not applicable
Road Surface	Fair	


CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Fair	
Coating	Fair	
Embedment Materials	Fair	
Fill	Fair	
Floor	Fair	
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Fair	large piece of rip rap partially covering inlet
Outlet	Poor	perched
Overall	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 2 of 2
Date Printed: 2016/01/25
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001C
File:

Structure #:	G6-034-2	Site #:	G6-034	Road Name:	FINLAY FSR	Inspection Date:	2015/09/20			
Riprap	Fair									
Roof	Fair									
Side Walls	Fair									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	2.5						
	Estimated High Water Level Clearance:	0.7								
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	Yes
	Comment:	lots of bank scour at outlet when pipe flows fast and full. armouring blocking inlet should be repositioned								
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Low	\$500.00	move large rip rap from restricting inlet					
MONITORS	#	Description								
	2	monitor scour of banks at outlet and erosion/blockage at inlet								
GENERAL	Inspector's Comment:	road is now signed as North Main- site at 21km board								
GENERAL	PEng's Comment:									
GENERAL	Replacement Date for full log haul traffic (year):	2023	Replacement Date for light vehicle traffic (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 1/25/2016 3:15:31PM						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.