



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 1 of 3
Date Printed: 2015/11/19
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-122	Site #:	G6-122	Road Name:	FINLAY-DAVIS	Inspection Date:	2015/06/17
KM:	15.20	User km:	90.00	Crossing Name:	Ivor Creek	Next Inspection Date:	2018/06/17
Project File ID #:	7829	Br.	09	Forest District:	Mackenzie Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Superstructure	Steel I-beam			Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials		
Total Length (metres):	15.3	# Spans:	1	Span Length(s) (metres):	15		
UTM Zone:	10	UTM Easting:	385011	UTM Northing:	6302823		
Inspector Name:	Hans Beurskens			Year Superstructure Installed:	1995		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	are not missing but are damage/warn
Delineator Missing Right (approaching structure)	0	are not missing but are damage/warn
Fender Condition	Fair	
Road Surface	Good	

DECK


Span 1

Concrete Deck	Good	
---------------	------	--

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 2 of 3
Date Printed: 2015/11/19
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-122	Site #:	G6-122	Road Name:	FINLAY-DAVIS	Inspection Date:	2015/06/17
--------------	--------	---------	--------	------------	--------------	------------------	------------

Curb Rail/Blocks/Posts	Poor	replace
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	
Running Surface	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	9.0
	Estimated High Water Level Clearance:	1.9		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									


REPAIRS	#	Status	Priority	Estimate	Description
	3	Required	High	\$1.00	delineators

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 3 of 3
Date Printed: 2015/11/19
User Id: IDIR\JOLMSTED
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-122	Site #:	G6-122	Road Name:	FINLAY-DAVIS	Inspection Date:	2015/06/17
GENERAL	Inspector's Comment:						
	Replacement Date for full log haul traffic (year):	2035	Replacement Date for light vehicle traffic (year):				
	Current Inspection Load Rating:	91.00	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Accepted By Jason Olmsted on 11/19/2015 12:51:08PM			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.