



BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 1 of 2
Date Printed: 2015/11/19
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001C
File:

Structure #:	G6-216	Site #:	G6-216	Road Name:	FINLAY-RUSSEL	Inspection Date:	2015/06/17
KM:	38.00	User km:	38.00	Crossing Name:	UNK	Next Inspection Date:	2018/06/17
Project File ID #:	7829	Br.	16	Forest District:	Mackenzie Natural Resource District		
Culvert Type:	Open Bottom			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	4,000			Outlet Cover (mm):	5,000		
Footing Type:	Steel Footing			Gradient (%):	5.0		
Culvert Length (metres):	18.4	Opening Height (mm):	2,400	Opening Width (mm):	6,600		
UTM Zone:	10	UTM Easting:	357565	UTM Northing:	6339668		
Inspector Name:	Hans Beurskens			Year Superstructure Installed:	2014		
Access:							

APPROACHES

Alignment	Good
-----------	------

Brushing Required	No
-------------------	----

Delineator Missing Left (approaching structure)	0
--	---

Delineator Missing Right (approaching structure)	0
---	---

Fender Condition	Excellent
------------------	-----------

Road Surface	Good
--------------	------

CULVERT ELEMENT

Baffles	Not Applicable
---------	----------------

Bolted Connections	Good
--------------------	------

Coupled Connections	Not Applicable
---------------------	----------------

Coating	Good
---------	------

Embedment Materials	Good
---------------------	------

Fill	Good
------	------

Floor	Not Applicable
-------	----------------

Footing	Good
---------	------

Head Wall	Excellent
-----------	-----------

Inlet	Excellent
-------	-----------

Outlet	Excellent
--------	-----------


Overall	Excellent
---------	-----------

Riprap	Excellent
--------	-----------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 2 of 2
Date Printed: 2015/11/19
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001C
File:

Structure #:	G6-216	Site #:	G6-216	Road Name:	FINLAY-RUSSEL	Inspection Date:	2015/06/17				
Roof	Good										
Side Walls	Good										
Trash Rack	Not Applicable										
Wiers/Backwater Structures	Not Applicable										
Wing Wall	Not Applicable										
CHANNEL	Estimated Present Water Level Depth:		0.0		Estimated Present Water Level Width:		5.0				
	Estimated High Water Level Clearance:		2.2								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No	
	Comment:										
REPAIRS	#	Status	Priority	Estimate	Description						
MONITORS	#	Description									
	1	Check for deterioration of geotextile due to UV exposure and physical damage									
GENERAL	Inspector's Comment:	no issues									
	Replacement Date for full log haul traffic (year):				2059		Replacement Date for light vehicle traffic (year):				
	Current Inspection Load Rating:		91.00		Design Load GVW (tonnes):		91		Design Vehicle Config.:		L100
	Professional Inspection Required?		No		Report Status:		Accepted By Jason Olmsted on 11/19/2015 9:58:32AM				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.