



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 1 of 3
Date Printed: 2015/11/18
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-281	Site #:	G6-281	Road Name:	PARSNIP EAST	Inspection Date:	2015/09/21
KM:	8.10	User km:	5.80	Crossing Name:	Gagnon Creek	Next Inspection Date:	2018/09/21
Project File ID #:	6143	Br.	02	Forest District:	Mackenzie Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Superstructure	Steel I-beam			Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials		
Total Length (metres):	24.0	# Spans:	1	Span Length(s) (metres):	24		
UTM Zone:	10	UTM Easting:	497813	UTM Northing:	6125027		
Inspector Name:	Knut Herzog			Year Superstructure Installed:	2002		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Good	
Road Surface	Good	

DECK


Span 1

Concrete Deck	Good	
---------------	------	--

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 2 of 3
Date Printed: 2015/11/18
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-281	Site #:	G6-281	Road Name:	PARSNIP EAST	Inspection Date:	2015/09/21
--------------	--------	---------	--------	------------	--------------	------------------	------------

Curb Rail/Blocks/Posts	Fair	Looks good but fruiting bodies evident . change for steel bullrails low use road
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.4	Estimated Present Water Level Width:	6.0
	Estimated High Water Level Clearance:	2.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Medium	\$1.00	Replace two missing delineators LC Side

MONITORS	#	Description

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 3 of 3
Date Printed: 2015/11/18
User Id: IDIR\JOLMSTED
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-281	Site #:	G6-281	Road Name:	PARSNIP EAST	Inspection Date:	2015/09/21
GENERAL	Inspector's Comment:	Replace missing delineators, low chain side - Medium Priority. M.D.					
	Replacement Date for full log haul traffic (year):			2050	Replacement Date for light vehicle traffic (year):		
	Current Inspection Load Rating:		91.00	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Accepted By Jason Olmsted on 11/18/2015 3:11:55PM	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.