



BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 1 of 2
Date Printed: 2015/11/18
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001C
File:

Structure #:	G6-328	Site #:	G6-328	Road Name:	THUTADE	Inspection Date:	2015/06/16
KM:	265.80	User km:	70.10	Crossing Name:	Wasi Creek	Next Inspection Date:	2018/06/16
Project File ID #:	9147	Br.	01	Forest District:	Mackenzie Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	300			Outlet Cover (mm):	300		
Footing Type:				Gradient (%):			
Culvert Length (metres):	13.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	363169	UTM Northing:	6207154		
Inspector Name:	Knut Herzog			Year Superstructure Installed:	1988		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	


CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Good	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Good	
Overall	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 2 of 2
Date Printed: 2015/11/18
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001C
File:

Structure #:	G6-328	Site #:	G6-328	Road Name:	THUTADE	Inspection Date:	2015/06/16				
Riprap	Fair										
Roof	Good										
Side Walls	Good										
Trash Rack	Not Applicable										
Wiers/Backwater Structures	Not Applicable										
Wing Wall	Not Applicable										
CHANNEL	Estimated Present Water Level Depth:	0.9			Estimated Present Water Level Width:	6.0					
	Estimated High Water Level Clearance:	0.8									
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No	
	Comment:										
REPAIRS	#	Status	Priority	Estimate	Description						
	1	Required	Medium	\$1.00	Brushing required						
MONITORS	#	Description									
GENERAL	Inspector's Comment:	Brushing required - Medium Priority. M.D.									
	Replacement Date for full log haul traffic (year):				2033	Replacement Date for light vehicle traffic (year):					
	Current Inspection Load Rating:		54.00	Design Load GVW (tonnes):		54	Design Vehicle Config.:				
	Professional Inspection Required?		No	Report Status:		Accepted By Jason Olmsted on 11/18/2015 2:41:32PM					
Corporate Bridge Register (CBR)											

Disclaimer:

1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.

2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.