



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 1 of 3
Date Printed: 2016/01/27
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001B
File:

Structure #:	G6-978	Site #:	G6-377	Road Name:	FINA 15440	Inspection Date:	2015/09/26
KM:	0.20	User km:		Crossing Name:	UNK	Next Inspection Date:	2017/09/26
Project File ID #:	10307	Br.	05	Forest District:	Mackenzie Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Superstructure	Steel I-beam			Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials		
Total Length (metres):	9.2	# Spans:	1	Span Length(s) (metres):	9.1		
UTM Zone:	10	UTM Easting:	453685	UTM Northing:	6131602		
Inspector Name:	Edward Folk, P.Eng.			Year Superstructure Installed:	2009		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	couldn't reach interior to check with axe exterior appears okay
Fill	Fair	
Hardware	Fair	
Piles or Posts	Not Applicable	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	starting to rot
Road Surface	Fair	

DECK


Span 1

Curb Rail/Blocks/Posts	Fair	
------------------------	------	--

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 2 of 3
Date Printed: 2016/01/27
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001B
File:

Structure #:	G6-978	Site #:	G6-377	Road Name:	FINA 15440	Inspection Date:	2015/09/26
--------------	--------	---------	--------	------------	------------	------------------	------------

Deck to Girder Bolts	Fair	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Nails	Unrated	covered in mud
Overall Deck Condition	Fair	
Running Planks	Unrated	covered in mud
Sub Deck	Fair	
Ties	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Fair	
Diaphragms	Fair	
Girders	Fair	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.8
	Estimated High Water Level Clearance:	0.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

GENERAL	Inspector's Comment:	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 3 of 3
Date Printed: 2016/01/27
User Id: IDIR\JOLMSTED
Database: PROD
Report Id: CBR001B
File:

Structure #:	G6-978	Site #:	G6-377	Road Name:	FINA 15440	Inspection Date:	2015/09/26
GENERAL	PEng's Comment:						
GENERAL	Replacement Date for full log haul traffic (year):		2030	Replacement Date for light vehicle traffic (year):			
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100	
	Professional Inspection Required?	No	Report Status:	Reviewed By Jason Olmsted on 1/27/2016 9:47:18AM			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.