



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 1 of 3
Date Printed: 2016/01/27
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001B
File:

Structure #:	G6-971	Site #:	G6-385	Road Name:	FISY 4100	Inspection Date:	2015/09/26
KM:	1.90	User km:	1.90	Crossing Name:	UNK	Next Inspection Date:	2017/09/26
Project File ID #:	10558	Br.	01	Forest District:	Mackenzie Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Superstructure	Steel I-beam			Abutments (Left/Right): (looking downstream)	Other		
Total Length (metres):	9.2	# Spans:	1	Span Length(s) (metres):	9.1		
UTM Zone:	10	UTM Easting:	401513	UTM Northing:	6131591		
Inspector Name:	Edward Folk, P.Eng.			Year Superstructure Installed:	2006		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Fair	logs
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	
Fill	Good	
General Abutment Condition	Fair	
Hardware	Fair	
Piles or Posts	Not Applicable	
Riprap	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	1	
Fender Condition	Fair	PI logs
Road Surface	Fair	


DECK

Span 1

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 2 of 3
Date Printed: 2016/01/27
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001B
File:

Structure #:	G6-971	Site #:	G6-385	Road Name:	FISY 4100	Inspection Date:	2015/09/26
--------------	--------	---------	--------	------------	-----------	------------------	------------

Curb Rail/Blocks/Posts	Fair	
Deck to Girder Bolts	Fair	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Nails	Fair	
Overall Deck Condition	Fair	
Running Planks	Fair	
Sub Deck	Good	
Ties	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	2.1
	Estimated High Water Level Clearance:	0.5		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

GENERAL	Inspector's Comment:	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 3 of 3
Date Printed: 2016/01/27
User Id: IDIR\JOLMSTED
Database: PROD
Report Id: CBR001B
File:

Structure #:	G6-971	Site #:	G6-385	Road Name:	FISY 4100	Inspection Date:	2015/09/26
GENERAL	PEng's Comment:						
GENERAL	Replacement Date for full log haul traffic (year):			2036	Replacement Date for light vehicle traffic (year):		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 1/27/2016 11:30:22AM	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.