



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 1 of 3
Date Printed: 2016/01/26
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001B
File:

Structure #:	G1-925	Site #:	G6-416	Road Name:	THNA 44000	Inspection Date:	2015/09/22
KM:	6.80	User km:		Crossing Name:	UNK	Next Inspection Date:	2017/09/22
Project File ID #:	10619	Br.	01	Forest District:	Mackenzie Natural Resource District		
Deck Type:	Timber - Treated - Panels			Running Surface:	Timber Planks		
Superstructure	Steel I-beam			Abutments (Left/Right): (looking downstream)	Other		
Total Length (metres):	15.2	# Spans:	1	Span Length(s) (metres):	15.2		
UTM Zone:	10	UTM Easting:	395269	UTM Northing:	6148623		
Inspector Name:	Edward Folk			Year Superstructure Installed:	2012		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
General Abutment Condition	Good	
Hardware	Fair	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Fair	bin wall-GRS

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	
Road Surface	Good	


DECK

Span 1

Corporate Bridge Register (CBR)

Disclaimer:

- Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 2 of 3
Date Printed: 2016/01/26
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001B
File:

Structure #:	G1-925	Site #:	G6-416	Road Name:	THNA 44000	Inspection Date:	2015/09/22
--------------	--------	---------	--------	------------	------------	------------------	------------

Curb Rail/Blocks/Posts	Good	
Deck to Girder Bolts	Good	
Hardware	Good	
Hand Rails/Walkouts	Not Applicable	
Nails	Good	
Overall Deck Condition	Good	
Running Planks	Good	
Sub Deck	Good	
Ties	Good	

SUPERSTRUCTURE

Span 1

Bracing	Not Applicable	
Diaphragms	Fair	
Girders	Fair	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.5	Estimated Present Water Level Width:	8.5
	Estimated High Water Level Clearance:	1.2		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description

MONITORS	#	Description

GENERAL	Inspector's Comment:	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 3 of 3
Date Printed: 2016/01/26
User Id: IDIR\JOLMSTED
Database: PROD
Report Id: CBR001B
File:

Structure #:	G1-925	Site #:	G6-416	Road Name:	THNA 44000	Inspection Date:	2015/09/22
GENERAL	PEng's Comment:						
GENERAL	Replacement Date for full log haul traffic (year):			2030	Replacement Date for light vehicle traffic (year):		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?		No	Report Status: Reviewed By Jason Olmsted on 1/26/2016 9:13:23AM			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.