



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 1 of 5
Date Printed: 2015/12/10
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-001	Site #:	G6-001	Road Name:	FINLAY FSR	Inspection Date:	2010/11/17
KM:	9.80	User km:	9.80	Crossing Name:	Pack River	Next Inspection Date:	2016/06/10
Project File ID #:	7829	Br.	01	Forest District:	Mackenzie Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Superstructure	Steel I-beam			Abutments (Left/Right): <small>(looking downstream)</small>	Binwall		
Total Length (metres):	72.8	# Spans:	4	Span Length(s) (metres):	16.7, 19.7, 19.7, 16.7		
UTM Zone:	10	UTM Easting:	492719	UTM Northing:	6108176		
Inspector Name:	Ed Folk			Year Superstructure Installed:	1989		
Access:	9.8 km from Hwy 39 down gravel Finlay FSR						

ABUTMENTS

Bearings	Fair	
Binwall	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left <small>(approaching structure)</small>	1	Add 1 u/s side
Delineator Missing Right <small>(approaching structure)</small>	0	
Fender Condition	Fair	one section on L.C D/S side is down fill slope
Road Surface	Good	

DECK

Span 1

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 2 of 5
Date Printed: 2015/12/10
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-001	Site #:	G6-001	Road Name:	FINLAY FSR	Inspection Date:	2010/11/17
Curb Rail/Blocks/Posts	Good	some minor equipment damage					
Deck to Girder Bolts	Good						
Hardware	Good						
Hand Rails/Walkouts	Not Applicable						
Nails	Good						
Overall Deck Condition	Good						
Running Planks	Good						
Sub Deck	Good						
Ties	Good						
Span 2							
Curb Rail/Blocks/Posts	Good						
Deck to Girder Bolts	Good						
Hardware	Good						
Hand Rails/Walkouts	Not Applicable						
Nails	Good						
Overall Deck Condition	Good						
Running Planks	Good						
Sub Deck	Good						
Ties	Good						
Span 3							
Curb Rail/Blocks/Posts	Good						
Deck to Girder Bolts	Good						
Hardware	Good						
Hand Rails/Walkouts	Not Applicable						
Nails	Good						
Overall Deck Condition	Good						
Running Planks	Good						
Sub Deck	Good						
Ties	Good						
Span 4							
Curb Rail/Blocks/Posts	Good	some minor equipment damage					
Deck to Girder Bolts	Good						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 3 of 5
Date Printed: 2015/12/10
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-001	Site #:	G6-001	Road Name:	FINLAY FSR	Inspection Date:	2010/11/17
Hardware	Good						
Hand Rails/Walkouts	Not Applicable						
Nails	Good						
Overall Deck Condition	Good						
Running Planks	Good						
Sub Deck	Good						
Ties	Good						
PIERS							
Pier 1							
Bearings	Fair						
Bracing or Sheathing	Good						
Caps	Good						
Cribs	Not Applicable						
Dolphins	Not Applicable						
Hardware	Good						
Overall	Good						
Piles or Posts	Good						
Riprap	Not Applicable						
Pier 2							
Bearings	Fair						
Bracing or Sheathing	Good						
Caps	Good						
Cribs	Not Applicable						
Dolphins	Not Applicable						
Hardware	Fair						
Overall	Good						
Piles or Posts	Good						
Riprap	Not Applicable						
Pier 3							
Bearings	Fair						
Bracing or Sheathing	Good						
Caps	Good						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 4 of 5
Date Printed: 2015/12/10
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-001	Site #:	G6-001	Road Name:	FINLAY FSR	Inspection Date:	2010/11/17
Cribs	Not Applicable						
Dolphins	Not Applicable						
Hardware	Fair						
Overall	Good						
Piles or Posts	Good						
Riprap	Not Applicable						
SUPERSTRUCTURE							
Span 1							
Bracing	Good						
Diaphragms	Unrated		N/A-no diaphragms				
Girders	Good						
Hardware	Good						
Under Trussing	Not Applicable						
Span 2							
Bracing	Good						
Diaphragms	Unrated		N/A-no diaphragms				
Girders	Good						
Hardware	Good						
Under Trussing	Not Applicable						
Span 3							
Bracing	Good						
Diaphragms	Unrated		N/A-no diaphragms				
Girders	Good						
Hardware	Good						
Under Trussing	Not Applicable						
Span 4							
Bracing	Good						
Diaphragms	Unrated		N/A-no diaphragms				
Girders	Good						
Hardware	Good						
Under Trussing	Not Applicable						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 5 of 5
Date Printed: 2015/12/10
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-001	Site #:	G6-001	Road Name:	FINLAY FSR	Inspection Date:	2010/11/17				
CHANNEL	Estimated Present Water Level Depth:		2.0		Estimated Present Water Level Width:		45.0				
	Estimated High Water Level Clearance:		4.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No	
	Comment:										
REPAIRS	#	Status	Priority	Estimate	Description						
	1	Suggested	High	\$1.00	move fender on L.C. D/S back to approach, laying downslope.						
	2	Suggested	High	\$1.00	Add delineator 1 left						
	3	Suggested	High	\$1.00	Add 2 Bridge ahead signs						
MONITORS	#	Description									
GENERAL	Inspector's Comment:										
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments									
GENERAL	Replacement Date for full log haul traffic (year):			2029		Replacement Date for light vehicle traffic (year):					
	Current Inspection Load Rating:		See footnote		Design Load GVW (tonnes):		91		Design Vehicle Config.:		L100
	Professional Inspection Required?		No		Report Status:		Accepted By IDIR\RMGETZLA on 4/26/2011 9:29:29AM				

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.