



BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 1 of 2
Date Printed: 2015/12/14
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001C
File:

Structure #:	G6-006	Site #:	G6-006	Road Name:	FINLAY FSR	Inspection Date:	2010/09/21
KM:	31.00	User km:	31.00	Crossing Name:	Lost Creek	Next Inspection Date:	2016/10/30
Project File ID #:	7829	Br.	01	Forest District:	Mackenzie Natural Resource District		
Culvert Type:	Elliptical			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,200			Outlet Cover (mm):	1,200		
Footing Type:				Gradient (%):			
Culvert Length (metres):	30.0	Opening Height (mm):	2,700	Opening Width (mm):	4,000		
UTM Zone:	10	UTM Easting:	486499	UTM Northing:	6125006		
Inspector Name:	Greg Honeysett			Year Superstructure Installed:	1980		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	Upstream side
Delineator Missing Left (approaching structure)	2	
Delineator Missing Right (approaching structure)	2	
Fender Condition	None	
Road Surface	Good	

CULVERT ELEMENT

Baffles	Good	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Good	
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	
Outlet	Fair	
Overall	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 2 of 2
Date Printed: 2015/12/14
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001C
File:

Structure #:	G6-006	Site #:	G6-006	Road Name:	FINLAY FSR	Inspection Date:	2010/09/21			
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.3	Estimated Present Water Level Width:	4.0						
	Estimated High Water Level Clearance:	2.4								
HAZARDS	High Water:	Yes	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	Yes
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	Scour occuring at the outlet								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Replacement Date for full log haul traffic (year):	2020	Replacement Date for light vehicle traffic (year):							
	Current Inspection Load Rating:	See footnote	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Accepted By IDIR\RMGETZLA on 4/4/2012 2:21:58PM						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.