



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 1 of 4

Date Printed: 2015/12/14

User Id: IDIR\SMROOKE

Database: PROD

Report Id: CBR001A

File:

Structure #:	G6-009	Site #:	G6-009	Road Name:	FINLAY FSR	Inspection Date:	2013/06/25
KM:	64.00	User km:	64.00	Crossing Name:	Nation Bay	Next Inspection Date:	2017/08/19
Project File ID #:	7829	Br.	01	Forest District:	Mackenzie Natural Resource District		
Deck Type:	Timber - Treated			Running Surface:	Timber Planks		
Superstructure	Steel I-beam			Abutments (Left/Right): (looking downstream)	Other		
Total Length (metres):	111.0	# Spans:	3	Span Length(s) (metres):	16.5, 78, 16.5		
UTM Zone:	10	UTM Easting:	472151	UTM Northing:	6151962		
Inspector Name:	Hans Beurskens			Year Superstructure Installed:	1975		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Good	
Fill	Good	
General Abutment Condition	Good	
Hardware	Good	Missing bolts on right abutment cap
Piles or Posts	Good	
Riprap	Not Applicable	
Wing Wall	Good	

APPROACHES

Alignment	Fair	soft hole before right approach
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Road Surface	Good	

DECK

Span 1

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 2 of 4

Date Printed: 2015/12/14

User Id: IDIR\SMROOKE

Database: PROD

Report Id: CBR001A

File:

Structure #:	G6-009	Site #:	G6-009	Road Name:	FINLAY FSR	Inspection Date:	2013/06/25
Curb Rail/Blocks/Posts	Good						
Deck to Girder Bolts	Good						
Hardware	Good						
Hand Rails/Walkouts	Not Applicable						
Nails	Good						
Overall Deck Condition	Good						
Running Planks	Good						
Sub Deck	Good						
Ties	Good						
Span 2							
Curb Rail/Blocks/Posts	Good						
Deck to Girder Bolts	Good						
Hardware	Good						
Hand Rails/Walkouts	Not Applicable						
Nails	Good						
Overall Deck Condition	Good						
Running Planks	Good						
Sub Deck	Good						
Ties	Good						
Span 3							
Curb Rail/Blocks/Posts	Good						
Deck to Girder Bolts	Good						
Hardware	Good						
Hand Rails/Walkouts	Not Applicable						
Nails	Good						
Overall Deck Condition	Good						
Running Planks	Good						
Sub Deck	Good						
Ties	Good						
PIERS							
Pier 1							
Bearings	Good						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 3 of 4
Date Printed: 2015/12/14
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-009	Site #:	G6-009	Road Name:	FINLAY FSR	Inspection Date:	2013/06/25
Bracing or Sheathing	Good						
Caps	Good						
Cribs	Not Applicable						
Dolphins	Not Applicable						
Hardware	Good						
Overall	Good						
Piles or Posts	Good						
Riprap	Not Applicable						
Pier 2							
Bearings	Good						
Bracing or Sheathing	Good						
Caps	Good						
Cribs	Not Applicable						
Dolphins	Not Applicable						
Hardware	Good						
Overall	Good						
Piles or Posts	Good						
Riprap	Not Applicable						
SUPERSTRUCTURE							
Span 1							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Good						
Under Trussing	Not Applicable						
Span 2							
Bracing	Good						
Diaphragms	Good						
Girders	Good						
Hardware	Good						
Under Trussing	Not Applicable						
Span 3							
Bracing	Good						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 4 of 4
Date Printed: 2015/12/14
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-009	Site #:	G6-009	Road Name:	FINLAY FSR	Inspection Date:	2013/06/25			
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	100.0			Estimated Present Water Level Width:	100.0				
	Estimated High Water Level Clearance:	15.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
	1	South pier bolts								
	2	paint on steel								
GENERAL	Inspector's Comment:	This bridge is to be added to the close proximity for next year. Past inspections noted broken bolts on south pier that should be monitored. It was also noted in the bridge file in 1992 that the steel should be repainted, there is not record that this was completed.								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Replacement Date for full log haul traffic (year):			2025	Replacement Date for light vehicle traffic (year):					
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:		L100	
	Professional Inspection Required?		No	Report Status:		Accepted By Jason Olmsted on 12/9/2013 12:00:00AM				
Corporate Bridge Register (CBR)										

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.