



BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 1 of 2
Date Printed: 2015/12/14
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001C
File:

Structure #:	G6-011	Site #:	G6-011	Road Name:	FINLAY FSR	Inspection Date:	1998/10/20
KM:	80.80	User km:	80.80	Crossing Name:	Unnamed creek	Next Inspection Date:	2016/06/25
Project File ID #:	7829	Br.	01	Forest District:	Mackenzie Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1			Outlet Cover (mm):	1		
Footing Type:				Gradient (%):			
Culvert Length (metres):	18.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	456161	UTM Northing:	6156848		
Inspector Name:	unknown			Year Superstructure Installed:	1997		
Access:	Inspection status: Inspect - even though size of pipe is 1600mm (<2000mm). This pipe is sitting on a flood plain - District advises to continue inspections. Only one pipe located at this site. MM April 4/12						

APPROACHES

Bridge Ahead Signs Missing	2	No Comment Available -Converter.RNI
Delineator Missing Left (approaching structure)	2	No Comment Available -Converter.RNI
Delineator Missing Right (approaching structure)	2	No Comment Available -Converter.RNI
Posted Load Rating	0.0	No Comment Available -Converter.RNI
Road Surface	Good	No Comment Available -Converter.RNI

CULVERT ELEMENT

Coupled Connections	Good	No Comment Available -Converter.RNI
Coating	Good	No Comment Available -Converter.RNI
Fill	Good	No Comment Available -Converter.RNI
Floor	Good	No Comment Available -Converter.RNI
Inlet	Good	No Comment Available -Converter.RNI
Outlet	Good	No Comment Available -Converter.RNI
Roof	Good	No Comment Available -Converter.RNI
Side Walls	Good	No Comment Available -Converter.RNI

CHANNEL	Estimated Present Water Level Depth:		Estimated Present Water Level Width:							
	Estimated High Water Level Clearance:	1.0								
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 2 of 2
Date Printed: 2015/12/14
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001C
File:

Structure #:	G6-011	Site #:	G6-011	Road Name:	FINLAY FSR	Inspection Date:	1998/10/20
REPAIRS	#	Status	Priority	Estimate	Description		
MONITORS	#	Description					
GENERAL	Inspector's Comment:	Approach: No rip-rap at the outlet - light scour at the left side. Culvert: 4) two dents in the connection.					
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments					
GENERAL	Replacement Date for full log haul traffic (year):		2037		Replacement Date for light vehicle traffic (year):		
	Current Inspection Load Rating:		See footnote	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Submitted By Admin on 5/1/2008 11:58:29PM	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.